

CS3/SPF17020690/11961

DO PAID

Wilson

ASSIGNMENT (OFFICE)

From: Abdul Rahman

SPF

30-05-2018

Referred to:

OD (1) WS/TIRES / OD BUS / EVA / INV / MV / C

To Inspect Vehicle No: FBD 2362Y

Insured: QX 567D

At Working on: K & T Accessory

93856103

or 3006 Ubi Rd | #01-372, 408700

Policy No:

Claim No: AEMD/105/009/2017/142

Sum Insured:

Excess:

Make of Vehicle:

Client's Name:

'wp'

After 5pm

DCA 27/10/2017

CA / RIV / REP. / REV 24 HRS

Date/Time: 1:49 @ 30/10/17

Person Contacted: Mr. Christopher

Work Done:

Status: OUT

Date/Time: Action/Inspection (X) Estimate

Do Not Finalize

FBD 2362Y-X

QX 567D-NA/INC 12010349 / 07-D.O.A: 18/05/2012

30/10/17 @ 6:30am checked with Christopher, the motorcycle not yet start repair.
Still awaiting for liability.

L/S #2800 4h (Red @ 1400, 33%)

RECEIVED 23 JUL 2018

PPS
10/10/10

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
To inspect Vehicle No FBD 2362 Y
at Workshop in K and T Accessories
of 3056, ubi Rd 1, # 21-372
Insured
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection

NS	OS

Est. or Market Value
JDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 3.4 days Res: Yes or No
Lump Sum: _____ % 3 Val: Yes or No
CA / REV / REP / 24 HRS
Date: _____ Person Contacted: _____
Vehicle IN / OUT

Veh No: FBD 2362 Y Page: 19/12/2008
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Shank cc: 645
Color: Black Insured / Std / NI / NA
Sp Reading: 146225 * Pass: Insured / Std / NI / NA
Eng No: _____
C No: JS1B1112100118798
Gen: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 110 / 80 R 19
R: 150 / 70 R 17
BS / DUN / EXNOVA / GY / FS / LIZ / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: _____ Rear: _____
R.Bal: 3 mm R.Bal: 3 mm
L.Bal: _____ mm L.Bal: _____ mm
D.O.A: 27/12/2007 to 30/12/2007
Survey held at: _____
Des. of Damages: Frt / Rear / OS / NS / UC / Rooftop or
The UC / Chassis frame / Body Structure affected due to collision

Date Time Action Instruction:
11/4 Submit DAR report - 15 12150
Accident Report Not Given - Only P. Ins Report

RECEIVED 11 APR 2010

Date Time File Pass: 22/12
Date Time File Return: _____
☐ : Preli. Report
☐ : Final Report
Days Of Repair: 84
Resurvey No. of Trip: _____
Add Fee: ☐ Site Insp \$
☐ Interview \$
☐ Tech Insp \$
☐ Weekend \$
Report Format: DAR 70
Lump Sum / I.B.R: 2800
Date Time File Pass: _____
Date Time File Return: _____
200

Celine Fong (LKKAUTO)

From: Olivia Lau (LKKAUTO)
Sent: Wednesday, 30 May 2018 9:57 AM
To: assignments
Cc: SUR
Subject: [SPF]: Request Re-Evaluation for FBD2362Y
Attachments: 2017-142 LKK Rpt16Apr2018.pdf, 2017-142 LH TeoAppraisalRpt.pdf, Re-Evaluation. FBD2362Ydocx.pdf

LKK Ref: CS3/SPF17020690/Wqbs2

Hi Assignments Team,

FYNA please.

Best Regards,

Olivia Lau | Admin Manager

LKK Auto Consultants

phone: 6256-3561 | email: olivialau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Make
good
use of
Today

From: Abdul Rahman MOHAMAD SALIM (SPF) [mailto:Abdul_Rahman_Mohamad_Salim@spf.gov.sg]
Sent: Monday, 28 May, 2018 2:48 PM
To: Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>
Cc: Rosalyn TAN (SPF) <Rosalyn_TAN@spf.gov.sg>
Subject: Request Re-Evaluation for FBD2362Y

Our Ref: AEMD/105/009/2017/142

Dear Olivia,

We spoke earlier wrt to the Damage Assessment Report dated **16 Apr 2018** by your Automotive Assessor, Wilson Teo Cheng Ming and K K Lau as attached.

Please find the scanned copy of M/s H L Teo Appraisal Services Rpt of **FBD2362Y** and your assignment for **re-evaluation** attached for your reference.

Regards

Abdul Rahnan (Mr)
Accident Claims Officer
Automotive Engineering & Management Division
Police Logistics Department
Singapore Police Force
DID: (65) 6478 4840 | FAX: (65) 6478 4848



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



**SINGAPORE
POLICE FORCE**



T/20171027/2133

Police Station Of Origin:
Kreta Ayer NPP
32 North Canal Road SINGAPORE 059282
Tel No: 1800-5359999

1 of 3

Report No. T/20171027/2133

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/10/2017 17:38		Vide Report No.: A/20171027/0057		Station Diary No.: 79	
Informant's Particulars					
Name of Informant: CHRISTOPHER RAJAPPAN JAMES			Address: APT BLK 911 HOUGANG STREET 91 #02-62 SINGAPORE 530911		
ID Type / ID No.: NRIC NO / S1801110G			Contact No.: Home/Office: Mobile: 93856103		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 50	Date of Birth: 23/08/1967	Type of Informant: Rider		
Race: Indian			Language: English		Institution / School Name:
Occupation: Senior Executive			Driving Licence Information: Class: 2B,2A,2 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Police Vehicle	Drink Drive: No	Date/Time of Accident: 27/10/2017 10:05	Type of Location: Car Park
Location: Along Road 1 NORTH CANAL ROAD Hong Lim Park carpark, motorcycle lot number 3.				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Controlled by Others e.g. Workmen		Traffic Volume: No Traffic
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBD2362Y	Motorcycle	SUZUKI	DL650AK8	Black	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBD2362Y	DIRECT ASIA INSURANCE (SINGAPORE) PTE. LTD.	MC/00374397	21/03/2017	20/03/2018

3



**SINGAPORE
POLICE FORCE**



T/20171027/2133

2 of 3

Police Station Of Origin:

Kreta Ayer NPP

32 North Canal Road SINGAPORE 059282

Tel No: 1800-5359999

Report No. T/20171027/2133

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	CHRISTOPHER RAJAPPAN JAMES	ID No.	S1801110G
Related Vehicle	FBD2362Y (Motorcycle)	Contact No.	93856103
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 27/10/2017 at about 0900 hrs I parked my motorcycle FBD 2362Y Suzuki at the motorcycle parking lot number 3 at Hong Lim Park open space carpark and left for work.

On 27/10/2017 at about 1630 hrs I returned to my motorcycle and discovered my motorcycle was damaged and a piece of Police note on my motorcycle asked me to lodge a Traffic accident report. Then I realised that a Police car has involved in traffic accident with my parked motorcycle vide incident A/20171027/0057.

The damages on my motorcycle; right signal light broken, slight dent and some scratches on the right fairing near to the fuel tank area, main-stand was broken and detached.

4



**SINGAPORE
POLICE FORCE**



T/20171027/2133

3 of 3

Report No. T/20171027/2133

Police Station Of Origin:

Kreta Ayer NPP

32 North Canal Road SINGAPORE 059282

Tel No: 1800-5359999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

A /

SI JUAY WEE HWA

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / DDGVT /

SI NOR AFFENDY BIN JAFFAR

Contact No.: 65476209

Signature Of Informant:

[Handwritten signature] 27/10

Date/Time:

27/10/2017 17:38

Classification Of Case:

Authentication Stamp

NP168

⑤

☐ Disabled (1) Enabled (4) Critical (5) Cn (8) Detected
☐ Deleted (9) Deleted (10) Deleted (11) Deleted (12) Deleted
☐ Deleted (13) Deleted (14) Deleted (15) Deleted (16) Deleted

FOR MOTORCYCLE

1. Replace $\sqrt{}$ 2. Replace () 3. Check 7000-01000

Vehicle No:

FBI 2362 Y

Motorcycle

Motorcycle				CON	AC	Qty
NAC	INC	Item				
1001	991856	Front Number Plate				
3001	995065	Front Tyre				
3002	995095	Front Rim				
3003	994872	Front Tyre Rim Spoke				
3004	991771	Front Fender Wheel Guard	RT/SC	✓		
3005	991283	Front Brake Disc				
3006	991281	Front Brake Caliper				
3007	991785	Front Fork Assy	RT	✓		
3008	991787	Front Fork Inner Tube				
3009	991789	Front Fork Outer Tube				
3010	991167	Front Fork Bracket				
3011	991182	Front Fork Oil Seal				
3012	991174	Front Fork Garnish				
3013	992376	Front Headlamp Rim				
3014	992328	Front Headlamp				
3015	992337	Front Headlamp Bracket				
3016	992345	Front Headlamp Fairing	SC	✓		
3017	992130	Front Windshield				
3018	992134	Front Wind Mirror				
3019	995245	Front LH Signal Lamp	SC	✓		
3020	995246	Front RH Signal Lamp	SC	✓		
3021	992556	Meter Casing				
3022	992553	Meter Assy				
1118	991019	ERP Bracket				
1119	991020	ERP Unit				
3023	992446	Ignition Switch				
3024	992442	Ignition Key Assy				
3025	990706	Cowling Stay				
3026	994470	Steering Stem				
3027	994427	Steering Cone				
3028	992299	Handle Bar				
3029	992312	Handle Bar Switch				
3030	992310	Handle Bar Grip				
3031	995184	Handle Bar Balancer LH				
3032	992300	Handle Bar Balancer RH				
1252	992179	Fuel Tank				
3033	990438	Brake Reservoir				
3034	990621	Clutch Lever				
3035	992293	Hand Brake Lever	RT/SC	✓		
3036	991119	Side Fairing				
3037	994220	Side Fairing Top Garnish				
3038	994219	Side Fairing Inner Garnish				
3039	991118	Fairing Shield (LHS)		R		
3040	992047	Front Top Fairing Inner Garnish				
3041	991123	Fairing Top Garnish				
3042	990538	Center Fairing				
3043	993378	Rear Fairing (LHS)		R		
3044	991121	Fairing Stopper				
3045	991117	Fairing Lower				
		Front Fairing (LHS) 100/SC		✓		
		→ (RHS)				
		RHS Fairing 100/SC		✓		

[illegible]

No of Items: _____

Assessor: _____

Labour 400

3 Day Report

As a result, the conversion

LHTEO Appraisal Services

3 Gambas Crescent, #07-14 Nordcom 1, Singapore 757088 Tel: 63966319 Fax: 63966320 Email: lhtas@singnet.com.sg

Loss Adjuster, Consulting Automotive Engineer, Accident Reconstruction & Analyst.**VEHICLE APPRAISAL REPORT**

Mr. Christopher Rajappan James
Apt Blk 911 Hougang Street 91
#02-62
Singapore - 530911

Our Ref : TP/1712/FBD2362/KT
Date : 25 January 2018

REFERENCE PARTICULARS

Your Reference No : Not Advised
Date of Accident : 27 Oct 2017

Date of Assignment : 19 Dec 2017
Date of Inspection : 19 Dec 2017
Date of Re-inspn. : 27 Dec & 15 Jan 2018

PARTICULARS OF VEHICLE

Regn. No : FBD 2362Y
Make : SUZUKI
Model : DL650AK8
Year : 2008 (COE.Exp : Dec 2018)

Odometer : Meter Damage
Color : Black
Chassis No. : JS1B1112100115798
Engine No : P509179914

TYRE / CONDITION

Location	Make
Front	Michelin
Rear	Michelin

Size
110 / 80 R 19
150 / 70 R 17

Thread Balance
5 mm
5 mm

DAMAGE PROFILE

The motor cycle sustained damage on Frontal and both sides.
Please refer to photographs and assessment of repairs for details.

ASSESSMENT SUMMARY

Repair cost to the vehicle is assessed as \$ **4,200.00 lump sum.**

Survey conducted at: K & T Accessory Trading

Enclosed (64) photographs depicting damage to the vehicle.

Estimated time required for repairs: (6) days.

The survey was conducted on a **WITHOUT PREJUDICE BASIS.**

ASSESSMENT FOR REPAIR : FBD 2362 Y

Qty	Description	Condition	Repairer's Estimate	Our Assessment
1 pc	Wind shield	Cut	307.00	307.00 X
1 pc	Head cowling	Cut	371.00	371.00 ✓
1 pc	Head cowling inner panel	Warped	150.00	150.00 X
		Slight Grazed - Reused	532.00	~ X
1 pc	Headlamp assy	Cut	98.00	98.00 ✓
1 pc	Mirror RH	Cracked	93.00	93.00 ✓
1 pc	Front signal LH	Broken	93.00	93.00 ✓
1 pc	Front signal RH	Bent	59.00	59.00 ✓
1 pc	Brake lever	Cut	277.00	277.00 ✓
1 pc	Front fender	Necessary	24.60	24.60 ✓
2 pcs	Front fender emblem @12.30	Cut	620.00	620.00 ✓
1 pc	Fork outer tube RH	Cut	333.00	333.00 10 JSN
1 pc	Side cowling LH	Dented	333.00	333.00 ✓
1 pc	Side cowling RH	Necessary	74.00	74.00 ✓
2 pcs	Emblem, "S" @37.00	Necessary	142.00	142.00 ✓
2 pcs	Emblem, "V-STROM" @71.00	Cut	111.00	111.00 X
1 pc	Front footrest assy RH	Bent	137.00	137.00 X
1 pc	Brake pedal	Cut	308.00	308.00 60 SN
1 pc	Tail cover LH	Cut	308.00	308.00 60 SN
1 pc	Tail cover RH	Broken	329.00	329.00 ✓
1 pc	Main stand	Cut	30.00	30.00 ✓
1 pc	Rear footrest RH	Cut / Bent	151.00	151.00 ✓
1 pc	Rear footrest bracket RH	Cut	71.00	71.00 ✓
1 pc	Exhaust protector, front	Cut	176.00	176.00 ✓
1 pc	Exhaust protector, chrome	Broken	137.00	137.00 ✓
1 pc	Rear number plate lamp assy	Grazed - Respray	144.00	S.N. 80.00 60 SN
1 pc	Rear fender		5,408.60	4,732.60
		Less 10%	540.86	473.26 3078.6
			4,867.74	4,259.34 2770.74

Special Nett Items

	Add special nett from above		80.00	
1 set	Steering cone and bearings	Necessary	180.00	120.00 ✓
1 pc	Body slider RH	Cut	80.00	80.00 X
1 pc	Engine under guard	Cut - Respray	See Labour	See Labour X
1 pc	Rear number plate	Bent	18.00	15.00 ✓
			278.00	295.00

Labour Charges

1	Repair and respray engine under guard	150.00	120.00
2	Body alignment	300.00 11	250.00 X
3	Workmanship to repair, renew damaged areas	400.00	350.00 250
		850.00	720.00

Total Parts & Labours Concluded

5,995.74 5,274.34

Lump Sum Repair Adjustment

4,200.00

Our Ref.: TP/1712/FBD2362/KT

ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle. We have listed the breakdown of our findings and our recommendation as per assessment above.

Inspected by



Dylan Lee

Faithfully Yours
L H TEO Appraisal Services



Teo Liak Hoo
Advance Automotive Engineer (UK)
Dip. Mech. Engr. M Prof BTM(Dip.BTM)
MIIE, MIMI, AMSIM an



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref : CS3/SPF17020690/Uqbs2-1

ACCIDENT CLAIM SECTION(SINGAPORE POLICE
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD
POLICE ACADEMYSINGAPORE 298333

Date : 26-07-2018



ATTN: ABDUL RAHMAN

Code : SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 567D	Veh. Inspected	FBD 2362Y
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2017/142	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	30/05/2018

2. Vehicle Particulars & Condition

Make & Model	SUZUKI	c.c	645
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JS1B1112100115798	Colour	BLACK
Odometer	146220	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	110/80R19	MICHELIN	3 mm
L/H Front Tyre			mm
R/H Rear Tyre	150/70R17	MICHELIN	3 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	27/10/2017	Inspection Date	30/10/2017
Survey held at	K & T ACCESSORY TRADING PTE LTD BLK 3006 #01-372 UBI ROAD 1 SINGAPORE 408700		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBD 2362Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	WIND SHIELD	SERVICEABLE	307.00	-
1	HEAD COWLING	CUT	371.00	371.00
1	HEAD COWLING INNER PANEL	NOT NECESSARY	150.00	-
1	HEADLAMP ASSY	SERVICEABLE	532.00	-
1	MIRROR RH	CUT	98.00	98.00
1	FRONT SIGNAL LH	CRACKED	93.00	93.00
1	FRONT SIGNAL RH	BROKEN	93.00	93.00
1	BRAKE LEVER	BENT	59.00	59.00
1	FRONT FENDER	CUT	277.00	277.00
2	FRONT FENDER EMBLEM @ \$12.30	NECESSARY	24.60	24.60
1	FORK OUTER TUBE RH	CUT	620.00	620.00
1	SIDE COWLING RH	DENTED	333.00	333.00
2	EMBLEM "S" @ \$37.00	NECESSARY	74.00	74.00
2	EMBLEM "V-STROM" @ \$71.00	NECESSARY	142.00	142.00
1	FRONT FOOTREST ASSY RH	NOT NECESSARY	111.00	-
1	BRAKE PEDAL	NOT NECESSARY	137.00	-
1	MAIN STAND	BROKEN	329.00	329.00
1	REAR FOOTREST RH	CUT	30.00	30.00
1	REAR FOOTREST BRACKET RH	CUT	151.00	151.00
1	EXHAUST PROTECTOR, FRONT	CUT	71.00	71.00
1	EXHAUST PROTECTOR, CHROME	CUT	176.00	176.00
1	REAR NUMBER PLATE LAMP ASSY	BROKEN	137.00	137.00
	LESS 10% DISCOUNT		-431.56	-307.86
			3,884.04	2,770.74
1	SIDE COWLING LH (SN)	RESPRAY	333.00	100.00
1	TAIL COVER LH (SN)	RESPRAY	308.00	60.00
1	TAIL COVER RH (SN)	RESPRAY	308.00	60.00
1	REAR FENDER (SN)	RESPRAY	144.00	60.00
	LESS 10% DISCOUNT		-109.30	-
			983.70	280.00
SPECIAL NETT ITEMS				
1	SET STEERING CONE AND BEARINGS (SN)	NECESSARY	180.00	120.00

Report Ref No. CS3/SPF17020690/Uqbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BODY SLIDER RH (SN)	NOT NECESSARY TO REPAIR SEE LABOUR BENT	80.00	-
1	ENGINE UNDER GUARD (NPA) (SN)		-	-
1	REAR NUMBER PLATE (SN)		18.00	15.00
			278.00	135.00
	LABOUR	NOT NECESSARY		
	REPAIR AND RESPRAY ENGINE UNDER GUARD.		150.00	120.00
	BODY ALIGNMENT.		300.00	-
	WORKMANSHIP TO REPAIR, RENEW DAMAGED AREAS. INCLUSIVE OF THE REPAIR OF ENGINE UNDER GUARD.		400.00	250.00
			850.00	370.00
GRAND TOTAL			5,995.74	3,555.74
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,800.00

Report Ref No. CS3/SPF17020690/Uqbs2-1

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.