

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18010952/Ups3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH			Date: 29-04-2020 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLR 8465C	Veh. Inspected	GBE 7761R
	Policy No.		Coverage (\$)	0.00
	Claim No.	S8M00KS9	Excess (\$)	0.00
	Assign From		Assign Date	18/06/2018
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KDH2010186126	Colour	GREY
	Odometer	173569	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	HIFLY	6 mm
	L/H Front Tyre	195 R15	HIFLY	6 mm
	R/H Rear Tyre	195 R15	HIFLY	6 mm
	L/H Rear Tyre	195 R15	HIFLY	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	23/05/2018	Inspection Date	01/08/2018
	Survey held at	THINK ONE AUTOCARE PTE LTD		
		NO.18 DEFU AVENUE 2 SINGAPORE 539522		
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days			