

7/10/2007

ASS. REC. BY:

REF:

CS/FCU8010992/Rlvbn2

Special Instruction:

SUMMARY

ASSIGNMENT (Office)

From (Person): WJG Karen Tan of FCL Date/Time: 18062018 1041am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLS 1739DInsured: SHD 3116Pat Workshop m/s PerformanceTel: 639 0174of 303 Alexandra Rd

Policy No: _____

Claim No: D18004726MFSH

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 12062018

(Client's Record)

CA / REV / REP. / REV 24 HRS. DS.

02072018

H.O.D. Endorsement: _____

Date/Time: 18052018 1:53pmPerson Contacted: Caroline

Vehicle IN / OUT

Date/Time

Action/Instruction (

✓) Estimate

Mama Oria.

SLS 1739D-X

SHD 3116P-NS/INC16024157/H146m2

DA: 15122016

3/7/18

Email preli revised to FCI

8/8/18

Final fig \$ 5692.45 confirmed by email (Recd 2137.20, 2790)

(08/11/13) wef
ASS. REC. BY:

REF: FCI

4120w

ASSIGNMENT

From: Date: 02/07/2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLS 1739D

at Workshop m/s Performance

of 303 Alexandra Rd

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Menna

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1 up

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLS 1739D Yr Regn: 2017 / SEP

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 116D c.c. 1496

Colour: BLUE A/C: Insured / Std / NI / NA

Sp. Reading: 31993 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA1V72070V945135

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 225/40ZR18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 12/06/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

8/8 - typist

Report Format: cws

Lump Sum / I.B.I: (\$ 5692.45)

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

TOTAL

150

50

50

26

276



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18004726MFSH
Our Ref: CS/FCI18010992/R1vb

Date : 3/7/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SLS 1739D


We thank you for your instruction on 18/6/2018

Please be informed that we had conducted the inspection of the above mentioned
2/7/2018 at the premises of M/s PERFORMANCE MOTORS LIMITED
and have the following to report:-

Workshop Estimate Amount	: S\$7,721.50
Revised Estimate Amount	: S\$2,871.30
"Check" Items Amount	: S\$3,831.20
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
front o/s portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 8 August 2018 11:46 AM
To: 'PBSP'; Rasul (LKKAUTO); SUR
Subject: RE: FINAL REPORT / SLS1739D

Dear Caroline,

WITHOUT PREJUDICE

Confirmed \$5,692.45 before GST

Repair days: 3 days

Kindly send Final invoice and all supporting documents to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Tuesday, 7 August 2018 6:31 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: FINAL REPORT / SLS1739D

Dear Rasul

We refer to the above and the attached Final Report.

Please confirm COR as follows:

Total Labour : 2,465.00
Total Parts : 3,227.45
Total Labour & Parts : 5,692.45

Repair days: 3

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

MOTOR SURVEY ASSIGNMENT

Date	13-06-2018	Our Ref No. D18004726MFSH
Accident Date	12-06-2018	Claim Type. Third Party
Insured Vehicle	SHD3116P	Third Party Vehicle. SLS1739D
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
Contact Person.	CAROLINE	
Contact No.	63190174/ 0	Fax No. 64794601
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 3 July 2018 12:14 PM
To: 'Claim Workflow System'
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004726MFSH/1, SLS 1739D
Attachments: SLS 1739D PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLS 1739D
Date of survey: 2/7/2018
Number of days :3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 18 June 2018 1:55 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004726MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 18 June, 2018 10:41 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004726MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180

Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944

Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

13 JUN 2018

Estimate No. : b1 47297
Date Estimated : 13/06/2018
Prepared By : Merina Chia San San

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

GABCAR
11 Rambai Road
#05-07 Sunshine Regency

Singapore 424331

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS1739D	V945135	12/09/2017	116d	0

DESCRIPTION

To replace front bumper including attachments etc and
to knock out dented area caused by accident

To paint front bumper

To replace left or right headlight including program
and conduct tests for proper function.

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

Sundries.

VALUE

✓ 850 1,700.00
✓ 934 1,038.00
✓ 451? 531.00
✓ 150 177.00
✓ A66 80.00

Total Labour 1: 3,526.00

DESCRIPTION

FRT BUMPER TOP MOUNT
RH CLOSED GRID (BASIS)
IMPACT ABSORNER TOP
FRONT BUMPER TOWING COVER PRIMED
FRT BUMPER PANEL PRIMED
EMBLEM GROMMET
FRT BUMPER LOWER MOUNT
PLAQUE 82MM
RH HEADLIGHT LED TECHNOLOGY
RH FOG LIGHT LED
DECOUPLING RING PDC TORQUE CONVERTE

QTY PRIC

1 361.65
1 93.20
1 42.45
1 38.00
1 786.20
2 0.80
1 128.00
1 69.50
1 2,263.60
1 391.10
4 5.05

VALUE

✓ 361.65
✓ 93.20
✓ 42.45
✓ 38.00
✓ 786.20
✓ 1.60
✓ 128.00
✓ 69.50
✓ 2,263.60
✓ 391.10
✓ 20.20

Total Parts : 4,195.50

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

260, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47297
Date Estimated : 13/06/2018
Prepared By : Merina Chia San San

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS1739D	V945135	12/09/2017	116d	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims CD / Third Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Estimate No. 02/07/18 @ 1415 Excess \$ _____

Surveyor's Name Rahul Sign. _____

Surveyor's Tel. 92000068 Authorised (Yes/No) _____

Estimate Date _____ Time _____

Estimate Validity 3 days

[Handwritten signature]
3/7/18

7829.65

Labour 1	:	3,526.00
Parts	:	4,195.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	540.51
Grand Total	:	8,262.01

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 47297
Date Estimated : 13/06/2018
Prepared By : Merina Chia San San

Page No. :

REPAIR FOR -
GABCAR
11 Rambai Road
#05-07 Sunshine Regency

Singapore 424331

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SLS1739D	V945135	12/09/2017	116d	0		
DESCRIPTION				ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments include knocking out dented areas caused by the accident				850.00		850.00
To spray paint front bumper				934.00		934.00
* To replace RH LED technology headlight include programming and conducting tests for proper function				451.00		451.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.				150.00		150.00
Sundries.				80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT	
# CLAMP *	3.20	10.00		32.00	(A)
FRT BUMPER PANEL PRIMED	786.20	1.00		786.20	
# SET PDC HOLDER FRONT *	23.10	1.00		23.10	(A)
PLAQUE 82MM	69.50	1.00		69.50	
RH HEADLIGHT LED TECHNOLOGY	2,263.60	1.00		2,263.60	
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05	(A)

SUPPLEMENTARY ITEMS

Total Labour :	2,465.00
Total Parts :	3,227.45
Total Labour & Parts :	5,692.45
Deduction for Excess :	
Total Repair Costs less Excess:	5,692.45
GST @7%:	398.47
Grand Total :	6,090.92

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020061-X



SUPPLEMENTARY

Estimate No. : b1 47297
Date Estimated : 13/06/2018
Prepared By : Merina Chia San San

Page No. :

REPAIR FOR -
GABCAR
11 Rambai Road
#05-07 Sunshine Regency

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

Singapore 424331

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SLS1739D	V945135	12/09/2017	116d	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLAMP *	3.20	10.00		32.00
# SET PDC HOLDER FRONT *	23.10	1.00		23.10
# (DG/SL) ADHESIVE SET K6 *	53.05	1.00		53.05

Total Labour :	
Total Parts :	108.15
Total Labour & Parts :	108.15



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18010992/R1vbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 14-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3116P	Veh. Inspected	SLS 1739D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004726MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	18/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	BMW 116D	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBA1V72070V945135	Colour	BLUE	
Odometer	31993	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 ZR18	MICHELIN	6 mm	
L/H Front Tyre	225/40 ZR18	MICHELIN	6 mm	
R/H Rear Tyre	225/40 ZR18	MICHELIN	6 mm	
L/H Rear Tyre	225/40 ZR18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/06/2018	Inspection Date	02/07/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 1739D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT BUMPER TOP MOUNT (SN)	SERVICEABLE	361.65	-
1	RH CLOSED GRID (BASIS)(SN)	SERVICEABLE	93.20	-
1	IMPACT ABSORNER TOP (SN)	SERVICEABLE	42.45	-
1	FRONT BUMPER TOWING COVER PRIMED (SN)	SERVICEABLE	38.00	-
1	FRT BUMPER PANEL PRIMED (SN)	DEFORMED	786.20	786.20
2	EMBLEM GROMMET (SN)	NOT NECESSARY	1.60	-
1	FRT BUMPER LOWER MOUNT (SN)	SERVICEABLE	128.00	-
1	PLAQUE 82MM (SN)	NECESSARY	69.50	69.50
1	RH HEADLIGHT LED TECHNOLOGY (SN)	CRACKED	2,263.60	2,263.60
1	RH FOG LIGHT LED (SN)	NOT NECESSARY	391.10	-
4	DECOUPLING RING PDC TORQUE CONVERTE (SN)	NOT NECESSARY	20.20	-
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
10	CLAMP (ADDITIONAL)(SN)	NECESSARY	32.00	32.00
1	SET PDC HOLDER FRONT (ADDITIONAL)(SN)	NECESSARY	23.10	23.10
1	(DG/SL) ADHESIVE SET K6 (ADDITIONAL)(SN)	NECESSARY	53.05	53.05
			4,383.65	3,307.45
LABOUR				
	TO REPLACE FRONT BUMPER INCLUDING ATTACHMENTS ETC AND TO KNOCK OUT DENTED AREA CAUSED BY ACCIDENT.		1,700.00	850.00
	TO PAINT FRONT BUMPER.		1,038.00	934.00
	TO REPLACE LEFT OR RIGHT HEADLIGHT INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION.		531.00	451.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.		177.00	150.00
	-		-	-
	-		-	-
	-		-	-
			3,446.00	2,385.00
GRAND TOTAL			7,829.65	5,692.45



RECOMMENDED COST OF REPAIRS			5,692.45
-----------------------------	--	--	----------

Report Ref No. CS/FCI18010992/R1vbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.