

6/20/2018

ASS REC BY

REF: CS3 / MSC 18006955 / G1rb-1

Special Instruction: *Longo*

ASSIGNMENT (Office)

From (Person): *Christina Wong* of *MSC* Date/Time: *18062018*

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: *GY 2057J* Insured: *FBK 87372*

at Workshop m/s: *Nee Huat Auto* Tel: *9684 8774*

of *Blk 1 Kaki Bukit Ave 6 #02-27*

Policy No: *MSD / VMFT / 18-990134* Claim No: *MSC / V / 18-000548*

Sum Insured: Excess:

Make of Veh: D.O.A. *13042018*  
(Client's Record)

CA / REV / REP. / REV 24 HRS w/p

Date/Time: *16042018 1056am* Person Contacted: *Richard* Vehicle *IN* / OUT

Date/Time	Action/Instruction ( X ) Estimate	Do Not Finalize
	<i>GY 2057J x</i>	
	<i>FBK 87372 x</i>	
<i>17/4/18</i>	<i>Dismantled</i>	
<i>19/4/18</i>	<i>After Repair</i>	
	<i>Submit &amp; /s \$ 3500 , 6 days</i>	
	<i>Red: \$ 3200 , 48%.</i>	

*[Signature]*  
*20/6/2018*

*Submit Paper survey*

RECEIVED 20 JUN 2018

ASSIGNMENT

From: Date: 16042018 Veh No: 6Y2057J Yr Regn: 26 Jan 2005  
 Estimated Cost: Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer or  
 To inspect Vehicle No: 6Y 2057J Make: Toyota Liteace cc 284  
 at Workshop m/s Nee Huat Auto Colour: Silver A/C: Insured / Std / NI / NA  
 of 1 Koki Bukit Ave 6 #02-27 Sp. Reading: 245787 T/Radio: Insured / Std / NI / NA  
 Insured: Eng/No: CR 42501104  
 Policy No: C/No: Gen. Cond: Good / Fair / Poor / Burnt  
 Claims No: Steering: Insider / Jammed / Leaked / Burnt or  
 Sum Insured: Excess: Brake: Insider / Jammed / Leaked / Burnt or  
 (Client's Record) Mod: S/Rim / STD A/Rim or  
 Make of Veh: Tyre Size: F: 185/60 R15  
 (Policy Condition) R: 11  
 Remark: The veh had commenced its BS / DUN / EXNOVA / GY / FS / LIZA / MIE / OHTSU / PIR / SUMI /  
 repair at the time of inspection. TOYO / YOKO or  
 Bal. or Market Value: Front Rear  
 IDAC Accident Report: Consistent? : Yes or No R/Bal. 6 mm R/Bal. 6 mm  
 GIA / PR Seen: Consistent? : Yes or No L/Bal. 6 mm L/Bal. 6 mm  
 Est. Repairs: days Res.: Yes or No D.O.A. D.O.I. 16-04-18  
 Lum Sum: % 3 Val.: Yes or No Survey held at W/S 5:20pm  
 CA / REV / REP. / 24 HRS Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 Date: Person Contacted: Vehicle: IN / OUT Near o/s  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Estimated repair range \$3,200 - \$4,000
12/6/18	Submit PRS Report
	RECEIVED 13 JUN 2018

Date/Time, File Pass to? ☐ : Preli. Report ☐ : Final Report  
 1) Date/Time, File Return to? Add Fee: ☐ Site Insp (\$)  
 2) ☐ Interview (\$)  
 Report Format : ☐ Tech. Invs (\$)  
 Lum Sum / I.B.I. (\$) ☐ Weekend (\$)  
 Days Of Repair: Resurvey No. of Trip: Survey Fee: 120  
 Transportation: 50  
 3 + RE \$  
 Photos  
 Others: 10  
 TOTAL: 180

## Catherine Chong (LKK Auto)

---

**From:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Sent:** Monday, 18 June, 2018 2:27 PM  
**To:** Christina Wong; assignments  
**Subject:** RE: Our ref:MSC/v/18-000548 TP GY2057J- URGENT-Paper Survey

Dear Christina,

Thank you for the email.

**Dear Catherine,**

**FYNA-CS3/MSG18006955/Gz4be2**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Christina Wong [mailto:Christina\_Wong@sg.msig-asia.com]  
**Sent:** Monday, 18 June 2018 2:19 PM  
**To:** Veron Chen (LKKAuto) <veronchen@lkkauto.com>  
**Subject:** Our ref:MSC/v/18-000548 TP GY2057J- URGENT-Paper Survey

Hi Veron

We refer to our email of 11.6.2018.





We just received the PRI report today, we have just sendback the report, please do Paper survey Urgently.

Thanks

Best Regards

**Christina Wong**  
Senior Executive, Claims Services (Motor)  
Direct line +65 6643 1311 | Direct fax +65 6225 7402 | [christina\\_wong@sg.msig-asia.com](mailto:christina_wong@sg.msig-asia.com)



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us on    

A member of  **MS&AD** INSURANCE GROUP

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Apr 2018		16 Apr 2018 09:58 Edit Adj Rpt	<b>\$0.00</b> Edit Estimates	<b>\$0.00</b> View Rpt		<b>Pending for Survey Report</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS			[Created by insurer]	
Insured:	MUHAMMAD FAZRYAN BIN AZMAN, ID: S9300758A			
Main Claimant:	OCTOPUS DESIGN & CONSULTANT PTE LTD, Co. Reg. No.: 200516794M			
Vehicle Reg. No.:	GY2057J	Date of Loss:	13/04/2018 07:00 - :59 [158 Months and 18 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / MSC/V/18-000548	Policy/Cover Note No.:	MSD/VMS/18-990134 (TP, Fire & Theft) Coverage: 11/03/2018 - 10/03/2019	
Vehicle Reg. No. (Insured):	FBK8737Z	Policy No. (Claimant):		
		Excess:		
Repairer:	M/s. Nee Huat Auto Services (HQ) 1 Kaki Bukit Ave 6 #02-27, Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 20/06/2018]			
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail
<ul style="list-style-type: none"> <li>MSIG_SG (18/06/2018): Report Send Back Alerts - GY2057J (TP)</li> </ul>				
<div> <div> <div> <div>ALL ASSOCIATED TASKS</div> <div> <div>Due Date</div> <div>Priority</div> <div>Type</div> <div>Task Group</div> <div>Subject</div> <div>Handler</div> </div> <div> <div>View All</div> <div>Search Tasks</div> <div>Create New Task</div> <div>Complete</div> </div> <div> <div>Assigned By</div> <div>Completed On</div> <div>Created On</div> <div>Done?</div> </div> </div> <div>No results.</div> </div> </div>				

# WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224

Email: Winsongkk@hotmail.com Contact: 9747 0063


Company Register No. 53326249J

Our Ref: WG/TP/2018-108  
Invoice No: TP/NH/2018-108  
Vehicle No: GY2057J  
Attn: OCTOPUS DESIGN AND CONSULTANT PTE LTD  
Company: NEE HUAT AUTO SERVICES  
Address: No1 Kaki Bukit Ave 6, #02-27. Singapore 417883

Date 17 April 2018

## Invoice

Surveyor Fee:	S\$290
Re-inspection Fee:	S\$50
Transport:	S\$50
Photographs:	S\$68/- (@ \$1 per photo, total 68 photos)
Total:	S\$450

Surveyor: Winsen Goh  
Signature:   
Date: 17/4/2018



# WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647. Singapore 542224  
Email: winsongkk@hotmail.com Contact: 9747 0063  
Company Register No. 53326249J

## ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S OCTOPUS DESIGN AND CONSULTANT PTE LTD  
C/O NEE HUAT AUTO SERVICES  
No1 Kaki Bukit Ave 6, #02-27  
Singapore 417883

Date : 17 April 2018  
Our Ref : WG/TP/2018-108

### REFERENCE PARTICULARS

Date of Accident : 13 April 2018  
Date of Inspection : 16 April 2018

Type of Inspection : Third Party Claim  
Date of Re-Inspn : 17 April 2018

### VEHICLE PARTICULARS

Registration No : GY2057J  
Make : TOYOTA  
Model : LITEAC 5DR  
Year : 2004

Engine No : 3C4007204  
Chassis No : CR425011104  
Odometer : 245181km  
Colour : Silver

### CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good  
Foot Brake : Serviceable  
Hand Brake : Serviceable

General Body Work : Good  
Steering : Serviceable  
Lightings : Serviceable

### TYRE CONDITION (Remaining estimated life of tyre in mm)

	<u>Make</u>	<u>Size</u>
Front Near side	: Yokohama	185/60R15
Front Off Side	: Yokohama	185/60R15
Rear Near Side	: Yokohama	185/60R15
Rear off Side	: Yokohama	185/60R15

<u>Thread Balance</u>
5 mm
5 mm
5 mm
5 mm

### GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the rear portion.  
For details, refer to assessment for repairs and photographs attached.

### ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was S\$6,700.00 nett at lump sum basis. (Subject to GST if applicable)  
Under normal circumstances, estimated period required for repairs : Twelve ( 12 ) working days.

Enclosed Sixty-eight ( 68 ) photographs depicting damage to the vehicle.

Inspection conducted at : NEE HUAT AUTO SERVICES  
No1 Kaki Bukit Ave 6, #02-27 .Singapore 417883

In accordance to your instruction, we have not authorise repairs and inspection was conducted strictly on a "WITHOUT PREJUDICE BASIS".

VEHICLE NO : GY2057J  
MODEL : LITEAC 5DR

Our Ref : WG/TP/2018-18

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

SPARE PARTS	QTY PC/SET	ASSESSED CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
1 REAR BUMPER	1	DEFORMED	\$ 544.00	\$ <del>544.00</del> 420
2 REAR BUMPER HOLDER RH	2	NECESSARY	\$ 121.00	\$ <del>121.00</del> 60.50
3 REAR RH BUMPER REFLECTOR	1	CRACKED	\$ 83.00	\$ 83.00
4 END PANEL	1	DENTED	\$ 581.00	\$ 581.00 XR
5 REAR RH TAILLAMP	1	CRACKED	\$ 383.00	\$ 383.00
6 REAR RH TAILLAMP PANEL	1	DENTED	\$ 290.00	\$ 290.00 XR
7 TAILGATE	1	DENTED	\$ 1,080.00	\$ 1,080.00
8 TAILGATE ABSORBER	2	NOT NECESSARY	\$ 280.00	\$ -
9 TAILGATE EMBLEM	1	NECESSARY	\$ 61.00	\$ 61.00
10 TAILGATE OUTER GARNISH	1	NOT NECESSARY	\$ 280.00	\$ -
11 TAILGATE GLASS MOULDING	1	NECESSARY	\$ 171.00	\$ 171.00
12 TAILGATE LOCK	1	JAMMED	\$ 310.00	\$ <del>310.00</del> 210
13 TAILGATE WEATHERSTRIP	1	TORN	\$ 280.00	\$ 280.00
14 TAILGATE LOCK STRIKER	1	BENT	\$ 53.00	\$ 53.00 XNN
15 REAR RH FENDER	1	DENTED	\$ 1,210.00	\$ 1,210.00 XR
16 REAR FENDER AIR VENT	1	CRACKED	\$ 40.00	\$ 40.00
17 REAR RH SLIDING ROLLER GARNISH	1	GARZE	\$ 150.00	\$ <del>150.00</del> CUT 110
			\$ 5,917.00	\$ 5,357.00
		Less 25%	\$ 1,479.25	\$ 1,339.25
			\$ 4,437.75	\$ 4,017.75

B) S/NETT ITEM

18 REAR BUMPER CLIP	1 SET	NECESSARY	\$ 60.00	\$ 50.00 30
19 6 PAX	1	NECESSARY	\$ 70.00	\$ 60.00 10
20 70KM/H	1	NECESSARY	\$ 60.00	\$ 50.00 10
21 REAR REVERSE SENSOR	1 SET	MALFUNCTION	\$ 400.00	\$ 300.00 200
22 WINDSCREEN SEALANT	1	NECESSARY	\$ 120.00	\$ 100.00 50
23 JOINT SEALANT	1	NECESSARY	\$ 120.00	\$ 100.00 XNN
			\$ 830.00	\$ 660.00

Parts Total :

\$ 5,267.75 \$ 4,677.75

C) LABOUR CHARGES & MISC

24 CHECK REAR WIRING AND LIGHTNING SYSTEM			\$ 60.00	\$ 50.00 30
25 REMOVE AND REFIT LINING, TRIM AND GARNISH			\$ 150.00	\$ 130.00 60
26 REMOVE AND RENEW REAR REVERSE SENSOR			\$ 120.00	\$ 100.00 50
27 REMOVE AND REFIT REAR WINDSCREEN			\$ 150.00	\$ 120.00 60
28 TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW			\$ 200.00	\$ 180.00 60
29 PANEL BEATING ON AFFECTED AREAS			\$ 1,500.00	\$ 1,400.00 700
30 SPRAY PAINTING ON AFFECTED AREAS			\$ 1,200.00	\$ 1,000.00 600
31 APPLY ANTI RUST ON AFFECTED AREAS			\$ 150.00	\$ 130.00 50
32 REMOVE AND RENEW STICKER ON AFFECTED AREAS			\$ 800.00	\$ 600.00 200
			\$ 4,330.00	\$ 3,710.00

Labour Total :

\$ 4,330.00 \$ 3,710.00

Total Parts and Labour :

\$ 9,597.55 \$ 8,387.75

FINAL LUMP SUM ADJUSTMENT

\$ 6,700.00

6 days

#### POINT OF IMPACT

The impact was confined to the rear portion of the vehicle.  
The damages appeared to be consistent as per the accident report statement.  
Please refer the attached schedule and photographs for details.

#### ADJUSTMENT/RECOMMENDATIONS

We have thoroughly inspected each and every item on the repairer's estimates against the actual damaged found on the vehicle. We have listed the breakdown of our findings and recommendations as per assessment above.

#### CONCLUSION

The repairer has agreed to undertake repair the vehicle at a lump sum basis of \$6,700.00 nett corresponding to replacement of parts, spray painting and labour charges. We now revert for your decision on the above claim.

Yours faithfully  
WG APPRAISAL SERVICES

Winson Goh  
Automotive Appraiser





### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Apr 2018		16 Apr 2018 09:58 <a href="#">Edit Adj Rpt</a>	<b>S\$3,500.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,500.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>MUHAMMAD FAZRYAN BIN AZMAN</b> , ID: S9300758A								
Main Claimant:	<b>OCTOPUS DESIGN &amp; CONSULTANT PTE LTD</b> , Co. Reg. No.: 200516794M								
Vehicle Reg. No.:	<b>GY2057J</b>	Date of Loss:	13/04/2018 07:00 - :59 [158 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / MSC/V/18-000548</b>	Policy/Cover Note No.:	MSD/VMS/18-990134 (TP, Fire & Theft) Coverage: 11/03/2018 - 10/03/2019						
Vehicle Reg. No. (Insured):	<b>FBK8737Z</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>M/s. Nee Huat Auto Services (HQ)</b> 1 Kaki Bukit Ave 6 #02-27, Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 20/06/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>MSIG_SG (18/06/2018): Report Send Back Alerts - GY2057J (TP)</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*GY2057J (MSC/V/18-000548)**  
**[FBK8737Z]**






































**TP**
















































**OCTOPUS DESIGN & CONSULTANT PTE LTD**

**Apr 13 2018 7:00AM**

**[MUHAMMAD FAZRYAN BIN AZMAN]**

**M/s. Nee Huat Auto Services**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
2	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
3	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
4	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
5	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
6	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
7	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
8	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
9	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
10	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
11	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
12	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
13	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
14	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
15	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
16	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
17	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
18	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
19	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
20	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
21	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
22	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
23	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
24	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
25	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
26	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
27	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
28	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
29	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
30	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
31	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
32	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
34	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	04/06/18 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	04/06/18 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	04/06/18 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	04/06/18 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/04/18 09:43	FBM4159H GIA Rpt	 Load PDF	
2	16/04/18 09:43	FBK8737Z GIA Rpt	 Load PDF	
3	16/04/18 09:45	PRI & LTA Search	 Load PDF	
4	12/06/18 10:21	TP Survey Report	 Load PDF	
5	12/06/18 10:21	TP Survey Report Pictures	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/06/18 11:12	PRS Invoice	 Load PDF	
2	21/06/18 11:13	PHOTO	 Load PDF	

## Documents Checklist

**DOCUMENTS CHECKLIST**

Reset

Save

Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18006955/GRBE2-1

Date: 21/06/2018

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/18-990134
Claimant Vehicle No :	GY2057J	Insured Vehicle No :	FBK8737Z
Date of Loss:	13/04/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000548

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GY2057J	Engine No:	3C4007204
Make & Model:	TOYOTA LITEACE, 2.2 5 DR (A)	Chassis No:	CR425011104
Reg. Date:	26/01/2005 (Man. Year: 2004)	Odometer:	245787 km
Colour:	Silver		
Engine Capacity:	2184 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,267.75	2,473.87	2,793.88	53.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,330.00	1,950.00	2,380.00	54.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,597.75</b>	<b>4,423.87</b>	<b>5,173.88</b>	<b>53.91</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>9,597.75</b>	<b>3,500.00</b>	<b>6,097.75</b>	<b>63.53</b>

### INSPECTION

Date of Assignment:	16/04/2018	
Date Inspected:	16/04/2018 Inspected At:	M/s. Nee Huat Auto Services (HQ) 1 Kaki Bukit Ave 6 #02-27, Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	6.0 days	

**Adjuster:** XING GUO QIANG

**Manager:** Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 21 Jun 2018)	
<b>Parts:</b>	N/A	TOYOTA LITEACE 2.2 5 DR (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GY2057J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	544.00 FL	*420.00 FL
2	1		*REAR BUMPER HOLDER	O/S Necessary	121.00 FL	*60.50 FL
3	1		*REAR RH BUMPER REFLECTOR	Cracked	83.00 FL	*83.00 FL
4	1		*END PANEL	Repair	581.00 FL	*- FL
5	1		*REAR RH TAILLAMP	Cracked	383.00 FL	*383.00 FL
6	1		*REAR RH TAILLAMP PANEL	Repair	290.00 FL	*- FL
7	1		*TAILGATE	Dented	1,080.00 FL	*1,080.00 FL
8	2		*TAILGATE ABSORBER	Not Necessary	280.00 FL	*- FL
9	1		*TAILGATE EMBLEM	Necessary	61.00 FL	*61.00 FL
10	1		*TAILGATE OUTER GARNISH	Not Necessary	280.00 FL	*- FL
11	1		*TAILGATE GLASS MOULDING	Necessary	171.00 FL	*171.00 FL
12	1		*TAILGATE LOCK	Jammed	310.00 FL	*210.00 FL
13	1		*TAILGATE WEATHERSTRIP	Torn	280.00 FL	*280.00 FL
14	1		*TAILGATE LOCK STRIKER	Not Necessary	53.00 FL	*- FL
15	1		*REAR RH FENDER	Repair	1,210.00 FL	*- FL
16	1		*REAR FENDER AIR VENT	Cracked	40.00 FL	*40.00 FL
17	1		*REAR RH SLIDING ROLLER GARNISH	Cut	150.00 FL	*110.00 FL
18	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
19	1		*6 PAX	Necessary	70.00 FS	*10.00 FS
20	1		*70KM/H	Necessary	60.00 FS	*10.00 FS
21	1		*SET REAR REVERSE SENSOR	Malfunction	400.00 FS	*200.00 FS
22	1		*WINDSCREEN SEALANT	Necessary	120.00 FS	*50.00 FS
23	1		*JOINT SEALANT	Not Necessary	120.00 FS	*- FS
					<b>Sub Total (\$\$)</b>	<b>6,747.00 3,198.50</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>1,479.25 724.63</b>
					<b>Total Parts (\$\$)</b>	<b>5,267.75 2,473.87</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK REAR WIRING AND LIGHTNING SYSTEM	New	60.00	30.00
2	REMOVE AND REFIT LINING, TRIM AND GARNISH	New	150.00	60.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	50.00
4	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
5	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	New	200.00	60.00
6	PANEL BEATING ON AFFECTED AREAS	New	1,500.00	700.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	600.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	50.00
9	REMOVE AND RENEW STICKER ON AFFECTED AREAS	New	800.00	280.00
Gross Labour Cost (S\$)			<b>4,330.00</b>	<b>1,950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >