

REF:

CC3/msg18011032/Vtbnz

## ASSIGNMENT

From \_\_\_\_\_ Date \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV \_\_\_\_\_

To Inspect Vehicle No: \_\_\_\_\_

at Workshop no: \_\_\_\_\_

of \_\_\_\_\_

Insured: **SLP 6003B**

Policy No: **A29069766MKF**

Claims No: **561022**

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS \_\_\_\_\_

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: **SHC 4781 S** Yr Regn: **Feb 2016**

Type: M.Car / M.Cycle / Bus / Van / Lorry /  Prime Mover /  
Truck / Trailer or \_\_\_\_\_

Make: **Toyota Prius** CC: **1798**

Colour: **Maroon** A/C: Insured / Std / NI / NA

Sp. Reading: **329437** T/Radio: Insured / Std / NI / NA

Eng/No: **2ZR6577660**

C/No: **JTDKN36U605767389**

Gen. Cond: Good /  Fair / Poor / Burnt

Steering:  In Order / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake:  In Order / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi:  Nil / S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: **195/65 R15**  
R: **195/65 R15**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or **Falken**

Front	Rear
R/Bal. <b>6</b> mm	R/Bal. <b>6</b> mm
L/Bal. <b>6</b> mm	L/Bal. <b>6</b> mm

D.O.A. **12/6/2018** D.O.I. **14/6/2018**

Survey held at **SMRT**

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or \_\_\_\_\_

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHC 4781S - NBA / INC1302/201/SA SLP 6003B - X
	DOA: 081113 TAX/06/18/2051
	MSIG
	- SLP 6003B
	Part by part \$4688.17 (Red: 4806.77 : 50%)
	RECEIVED 12 JUL 2018

Date/Time, File Pass to?

12/7 Typist

Date/Time, File Return to?

3)

Report Format :

4688.17

 Preli. Report Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:  Site Insp (\$ Interview (\$ Tech Insp (\$ ... (\$

Survey Fee

Transportation

) ... SI

) Photos

) Filters

190  
10

160

> [Back to OneMotoring](#)

## Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SHC47815		
Vehicle Type :	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1 :	Air-Con (Taxi)		
Vehicle Scheme :	Taxi (Company)		
Vehicle Make :	TOYOTA		
Vehicle Model :	PRIUS TAXI (SMRT)		
Chassis No. :	JTDKN36U605767389		
Propellant :	Petrol-Electric		
Engine No. :	2ZR6577660		
Motor No. :	3JM6577660		
Engine Capacity :	1798 cc		
Power Rating :	60.0 kW		
Maximum Power Output :	100.0 kW ( 134 bhp )		
Maximum Laden Weight :	1805 kg		
Unladen Weight :	1370 kg		
Year Of Manufacture :	2015		
Original Registration Date :	05 Feb 2016		
Lifespan Expiry Date :	04 Feb 2024		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
PQP Paid :	\$43,040.00		
COE Expiry Date :	04 Feb 2024		
Road Tax Expiry Date :	04 Aug 2018		
PARF Eligibility Expiry Date :	04 Feb 2024		
Inspection Due Date :	04 Feb 2019		
Intended Transfer Date :	19 Jun 2018		
CO2 Emission :	92.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$28,312.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
<p>The current road tax expiry is 04 Aug 2018. You may renew the road tax from 05 May 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 04 Aug 2018, late renewal fee(s) will be imposed. Please use <a href="#">Enquire Road Tax Payable</a> to check on the late fee(s) payable.</p> <p>Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.</p>			
<b>Amount Payable (From 05 Aug 2018 to 04 Feb 2019)</b>			
	<b>Amount Before GST</b>	<b>GST Amount</b>	<b>Amount After GST</b>
	<b>(S\$)</b>	<b>(S\$)</b>	<b>(S\$)</b>
Transfer Fee :	25.00	-	25.00
<b>Sub Total :</b>			<b>25.00</b>
Nett Road Tax Amount (After Offsetting Over Payment) :	510.00	-	510.00
<b>Total Amount Payable :</b>			<b>535.00</b>
<b>Message</b>			
<p>Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.</p>			

You may print this page for reference.

OK

Print

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	12/06/2018 16:00
Date Of Accident	12/06/2018 12:45
Exact Location Of Accident	BEDOK RESERVOIR ROAD TOWARDS UBI
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4781S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	
<b>Driver</b>	
Name of Driver	TAN HUA YONG
NRIC No	S1178312J
Date Of Birth	31/08/1955
Occupation	OUTDOOR
Date Of Driving Pass	13/01/1976
Driving Experience	42 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address 18-121  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - HIRER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident SIDE SWIPE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 4  
 Passenger 1 NAME: : UNKNOWN  
 GENDER: : FEMALE  
 Passenger 2 NAME: : UNKNOWN  
 GENDER: : FEMALE  
 Passenger 3 NAME: : UNKNOWN  
 GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

I WAS TRAVELLING ALONG BEDOK RESERVOIR ROAD TOWARDS UBI WITH THREE PASSENGERS(CHINESE FEMALE) ON BOARD. SUDDENLY I FELT AN IMPACT AT THE LEFT PORTION OF MY TAXI. A VEHICLE SLP6003B CAME OUT FROM THE CAR PARK AND DID NOT STOP AT THE STOP LINE TO GIVE WAY TO MY TAXI. AS SUCH COLLIDED ONTO THE LEFT PORTION OF MY TAXI.

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLP6003B  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver YACOB BIN ISHAK

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
 Policyholder's Signature
   
 Date & Time:

 12/6
   
 Driver's Signature
   
 (If driver is not the policyholder)
   
 Date & Time:


  
 Reporting Centre Personnel's Signature
   
 Name:
   
 NRIC/FIN No.:

## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4781S  
 Ref. No : TAX/06/18/2051  
 Reg. Date : 05/02/2016  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : TAN HUA YONG  
 Type of Accident : HEAD TO SIDE  
 Date / Time of Accident : 12/06/2018 12:45:00 PM  
 Accident Reported Date / Time : 12/06/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024096544  
 Special Instruction to ARC,if any :  
 SLP6003B  
 Prepared Date : 12/06/2018 04:31:06 PM



Sathya Sai

14/6/2018

98072012

sebastianyeang@lkkauto.com

- Part by Part repair
- Question mark item photo
- Photo before paint.

4 days

LKK Auto Consultancy to certify  
 the Repairer of the repair

- To resurvey before labour display painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U605767389

Mileage


: 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
Total Labour Charges	: 1,183.00	0.00
Total Spray Painting Charges	: 1,674.00	0.00
Total Material Charges	: 4,167.95	4,167.95
Other Charges	: 1,185.00	0.00
<b>TOTAL</b>	<b>: 8,209.95</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 7.00	<i>0.00 4 days</i>
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 13/06/2018 10:29:01 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 13/06/2018 10:28:51 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1,183.00	<del>0.00</del> 800
<b>Total Labour</b>	<b>1,183.00</b>	<b>0.00</b>

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR DOOR LH	378.00	<del>0.00</del> 200
TO RESPRAY ROCKER PANEL MOULDING	180.00	<del>0.00</del> 100
TO RESPRAY REAR FENDER LH	378.00	<del>0.00</del> 200
TO RESPRAY FUEL LID COVER	180.00	<del>0.00</del> 80
TO RESPRAY RIM	180.00	<del>0.00</del> 100
TO REPSRAY REAR BUMPER	378.00	<del>0.00</del> 200
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,674.00</b>	<b>0.00</b>

## Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	<del>0.00</del> 40
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	<del>0.00</del> 50
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	<del>0.00</del> 60
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	<del>0.00</del> 60
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 ✓
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	<del>0.00</del> 60
TO REMOVE & REFIT FUEL TANK	120.00	<del>0.00</del> 60
TO TRANSFER DOOR MECHANISM	120.00	<del>0.00</del> 60
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	<del>0.00</del> 60
TO REPLACE SUNDRY PARTS	100.00	<del>0.00</del> 20
TO WASH AND VACUUM	60.00	0.00 X
<b>Total Other Costs</b>	<b>1,185.00</b>	<b>0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
67004-47080		6505487	DOOR RR/LH ✓DT	1	954.50	25.00	715.87	Replace	Replace	No
75852-47900			MOULDING BODY, LH ✓CUT	1	673.60	25.00	505.20	Replace	Replace	No
65632-47041			SILL MEMBER PLATE RR/LH ✓CUT	1	57.50	25.00	43.12	Replace	Replace	No
61602-47091		6505476	FENDER RR/LH ✓DMG	1	766.80	25.00	575.10	Replace	Replace	No
65638-47021		6505477	FENDER LINER ? RR/LH	1	141.30	25.00	105.97	Replace	Replace	No
	COMMO N		SMRT LOGO ✓NEC	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888 ✓NEC	1	21.60	0.00	21.60	Replace	Replace	No
62720-47031			QUARTER GLASS RR/LH ✗	1	168.10	25.00	126.07	Replace	Replace	No
	COMMO N		SEALANT W/SCREEN ✗	1	37.00	0.00	37.00	Replace	Replace	No
77350-47030			LID ASSY, FUEL ✓SCR	1	102.00	25.00	76.50	Replace	Replace	No
77035-47090			CABLE SUB-ASSY, FUEL LID ?	1	63.90	25.00	47.92	Replace	Replace	No
77377-75010			RETAINER, FUEL LID ? CABLE	1	5.90	25.00	4.42	Replace	Replace	No
77366-52010			SPRING, FUEL FILLER OPENING LID ? HINGE	1	1.50	25.00	1.12	Replace	Replace	No
		6503707	TYRE ✗	1	126.74	0.00	126.74	Replace	Replace	No
42611-47140		6505658	WHEEL, DISC R	1	1,490.20	25.00	1,117.65	Replace	Replace	No
52159-47905		6505548	BUMPER REAR ✓CUT	1	458.60	25.00	343.95	Replace	Replace	No
52592-47021			BUMPER SEAL, RR ? LH	1	88.90	25.00	66.67	Replace	Replace	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH ?	1	94.80	25.00	71.10	Replace	Replace	No
76088-47020		6505617	BUMPER LIP COVER RR/LH ✗	1	72.20	25.00	54.15	Replace	Replace	No
			PIXEL STICKER ✓NEC	2	60.00	0.00	120.00	Replace	Replace	No

**TOTAL MATERIALS**

**4,167.99 4,167.95**

**TOTAL MATERIALS(Discounted)**

**4,167.95 4,167.95**

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									

20-6-18 / 16:42


20-6-18 / 16:42

14-6-18 / 16:42

### SMRT Accident Vehicle Repair Estimates

**Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre**

Reg. No : SHC4781S  
 Ref. No : TAX/06/18/2051  
 Reg. Date : 05/02/2016  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : TAN HUA YONG  
 Type of Accident : HEAD TO SIDE  
 Date / Time of Accident : 12/06/2018 12:45:00 PM  
 Accident Reported Date / Time : 12/06/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : Sathya 4781  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024096544



Special Instruction to ARC, if any :

SLP6003B mslk P/P

BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, Question mark item photo, part by part repair, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SATHYA (LKK) & Email :sebastianyeang @lkkauto.com HP:9807 2012

Prepared Date : 12/06/2018 04:31:06 PM

Recording Camera    
 Radio Antenna    
 1<sup>st</sup> witness Mr Date 14-6-18  
 2<sup>nd</sup> witness \_\_\_\_\_ Date \_\_\_\_\_

329438 km

22/6/18 329501  
 11.52 PSCS

Supplementary  
 & Refer to the Supplementary part list

LEE SHENG AUTO PTE LTD

Vehicle Return Date: 22-6-2018

Vehicle Return Time: 10:00 am

SMRT staff sign:


**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U605767389 Mileage : 0

Work Shop : Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,183.00	800.00
Total Spray Painting Charges	: 1,674.00	880.00
Total Material Charges	: 2,690.58	2,413.17
Other Charges	: 1,185.00	595.00
<b>TOTAL</b>	<b>: 6,732.58</b> <i>9494.94</i>	<b>4,688.17</b>
Lump Sum Total	: 0.00	0.00
No. of Repair Days	: 7.00	5.00 ✓
Prepared / Adjusted By	:	SATHYA SAI
Arc / Surveyor Sign Off Date	: 13/06/2018 10:29:01 AM	14/06/2018 04:42:06 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 13/06/2018 10:28:51 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : *QN-1806-0568* Invoice No :  
Quotation Date : *26/6* Invoice Date :  
Invoice Amount : 0.00 Prepared Date : 6/22/2018 1:11:26 PM

**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	1,183.00	800.00 ✓
<b>Total Labour</b>	<b>1,183.00</b>	<b>800.00 ✓</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR DOOR LH	378.00	200.00 ✓
TO RESPRAY ROCKER PANEL MOULDING	180.00	100.00 ✓
TO RESPRAY REAR FENDER LH	378.00	200.00 ✓
TO RESPRAY FUEL LID COVER	180.00	80.00 ✓
TO RESPRAY RIM	180.00	100.00 ✓
TO REPSRAY REAR BUMPER	378.00	200.00 ✓
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,674.00</b>	<b>880.00 ✓</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	50.00 ✓
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60.00 ✓
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	60.00 ✓
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	125.00 ✓ nec
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	60.00 ✓
TO REMOVE & REFIT FUEL TANK	120.00	60.00 ✓
TO TRANSFER DOOR MECHANISM	120.00	60.00 ✓
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60.00 ✓
TO REPLACE SUNDRY PARTS	100.00	20.00 ✓
TO WASH AND VACUUM	60.00	0.00
<b>Total Other Costs</b>	<b>1,185.00</b>	<b>595.00 ✓</b>

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached	
67004-47080		6505487	DOOR RR/LH	1	954.50	30.00	668.15	Replace	Replace	No /	DT
75852-47900			MOULDING BODY, LH	1	673.60	30.00	471.52	Replace	Replace	No /	CUT
65632-47041			SILL MEMBER PLATE RR/LH	1	57.50	30.00	40.25	Replace	Replace	No /	CUT
61602-47091		6505476	FENDER RR/LH	1	766.80	30.00	536.76	Replace	Replace	No /	DMG
65638-47021		6505477	FENDER LINER RR/LH	1	141.30	30.00	98.91	Replace	Check	No X	NN
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No /	} NEC
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No /	
62720-47031			QUARTER GLASS RR/LH	1	168.10	30.00	117.67	Replace	Replace S	No /	} SCR
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace S	No /	
77350-47030			LID ASSY, FUEL	1	102.00	30.00	71.40	Replace	Replace	No /	} NN
77035-47090			CABLE SUB-ASSY, FUEL LID	1	63.90	30.00	44.73	Replace	Check	No X	
77377-75010			RETAINER, FUEL LID CABLE	1	5.90	30.00	4.13	Replace	Check	No X	} NN
77366-52010			SPRING, FUEL FILLER OPENING LID HINGE	1	1.50	30.00	1.05	Replace	Check	No X	
		6503707	TYRE	0	126.74	0.00	0.00	Replace	Not given	No X	} NN
42611-47140		6505658	WHEEL, DISC	1	1,490.20	100.00	0.00	Replace	Repair	No R	
52159-47905		6505548	BUMPER REAR	1	458.60	30.00	321.02	Replace	Replace	No /	CUT
52592-47021			BUMPER SEAL, RR LH	1	88.90	30.00	62.23	Replace	Check	No X	} NN
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	30.00	66.36	Replace	Check	No X	
76088-47020		6505617	BUMPER LIP COVER RR/LH	0	72.20	30.00	0.00	Replace	Not given	No X	} NEC
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No /	
TOTAL MATERIALS								2,690.58	2,413.17		
TOTAL MATERIALS(Discounted)								2,690.58	2,413.17		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

2413.17 ✓  
 + 800.00 ✓  
 + 1475.00 ✓  


---

 4688.17 @ 5 days  
 confirmed

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18011032/VTBN2

Date: 13/07/2018

**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29069766MKF
Claimant Vehicle No :	SHC4781S	Insured Vehicle No :	SLP6003B
Date of Loss:	12/06/2018	Nature of Claim:	TP
		Claim No:	561022

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	SHC4781S	Engine No:	2ZR6577660
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKN36U605767389
Reg. Date:	05/02/2016 (Man. Year: 2015)	Odometer:	329437 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,577.94	2,538.17	3,039.77	54.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,917.00	2,150.00	1,767.00	45.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>9,494.94</b>	<b>4,688.17</b>	<b>4,806.77</b>	<b>50.62</b>

**INSPECTION**

Date of Assignment:	20/06/2018	
Date Inspected:	14/06/2018	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705

Estimated Period of Repair: 5.0 days

Adjuster: Sathya Sai Kathirrasen

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 13 Jul 2018)
<b>Parts:</b> 144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHC4781S)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*DOOR RR/LH (DISC 30%)	Dented	954.50 F	*668.15 F	
2	1		*MOULDING BODY,LH (DISC 30%)	Cut	673.60 F	*471.52 F	
3	1		*SILL MEMBER PLATE RR/LH (DISC 30%)	Cut	57.50 F	*40.25 F	
4	1		*FENDER RR/LH (DISC 30%)	Damaged	766.80 F	*536.76 F	
5	1		*QUARTER GLASS RR/LH (DISC 30%)	Necessary	168.10 F	*117.67 F	
6	1		*LID ASSY,FUEL (DISC 30%)	Scratched	102.00 F	*71.40 F	
7	1		*BUMPER REAR (DISC 30%)	Cut	458.60 F	*321.02 F	
8	1		*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F	
9	1		*STICKER DECAL 65558888 (SN)	Necessary	21.60 F	*21.60 F	
10	1		*SEALANT W/SCREEN (SN)	Necessary	37.00 F	*37.00 F	
11	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F	
12	1		*SOLAR FILM (SN)	Necessary	125.00 F	*125.00 F	
13	1		*FENDER LINER RR/LH	Not Necessary	141.30 F	*- F	
14	1		*CABLE SUB-ASSY,FUEL LID	Not Necessary	63.90 F	*- F	
15	1		*RETAINER,FUEL LID CABLE	Not Necessary	5.90 F	*- F	
16	1		*SPRING,FUEL FILLER OPENING LID HINGE	Not Necessary	1.50 F	*- F	
17	1		*TYRE	Not Necessary	126.74 F	*- F	
18	1		*BUMPER SEAL,RR LH	Not Necessary	88.90 F	*- F	
19	1		*BUMPER SIDE RETAINER RR/LH	Not Necessary	94.80 F	*- F	
20	1		*BUMPER LIP COVER RR/LH	Not Necessary	72.20 F	*- F	
21	1		*WHEEL,DISC	Repair	1,490.20 F	*- F	
					<b>Total Parts (S\$)</b>	<b>5,577.94</b>	<b>2,538.17</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING & BODY WORK	New	1,183.00	800.00
2	SPRAY PAINT	New	1,674.00	880.00
3	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	40.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	50.00
5	TO DO WHEEL ALIGNMENT/TYRE BALANCING	New	120.00	60.00
6	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	60.00
7	TO REMOVE & REFIT REAR QUARTER GLASS LH	New	120.00	60.00
8	TO REMOVE & REFIT FUEL TANK	New	120.00	60.00
9	TO TRANSFER DOOR MECHANISM	New	120.00	60.00
10	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	60.00
11	TO REPLACE SUNDRY PARTS	New	100.00	20.00
12	TO WASH AND VACUUM	New	60.00	-
<b>Gross Labour Cost (S\$)</b>			<b>3,917.00</b>	<b>2,150.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >