



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 7936P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER (CONSISTENT)	DENTED /DEFORMED	601.00	601.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	CRACKED	304.00	304.00
1	REAR BUMPER ABSORBER FOAM (CONSISTENT)	TORN	125.00	125.00
2	REAR BUMPER SIDE RETAINERS @\$22.00 (CONSISTENT)	BENT	44.00	44.00
6	REAR BUMPER CLIPS @\$4.30 (CONSISTENT)	NECESSARY	25.80	25.80
4	REAR BUMPER BOTTOM BRACKET @\$24.00 (CONSISTENT)	NOT NECESSARY	96.00	-
	LESS 10% DISCOUNT		-119.58	-109.98
			1,076.22	989.82
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER LOWER SPOILER (SN) (CONSISTENT)	CRACKED	800.00	800.00
1	SET REAR BUMPER PARKING SENSOR (SN) (CONSISTENT)	NOT NECESSARY	450.00	-
			1,250.00	800.00
	<u>LABOUR</u>			
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		120.00	50.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		50.00	20.00
	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.		700.00	300.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		700.00	480.00
			1,570.00	850.00
	GRAND TOTAL		3,896.22	2,639.82
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,100.00

Report Ref No. CC4/ASM18011059/Uga3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.