

ASS. REC. BY:

REF:

CS / MSG18011061 / Aq0302

Special Instruction:

Survivor
MeimienAdrian
Irene Tan

From (Person):

ASSIGNMENT (Office)

of MSIG

Date/Time: 19/6/18 @ 9:16am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GZ 8796P

Insured:

STD 8692L

at Workshop m/s

Twincell Automotive

Tel:

6842 0051

of

Blk 2 Kaki Bukit # 01-17/18

Policy No:

A80445212QMY

Claim No:

561499

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

14/06/2018

21/06/2018

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

lup

Date/Time:

10:41am @ 19/6/18

Person Contacted:

Melody

Vehicle IN

OUT

Date/Time	Action/Instruction (✓) Estimate
	GZ 8796P - NA / LPC18010965 / K1 DOA: 14/06/2018
	STD 8692L - NA / LPC18010965 / K4 DOA: 14/06/2018
21/6/18 @ 2pm	Informed Irene Tan, we are pending estimate from repairer.
17/10/18 @ 11:25am	varised to Irene Tan vs Meimien.
	US \$ 8200, 7 days CRD \$ 9052.00, 5%.

REF: MSIG

Gd estimate

ASSIGNMENT

From

Date:

21/06/2018

Veh No.

GZ8796P

Yr Regn:

2006, Sept

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

Pick-up

To inspect Vehicle No:

GZ8796P

Make:

Ssangyong

Mussoco

2874.

at Workshop m/s

Twincar Automotive

Colour

white

A/C: Insured / Std / NI / NA

of

Blk 2 Kaki Bukit # 01-17/18

Sp. Reading

248590

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

KPAWA2EDS6P415716.

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh.

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

7

days

Res.:

Yes or No

D.O.A.

D.O.I.

21/06/18

Lum Sum:

%

3 Val.:

Yes or No

Survey held at

Twincar.

CA / REV / REP. / 24 HRS

hup

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP MSIG

COE Expiry: 31/08/21

12/10/2018

RECEIVED 12 OCT 2018

 MV: 22K
 PV: 48K
 Nett: 7-21K

Date/Time: File Pass to?

☐

Preli. Report

Days Of Repair:

7

1) 12/10/2018

☐

Final Report

Resurvey No. of Trip:

Date/Time: File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format:

MER-TP

Lump Sum / I.B.A. (\$

8200

Survey Fee:

200

Transportation:

) \$ + RS. \$

Photos

Others

10

TOTAL

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18011061/Aqd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 19-06-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLD 8692L	Veh. Inspected	GZ 8796P	
Policy No.	A80445212QMY	Coverage (\$)	0.00	
Claim No.	561499	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAN)	Assign Date	19/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/06/2018	Inspection Date		
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Jun 2018		19 Jun 2018 09:16 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MOHAMED YUSOF BIN ABDULLAH, ID: S7145338C		
Main Claimant:	DENSCO ELECTRICAL ENGINEERING PTE LTD, Co. Reg. No.: 199003082R		
Vehicle Reg. No.:	GZ8796P	Date of Loss:	14/06/2018 21:00 - :59 [140 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 561499	Policy/Cover Note No.:	A80445212QMY (Comprehensive) Coverage: 29/10/2017 - 28/10/2018
Vehicle Reg. No. (Insured):	SLD8692L	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/06/2018]		
Driver/Custodian (Insured):	MOHAMED YUSOF BIN ABDULLAH (), NRIC: S7145338C		
Adj Asg. Remarks:	LIABILITY-100% TP AGREE SJE -Mr Adrian Ling APPOINT LKK AUTO CONSULTANTS PTE LTD AS SJE(ACCORDING TO SURVEYOR ASSIGNMENT LISTING CHART)		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Eileen Goh

From: Woon Choo Kwok
Sent: Monday, 18 June, 2018 1:55 PM
To: Irene Tan; Eileen Goh
Cc: Foo Ai Ngoh
Subject: FW: GZ8796P & SLD8692L - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS
Attachments: 18062018103952-0001.pdf

Follow Up Flag: Follow up
Flag Status: Flagged

Dear officers

fya

Best Regards

Kwok Woon Choo
Senior Admin Officer, Claims Services
Tel : 6643 1330 Fax: 6225 7402 | woonchoo_kwok@sg.msigg-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msigg.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Agnes Lee
Sent: Monday, June 18, 2018 1:35 PM
To: Woon Choo Kwok <WoonChoo_Kwok@sg.msigg-asia.com>
Subject: FW: GZ8796P & SLD8692L - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

From: Chin Hui Xin [<mailto:huixin@n51.com.sg>]
Sent: 18 June 2018 10:43
To: Claims <claims@sg.msigg-asia.com>
Subject: GZ8796P & SLD8692L - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer attachment and:-

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 12 Oct 2018

Preliminary Advice

Insured Vehicle No	: SLD8692L	Accident Date	: 14/06/2018
TP Vehicle No	: GZ8796P	Assignment Date	: 19/06/2018
Make	: SANYANG LA18W1-6	Est. Duration of Repair	: 7
Date of Inspection	: TWINCAR AUTOMOTIVE PTE LTD		
Inspection At	: 21/06/2018		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,252.90
Revised Amount	:S\$	10,279.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	10,279.00
 Lump Sum Repair	 :S\$	 8,200.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Friday, 22 June 2018 2:00 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE GZ 8796P (YOUR REF: 561499)

This mail is associated with :
***GZ8796P (561499)**
[SLD8692L]
TP
DENSCO ELECTRICAL ENGINEERING PTE LTD
Jun 14 2018 9:00PM
[MOHAMED YUSOF BIN ABDULLAH]
Twincar Automotive Pte Ltd

Dear Irene,

Please be informed that we have inspected the vehicle GZ 8796P on 21/06/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3082R
Vehicle Details	
Vehicle No.:	GZ8796P
Vehicle to be Exported:	Yes
Intended De-registration Date:	21 Jun 2018
Vehicle Make:	SSANGYONG
Vehicle Model:	MUSSO 4X2 AT
Primary Colour:	White
Manufacturing Year:	2005
Engine No.:	66292012162929
Chassis No.:	KPAWA2EDS6P415716
Maximum Power Output:	-
Open Market Value:	\$18,722.00
Original Registration Date:	27 Sep 2006
First Registration Date:	27 Sep 2006
Transfer Count:	1
Actual ARF Paid:	\$20,595.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2021
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$23,127.00
COE Rebate Amount:	\$14,771.00
Total Rebate Amount:	\$14,771.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 21 Jun 2018

OK



FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Weekend Promo, Free Warranty With Servicing Package.

Accident Free, Low Mileage, Ori
Paintwork, No Repairs Needed
Call Now To Enquire
Sincere Trading - StarAd



Republic

**CERTIFIED PRE-OWNED
MERCEDES-BENZ**

[View our cars](#)

Browse by Category

[Save Search](#)[Print](#)

Sort by Date Posted

20 results/page

3 vehicles

[Search](#)

Musso

[Advanced Search](#)[Search](#)[View All](#)

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

Search Selection

Musso

Any

Any

> 10 year(s)
old

Any

Any

Any

Available



☐ **Ssangyong Musso Double-Cab**
(COE till 01/2021)

\$15,800

\$6,190 /yr

09-Jan-2006

2,874 cc

70,000 km

Truck

Available

Fuel Type: Diesel

1 Private Owner And Low Mileage.

[DIRECT OWNER](#)

☆ Posted: 31-May-2018 Tags: 2006 Ssangyong Musso, Ssangyong Musso, Ssangyong, Musso, Used Ssangyong



☐ **Ssangyong Musso Double-Cab**
(COE till 03/2021)

\$19,800

\$7,310 /yr

06-Mar-2006

2,874 cc

-

Truck

Available

Fuel Type: Diesel

Well Maintained In Good Condition! Undercarriage Fully Serviced, Servicing Just Done! No Repairs Required. Ample Cargo Space With Cover. No Hassle In-House Loan Available. Call For Viewing Now.

[PREMIUM AD](#)

OK2 Pte Ltd

☆ Posted: 08-Jun-2018 Tags: 2006 Ssangyong Musso, Ssangyong Musso, Ssangyong, Musso, Used Ssangyong



☐ **Ssangyong Musso Double-Cab**
(COE till 10/2021)

\$22,800

\$6,880 /yr

13-Oct-2006

2,874 cc

-

Truck

Available

Fuel Type: Diesel

Reliable Mercedes Engine, Affordable And Powerful Twin Cab Pickup, Drive Away Condition. High Loan Available And Trade In Welcome! This Is A Quality Car For Those Who Knows It Best!

[PREMIUM AD](#)

OK2 Pte Ltd

☆ Posted: 23-May-2018 Tags: 2006 Ssangyong Musso, Ssangyong Musso, Ssangyong, Musso, Used Ssangyong

Save this search criteria, to get email alerts whenever a match is found.

[Save Search](#)

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view [Expired ads](#)

20 results/page

sgCarMart is the number one car classified for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Musso, Musso Singapore, used Musso Singapore, used Musso, used vehicles Singapore or even buy used Musso Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/06/2018 15:44
Date Of Accident	14/06/2018 21:45
Exact Location Of Accident	TAMPINES AVE 9 TURNING INTO TAMPINES AVE 10 (TPE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GZ8796P
-----------------------------	---------

Insured/Policyholder

Name Of Registered Owner	DENSCO ELECTRICAL ENGINEERING PTE LTD
Co Reg No	-
Email Address	TERRYYL@LIVE.COM.SG
Mobile Phone No	(LOCAL) +65-96662678
Alternative Phone No	OFFICE-96662678

Vehicle Particulars

Manufacturer	SSANGYONG
Model	-
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	Z/18/VC00/101326
Cover Note Number	

Driver

Name of Driver	GOH CHENG CHUAN TERRY
NRIC No	S8827636A
Date Of Birth	27/07/1988
Occupation	OUTDOOR
Date Of Driving Pass	08/03/2007
Driving Experience	11 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96440391
Fax Number	
Contact Number	OTHERS-96440391
Email Address	TERRYYL@LIVE.COM.SG

Address	BLK 676D PUNGGOL DRIVE #04-740
Postcode	824676
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD8692L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MOHAMED YUSOF BIN ABDULAH
NRIC/Passport Number	
Contact Number	96834026
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	GOH CHENG CHUAN TERRY
------	-----------------------

Approximate Age

Injuries Sustain

SLIGHT

Injured person in which vehicle?

GZ8796P

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer [collectively the "Personal Information"] and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"], the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims [collectively the "Purposes"]
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT Temple Ave 9

I was driving along Temple Ave 9 moving into Temple Ave 10 (divided T-junction). I stopped as the light was red. Signal crossing the road (green then). As I was waiting, vehicle B came from the rear and collided directly into the rear of my vehicle.

A - 62 8196 P
B - 520 9612 L

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name
NRIC/Fin No:

18/6/2018

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TPMS16
Xiao Chan

DENSCO ELECTRICAL ENGINEERING PTE
LTD
209 KAKI BUKIT AVE 1
SINGAPORE 416039

ESTIMATE

Repair Code : CLM14110

Date in : 14/06/2018

Vehicle Num. : GZ8796P

Model : SSANGYONG MUSSO 4X2 AT

Chassis/Eng# : KPAWA2EDS6P415716/66292012162929

Contact : 67498988 96662678, 96440391

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Distorted</i>	1	1750.00	1,750.00 1245
REAR BUMPER BRACKET L/R <i>Bent</i>	2	158.00	316.00
REAR BUMPER REFLECTOR L/R <i>Not new</i>	2	198.00	396.00 +
REAR BUMPER SIDE GARNISH L/R <i>Rt Deformed</i>	2	425.00	850.00 425
REAR BUMPER SIDE GARNISH RETAINER L/R <i>Rt Danged</i>	2	105.00	210.00 105
REAR BUMPER STEP GARNISH <i>Deformed</i>	1	425.00	425.00
REAR END PANEL 'INNER' <i>Dented</i>	1	658.00	658.00
REAR END PANEL 'OUTER'	1	589.00	589.00
REAR END PANEL TOP GARNISH <i>crushed</i>	1	358.00	358.00
REAR SILENCER BOX <i>Bent</i>	1	1208.00	1,208.00
REAR SILENCER BOX MOUNTING <i>Not new</i>	2	35.00	70.00 +
REAR SPARE TYRE CARRIAGE <i>Danged</i>	1	428.00	428.00 285
REAR TAILGATE <i>Dented</i>	1	2250.00	2,250.00 183
REAR TAILGATE 'LOGO' EMBLEM <i>2</i>	1	105.00	105.00
REAR TAILGATE 'MUSSO' EMBLEM <i>new</i>	1	98.00	98.00
REAR TAILGATE 'SPORTS' EMBLEM	1	98.00	98.00
REAR TAILGATE HINGES L/R <i>Not new</i>	2	165.00	330.00 +
REAR TAILGATE INNER TRIM BOARD <i>Not new</i>	1	425.00	425.00 +

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

DENSCO ELECTRICAL ENGINEERING PTE LTD

209 KAKI BUKIT AVE 1
SINGAPORE 416039

Contact : 67498988 96662678, 96440391

ESTIMATE

Repair Code : CLM14110

Date in : 14/06/2018

Vehicle Num. : GZ8796P

Model : SSANGYONG MUSSO 4X2 AT

Chassis/Eng# : KPAWA2EDS6P415716/66292012162929

REAR TAILGATE MECHANISM LOCK L/R <i>not new</i>	2	258.00	516.00 *
REAR TAILGATE NUMBER PLATE LAMP L/R <i>not new</i>	2	105.00	210.00 *
REAR TAILGATE OUTER GARNISH <i>8660</i>	1	498.00	498.00 *
REAR TAILGATE OUTER HANDLE <i>7794</i>	1	208.00	208.00 *
REAR TAILGATE WEATHER STRIP	1	425.00	425.00 *
REAR TAILLAMP L/R <i>cracked</i>	2	505.00	1,010.00 708
Subtotal before discount			13,431.00
Percentage discount 10%			1,343.10
Sub-total 1			12,087.90
REAR BUMPER REVERSE SENSOR <i>Damaged</i>	1	350.00	350.00 200
REAR BUMPER SIDE GARNISH CLIPS L/R - SET <i>new</i>	2	50.00	100.00 20
REAR END PANLE TOP GARNISH CLIPS - SET <i>new</i>	1	50.00	50.00 10
REAR TAILGATE '70KM' STICKER <i>new</i>	1	15.00	15.00 -
REAR TAILGATE 'GREEN' STICKER <i>new</i>	1	45.00	45.00 20
REAR TAILGATE CAMERA <i>Damaged</i>	1	800.00	800.00 380
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>not new</i>	1	100.00	100.00 +
REAR TAILGATE NUMBER PLATE <i>not new</i>	1	25.00	25.00 *
REAR TAILGATE NUMBER PLATE HOLDER <i>not new</i>	1	50.00	50.00 +

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

DENSCO ELECTRICAL ENGINEERING PTE LTD

209 KAKI BUKIT AVE 1
SINGAPORE 416039

Contact : 67498988 96662678, 96440391

ESTIMATE

Repair Code : CLM14110

Date in : 14/06/2018

Vehicle Num. : GZ8796P

Model : SSANGYONG MUSSO 4X2 AT

Chassis/Eng# : KPAWA2EDS6P415716/66292012162929

REAR TAILGATE OUTER GARNISH CLIPS - SET <i>HEM</i>	675	1	80.00	80.00 <i>x</i>
REAR TAILLAMP CLIPS L/R - SET <i>all</i>		1	30.00	30.00 <i>✓</i>
Subtotal before discount				1,645.00
Percentage discount 0%				0.00
Sub-total 2				1,645.00
Parts-total				13,732.90

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	3,520.00
Parts & Labour Total	17,252.90

*** This is a computer-generated document which requires no signature.***

page 3

Insurance Company to be notified

Repair estimate following:

- To remove, reinstall and spray painting
- To remove, change bodyparts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by: *[Signature]*

Signature: _____

Date: _____

Total: 10279.

4/5.8.2K.-

07 days.-

(ole)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Jun 2018		19 Jun 2018 09:16 Edit Adj Rpt	S\$8,200.00 Edit Estimates	S\$8,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: MOHAMED YUSOF BIN ABDULLAH , ID: S7145338C									
Main Claimant: DENSCO ELECTRICAL ENGINEERING PTE LTD , Co. Reg. No.: 199003082R									
Vehicle Reg. No.: GZ8796P		Date of Loss: 14/06/2018 21:00 - :59 [140 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 561499		Policy/Cover Note No.: A80445212QMY (Comprehensive) Coverage: 29/10/2017 - 28/10/2018							
Vehicle Reg. No. (Insured): SLD8692L		Policy No. (Claimant):							
		Excess: S\$500.00							
Repairer: Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 19/07/2018]									
Driver/Custodian (Insured): MOHAMED YUSOF BIN ABDULLAH (), NRIC: S7145338C									
Adj Asg. Remarks: LIABILITY-100% TP AGREE SJE -Mr Adrian Ling APPOINT LKK AUTO CONSULTANTS PTE LTD AS SJE(ACCORDING TO SURVEYOR ASSIGNMENT LISTING CHART)									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GZ8796P (561499)

[SLD8692L]

TP














































DENSCO ELECTRICAL ENGINEERING PTE LTD






























Jun 14 2018 9:00PM

[MOHAMED YUSOF BIN ABDULLAH]

Twincar Automotive Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail	Print	
1	18/06/18 17:51	Accident Statement From: SC - Reg. No: SLD8692L, Claimant: MOHAMED YUSOF BIN ABDULLAH					Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	12/10/18 11:25	Adjuster Immediate Advice					Load HTM		
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
2	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
3	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
4	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
5	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
6	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
7	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
8	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
9	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
10	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
11	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
12	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
13	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
14	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
15	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
16	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
17	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
18	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
19	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
20	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
21	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
22	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
23	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
24	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
25	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
26	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
27	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
28	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
29	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
30	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
31	11/10/18 17:51	General View					Load JPG	<input checked="" type="checkbox"/>	
32	11/10/18 17:51	General View					Load JPG		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	11/10/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
34	11/10/18 17:51	General View	 Load JPG	<input checked="" type="checkbox"/>
35	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
82	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	11/10/18 17:51	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	18/06/18 17:42	EMAIL APPOINT LKK-GZ8796P.pdf	 Load PDF	
2	18/06/18 17:42	EMAIL CONFIRM APPOINT LKK-GZ8796P.pdf	 Load PDF	
3	18/06/18 17:42	Email 10 SURYVORS to TPD GZ8796P.pdf	 Load PDF	
4	18/06/18 17:42	PRI -GZ8796P.pdf	 Load PDF	
5	18/06/18 17:51	TP GIA Report - GZ8796P From:SC - Reg. No: SLD8692L, Claimant: MOHAMED YUSOF BIN ABDULLAH	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18011061/AQD3E2

Date: 16/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80445212QMY

Claimant Vehicle
No : GZ8796P

Insured Vehicle No : SLD8692L

Date of Loss: 14/06/2018

Nature of Claim: TP

Claim No: 561499

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GZ8796P**

Make & Model: SSANGYONG MUSSO, 2.9 D (M)

Engine No: 66292012162929

Reg. Date: 27/09/2006 (Man. Year: 2005)

Chassis No: KPAWA2EDS6P415716

Colour: White

Odometer: 248990 km

Engine Capacity: 2874 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/70 R16	Rear Tyre Size:	245/70 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,732.90	8,469.00	5,263.90	38.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,520.00	1,810.00	1,710.00	48.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,252.90	10,279.00	6,973.90	40.42
Approved Total (Overridden) (S\$)		8,200.00		
(S\$)	17,252.90	8,200.00	9,052.90	52.47
+ GST 7.00/7.00% (S\$)	1,207.70	574.00	633.70	52.47
Nett Amount (S\$)	18,460.60	8,774.00	9,686.60	52.47

INSPECTION

Date of Assignment: 19/06/2018

Date Inspected: 21/06/2018 Inspected At:

Twincar Automotive Pte Ltd (Kaki Bukit)
BLK 2 KAKI BUKIT, #01-17/18 KAKI
BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING**Manager:** Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Oct 2018)
Parts:	M1-SUV	SSANGYONG MUSSO 2.9 D (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GZ8796P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,750.00 FL	*1,245.00 FL
2	2		*REAR BUMPER BRACKET L/R	Bent	316.00 FL	*316.00 FL
3	2		*REAR BUMPER REFLECTOR L/R	Not Necessary	396.00 FL	*- FL
4	1		*REAR BUMPER SIDE GARNISH L/R	O/S Deformed	850.00 FL	*425.00 FL
5	1		*REAR BUMPER SIDE GARNISH RETAINER L/R	O/S Damaged	210.00 FL	*105.00 FL
6	1		*REAR BUMPER STEP GARNISH	Deformed	425.00 FL	*425.00 FL
7	1		*REAR END PANEL INNER	Dented	658.00 FL	*658.00 FL
8	1		*REAR END PANEL OUTER	Dented	589.00 FL	*589.00 FL
9	1		*REAR END PANEL TOP GARNISH	Cracked	358.00 FL	*358.00 FL
10	1		*REAR SILENCER BOX	Bent	1,208.00 FL	*1,208.00 FL
11	2		*REAR SILENCER BOX MOUNTING	Not Necessary	70.00 FL	*- FL
12	1		*REAR SPARE TYRE CARRIAGE	Damaged	428.00 FL	*285.00 FL
13	1		*REAR TAILGATE	Dented	2,250.00 FL	*1,837.00 FL
14	1		*REAR TAILGATE LOGO EMBLEM	Necessary	105.00 FL	*105.00 FL
15	1		*REAR TAILGATE MUSSO EMBLEM	Necessary	98.00 FL	*98.00 FL
16	1		*REAR TAILGATE SPORTS EMBLEM	Necessary	98.00 FL	*98.00 FL
17	2		*REAR TAILGATE HINGES L/R	Not Necessary	330.00 FL	*- FL
18	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	425.00 FL	*- FL
19	2		*REAR TAILGATE MECHANISM LOCK L/R	Not Necessary	516.00 FL	*- FL
20	2		*REAR TAILGATE NUMBER PLATE LAMP L/R	Not Necessary	210.00 FL	*- FL
21	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	498.00 FL	*- FL
22	1		*REAR TAILGATE OUTER HANDLE	Not Necessary	208.00 FL	*- FL
23	1		*REAR TAILGATE WEATHER STRIP	Not Necessary	425.00 FL	*- FL
24	2		*REAR TAILLAMP L/R	Cracked	1,010.00 FL	*908.00 FL
25	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
26	2		*SET REAR BUMPER SIDE GARNISH CLIPS L/R	Necessary	100.00 FS	*20.00 FS
27	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*10.00 FS
28	1		*REAR TAILGATE 70KM STICKER	Necessary	15.00 FS	*15.00 FS
29	1		*REAR TAILGATE GREEN STICKER	Necessary	45.00 FS	*20.00 FS
30	1		*REAR TAILGATE CAMERA	Damaged	800.00 FS	*380.00 FS
31	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	100.00 FS	*- FS
32	1		*REAR TAILGATE NUMBER PLATE	Not Necessary	25.00 FS	*- FS
33	1		*REAR TAILGATE NUMBER PLATE HOLDER	Not Necessary	50.00 FS	*- FS
34	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
35	1		*SET REAR TAILLAMP CLIPS L/R	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 15,076.00 9,335.00
 - List Item Discount on L Items 10.00/10.00% (\$\$) 1,343.10 866.00

Total Parts (\$\$) 13,732.90 8,469.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	120.00	80.00
2	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,300.00	800.00
3	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	180.00	80.00
4	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,800.00	800.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	50.00
Gross Labour Cost (\$\$)			3,520.00	1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >