



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD  
8 SHENTON WAY #24-01  
AXA TOWERS SINGAPORE 068811  
ATTN: TAN JUN HONG

Ref: CS3/ASM18003040/Wga3q2-1  
Date: 28/04/2022  
Code: ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	YP 6485P	<b>Veh. Inspected</b>	MBM 7512
<b>Policy No.</b>	P1993413	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S8M008RU	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	14/02/2018

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	ISUZU	<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	0
<b>Chassis No.</b>		<b>Colour</b>	WHITE
<b>Odometer</b>	424433 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	7.00 R16	BRIDGESTONE	4 mm
<b>L/H Front Tyre</b>	7.00 R16	BRIDGESTONE	4 mm
<b>R/H Rear Tyre</b>	7.00 R16	YOKOHAMA	4 mm
<b>L/H Rear Tyre</b>	7.00 R16	YOKOHAMA	4 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	09/02/2018	<b>Inspection Date</b>	23/02/2018
<b>Survey held at</b>	ETHICARZ PTE LTD 56 LOYANG WAY #04-04 LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**