

CHENG MOTOR WORK CO

1 KAKI BUKIT AVE.6 #01-83

SINGAPORE 417883

Tel:65551185/6 Fax:65551184

H/P: 96713335

E-mail:chengmotor27@yahoo.com

KK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

13/6/2018

AXA Insurance Singapore Pte. Ltd.

8 Shenton Way #27-01

AXA Tower

Singapore 068811

Attn: motor claims Dept

Estimate cost of repair vehicle no: GY3015

Front Door R/h

Front door signal lamp

Front bumper

Front headlamp

Front step garnish

h \$1218.85 *X*
11 172.45 *X*
Repair 374.45 *✓*
cm 1217.45 *✓*
SVC 374.10 *X*

\$3357.30

Less 25%

839.32

2517.98

Labour for knocking,welding,cutting,repairing

And replacement of parts.

To spray paint on the damage parts.

To check wiring.

To transfer door mechanical

Door side marker

750.00 *300*
 800.00 *400*
 45.00 *20*
11 180.00 *X*
nu 40.00 *30*
\$4332.98

Total

Not Adult
h
take ph. before pay.
3 day.
19/6/18