ASS. REC. BY:		REF:	cs/	CTLI8	011088/K	gbez special survers	on.	
Surveyor	Kenneth		ASSI		NT (Office)	-		2000
Prom (Person):	Chong Boo	n Sen	of		CTL	Date/Time	19097018	339 bu
Estimated Cost:	7				Bill to:			
OH/TP/WS/T	PRES / OD RE	S/EVA	INV /	MV/C	S			
To Inspect Vehicle	No:	922	241	1D		Insured:		
at Workshop m/s		hai h	luut (mena	Kel)	Tel:		
of			ming	DAG	# OL-01			
Policy No. Dm	18EEUS 1239	1702			Claim No:	SNMIB DOJU	103F2	
Sum Insured:					Excess:	# 1000 00		
Make of Veh.						D.O.A.	15062018	
CA / REV / RI	OP. / BRV 24 B	no c		9000	2018	HOD E		
Date/Time 19			on Cont	noted:_	Debrah	Vehicle IIV	OUT	
Date/Time A	ction/histraction	(1) Est	imate				
	JP 24170 -	X:						
20/6/1802	Sopy Nev	ent t	0 0	RONG	born Sen	in mein	1807	
21/4/18@ 50	15/h Susa	on Tec	in	Somo	d c/A 1	TO METERNA	- 4	
						Ex= 8 1000 6		
the state of the s						red Ag 8 24		Jey
	Red 8 201				U	U		U

· invitio	REF: CTI	(s/cTU	8011088/Kg6		
		ASSIGNMENT	AREA.		
From	Date: 20106	2018 Velt No.	STP 2412	D Yr Regn O.	3 09
Estimuted Cost	50 50		M.Gycle / Bus / Van / L		
OD TP/WS/TP RES/OD R	ES/EVA/INV/MV		Trailer or		
0	JP 2412D	Make	Toy Co	my as	2362
	iat (Mena Kee	2	M. Black	A/C: Insured /	Std / NI / NA
160 Sin Ming 1		Sn Reading	151065		Std / NI / NA
100 21	SNIA'S II O-L OI	Eng/No			
Policy No.		C/No	MR 653	BK 4007	03325
Claims No.			ood) Fair / Poor / Burn		- , , ,
Sum Insured:	Excess # II		der Jammed / Leaked		
(Client's Record)	3-3-3-1	33.00	rier / Jammed / Leaked	/ Burnt or	
Maker of Velu		Modi: Nil	SIRim / STD AIRIN	of:	
101		Tyre Size:		15/55R	17
(Policy Condition)	. /		R:		_
Remark: The veh had commer	nced its N/S	O/S BS / DUN / E	XNOVA / GY / FS / LIZA	/ MIC / OHTSU / PIR /	SUMI/
repair at the time of		TOYOTYPE	(O) or		
Ball or Market Value.	2 ok	Front		Rear	
IDAC Accident Roort	Consistent?: Yes or No	R/Bal	3	R/Bal.	3
GIA / PR Seen:	Consistent? : Yes or No	L/Bal	3 mm	L/Bal.	3 "
Est Repairs: 05		D.O.A.	15/6/18	DOI 20	16/18
Lum Sum I-B 1		Survey held a			
			iges Frt / Rear / 0/5	I N/S / U/C / Roofte	op or
CA / REV / REP. / 241	TRS Vehicle	INTOUT OIS	m		
Date Person	Contacted		/ Chassis frame / Boo	ly Structure affected d	tue to collision.
Date / Time Action / Instr		ED 0 8 OCT 2010	3	8/2	pois
DonoTime: File Pass to *	: Prell. Report	Days Of Rep	nair:		
109/10 MAST	Final Report	Resurvey No	o. of Trip:	Survey Feet Transportation	200
	,	Add Fee: Site I	msp (\$	1_0+R5_5/	
	120	Inter	pew 15	Photo:	
Report Format	MER-0D 2453.70		6079-13	1 there	
Lump Sum / LB I: 18	2453.70	VVec	end (\$		1
> *				20140	220

...CLAIM SUBFOLDER...(New Assignment)

Case	Natified	Est Submitted	Adj Assigned	Adj Rpt	Ad) Submitted	Ins Autived	Status	
Main	18 Jun 2018 Sendback Est	18 Jun 2018 16:59 5\$2,546.30	19 Jun 2018 14:36 Assign				New Assignment Cancel Case	

Main	Reference	Claim Details	Documents	Show All			
CLAIM SUBFOLDER DETAILS							
Insured:	TAN TECK SAI, ID: S0749	874H, Tel: +6596217783, Emai	: STT@BLITW.COM				
Vehicle Reg. No.:	S3P2412D	Date of Loss:	15/06/2018 21 [110 Months a LTA Reg Date (nd 30 Days From			
Claim Type:	OD / SNM18D03027C01	Palicy/Cover Note No.:	DMPCSN30338 (Comprehensiv				
		Excess:	\$\$1,000.00	5\$1,000.00			
Repairer:	Ming - Tel: 64538110	r Pte Ltd (Sin Ming) 160 Sin Min					
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel:	6389 6111 [Handled by	Chong Boon Sen)			
Adjuster:	LKK Auto Consultants Pte	Ltd (HQ) - Tei: 6256-3561 [Fi	nal Rpt due 28/06/201	[8]			
Driver/Custodian:	TAN TECK SAI (67 / Male),	NRIC: S0749874H, Tel: +65962	1//03				
Driver/Custodian: Adj Asg. Remarks:	SURVEY REVERT	NRIC: 50749874H, Tel: +65962	17783				
	SURVEY REVERT	NRIC: 50749874H, Tel: +62962	processing to the second	Compose Case Mail			
Adj Asg. Remarks:	SURVEY REVERT	NRIC: 50749874H, Tel: +62962	processing to the second	Compose Case Mail			
Adj Asg. Remarks: ASSOCIATED MAIL RECEIVED	SURVEY REVERT		processing to the second				

Shiau Chan (LKKAuto)

From:

Do-Not-Reply <do-not-reply@merimen.com>

Sent:

Friday, 31 August 2018 6:00 PM do-not-reply@merimen.com

To: Cc:

SUR

Subject:

VEHICLE SJP 2412D (YOUR REF: SNM18D03027C01)

This mail is associated with: SJP2412D (SNM18D03027C01)

OD
Jun 15 2018 9:00PM
[TAN TECK SAI]
Lai Huat (Meng Kee) Motor Pte Ltd

Dear Boon Sen,

We have received supplementary of \$110.00 from repairer. Our surveyor had since checked and verified the supplementary parts and is of the view that the supplementary parts are consistent to the nature of the accident, within authorise limit and is economical to repair.

Thanks & Regards,

Shiau Chan (Ms) LKK Auto Consultants Pte Ltd Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Friday, 22 June 2018 10:48 AM

To:

jenny.lim@laihuat.com.sg

Cc:

SUR

Subject:

VEHICLE SJP 2412D (DOA: 15/06/2018)

Attachments:

SJP2412 CTI AUDATEX.pdf

Dear Jenny,

As instructed by our client China Taiping Insurance, please proceed to repair the insured vehicle SJP 2412D (excess \$1,000/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

-	UDIT TRAIL	Audit	Remarks	By
(p.	On	Audie	ALCITION NO.	[R] Jenny
1	18 Jun 2018 16:51	Clm Veh Model Changed	(204458) TOYOTA CAMRY 2.4 ABS AIRBAG (A).	Lim Lai Foong
	18 Jun 2018 16:51	Clm Created	Reg No: SJP2412D. Policy No: DMPCSN3033811702. Acct Date: 2018/06/15. Claim T ype: OD. Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming). Created from SAS:MLHM18078081	Foong
	18 Jun 2018 16:59	Clm Submitted	2546.30.	Lim Lai Foong
	19 Jun 2018 14:36	Cim Registration Modified	Excess: -> 1000,00,	[I] Chon Boon Se
	19 Jun 2018 14:36	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):SURVEY REVERT	[I] Chon Boon Se
5	19 Jun 2018 14:36	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/28	[I] Chon Boan Se
	19 Jun 2018 14:36	Adj Mandate Set	Approved:0.00.	[I] Chan Boon Se
8	19 Jun 2018 15:25	Assignment 1st Accessed		[A] CATHERII CHONG KAI LIN
9	19 Jun 2018 15:40	Adj Adjuster Assigned	[None] -> KENNETH KONG	CATHERI CHONG KAI LIN
10	20 Jun 2018 14:46	Adj Rpt Initiated		[A] SHIA CHAN
11	20 Jun 2019	Adj Im. Advice Submitted	Next Rpt:Final Rpt,Due Date;2018/06/28	(A) SHIA CHAN
12	20 him 2010	Adj Mandate Request	Cur.Req:2462.30:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NO T AUTHORISE REPAIR.	CHAN
13	17:45	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/28	[I] Susa Teo
14	21 Jun 2018 17:45	Adj Mandate Set	Approved:2462.30.	[I] Susa Teo

Date From

■ ► Date To

■ ► Audit Type None

♥ Go

ACTIVITY No record

erimen Billin	g for this case -	Fransaction H	istory				
Bill Ref No.	Bill Date	Acc Type	Acc Name	(Branch)	SirC1	Birt Z	Amount
1835026	18/06/2018 16:51	Motor	Lai Huat (Meng Kee) Motor Pte Ltd	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	SJP2412D		XX.XX
1837104	20/06/2018 14:46	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	S3P2412D		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park

Singapore 408933

Attn:

Chong Boon Sen

Date: 20 Jun 2018

Preliminary Advice

Vehicle No

: SJP2412D

Accident Date

: 15/06/2018

Policy No.

Make

: TOYOTA CAMRY

: DMPCSN3033811702

Assignment Date

: 19/06/2018

Excess

:S\$

: S\$1,000.00

Date of Inspection : 20/06/2018

: 5.00

Est. Duration of Repair

Inspection At

: LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING)

160 SIN MING DRIVE #04-01, SIN MING AUTOCITY

SINGAPORE 575722

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

:S\$	2,546.30
:S\$	2,407.30
:SS	55.00
:S\$	2,462.30
	:S\$:S\$

Lump Sum Repair

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	20,000.00
COE / PARF Rebate	:S\$	14,279.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,721.00

Remarks

(X	The vehicle is repairable at our adjusted amount, let us have your authorisation.	We	have	also	confirmed	excess	and	policy	coverage.	Kindly

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

ehicle Owner Particulars	WEVE
wner ID Type:	Singapore NRIC
wner ID:	9874H
ehicle Details	one of action or handless of
ehicle No.:	SJP2412D
ehicle to be Exported:	No
tended De-registration Date:	20 Jun 2018
ehicle Make:	TOYOTA
ehicle Model:	CAMRY 2.4 AUTO ABS AIRBAG
rimary Colour:	Black
lanufacturing Year:	2009
ngine No.:	2AZE130880
hassis No.:	MR053BK4007033254
laximum Power Output:	123.0 kW (164 bhp)
pen Market Value:	\$27,844.00
riginal Registration Date:	16 Mar 2009
irst Registration Date:	16 Mar 2009
ransfer Count:	2
ctual ARF Paid:	\$27,844.00
ntended PARF Rebate Details	
ARF Eligibility:	Yes
ARF Eligibility Expiry Date:	15 Mar 2019
ARF Rebate Amount:	\$13,922.00
ntended COE Rebate Details	
OE Expiry Date:	15 Mar 2019
OE Category:	B - Car (1601cc & above)
OE Period(Years):	10
P Paid:	\$4,889.00
OE Rebate Amount:	\$357.00
otal Rebate Amount:	\$14,279.00

The information contained herein is correct as at 20 Jun 2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

621 26

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 5. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

THE RESIDENCE	ACCIDENT STATEMENT				
Date Of Report	18/06/2018 12:42				
Date Of Accident	15/06/2018 21:30				
Exact Location Of Accident	JURONG WEST CENTRAL 3 NEAR TO BOON LAY BUS INTERCH				
Country/State of Loss	SINGAPORE				

A STATE OF THE PARTY OF THE PAR	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJP2412D	
Insured/Policyholder		
Name Of Registered Owner	TAN TECK SAI	

NRIC No S0749874H Email Address STT@BLITW.COM Mobile Phone No (LOCAL) +65-96217783 Alternative Phone No OTHERS-96217783

Vehicle Particulars

Manufacturer TOYOTA

Model CAMRY-2.4 ABS AIRBAG (A)

Exact Purpose for which vehicle was being used at PRIVATE USE

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. Name of Insurance Company

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number DMPCSN3033811702

Cover Note Number

Driver

Name of Driver TAN TECK SAL NRIC No. S0749874H Date Of Birth 22/02/1951 Occupation OUTDOOR Date Of Driving Pass 12/04/1973

Driving Experience 45 YEARS AND 2 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-96217783

Fax Number

Contact Number OTHERS-96217783 EMail Address STT@BLITW.COM

Address BLK 552 BEDOK NORTH AVENUE 1

#11-488

Postcode 460552

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

.

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by

ambulance?

YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

BEDOK NORTH NEIGHBOURHOOD POLICE CENTRE

Police Station Address ROAD: 30 BEDOK NORTH ROAD , POSTCODE: 469676 , COUNTRY:

SINGAPORE

Police Station Contact TEL NO: 1800-2449999 - FAX NO: 62447258

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT: T/20180613/2002

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBD9088T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category MOTORCYCLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

Page 2 of 15

DETAILS OF INJURED PERSON 1

Name

 $\sum_{i=1}^{n} \frac{d_i p_{i+1}}{q_i} = 0$

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBD9088T

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary Investigations relating to the claims;
 - (ii) investigating the accident and/or my claims:
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- [b] III insurer[s] who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- [d] my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

1 B JUN 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Ceobe Personnel's Signature

Name:

NRIC/FIN No. Poh Kwee Choo

S6840583A

Sketch Plan Pg. 2 SKETCH PLAN Bus DESCRIBE CIRCUMSTANCES OF THE ACCIDENT Please refer to Police report = T/29/8-616/2002. DECLARATION t/We declare the loregoing particulars are true in every respect. Driver's Signature Reporting Centre Personnel's Signature
Name: Poh Kwee Choo
NSIC/FIN No.: S6840583A Policyhoider's Signature Name: Date & Times JUN 2018 (if driver is not the policyholder) NRIC/FIN No.: Date & Time:

12:437





Police Station Of Origin: Bedok North N.P.C

30 Bedok North Road SINGAPORE 469676

Tel No: 1800-2449999

1 of 4 Report No. T/20180616/2002

REPORT	OF A	TRAFFIC	ACCIDENT
--------	------	---------	----------

Date/Time Report Made: 16/06/2018 00:14		Made:	Vide Report No.; J/20180615/0260	Station Diary No.:		
Informa	nt's Partici	ulars	CHARLEST THE STREET			
Name of	Informant: CK SAI		Address: APT BLK 552 BEDOK NORTH AVENUE 1 #11-488 SINGAPORE 460552			
ID Type / ID No.: NRIC NO / S0749874H			Contact No.: Home/Office: Mobile: 96217783			
National SINGAP	ity: ORE CITIZ	EN	Email:			
Sex: Male	Age: 67	Date of Birth: 22/02/1951	Type of Informant: Driver			
Race: Chinese			Language: Institution / School Nam			
Occupation: CONTRACTOR		<u> </u>	Driving Licence Information: Class: 3 Date of Expiry:			

Type of Accident:	Injury Conveyed By Ambular	nce Drink No	Date/Time of Accident: 15/06/2018 21:30	Type of Location Straight Road
	ST CENTRAL 3 Lay Bus Interchange	Road Surface:		Dood Speed Limit
Clear	10	Road Surface: Dry		Road Speed Limit:
		Traffic Control:		Traffic Volume:
Traffic Flow: Two Way		Traffic Light - W	orking	Light

Details of V	ehicle involve	d	Carlo Service		Marie Landon	A CONTRACTOR OF THE PARTY OF TH
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBD9088T	Motorcycle				Seriously Damaged	0
SJP2412D	Car	TOYOTA	CAMRY 2.4 AUTO ABS AIRBAG	Black	Seriously Damaged	0

Details of Vehicle Insurance	
Vehicle No. Insurance Company	Insurance No. Effective Expiry Date





Police Station Of Origin: Bedok North N.P.C 30 Bedok North Road SINGAPORE 469676 Tel No: 1800-2449999 2 of 4 Report No. T/20180616/2002

CONTINUATION OF REPORT

Details of V	ehicle insurance	and the land of the last of the last	1000	dentista.
Vehicle No.	Insurance Company	Insurance:No. 34 M	Effective	Expiry Date
SJP2412D	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	DMPCSN30338117 02	16/09/2017	15/09/2018

Details of Perso			- pre- page -	CALE	OF THE	可。在海域和6000年
Any Pedestrian II	rvolved: No					
No. of Pedestrian	s Injured: NIL		Use of Pec	festrian	Cross	ing: NA
Driver	M/98-23763 Pay 75	1 20	20F3WH25	15,110	3113	MALES FOR STATE OF THE STATE OF
Name	TAN TECK SAI			ID No.		S0749874H
Related Vehicle	SJP2412D (Car)			Conta	ct No.	96217783
Hospital/Clinic	NIL			Class Drivin Licent Expiry	g	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Disc	harge	NIL	
No. of Days gran	ted Medical Leave	NIL	Degree of	injury	NIL	

Brief Details.

On 15/06/2018, at about 2130hrs, I was travelling along Jurong West Central 3 near to Boon Lay Bus Interchange in my vehicle bearing registration plate number SJP 2412D. I was travelling on the right side of a 2 lane road with a bus on the left lane. The left lane allows buses to turn left into the bus interchange while my lane only allows vehicles to go straight. Both the bus and myself were the first vehicles in line at the traffic light which was red at the point of time. When the traffic lights turned green, the bus that was situated on my left, slightly behind me signalled for me to move. Thinking that the bus may require more space for the left turn, I inched slightly to the right to create more space for the bus. I wish to say that the bus was quite close to me when we were at the traffic light.

While I was inching, I suddenly felt an impact from right side of my vehicle. After seeing that a motorcycle had collided into my vehicle, I immediately came out of my vehicle to make a check. I admit that it is my negligence to not check for vehicle coming on my right while inching however, I believe that the said motorcycle was travelling at a fast speed and was trying to squeeze through the space between my vehicle and the center divider. The female rider was conscious and told me that her legs were injured and she was subsequently conveyed by ambulance at scene.

After a short while, traffic police attended to the incident and interviewed me. The officer questioned if I had intentions to make an illegal U-turn resulting in this accident, and I denied. I was on my way to fetch my wife from Jurong Point Pick up point and to reach there, I would have to make a left turn further down the road, thus, there was no reason for me to make a U-turn at that junction. I then left the scene after the Police officer interviewed me.

I am not injured from this accident. As a result of this collision, my vehicle sustained damages to the right side and lights of the car. The motorcycle was also quite severely damaged. I do not have the particulars of the rider as she was conveyed by ambulance. The bus was not involved in this accident as well.





Police Station Of Origin: Bedok North N.P.C

30 Bedok North Road SINGAPORE 469676 Tel No: 1800-2449999

Report No. T/20180816/2002

3 of 4

CONTINUATION OF REPORT





Police Station Of Origin: Bedok North N.P.C

30 Bedok North Road SINGAPORE 469678

Tel No: 1800-2449999

CONTINUATION OF REPORT

4 of 4

Report No. T/20180616/2002

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 NG YU NING	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 16/06/2018 00:14
Officer In Charge Of Case: TP / GIT / Staff Sgt YAN MINGSHENG DANIELE FLORE Contact No.: 65476252	Classification Of Case:
Authentication Stamp NP168	URE

REPUBLIC OF SINGAPORE IDENTITY CARD NO. S0749874H





hiame

TAN TECK SAI

陳 澤 獅

CHINESE 22-02-1951 M

SINGAPORE

107498741



4818639



31-01-2012

APT BLK 552 BEDOK NORTH AVENUE 1 #11-488 SINGAPORE 460552

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES)

EFFECTIVE DATE

Motor cars with unladen weight == 3000kg with =< 7 12 Apr 1973 passengers, exclusive of driver; and other motor vehicles with unladen weight =< 2500kg





中国太平保险(新加坡)有限公司

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD.

Co. Reg. No. 200208384E

MXIF R SN AN0365A Cov.Type: C

MOTOR PRIVATE CAR

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 180) Motor Vehicles (Third-Party Risks and Compensation) Rules, 1990 Road Transport Act, 1967 (Malaysia) Motor Vehicles (Third-Party Risks) Rules, 1999 (Malaysia)

ORIGINAL

Engine No :2AZE130880 CERTIFICATE No. DMPCSN3033831702 ChaNo: MR053BK4007033254 1. Index Mark and Registration S3F2412D AUTOSAFE Number of Venice 2. Name of Policy Holder MR TAN TECK SAI Effective sate of the Commercement of Insurance for the purposes of the Regulations, Ordinance or Enactment 16 September 2017 Named Drivers Ex Sect. I 5\$1,300.00 Additional Ex Other than Named Drivers: Ex Sect. I - Age \Leftrightarrow 25...... 553,000.00 4. Date of Expiry of Insurance 15 September 2018 Ex Sect. I - Age >= 26...... 5\$500.00 " Age as at date of accident 5. Persons or Classes of Persons syrifted to srive?

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor vehicle.

it. Limitations as to use."

use for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover use for hire or reward tuition driving test racing pace-making, reliability trial, speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

Excess whichever is applicable for losses occurring outside Singapore (Constructive Total Loss/Theft) will be doubled.

One time waiver of Excess for the first \$\$500 will apply to the Insured and Named Drivers in the event of Own Damage Claim at our Authorised Workshops for each Policy Year.

HIRE PURCHASE CO.: TAI THONG LEE TDG (PTE) LTD AS HP OWNER.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Fasis and Compensation) Act (Chapter 15%) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Mnlaysia).

Please see reverse

力 企 HIGH POWER ENTERPRISE Blk 150 Bishan Street 11

#01-137 Singapore 570150

Tel: 6258 1968 Fax: 6258 7167 Email: gl@highpower.sg

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

10000

Authorised Signatory

lasued By: HIGH POWER FATERPRISE Authorised Officer

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

9874H

Vehicle Details

Vehicle No.:

SJP2412D

Vehicle to be Exported:

Yes

Intended De-registration Date:

18 Jun 2018

Vehicle Make:

TOYOTA

Vehicle Model:

CAMRY 2.4 AUTO ABS AIRBAG

Primary Colour:

Black

Manufacturing Year:

2009

Engine No.:

2AZE130880

Chassis No.:

MR053BK4007033254

Maximum Power Output:

123.0 kW (164 bhp)

Open Market Value:

\$27,844.00

Original Registration Date:

16 Mar 2009

First Registration Date:

16 Mar 2009

Transfer Count:

2

Actual ARF Paid:

\$27,844.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

15 Mar 2019

PARF Rebate Amount:

\$13,922.00

Intended COE Rebate Details

COE Expiry Date:

15 Mar 2019

COE Category:

B - Car (1601cc & above)

COE Period(Years):

10

QP Paid:

\$4,889.00

COE Rebate Amount:

\$360.00

Total Rebate Amount:

\$14,282.00

The information contained herein is correct as at 18 Jun 2018

OK

LAI HUAT (MENG KEE) MOTOR PTE LTD SIN MING INDUSTRIAL ESTATE SECTOR A BLK 21 #01-58 SINGAPORE 575679

Claim Reference:

Full Report - V1 Registration: SJP 2412D

Assessment Number: LHM61111

Version: LAI HUAT/1

Printed: 18/06/2018 16:44

SGD

15/06/2018

Date Calculated: 18/06/2018 09:43

Summary Information

Claim

Location:

Printed by:

Authorisation Status:

Work Provider:

Claim Reference: Policy Number:

Other Reference:

Third Party: Insured Amount: Under Warranty: Warranty Expired: Singapore (SG)

Jenny Lim Interim

China Taiping Insurance

(S) Pt

DMPCSN3033811702

OD CLAIM

TOYOTA

BASE MODEL

Camry

YCA 01

SJP 2412D

Not Known

Currency:

Date of Incident:

Able to Authorise Repairs: TBA TRA

Repairs Authorised:

Estimated Repair Time: Quote Due Date: Actual Repair Days:

Parts Ordered Date: Hire Car Start: Hire Car End: Vehicle Collected:

Vehicle Details

Vehicle

Manufacturer: Model:

Sub Model: Model Sheet Number:

Registration:

Registration Month:

Registration Year:

VIN Number:

Odometer: Colour:

Engine Number:

Fuel Level:

%

Model Specs

FROM 03/2009 XENON HEADLAMPS HEADLAMP WASHERS TYRES 215/55 YR 17 VERSION THAILAND

PREPARE OFF VEHICLE

AUTO AIR CON FOG LAMPS 2.4 LTR 123KW

WHEELS 7J X 17 ALLOY

E Not Northerner
Resumy B4 paint

[ax:62564315

5day

Vehicle Condition

Vehicle Status

Pre-Accident Condition:

Steering:

Brakes Pedal Travel: Place of Inspection: Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF: Tread Depth LHR:

Damage Areas:

Severity of Impact:

Vehicle Status on Inspection:

Date of Inspection:

18/06/2018

LKK Auto Consultants hence notify the Repairer of the following: * To resurvey before/after spray painting

Tread Depth RHR: * Parts prices are subject to confirmation

Tread Depth RHF: *To display damaged part(s) during resurvey.

Direction of Impact: Third party survey is on a "Without Prejudice" basis

* No illegal modification(s) is allowed

. Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Osted

Claim Reference:

Full Report - V1


Assessment Number: LHM61111


Registration: SJP 2412D

Version: LAI HUAT/1

Printed: 18/06/2018 16:44

Date Calculated: 18/06/2018 09:43





Addresses

Cost Summary		
Total Labour		\$924.00
Total Paint/Material		\$226.30
Total Parts		\$1,181.00
Total of Additional Costs		\$215.00
Repair Cost Exc GST:		\$2,546.30
Overall Discount (0.0%):		- \$0.00
Excess:		-\$500.00
After Deduction -	Grand Total Exc GST:	\$2,046.30
	7 % GST:	\$143.24
	Grand Total Inc GST:	\$2,189,54

Repair Information LABOUR

LABOUR	Time Basis 10 W	U = 1 HR		= \$42.00/HR = \$42.00/HR
Repair /				
	er Repair Details		WU	Cost Price (\$)
B125	R + R LOCK INSERT		4.0	16.80
NO NUMBER	RENEW R/FRONT PANELLING EXTENSION		4.0	16.80
B110	RENEW R/FRT WING (FRT BUMPER AND R/HEADLAMP ASSY		5.0	21.00
	REMOVED)			
B100	R + R RIGHT SILL RAIL		3.0	12.60
B040	RENEW R/HEADLAMP (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMPS.		5.0	21.00
B040	R + R RIGHT HEADLAMP UNIT (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMP		3.0	12.60
B020	RENEW FRONT BUMPER INCLUDES: R + R FRONT BUMPER, RADIATOR GRILLE AND NECESSARY ATTACHED PARTS		15.0	63.00
851091)	R + R WASHER RESERVOIR		4.0	16.80
0471	REPAIR BONNET	15		84.00
1009	REPAIR FRONT PANEL	20	30:0*	126.00
1118	REPAIR R/F WHEELHOUSE CPL	15		84.00
LA	BOUR COST	7.		
	Total Work Units		113.0	
	Corrosion Protection External Labour		0.0HRS	0.00
	Corrosion Protection Internal Labour		0.0HRS	0.00
	Sub Total		11.3HRS	\$474.60
	Paint Labour		10.7HRS	\$449.40
	Total Labour		22.0HRS	\$924.00

Claim Reference:

Full Report - V1

Assessment Number: LHM61111

Registration: SJP 2412D

Version: LAI HUAT/1

Printed: 18/06/2018 16:44

Date Calculated: 18/06/2018 09:43

PAINT WORK	Time	e Basis 10 WU = 1 HR. Price	= \$42.00/HR
Guide Number	Description	wu	Cost Price (\$
	- TWO COAT METALLIC		
	 PREPARE OFF VEHICLE 		
742	R/F WING NEW PART PAINTING	10.0	
283	FRONT BUMPER NEW PART PAINT K1R	13.0	
298	R/FOG LAMP COVER NEW PART PAINT K1	R 3.0	
344	FRT BUMPER ABSORBER SURFACE PAINT	PLAST. 3.0	
410	GRILLE NEW PART PAINT K1R	3.0	
171	BONNET REPAIR PAINTING <50%	26.0	
741	L/F WING SURFACE PAINT	6.0	
1009	FRONT PANEL SURFACE PAINT	7.0	
1118	R/F WHEELHOUSE CPL SURFACE PAINT	6.0	
LAB	OUR COST - PAINT		
	TIME(PAINT)	77.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	107.0	
	Total Paintwork Labour	10.7HRS	\$449.40
MAT	ERIAL COST - PAINT		Cost Price
	New Part Painting		\$20.64
	New Part Painting - Plastic K1R		\$70.36
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$41.33
	Surface Paint Plastic		\$1.46
	Repair Painting		\$54.91
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$226.30
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$226.30
PARTS		10254100mg	vanteri overvi bestrativeko e
	Description Part Num		Valid: 01/06/2015 et. Price (\$)

					Price Vali	d: 01/06/2015
Guide N	No. Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1000	1	BONNET EMBLEM	Renew	5/5/	0%	May 20.00 =
283	1	FRONT BUMPER	52119 06940		0%	四 170.00* —
257	1	FRONT NUMBER PLATE	KNPL3		0%	0.00F
344	1	FRT BUMPER ABSORBER	52611 06150		0%	M1735.00*
410	1	GRILLE	53111 06280		0%	115.00° -
639	1	L/F BUMPER MOULDING	52713 06010		0%	30.00* —
640	1	R/F BUMPER MOULDING	52712 06010		0%	14 30.00° -
638	1	R/F FOG LAMP CPL	81210 02121		0%	Bu 80.00*
1028	1	R/F PANEL REINF	52141 06050		0%	写 30.00* —
318	1	R/F UPP BUMPER BRKT	52535 06090		0%	21726.00*
742	1	R/F WING	53801 06130		0%	年 160.00* 二
298	1	R/FOG LAMP COVER	52030 06080		0%	4/7 20.00
842	1	R/WHEELHOUSE SHELL	53875 06081		0%	M 55.00 7
562	1	RIGHT HEADLAMP ASSY	81110 06251		0%	50 350.00°
1436	1	WASHER CONTAINER	85315 06160		0%	nu 60.00 =
f: OEM I	Parts		Saving			\$18.00

Claim Reference:

Full Report - V1

\$1,181.00

Assessment Number: LHM61111

Registration: SJP 2412D

Version: LAI HUAT/1

Printed: 18/06/2018 16:44

Date Calculated: 18/06/2018 09:43

g: Original	Sub Total		\$1,181.00
h: Secondhand	Sundry Parts	(Fixed)	\$0.00
p: Parallel	Total Parts		\$1,181.00

x: Exchange

Total Parts

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description		Betterment	Price
SUNDRY PARTS	SPECIALIST	0%	\$100.00
FRONT NUMBER	SPECIALIST		\$35.00
PLATE WHEEL ALIGNMENT	SPECIALIST	0%	\$80.00
		Total Extras	\$215.00

Final Calculation

		4 -1
Labour		
Total Panel/Mechanical	\$474.60	
Total Paintwork	\$449.40	
Total Labour	10	\$924.00
Additional Costs		10
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$215.00	
Total of Additional Costs		\$215.00
Total Paint/Material Costs		\$226.30
Repair Costs Excludes GST		\$2,546.30
Deductions	-	
Deduction for Excess (Fixed)	-\$500.00	
Total Deductions	Link Medicine Construction	-\$500.00
Grand Total Excludes GST (After Deduction)		\$2,046.30
GST @ 7 %		\$143.24
Grand Total Includes GST (After Deduction)		\$2,189.54

Assessment Notes

2656.30

Claim Reference:

Full Report - V1

Assessment Number: LHM61111

Registration: SJP 2412D

Version: LAI HUAT/1

Printed: 18/06/2018 16:44

Date Calculated: 18/06/2018 09:43

g: Original

Sub Total

\$1,181.00

h: Secondhand

Sundry Parts

(Fixed) \$0.00

p: Parallel

Total Parts

\$1,181.00

Price

x: Exchange

THIS ASSESSMENT CONTAINS UNPRICED PARTS

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description SUNDRY PARTS FRONT NUMBER

SPECIALIST SPECIALIST Betterment 0%

Ne \$35.00

PLATE

WHEEL ALIGNMENT SPECIALIST

0%

\$80.00

\$1,181.00

\$924.00

Total Extras \$215.00

Final Calculation

Total Parts
Labour
Total Panel/Mechanical
Total Paintwork

\$474.50

\$449.40

Total Labour Additional Costs

Corr Prot Materials External \$0.00
Corr Prot Materials Internal \$0.00
Cost of Specialist \$215.00

Total of Additional Costs Total Paint/Material Costs Repair Costs Excludes GST \$215.00 \$226.30

\$2,546,30

Deductions

Deduction for Excess (Fixed)

-\$500.00

Total Deductions
Grand Total Excludes GST (After Deduction)
GST @ 7 %

-\$500.00 \$2,046.30

Grand Total Includes GST (After Deduction)

\$143.24 \$2,189.54

Assessment Notes

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

LAI HUAT (MENG KEE) MOTOR PTE LTD SIN MING INDUSTRIAL ESTATE SECTOR A BLK 21 #01-58 SINGAPORE 575679

Claim Reference:

Assessment Number: LHM61111

Version: LAI HUAT/3

Date Calculated: 29/08/2018 06:51

Full Report - V1

Registration: SJP 2412D

Printed: 29/08/2018 13:52

SGD

TBA

15/06/2018

Summary Information

Claim

Location:

Printed by:

Authorisation Status:

Work Provider:

Jenny Lim

DMPCSN3033811702

Interim

OD CLAIM

TOYOTA

BASE MODEL

SJP 2412D

Not Known

Camry

YCA 01

(S) Pt

Claim Reference: Policy Number:

Other Reference: Third Party:

Insured Amount: Under Warranty: Warranty Expired: Singapore (SG) Currency:

Date of Incident: Able to Authorise Repairs: TBA

China Taiping Insurance Repairs Authorised:

Estimated Repair Time:

Ouote Due Date: Actual Repair Days: Parts Ordered Date: Hire Car Start: Hire Car End: Vehicle Collected:

Vehicle Details

Vehicle

Manufacturer: Model:

Sub Model: Model Sheet Number:

Registration:

Registration Month: Registration Year:

VIN Number:

Odometer: Colour:

Engine Number:

Fuel Level:

96

Model Specs

FROM 03/2009 XENON HEADLAMPS HEADLAMP WASHERS TYRES 215/55 YR 17

VERSION THAILAND PREPARE OFF VEHICLE AUTO AIR CON FOG LAMPS

2.4 LTR 123KW WHEELS 73 X 17 ALLOY TWO COAT METALLIC

Vehicle Condition

Vehicle Status

Pre-Accident Condition: Steering:

Brakes Pedal Travel: Place of Inspection: Pre-Accident Damage: Severity of Impact: Vehicle Status on

Inspection:

Date of Inspection:

18/06/2018

Tyres Condition:

Tread Depth LHF: Tread Depth LHR:

Damage Areas:

Tread Depth RHF: Tread Depth RHR: Direction of Impact:

Claim Reference:

Full Report - V1


Assessment Number: LHM61111


Registration: SJP 2412D

Version: LAI HUAT/3

Printed: 29/08/2018 13:52

Date Calculated: 29/08/2018 06:51





Addresses

Cost	Sum	mary

Total Labour		\$805,40
Total Paint/Material		\$226.30
Total Parts		\$1,261.00
Total of Additional Costs		\$215.00
Repair Cost Exc GST:		\$2,508.70
Overall Discount (0.0%):		- \$0.00
Excess:		-\$1,000.00
After Deduction -	Grand Total Exc GST:	\$1,508.70
	7 % GST:	\$105.61
	Grand Total Inc GST:	\$1,614.31

Repair Information

LABOUR	Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
	16.0 Head Live Part (1.1 Head 1.1 Head

Danada /		Price/Dent	= \$42.00/HR
Repair /	na Panala Batalla	2000	5 755 F MV
	er Repair Details	wu	Cost Price (\$)
NO NUMBER	- 1.0.1.5.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.	2.0	8.40
B110	RENEW R/FRT WING	5.0	21.00
	(FRT BUMPER AND R/HEADLAMP ASSY		
4000	REMOVED)		
B100	R + R RIGHT SILL RAIL	3.0	12.60
B020	RENEW FRONT BUMPER	13.0	54.60
	INCLUDES: R + R FRONT BUMPER, RADIATOR		
	GRILLE AND NECESSARY ATTACHED PARTS		
B040	RENEW R/HEADLAMP	5.0	21.00
	(BUMPER REMOVED)		
	INCLUDES: ADJUST HEADLAMPS.		
B040	R + R RIGHT HEADLAMP UNIT	3.0	12.60
	(BUMPER REMOVED)		
	INCLUDES: ADJUST HEADLAMP		
851091)	R + R WASHER RESERVOIR	4.0	16.80
0471	REPAIR BONNET	15.0*	63.00
1009	REPAIR FRONT PANEL	20.0*	84.00
1118	REPAIR R/F WHEELHOUSE CPL	15.0*	63.00
LAI	BOUR COST		
	Total Work Units	85.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	8.5HRS	\$357.00
	Paint Labour	10.7HRS	\$449.40
	Total Labour	19.2HRS	\$806.40

Claim Reference:

Full Report - V1

Assessment Number: LHM61111

Registration: SJP 2412D

Version: LAI HUAT/3

Printed: 29/08/2018 13:52

Date Calculated: 29/08/2018 06:51

	ORK		Time Basi	s 10 WU = 1 H	R. Price = :	\$42.00/HR
Guide Nu	ımbe	r Description		W		Cost Price (\$)
		- TWO COAT MET	ALLIC			
		- PREPARE OFF V				
742		R/F WING NEW PART PAIN		10.	.0	
283		FRONT BUMPER NEW PART		13.	.0	
298		R/FOG LAMP COVER NEW F		3.	.0	
344		FRT BUMPER ABSORBER SU	JRFACE PAINT PLAST	. 3.	.0	
410		GRILLE NEW PART PAINT K		3.	.0	
471		BONNET REPAIR PAINTING	<50%	26.	.0	
741		L/F WING SURFACE PAINT		6.	0	
1009		FRONT PANEL SURFACE PA	INT	7.	0	
1118		R/F WHEELHOUSE CPL SUP	FACE PAINT	6.	0	
	LAB	OUR COST - PAINT	A LOUIS COMPANY			
		TIME(PAINT)		77.	0	
		Preparation Main Work F	Plastic	5.		
		Preparation Main Work !	Metal	25.	0	
		Preparation Work Multi !	Layer Paint	0.		
		Total Work Units (10WU	/HR)	107.		
		Total Paintwork Labour		71071700	7HRS	\$449.40
	MAT	ERIAL COST - PAINT				Cost Price
		New Part Painting				\$20.64
		New Part Painting - Plas	tic K1R			\$70.36
		Material-Constant Main \	Work Metal			\$28.60
		Surface-/Blend Paint				\$41.33
		그렇게 되었다면 하다 하다니 말하다 프로그램의 경기 (1972 A.P.)				
		Surface Paint Plastic				
		Surface Paint Plastic Repair Painting				\$1.46
		Repair Painting	k Plastic			\$1.46 \$54.91
		Repair Painting Material-Const Main Wor				\$1.46 \$54.91 \$9.00
		Repair Painting Material-Const Main Wor Total Excluding Pearlesc	ent Uplift			\$1.46 \$54.91 \$9.00 \$226.30
		Repair Painting Material-Const Main Wor	ent Uplift %			\$1.46 \$54.91 \$9.00 \$226.30 \$0.00
PARTS		Repair Painting Material-Const Main Wor Total Excluding Pearlesc Pearlescent Uplift @ 0.00	ent Uplift %			\$1.46 \$54.91 \$9.00 \$226.30 \$0.00 \$226.30
		Repair Painting Material-Const Main Wor Total Excluding Pearlesc Pearlescent Uplift @ 0.00 Total Paint Material Cost	ent Uplift %	220000122000		\$1.46 \$54.91 \$9.00 \$226.30 \$0.00 \$226.30
Guide No		Repair Painting Material-Const Main Wor Total Excluding Pearlesc Pearlescent Uplift @ 0.00 Total Paint Material Cost Description	ent Uplift % Part Number	Supplier	Bet.	\$1.46 \$54.91 \$9.00 \$226.30 \$0.00 \$226.30 id: 01/06/2015 Price (\$)
Guide No	1	Repair Painting Material-Const Main Wor Total Excluding Pearlesc Pearlescent Uplift @ 0.00 Total Paint Material Cost Description BONNET EMBLEM	Part Number Renew	Supplier	Bet. 0%	\$1.46 \$54.91 \$9.00 \$226.30 \$0.00 \$226.30 id: 01/06/2015 Price (\$) 20.00*
Guide No 1000 183	1	Repair Painting Material-Const Main Wor Total Excluding Pearlesc Pearlescent Uplift @ 0.00 Total Paint Material Cost Description BONNET EMBLEM FRONT BUMPER	Part Number Renew 52119 06940	Supplier	Bet. 0% 0%	\$1.46 \$54.91 \$9.00 \$226.30 \$0.00 \$226.30 id: 01/06/2015 Price (\$) 20.00* 170.00*
Guide No 1000 183 157	1 1 1	Repair Painting Material-Const Main Wor Total Excluding Pearlesc Pearlescent Uplift @ 0.00 Total Paint Material Cost Description BONNET EMBLEM FRONT BUMPER FRONT NUMBER PLATE	Part Number Renew 52119 06940 KNPL3	Supplier	Bet. 0% 0% 0%	\$1.46 \$54.91 \$9.00 \$226.30 \$0.00 \$226.30 id: 01/06/2015 Price (\$) 20.00*
Guide No 1000 183 157	1 1 1 1	Repair Painting Material-Const Main Wor Total Excluding Pearlesc Pearlescent Uplift @ 0.05 Total Paint Material Cost Description BONNET EMBLEM FRONT BUMPER FRONT NUMBER PLATE FRT BUMPER ABSORBER	Part Number Renew 52119 06940 KNPL3 52611 06150	Supplier	Bet. 0% 0% 0% 0%	\$1.46 \$54.91 \$9.00 \$226.30 \$0.00 \$226.30 id: 01/06/2015 Price (\$) 20.00* 170.00* 0.00F 35.00*
Guide No 1000 283 257 344	1 1 1 1 1	Repair Painting Material-Const Main Wor Total Excluding Pearlesc Pearlescent Uplift @ 0.00 Total Paint Material Cost Description BONNET EMBLEM FRONT BUMPER FRONT NUMBER PLATE FRT BUMPER ABSORBER GRILLE	Part Number Renew 52119 06940 KNPL3 52611 06150 53111 06280	Supplier	Bet. 0% 0% 0% 0%	\$1.46 \$54.91 \$9.00 \$226.30 \$0.00 \$226.30 id: 01/06/2015 Price (\$) 20.00* 170.00* 0.00F 35.00* 115.00*
Guide No .000 .883 .57 .444 .10 .339	1 1 1 1 1 1	Repair Painting Material-Const Main Wor Total Excluding Pearlesc Pearlescent Uplift @ 0.00 Total Paint Material Cost Description BONNET EMBLEM FRONT BUMPER FRONT NUMBER PLATE FRT BUMPER ABSORBER GRILLE L/F BUMPER MOULDING	Part Number Renew 52119 06940 KNPL3 52611 06150 53111 06280 52713 06010	Supplier	Bet. 0% 0% 0% 0% 0%	\$1.46 \$54.91 \$9.00 \$226.30 \$0.00 \$226.30 id: 01/06/2015 Price (\$) 20.00* 170.00* 0.00F 35.00* 115.00* 30.00*
Guide No .000 .883 .57 .444 .10 .39 .40	1 1 1 1 1 1	Repair Painting Material-Const Main Wor Total Excluding Pearlesc Pearlescent Uplift @ 0.00 Total Paint Material Cost Description BONNET EMBLEM FRONT BUMPER FRONT NUMBER PLATE FRT BUMPER ABSORBER GRILLE L/F BUMPER MOULDING R/F BUMPER MOULDING	Part Number Renew 52119 06940 KNPL3 52611 06150 53111 06280 52713 06010 52712 06010	Supplier	Bet. 0% 0% 0% 0% 0% 0%	\$1.46 \$54.91 \$9.00 \$226.30 \$0.00 \$226.30 id: 01/06/2015 Price (\$) 20.00* 170.00* 0.00F 35.00* 115.00* 30.00* 30.00*
Guide No .000 .883 .57 .44 .10 .339 .40 .38	1 1 1 1 1 1 1 1 1	Repair Painting Material-Const Main Wor Total Excluding Pearlesc Pearlescent Uplift @ 0.00 Total Paint Material Cost Description BONNET EMBLEM FRONT BUMPER FRONT NUMBER PLATE FRT BUMPER ABSORBER GRILLE L/F BUMPER MOULDING R/F BUMPER MOULDING R/F FOG LAMP CPL	Part Number Renew 52119 06940 KNPL3 52611 06150 53111 06280 52713 06010 52712 06010 81210 02121	Supplier	Bet. 0% 0% 0% 0% 0% 0% 0%	\$1.46 \$54.91 \$9.00 \$226.30 \$0.00 \$226.30 id: 01/06/2015 Price (\$) 20.00* 170.00* 0.00F 35.00* 115.00* 30.00* 80.00*
Guide No 1000 283 257 344 410 539 640 538 318	1 1 1 1 1 1 1 1 1 1	Repair Painting Material-Const Main Wor Total Excluding Pearlesc Pearlescent Uplift @ 0.00 Total Paint Material Cost Description BONNET EMBLEM FRONT BUMPER FRONT NUMBER PLATE FRT BUMPER ABSORBER GRILLE L/F BUMPER MOULDING R/F BUMPER MOULDING R/F FOG LAMP CPL R/F UPP BUMPER BRKT	Part Number Renew 52119 06940 KNPL3 52611 06150 53111 06280 52713 06010 52712 06010 81210 02121 52535 06090	Supplier	Bet. 0% 0% 0% 0% 0% 0% 0%	\$1.46 \$54.91 \$9.00 \$226.30 \$0.00 \$226.30 id: 01/06/2015 Price (\$) 20.00* 170.00* 0.00F 35.00* 115.00* 30.00* 30.00* 80.00*
Guide No .000 .883 .57 .844 .610 .639 .40 .638 .18	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Repair Painting Material-Const Main Wor Total Excluding Pearlesc Pearlescent Uplift @ 0.00 Total Paint Material Cost Description BONNET EMBLEM FRONT BUMPER FRONT NUMBER PLATE FRT BUMPER ABSORBER GRILLE L/F BUMPER MOULDING R/F BUMPER MOULDING R/F FOG LAMP CPL R/F UPP BUMPER BRKT R/F WING	Part Number Renew 52119 06940 KNPL3 52611 06150 53111 06280 52713 06010 52712 06010 81210 02121 52535 06090 53801 06130	Supplier	Bet. 0% 0% 0% 0% 0% 0% 0% 0%	\$1.46 \$54.91 \$9.00 \$226.30 \$0.00 \$226.30 id: 01/06/2015 Price (\$) 20.00* 170.00* 0.00F 35.00* 115.00* 30.00* 30.00* 80.00* 26.00* 160.00*
Guide No .000 .883 .57 .644 .610 .639 .640 .638 .648 .648 .649 .64	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Repair Painting Material-Const Main Wor Total Excluding Pearlesc Pearlescent Uplift @ 0.00 Total Paint Material Cost Description BONNET EMBLEM FRONT BUMPER FRONT NUMBER PLATE FRT BUMPER ABSORBER GRILLE L/F BUMPER MOULDING R/F BUMPER MOULDING R/F FOG LAMP CPL R/F UPP BUMPER BRKT R/F WING R/FOG LAMP COVER	Part Number Renew 52119 06940 KNPL3 52611 06150 53111 06280 52713 06010 52712 06010 81210 02121 52535 06090 53801 06130 52030 06080	Supplier	Bet. 0% 0% 0% 0% 0% 0% 0% 0%	\$1.46 \$54.91 \$9.00 \$226.30 \$0.00 \$226.30 id: 01/06/2015 Price (\$) 20.00* 170.00* 0.00F 35.00* 115.00* 30.00* 80.00* 26.00* 160.00*
Guide No .000 .883 .57 .644 .610 .639 .640 .638 .642 .98 .170	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Repair Painting Material-Const Main Wor Total Excluding Pearlesc Pearlescent Uplift @ 0.00 Total Paint Material Cost Description BONNET EMBLEM FRONT BUMPER FRONT NUMBER PLATE FRT BUMPER ABSORBER GRILLE L/F BUMPER MOULDING R/F BUMPER MOULDING R/F FOG LAMP CPL R/F UPP BUMPER BRKT R/F WING R/FOG LAMP COVER R/FADIATOR AIR GUIDE	Part Number Renew 52119 06940 KNPL3 52611 06150 53111 06280 52713 06010 52712 06010 81210 02121 52535 06090 53801 06130 52030 06080 53293 06100	Supplier	Bet. 0% 0% 0% 0% 0% 0% 0% 0% 0%	\$1.46 \$54.91 \$9.00 \$226.30 \$0.00 \$226.30 id: 01/06/2015 Price (\$) 20.00* 170.00* 0.00F 35.00* 115.00* 30.00* 80.00* 26.00* 160.00* 20.00*
Guide No .000 .883 .57 .644 .610 .639 .640 .638 .642 .98 .170 .642	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Repair Painting Material-Const Main Wor Total Excluding Pearlesc Pearlescent Uplift @ 0.00 Total Paint Material Cost Description BONNET EMBLEM FRONT BUMPER FRONT NUMBER PLATE FRT BUMPER ABSORBER GRILLE L/F BUMPER MOULDING R/F BUMPER MOULDING R/F FOG LAMP CPL R/F UPP BUMPER BRKT R/F WING R/FOG LAMP COVER R/RADIATOR AIR GUIDE R/WHEELHOUSE SHELL	Part Number Renew 52119 06940 KNPL3 52611 06150 53111 06280 52713 06010 52712 06010 81210 02121 52535 06090 53801 06130 52030 06080 53293 06100 53875 06081	Supplier	Bet. 0% 0% 0% 0% 0% 0% 0% 0% 0%	\$1.46 \$54.91 \$9.00 \$226.30 \$0.00 \$226.30 id: 01/06/2015 Price (\$) 20.00* 170.00* 0.00F 35.00* 115.00* 30.00* 80.00* 26.00* 160.00* 20.00*
Guide No .000 .883 .57 .644 .10 .639 .640 .638 .18 .442 .98 .170 .442 .662	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Repair Painting Material-Const Main Wor Total Excluding Pearlesc Pearlescent Uplift @ 0.00 Total Paint Material Cost Description BONNET EMBLEM FRONT BUMPER FRONT NUMBER PLATE FRT BUMPER ABSORBER GRILLE L/F BUMPER MOULDING R/F BUMPER MOULDING R/F FOG LAMP CPL R/F UPP BUMPER BRKT R/F WING R/FOG LAMP COVER R/RADIATOR AIR GUIDE R/WHEELHOUSE SHELL RIGHT HEADLAMP ASSY	Part Number Renew 52119 06940 KNPL3 52611 06150 53111 06280 52713 06010 52712 06010 81210 02121 52535 06090 53801 06130 52030 06080 53293 06100 53875 06081 81110 06251	Supplier	Bet. 0% 0% 0% 0% 0% 0% 0% 0% 0%	\$1.46 \$54.91 \$9.00 \$226.30 \$0.00 \$226.30 id: 01/06/2015 Price (\$) 20.00* 170.00* 0.00F 35.00* 115.00* 30.00* 30.00* 40.00* 20.00* 40.00* 55.00* 350.00*
Guide No 1,000 2,83 2,57 3,44 410 639 640 638 318 742 1,98 1,170 3,42 662 1,436	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Repair Painting Material-Const Main Wor Total Excluding Pearlesc Pearlescent Uplift @ 0.00 Total Paint Material Cost Description BONNET EMBLEM FRONT BUMPER FRONT NUMBER PLATE FRT BUMPER ABSORBER GRILLE L/F BUMPER MOULDING R/F BUMPER MOULDING R/F FOG LAMP CPL R/F UPP BUMPER BRKT R/F WING R/FOG LAMP COVER R/RADIATOR AIR GUIDE R/WHEELHOUSE SHELL RIGHT HEADLAMP ASSY WASHER CONTAINER	Part Number Renew 52119 06940 KNPL3 52611 06150 53111 06280 52713 06010 52712 06010 81210 02121 52535 06090 53801 06130 52030 06080 53293 06100 53875 06081 81110 06251 85315 06160	Supplier	Bet. 0% 0% 0% 0% 0% 0% 0% 0% 0% 0%	\$1.46 \$54.91 \$9.00 \$226.30 \$0.00 \$226.30 id: 01/06/2015 Price (\$) 20.00* 170.00* 0.00F 35.00* 115.00* 30.00* 30.00* 26.00* 160.00* 20.00* 40.00* 55.00* 35.00*
PARTS Guide No 1000 283 257 344 410 539 540 538 318 742 298 1170 342 562 1436 1437 : OEM Pai	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Repair Painting Material-Const Main Wor Total Excluding Pearlesc Pearlescent Uplift @ 0.00 Total Paint Material Cost Description BONNET EMBLEM FRONT BUMPER FRONT NUMBER PLATE FRT BUMPER ABSORBER GRILLE L/F BUMPER MOULDING R/F BUMPER MOULDING R/F FOG LAMP CPL R/F UPP BUMPER BRKT R/F WING R/FOG LAMP COVER R/RADIATOR AIR GUIDE R/WHEELHOUSE SHELL RIGHT HEADLAMP ASSY	Part Number Renew 52119 06940 KNPL3 52611 06150 53111 06280 52713 06010 52712 06010 81210 02121 52535 06090 53801 06130 52030 06080 53293 06100 53875 06081 81110 06251	Supplier	Bet. 0% 0% 0% 0% 0% 0% 0% 0% 0%	\$1.46 \$54.91 \$9.00 \$226.30 \$0.00 \$226.30 id: 01/06/2015 Price (\$) 20.00* 170.00* 0.00F 35.00* 115.00* 30.00* 30.00* 40.00* 20.00* 40.00* 55.00* 350.00*

Sub Total

Claim Reference:

o: Original

Full Report - V1

-\$1,000.00

\$1,508.70

\$1,614.31

\$105.61

et 261 00

Assessment Number: LHM61111

Registration: SJP 2412D

Version: LAI HUAT/3

Printed: 29/08/2018 13:52

Date Calculated: 29/08/2018 06:51

g: Original			Sub Total		\$1,261.00
h: Secondhand			Sundry Parts	(Fixed)	\$0.00
p: Parallel			Total Parts		\$1,261.00
x: Exchange	122742-2574				
			ONTAINS UNPRICED PA		
	NB - COLOUR (CODED ITEMS/	TRIM - PART NUMBERS	MAY DIFFER	
Extras					
	Description		Betterment		Price
	SUNDRY PARTS	SPECIALIST	0%		\$100.00
	FRONT NUMBER	SPECIALIST			Me \$35.00
	PLATE				
	WHEEL ALIGNMENT	SPECIALIST	0%		\$80.00
			Total Extras		\$215.00
Final Calcul	ation				
Total Parts					\$1,261.00
Labour					
	l Panel/Mechanical			\$357.00	
Tota	l Paintwork			\$449.40	
Total Labour				OK TOURN SOURCE	\$806.40
Additional Cos	sts				
Corr	Prot Materials Externa	al		\$0.00	
Corr	Prot Materials Interna	al .		\$0.00	
	of Specialist			\$215.00	
Total of Addit	ional Costs			3	\$215.00
Total Paint/M	aterial Costs				\$226.30
Repair Costs I	Excludes GST				\$2,508.70
Deductions					134-380-5
Dedi	uction for Excess (Fixe	ed)		-\$1,000.00	
Total Doductio					The same are a second

Assessment Notes

GST @ 7 %

Grand Total Excludes GST (After Deduction)

Grand Total Includes GST (After Deduction)

Total Deductions

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity 160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722 Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg UEN: 199407592C

INSURER:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:

OD (OWN DAMAGE)

Ref. No:

69584

Policy No:

DMPCSN3033811702

Date of Loss:

15/06/2018

Vehicle Reg. No.:

SJP2412D

Driveable?

UNKNOWN

Driver Age/Info:

67 / MALE

Party At Fault: Third Party Involved? YES

TP Injury Involved?

YES TAN TECK SAI

Contact No:

+6596217783

Insured/Claimant: Driver:

TAN TECK SAI

Make/Model:

TOYOTA CAMRY, 2.4 ABS AIRBAG

Vehicle Reg. Date:

16/03/2009

Vehicle Colour:

(A)

Engine No:

BLACK 2AZE130880

Chassis No:

MR053BK4007033254

Odometer:

0 KM

Paint Type:

Total Loss?

NO

Est. Duration of Repair

(day)

Description of

Accident/Loss

Present Location:

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT: T/20180613/2002

LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) / DERRICK TAY

Amount
1,181.00
215.00
1,150.30
0.00
0.00
2,546.30
500.00
2,046.30
143.24
2,189.54

This claim is handled by: DERRICK TAY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 18 Jun 2018) Part Source: MRM-SG

TOYOTA CAMRY 2.4 ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)*

Parts:

(Price-denominated Standard List) Labour: Repairer's Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SJP2412D/18/06/2018 16:59

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with Validity:

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr		Amount
1	1	NA	*BONNET EMBLEM		0.00	0.00	No	*20.00 F
2	1	NA	*FRONT BUMPER		0.00	0.00	64	*170.00 F
3	1	NA	*FRT BUMPER ABSORBER		0.00	0.00	1815	*35,00 F
4	1	NA	*GRILLE		0.00	0.00	CRIT	*115.00 F
5	1	NA	*L/F BUMPER MOULDING		0.00	0.00	120	*30.00 F
6	1	NA	*R/F BUMPER MOULDING		0.00	0.00	146	*30.00 F
7	1	NA	*R/F FOG LAMP CPL		0.00	0.00	Sin	*80.00 F
8	1	NA	*R/F PANEL REINF		0.00	0.00	CO.	*30.00 F
9	1	NA	*R/F UPP BUMPER BRKT		0.00	0.00	p+13	*26,00 F
10	1	NA	*R/F WING		0.00	0.00	84	*160.00 F
11	1	NA	*R/FOG LAMP COVER		0.00	0.00	AUS	*20.00 F
12	1	NA	*R/WHEELHOUSE SHELL		0.00	0.00	CRA	*55.00 F
13	1	NA	*RIGHT HEADLAMP ASSY		0.00	0.00	BEO	*350.00 F
14	1	NA	*WASHER CONTAINER		0.00	0.00	20	*60.00 F
F≃Fra	inchise	part.		-				4 404 00
				Total Parts (S\$)				1,181.00

Lai Huat (Meng Kee) Motor Pte Ltd/SJP2412D/18/06/2018 16:59. Not valid without Reference section. Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Qty Particulars		Amount
ellaneous Items		
1 FRONT NUMBER PLATE		35.00
1 SUNDRY PARTS		100.00
1 WHEEL ALIGNMENT		6 80.00
	Sub Total (S\$)	215.00
	1 FRONT NUMBER PLATE 1 SUNDRY PARTS	1 FRONT NUMBER PLATE 1 SUNDRY PARTS 1 WHEEL ALIGNMENT

Estimates on Labour

No	Particulars	Lab.Type		Amount
Lab	our Items			
1	Total Paint Labour	New		449.40
2	Total Paint Materials	New	-	226.30
3	Total Panel/Mechanical Labour	New 35	1	474.60
		Gross Labour Cost (S\$)		1,150.30

Lai Huat (Meng Kee) Motor Pte Ltd/SJP2412D/18/06/2018 16:59. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

來發(明記)摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sin Ming Autocity 160 Sin Ming Drive #04-01/#04-02/#07-03 Singapore 575722 Tel: 64538110 Fax: 64596267 Email: info@laihuat.com.sg UEN: 199407592C

(SUPPLEMENTARY)

INSURER:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:

OD (OWN DAMAGE)

Ref. No:

69584

Policy No:

DMPCSN3033811702

Date of Loss:

15/06/2018

Vehicle Reg. No.:

SJP2412D

Driveable?

UNKNOWN

Driver Age/Info:

67 / MALE

Party At Fault:

TP Injury Involved?

YES

Third Party Involved? YES

Insured/Claimant:

TAN TECK SAI TAN TECK SAI

2AZE130880

Contact No:

+6596217783

Make/Model:

Driver:

TOYOTA CAMRY, 2.4 ABS AIRBAG

Vehicle Reg. Date:

16/03/2009

Vehicle Colour:

(A) BLACK

Chassis No:

MR053BK4007033254

Engine No: Odometer:

0 KM

Paint Type:

Total Loss?

NO

Est. Duration of Repair

(day)

7

Description of Accident/Loss PLEASE REFER TO SKETCH PLAN AND POLICE REPORT: T/20180613/2002

Present Location:

LAI HUAT (MENG KEE) MOTOR PTE LTD (SIN MING) / DERRICK TAY

COST OF CLAIMS		Amount
Parts		110.00
Miscellaneous Items		0.00
Labour		0.00
Paintwork Labour		0.00
Towing		0.00
	Gross Total (S\$)	110.00
	+ GST 7.00% (S\$)	7.70
	Nett Amount (S\$)	117.70
	+ Previous Estimates (S\$)	2,189.54
	Claim Total (S\$)	2,307.24

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 29 Aug 2018)

Parts: Labour:

TOYOTA CAMRY 2.4 ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)

(Price-denominated Standard List) Repairer's

Print Code: Lai Huat (Meng Kee) Motor Pte Ltd/SJP2412D/29/08/2018 13:52

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty Part No.	Particulars		%Disc	%Depr	Amour	nt
1	1	*WASHER PUMP		0.00	0.00	SEE *70.0	00 F
2	1	*R/RADIATOR AIR GUIDE		0.00	0.00	€/° *40.0	00 F
F=Fn	anchise part.		Total Parts (S\$)			110.0	00

Lai Huat (Meng Kee) Motor Pte Ltd/SJP2412D/29/08/2018 13:52. Not valid without Reference section. Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Lai Huat (Meng Kee) Motor Pte Ltd/SJP2412D/29/08/2018 13:52. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

408933

Claim Reference: SNM18D03027C01 Assessment Number: LHM61111

Version: LKKAUTOC/4

Date Calculated: 31/08/2018 10:47

Full Report - V1 Registration: SJP 2412D

Printed: 06/09/2018 17:02

SGD

TBA

15/06/2018

Summary Information

Claim

Location:

Printed by: Authorisation Status:

Work Provider:

Claim Reference:

Policy Number: Other Reference:

Third Party: Insured Amount: Under Warranty: Warranty Expired: Singapore (SG) LKK AUTO

SNM18D03027C01

Interim

China Taiping Insurance (S) Pt

DMPCSN3033811702

OD CLAIM

TOYOTA

BASE MODEL

Camry

YCA 01

SJP 2412D

Not Known

Currency:

Date of Incident:

Able to Authorise Repairs: TBA

Repairs Authorised:

Estimated Repair Time: Ouote Due Date: Actual Repair Days: Parts Ordered Date: Hire Car Start:

Hire Car End: Vehicle Collected:

Vehicle Details

Vehicle Manufacturer:

Model:

Sub Model:

Model Sheet Number: Registration:

Registration Month:

Registration Year:

VIN Number:

Odometer:

Colour:

Engine Number:

Fuel Level:

%

FROM 03/2009 XENON HEADLAMPS HEADLAMP WASHERS TYRES 215/55 YR 17

VERSION THAILAND PREPARE OFF VEHICLE

Model Specs

AUTO AIR CON FOG LAMPS 2.4 LTR 123KW

WHEELS 7J X 17 ALLOY TWO COAT METALLIC

Vehicle Condition

Vehicle Status

Pre-Accident Condition:

Steering:

Brakes Pedal Travel: Place of Inspection: Pre-Accident Damage:

Tyres Condition:

Tread Depth LHF: Tread Depth LHR: Damage Areas:

Severity of Impact: Vehicle Status on

Inspection:

Date of Inspection:

18/06/2018

Tread Depth RHF: Tread Depth RHR:

Direction of Impact:

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: SNM18D03027C01 Assessment Number: LHM61111

Version: LKKAUTOC/4


Date Calculated: 31/08/2018 10:47


Full Report - V1 Registration: SJP 2412D

Printed: 06/09/2018 17:02

\$101.76

\$1,555.46





Addresses

Cost Sun	nmary		
	Total Labour		\$806.40
	Total Paint/Material		\$226.30
	Total Parts		\$1,361.00
	Total of Additional Costs		\$60.00
	Repair Cost Exc GST:		\$2,453.70
	Overall Discount (0.0%):		- \$0.00
	Excess:		-\$1,000.00
	After Deduction -	Grand Total Exc GST:	\$1,453.70
	the state of the s		

7 % GST:

Grand Total Inc GST:

Repair Information

LABOUR	Time Basis 10 W	U = 1 HR. Price/CL 1 Price/Dent	= \$42.00/HR = \$42.00/HR
Repair /			
Guide Numb	er Repair Details	wu	Cost Price (\$)
NO NUMBER	R + R R/RADIATOR GRILLE MOULDING	2.0	8.40
B110	RENEW R/FRT WING	5.0	21.00
	(FRT BUMPER AND R/HEADLAMP ASSY REMOVED)		
B100	R + R RIGHT SILL RAIL	3.0	12.60
B020	RENEW FRONT BUMPER	13.0	54.60
	INCLUDES: R + R FRONT BUMPER, RADIATOR		
	GRILLE AND NECESSARY ATTACHED PARTS		
B040	RENEW R/HEADLAMP	5.0	21.00
	(BUMPER REMOVED)		
	INCLUDES: ADJUST HEADLAMPS.		
B040	R + R RIGHT HEADLAMP UNIT	3.0	12.60
	(BUMPER REMOVED)		
	INCLUDES: ADJUST HEADLAMP		
851091)	R + R WASHER RESERVOIR	4.0	16.80
0471	REPAIR BONNET	15.0*	63.00
1009	REPAIR FRONT PANEL	20.0*	84.00
1118	REPAIR R/F WHEELHOUSE CPL	15.0*	63.00
LA	BOUR COST		
	Total Work Units	85.0	
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	8.5HRS	\$357.00
	Paint Labour	10.7HRS	\$449.40
	Total Labour	19.2HRS	\$806.40

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: SNM18D03027C01 Full Report - V1
Assessment Number: LHM61111 Registration: SJP 2412D
Version: LKKAUTOC/4 Printed: 06/09/2018 17:02

Date Calculated: 31/08/2018 10:47

PAINT W		900 LENSE	Time Bas	is 10 WU = 1		
Guide Nu	mber	Description	20022		wu	Cost Price (\$)
		- TWO COAT MET				
		- PREPARE OFF VI				
742		R/F WING NEW PART PAINT			0.0	
283		FRONT BUMPER NEW PART			13.0	
298		R/FOG LAMP COVER NEW P		-	3.0	
344		FRT BUMPER ABSORBER SL		1.	3.0	
410		GRILLE NEW PART PAINT K			3.0	
471		BONNET REPAIR PAINTING	<50%		26.0	
741		L/F WING SURFACE PAINT			6.0	
1009		FRONT PANEL SURFACE PA			7.0	
1118		R/F WHEELHOUSE CPL SUR	FACE PAINT		6.0	
	LAB	OUR COST - PAINT		1		
		TIME(PAINT)	2 10		77.0	
		Preparation Main Work P		3	5.0	
		Preparation Main Work N			25.0	
		Preparation Work Multi L		100	0.0	
		Total Work Units (10WU)	/HR)		07.0	
		Total Paintwork Labour			10.7HRS	\$449.40
	MAT	ERIAL COST - PAINT				Cost Price
		New Part Painting				\$20.64
		New Part Painting - Plas				\$70.36
		Material-Constant Main \	Work Metal			\$28.60
		Surface-/Blend Paint				\$41.33
		Surface Paint Plastic				\$1.46
		Repair Painting				\$54.91
		Material-Const Main Wor	k Plastic			\$9.00
		Total Excluding Pearlesc	ent Uplift			\$226.30
		Pearlescent Uplift @ 0.00				\$0.00
		Total Paint Material Cost				\$226.30
PARTS					Price Val	id: 01/06/2015
Guida Na	Otv	Description	Part Number	Supplier	Bet.	Price (\$)
283	1	FRONT BUMPER	52119 06940	Supplier	0%	170.00*
298	i	R/FOG LAMP COVER	52030 06080		0%	20.00*
318	1	R/F UPP BUMPER BRKT	52535 06090		0%	26.00*
344	1	FRT BUMPER ABSORBER	52611 06150		0%	35.00*
	1				0%	115.00*
410 562	1	RIGHT HEADLAMP ASSY	53111 06280 81110 06251		0%	350.00*
	1		81210 02121		0%	80.00*
638	1	R/F FOG LAMP CPL			0%	30.00*
639	1	L/F BUMPER MOULDING	52713 06010		0%	30.00*
640	1	R/F BUMPER MOULDING	52712 06010		0%	160.00*
742	1	R/F WING	53801 06130		0%	55.00*
842	1	R/WHEELHOUSE SHELL	53875 06081		0%	40.00*
1170	1	R/RADIATOR AIR GUIDE	53293 06100		0%	60.00*
1436	1	WASHER CONTAINER	85315 06160			70.00*
1437	1	WASHER PUMP	85330 21010		0%	20.00*
1000	1	BONNET EMBLEM	Renew Sub Total	ř.	0%	\$1,261.00
f: OEM Pa			Sub Tota		(Fixed)	\$100.00
g: Origina	i		Sundry P	di (S	(Fixed)	\$100.00

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference: SNM18D03027C01 Assessment Number: LHM61111 Full Report - V1
Registration: SJP 2412D

Version: LKKAUTOC/4

Assessment Notes

Printed: 06/09/2018 17:02

Date Calculated: 31/08/2018 10:47

h: Secondhand p: Parallel x: Exchange		,	Total Parts	\$1,361.00
A. Excitating	NB - COLOUR (CODED ITEMS/TR	M - PART NUMBERS MAY DIF	FER
Extras				
	Description		Betterment	Price
	FRONT NUMBER	SPECIALIST	0%	\$0.00
	PLATE			
	WHEEL ALIGNMENT	SPECIALIST		\$60.00
			Total Extras	\$60.00
Final Calcul	ation			
Total Parts				\$1,361.00
Labour				
Tota	I Panel/Mechanical		1000000	7.00
Tota	l Paintwork		\$449	50.50 (1977)
Total Labour				\$806.40
Additional Cos	sts			
Corr	Prot Materials Extern	al		0.00
Corr	Prot Materials Interna	al		0.00
Cost	of Specialist		\$60	0.00
Total of Addit	ional Costs			\$60.00
Total Paint/M	aterial Costs			\$226.30
Repair Costs I	Excludes GST		_	\$2,453.70
Deductions				
Ded	uction for Excess (Fix	ed)	-\$1,000	
Total Deduction	ons	1555.40		-\$1,000.00
Grand Total E	xcludes GST (After I	Deduction)		\$1,453.70
	@ 7 %			\$101.76
Grand Total I	ncludes GST (After I	Deduction)		\$1,555.46

Merimen e-Claims Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Natified	Est Submitted	Adi Assigned	Adj Rpt	t	Adj Submitted	Ins Authred	Status	
Main	18 Jun 2018 Sendback Est	18 Jun 2018 16:59 \$\$2,546.30	19 Jun 2018 14:36 Edit Adj Rpt	\$\$2,45 Edit I	stimates	\$\$2,453.70 View Rpt		Pendin Report Cancel	
Supp #1	29 Aug 2018 13:52	29 Aug 2018 13:52 5\$110.00	29 Aug 2018 13:52				(Combined)	Combined with M Uncombine Suppli	
	Main	Refer	ence	c	laim Detail	· 1	Documents		Show All
CLAIM S	JBFOLDER DETA	ils							
Insured:	TAN TECK SA	1, 1D: S0749874	H, Tel: +65962	17783, 1	mail: STT@	BLITW.COM			
Vehicle Re No.:	SJP2412D				Date of Los		15/06/2018 21:00 - :59 [110 Months and 30 Days From LTA Reg Date (Man Y		
Claim Type	OD / SNM18	OD / SNM18D03027C01				DMPCSN3033811702 (Comprehensive)			
					Excess:	S\$1,000.00			
Repairer:	Lai Huat (Me	ng Kee) Motor P	te Ltd (Sin Ming)	160 5in	Ming Drive	#04-01, Sin Ming	AutoCity, 57572	2 Sin Ming -	Tel: 64538110
Handling Insurer:			gapore) Pte. Ltd	200					
Adjuster:		sultants Pte Ltd	(HQ) - Tel: 6256	-3561	[Handled by	KENNETH KO	(G) [Final R	pt due 28/	06/2018]
Driver/Cus dian:	TAN TECK SAI	(67 / Male), NR	IC: S0749874H,	Tel: +65	96217783				
Adj Asg. Remarks:	SURVEY REVE	RT							
ASSOCIA	TED MAIL RECEI	VED					View	All Com	pose Case Mail
 CHINA 	TAIPING (21/06/20)18): Alert - Adj	Mandate Approv	ed (S\$24	162.30) - S	JP2412D - Clai	m Handler: Cho	ng Boon	
ALL ASS	OCIATED TASKS	3				View All Se	arch Tasks Cr	eate New Task	Complete
Due Da		ype Task Gr	oup Subject	Handl	er Ass	gned By	Completed On	Created	On Done?

Claim Documents

Ass	essment Reports		1 per i	page V	50
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	- Indiana	Thumbnall	-
1	18/06/18 15:17	Accident Statement	0	Load HTM	
2	18/06/18 16:59	Repairer Estimates	0	Load HTM	
3	29/08/18 13:52	Repairer Estimates Suppl. #1	0	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/06/18 14:55	Adjuster Immediate Advice	0	Load HTM	_
Pho	otos/Images		3 per s	rage 🔽	V
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnall	Print
I	18/06/18 15:17	Accident Photo [Linked Accident Report Documents]	0	Load JPG	☑
2	18/06/18 15:17	Accident Photo [Linked Accident Report Documents]	0	Load JPG	120
3	18/06/18 15:17	Accident Photo [Linked Accident Report Documents]	0	Load JPG	V
4	18/06/18 15:17	CHASSIS NUBER [Linked Accident Report Documents]	0	Load JPG	☑
5	18/06/18 16:55	Front View	0	Load JPG	3
6	18/06/18 16:55	Front View Left	0	Load JPG	V
7	18/06/18 16:55	Front View Right	0	Load JPG	V
8	18/06/18 16:55	Front View Right	0	Load JPG	V
9	18/06/18 16:55	Chassis Number	0	Load JPG	8
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/10/18 12:05	General View	0	Load 3PG	8
2	09/10/18 12:05	General View	0	Load 3PG	V
3	09/10/18 12:05	General View	0	Load 3PG	[2]
4	09/10/18 12:05	General View	0	Load JPG	V
5	09/10/18 12:05	General View	0	Load JPG	V
6	09/10/18 12:05	General View	0	Load JPG	V
7	09/10/18 12:05	General View	0	Load JPG	4
8	09/10/18 12:05	General View	0	Load JPG	1
9	09/10/18 12:05	General View	0	Load JPG	V
10	09/10/18 12:05	General View	0	Load JPG	V
11	09/10/18 12:05	General View	0	Load 3PG	V
12	09/10/18 12:05	Odometer Reading	0	Load 3PG	8
13	09/10/18 12:06	Reinspection Photo	0	Load JPG	V
14	09/10/18 12:06	Reinspection Photo	0	Load JPG	V
15	09/10/18 12:06	Reinspection Photo	0	Load JPG	V
16:	09/10/18 12:06	Reinspection Photo	0	Load JPG	V
17	09/10/18 12:06	Reinspection Photo	0	Load JPG	V
18	09/10/18 12:06	Reinspection Photo	0	Load 3PG	[2]
19	09/10/18 12:06	Reinspection Photo	0	Load 3PG	V

Merimen e-Claims Page 2 of 2

Ass	essment Reports		1 per	page 🔍	W
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	18/06/18 15:15	Sketch Plan [Linked Acodent Report Documents]	0	Load TJF	
2	18/06/18 15:15	POLICE REPORT [Linked Accident Report Documents]	0	Load TJF	
3	18/06/18 15:15	CERTIFICATE OF INSURANCE [Linked Accodent Report Documents]	0	Load TIF	
4	18/06/18 15:15	DRIVER'S NRIC & DRIVING LICENCE [Linked Acodemt Report Documents]	0	Load TIF	
5	18/06/18 16:59	E-filed GIA report	0	Load PDF	
6	18/06/18 16:59	Driver's NRIC + Driving License	0	Load PDF	
7	18/06/18 16:59	Certificate of Insurance	0	Load PDF	
8	18/06/18 16:59	Enquire PARF / COE Rebate for Registered Vehicle	0	Load PDF	
Νo	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	21/06/18 10:01	Revised Estimate	0	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/06/18 14:55	ESTIMATE	0	Load PDF	
2	20/06/18 14:55	AUDATEX	0	Load PDF	
3	11/10/18 11:33	Parts Invoice	0	Load PDF	
4	11/10/18 11:41	Supplementary	0	Load PDF	

Linked Accident Report Documents



Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			~
Show Remarks To: Repairer Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607 198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

OD

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

Singapore 079909

Our File No:

CS/CTI18011088/KQBE2

Date:

11/10/2018

REFERENCE

Insured/Claimant: Date of Loss:

TAN TECK SAI

Policy No:

DMPCSN3033811702

15/06/2018 Nature of Claim:

Claim No: SNM18D03027C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJP2412D

Make & Model:

TOYOTA CAMRY, 2.4 ABS AIRBAG (A)

Engine No:

2AZE130880

Reg. Date:

16/03/2009 (Man. Year: 2009)

Chassis No:

MR053BK4007033254

Colour:

Metallic Black

Odometer:

151065 km

Engine Capacity:

2362 cc

Market Value/New Car Price: S\$20,000.00 Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

215/55 R17

Rear Tyre Size:

No

215/55 R17

Front Tyre Size: Front Left Side:

Yokohama 3 mm

Rear Left Side:

Yokohama 3 mm

Front Right Side:

Yokohama 3 mm

Rear Right Side:

Yokohama 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,291.00	1,261.00	30.00	2.32
Miscellaneous Items	215.00	160.00	55.00	25.58
Labour	1,150.30	1,032.70	117.60	10.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,656.30	2,453.70	202.60	7.63
- Excess (S\$)	500.00	1,000.00	-500.00	-100.00
(S\$)	2,156.30	1,453.70	702.60	32.58
+ GST 7.00/7.00% (S\$)	150.94	101.76	49.18	32.58
Nett Amount (S\$)	2,307.24	1,555.46	751.78	32.58

INSPECTION

Date of Assignment:

19/06/2018 Present Location:

Lai Huat (Meng Kee) Motor Pte Ltd (Sin

Date Inspected:

20/06/2018 Inspected At:

Lai Huat (Meng Kee) Motor Pte Ltd (Sin

Ming)

160 Sin Ming Drive #04-01, Sin Ming

AutoCity

Singapore 575722

Estimated Period of Repair:

5.0 days

Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Oct 2018)

Parts: 143 TOYOTA CAMRY 2.4 ABS AIRBAG (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJP2412D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
t	1	NA	*BONNET EMBLEM	Necessary	20.00 F	*20.00 F
2	1	NA	*FRONT BUMPER	Bent	170.00 F	*170.00 F
3	1	NA	*FRT BUMPER ABSORBER	Missing	35.00 F	*35.00 F
4	1	NA	*GRILLE	Cracked	115.00 F	*115.00 F
5	1	NA	*L/F BUMPER MOULDING	Necessary	30.00 F	*30.00 F
6	1	NA	*R/F BUMPER MOULDING	Necessary	30.00 F	*30.00 F
7	1	NA	*R/F FOG LAMP CPL	Broken	80.00 F	*80.00 F
8	1	NA	*R/F PANEL REINF	Not Necessary	30.00 F	*-F
9	1	NA	*R/F UPP BUMPER BRKT	Distorted	26.00 F	*26.00 F
10	1	NA	*R/F WING	Bent	160.00 F	*160.00 F
11	1	NA	*R/FOG LAMP COVER	Missing	20.00 F	*20.00 F
12	1	NA	*R/WHEELHOUSE SHELL	Cracked	55.00 F	*55.00 F
13	1	NA	*RIGHT HEADLAMP ASSY	Broken	350.00 F	*350.00 F
14	1	NA	*WASHER CONTAINER	Dented	60.00 F	*60.00 F
Sup	pleme	entary #1				
15	1		*WASHER PUMP	Cracked	70.00 F	*70.00 F
16	1		*R/RADIATOR AIR GUIDE	Cracked	40.00 F	*40.00 F
F≍Fn	anchise	part.		Total Books (DE)	4 204 00	4 204 20
				Total Parts (S\$)	1,291.00	1,261.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Mis	cellan	eous Items			
1	1	FRONT NUMBER PLATE (NOT NECESSARY) (NOT NECESSARY) (NOT NECESSARY)		0.00	
2	1	SUNDRY PARTS (NECESSARY)		100.00	100.00
3	1	WHEEL ALIGNMENT	_	80.00	60.00
			Sub Total (S\$)	215.00	160.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	Total Paint Labour	New	449.40	449.40
2	Total Paint Materials	New	226.30	226.30
3	Total Panel/Mechanical Labour	New	474.60	357.00
		Gross Labour Cost (S\$)	1,150.30	1,032.70

Report was unsubmitted during this print-out.

< END OF ESTIMATES >