

22/03/2002

ASS. REC. BY:

REF:

CS3/LCR18011099/AZ4037

Special Instruction:



Survivor
Norman

Adnan

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

LCR

Date/Time:

19/6/18 @ 10:58am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 8591 G

Insured:

SH 83782

at Workshop m/s

Twincar Automotive

Tel:

68420051

of

2 Kaki Bukit Ave 2 # 01-17

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/06/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

11:20am @ 19/6/18

Person Contacted:

Melody

Vehicle: ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	SLP 8591 G - NA / AIG 18011023/24 DOA: 16/06/2018
	SH 83782 - NA / AIG 18011023/24 DOA: 16/06/2018
20/6/18	Dis-mantled
25/6/18	After Repair

REF:

ASS. REC. BY: Adrian King

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SLP8591G Yr Regn: 2017, Jue

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Kia Grato KC3 c.c 1591

Colour: _____

Blue A/C: Insured / Std / NI / NA

Sp. Reading: _____

19687. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

KNAPZ411M H572522

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: 215/45R17

R: 215/45R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen.

Front

Rear

R/Bal. _____

mm

R/Bal. _____

mm

L/Bal. _____

mm

L/Bal. _____

mm

D.O.A. _____

D.O.I. _____

19/06/18.

Survey held at _____

Twincar.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s, u/c.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TPAIG PRS.

28/6/18

Submit DAR Report.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / U.B.t: (%)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

180

20

200




**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE
SLH8378Z AND SLP8591G ON 16/06/2018**

From: Chin, Lee-Ying

To: assignments@lkkauto.com, Admin A

Cc: Fong, Andy-SY

Sent: 19/6/2018 10:58:46 AM

Attachments:  [19062018104006.pdf](#)  [18062018181301-0001.pdf](#)  [19062018094558.pdf](#)

Hi LKK,

Kindly assist to survey, vehicle in.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub

2 Kaki Bukit Ave 2, #01-17

Singapore 417921

Tel No. : +65 6744 0510 / 6842 0051 Fax No. : +65 6741 0510

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

Our Ref: SLP 8591 G

Your ref: SLH 8378 Z

19 June 2018

AIG ASIA PACIFIC INSURANCE PTE. LTD.

NO: 78 SHENTON WAY

#07-16 CHARTIS BUILDING

SINGAPORE 079120

Attn: Motor Claims Department

BY EMAIL yokeshi.chan@aig.com ONLY

Dear Sir/Madam,

NAME OF CLAIMANT : NG XIAN SUI, BLISS

VEHICLE NUMBER : SLP 8591 G

YOUR INSURED VEHICLE NUMBER : SLH 8378 Z

**ACCIDENT ON 16 June 2018 ALONG MERCHANT RD TWD NORTH CANAL RD
AT ABOUT 22:10 HOURS**

We refer to your email/fax dated **19 June 2018** wherein there is no agreement to the appointment to the appointment of Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

TWINCAR AUTOMOTIVE PTE LTD

Kaki Bukit Autohub

2 Kaki Bukit Avenue 2

#01-17

Singapore 417921

6842 0051 / 6744 0510 (Melody)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



Twincar Automotive Pte Ltd

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!

Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection:

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub

2 Kaki Bukit Ave 2, #01-17

Singapore 417921

Tel No. : +65 6744 0510 / 6842 0051 Fax No. : +65 6741 0510

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

Our Ref: **SLP 8591 G**

Your ref: **SLH 8378 Z**

18 June 2018

AIG ASIA PACIFIC INSURANCE PTE. LTD.

NO: 78 SHENTON WAY

#07-16 CHARTIS BUILDING

SINGAPORE 079120

Attn: Motor Claims Department

BY FAX 6835-7416 & EMAIL :

AIGSGP_ClaimsSurvey@aig.com

Dear Sir/Madam,

DATE OF ACCIDENT: 16 June 2018

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

PURSUANT TO PARAGRAPH 2.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES

We are instructed by **NG XIAN SUI, BLISS** to notify you of a road traffic accident on **16 June 2018** at about **22:10 HOURS** At **MERCHANT RD TWD NORTH CANAL RD** involving our client's vehicle **SLP 8591 G & SLH 8378 Z** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please be inform that we don't excess to Merimen System and kindly reply to us by Email / Fax.

Yours faithfully,



.....
Twincar Automotive Pte Ltd

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
2 Kaki Bukit Ave 2, #01-17
Singapore 417921
Tel No. : +65 6744 0510 / 6842 0051 Fax No. : +65 6741 0510
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

Our Ref: SLP 8591 G
Your ref: SLH 8378 Z

19 June 2018

AIG ASIA PACIFIC INSURANCE PTE. LTD.
NO: 78 SHENTON WAY
#07-16 CHARTIS BUILDING
SINGAPORE 079120
Attn: Motor Claims Department

BY EMAIL yokeshi.chan@aig.com ONLY

Dear Sir/Madam,

NAME OF CLAIMANT : NG XIAN SUI, BLISS
VEHICLE NUMBER : SLP 8591 G
YOUR INSURED VEHICLE NUMBER : SLH 8378 Z
ACCIDENT ON 16 June 2018 ALONG MERCHANT RD TWD NORTH CANAL RD
AT ABOUT 22:10 HOURS

- 1) We refer to your fax / email of **19 June 2018** informing that you wish to conduct a pre-repair survey and to your List of Surveyors.
- 2) TAKE NOTICE that we object to all your surveyors stated in your said List, for appointment as the Single joint Expert.
- 3) Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following 10 surveyors for your consideration:-

(a) B J Loi
(b) Patrick Ng
(c) Sebastian Lim Yong Tian
(d) Dave Chang Fuh Keong
(e) Ng Cheng Meng
(f) Danny Ho Joo Long
(g) Lee Kok Weng
(h) Philip Foo
(i) Ong Ah Heng, Kent
(j) Zali Saidi

PAR AUTOMOTIVE CONSULTANCY
CARLINK CONSULTANCY
CONSTANT APPRAISER SERVICES
SINCERE APPRAISAL SERVICES
CM AUTOMOTIVE CONSULTANCY
HJL AUTO APPRAISER SERVICES
LEE AUTOMOBILE APPRAISER SERVICES
PRECISION APPRAISAL SERVICES
KTO AUTOMOBILE ASSESSORS
ISP MANAGEMENT PTE LTD

- 4) Please reply within 2 working days.

Yours faithfully,



Twincar Automotive Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/LCR18011099/Az4d3

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120

Date : 19-06-2018



Code : LCR

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLH 8378Z	Veh. Inspected	SLP 8591G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	CHIN LEE YING	Assign Date	19/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/06/2018	Inspection Date	19/06/2018
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/06/2018 18:40
Date Of Accident	16/06/2018 22:10
Exact Location Of Accident	MERCHANT RD TWDS NORTH CANAL RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP8591G
Insured/Policyholder	
Name Of Registered Owner	NG XIAN SUI BLISS
NRIC No	S9034855H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93209664
Alternative Phone No	OFFICE-93209664

Vehicle Particulars

Manufacturer	KIA
Model	CERATO K3 1.6A SUNROOF
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700015954
Cover Note Number	

Driver

Name of Driver	WANG JIANQIANG, JOSEPH
NRIC No	S9015676D
Date Of Birth	07/05/1990
Occupation	INDOOR
Date Of Driving Pass	25/05/2015
Driving Experience	3 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98329732
Fax Number	
Contact Number	OFFICE-98329732
EEmail Address	NOEMAIL

Address	BLK 502 TAMPINES CENTRAL 1 #04-275
Postcode	520502
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TOM STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH8378Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KOH KWEE BOO
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/Fin No.:

Accident Sketch Plan

SKETCH PLAN MERCHANT ROAD TOWARDS NORTH CANAL ROAD

VEHICLE A - SLH 8591 G

VEHICLE B - SLH 8378 Z



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING STRAIGHT ALONG MERCHANT ROAD TOWARDS NORTH CANAL ROAD. I WAS ON THE RIGHT LANE.
WHILE TRAVELLING FORWARD, SUDDENLY A VEHICLE TURNED RIGHT ON THE RIGHT SIDE. I TRIED TO SWERVE BUT COULDN'T REACT ON TIME AND END UP THE FRONT RIGHT PORTION OF MY VEHICLE WAS DAMAGED.
ALIGHTED FROM MY VEHICLE AND REALIZED I WAS A VEHICLE BEARER (SLH 8378 Z) DIDN'T STOPPED AT THE GIVEWAY LINE AND JUST DROVE OUT FROM THE LINE THAT CAUSE THIS COLLISION TO THE FRONT RIGHT PORTION OF MY VEHICLE.
VEHICLE A - SLH 8591 G
VEHICLE B - SLH 8378 Z

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

MOTOR CAR (Fr)

182

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	BR	✓	
1005	992341	Frt Bumper Clips	NE	✓	
1006	991325	Frt Bumper Bracket	BR	✓	
1007	991462	Frt Bumper Side Retainer	RA	✓	
1008	991433	Frt Bumper Reinforcement	BR	✓	
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge	CUT	✓	
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor	CUT	✓	
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp	BR	✓	
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	CRA	✓	
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy	BR	✓	
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No: SLP 85916

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank	BR	✓	
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender	BUC	✓	
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield	CUT	✓	
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim	CUT	✓	
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre	CUT	✓	60%
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

No of Items:

Assessors

*

28/6/2008

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

ACTION (AL)
(1) Replace (✓) (2) Repair (X) (3) Check (?)
(4) Not Consistent (NC)

20/52

Vehicle No: SLP 8521G

NAC	INC	Item	CON	AC	Qty
1372	995163	Frt LH Shock Absorber			
1373	991944	Frt LH Shock Absorber Mounting			
1374	990632	Frt LH Coil Spring			
1375	995198	Frt LH Knuckle Arm			
1376	995199	Frt LH Knuckle Arm Bearing			
1377	995178	Frt LH Lower Arm			
1378	995169	Frt LH Upper Arm			
1379	995183	Frt LH Tie Rod			
1380	995143	Frt LH Drive Shaft			
1381	990661	Frt LH Control Arm			
1382	992062	Frt LH Trailing Arm			
1383	991848	Frt LH Leaf Spring			
1384	991293	Frt LH Brake Disc Rotor			
1385	991281	Frt LH Brake Caliper			
1386	991292	Frt LH Brake Pipe			
1387	991287	Frt LH Brake Hose			
1388	991295	Frt LH Brake Sensor Wire			
1389	991989	Frt Stay Bar Bracket			
1390	994455	Steering Rack & Pinion			
1391	994435	Steering Cross Member			
1392	994519	Frt Sub Frame			
1393	992003	Frt Sub Frame Mounting			
1394	991217	Frt Anti Roll Bar			
1395	991219	Frt Anti Roll Bar Linkage			
1396	990887	Engine Block			
1397	990890	Engine Block Gasket			
1398	990972	Engine Oil Sump			
1399	990960	Engine Oil			
1400	992224	Gear Box Assy			
1401	992229	Gear Box Gasket			
1402	992241	Gear Box Oil Sump			
1403	992257	Gear Oil			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1404	991134	Floor Panel			
1405	993719	Rear LH Shock Absorber			
1406	993723	Rear LH Shock Absorber Mounting			
1407	993170	Rear LH Coil Spring			
1408	993550	Rear LH Knuckle Arm			
1409	993551	Rear LH Knuckle Arm Bearing			
1410	993597	Rear LH Lower Arm			
1411	993884	Rear LH Upper Arm			
1412	995161	Rear LH Drive Shaft			
1413	995216	Rear LH Control Arm			
1414	993881	Rear LH Trailing Arm			
1415	993573	Rear LH Leaf Spring			
1416	992941	Rear LH Brake Disc Rotor			
1417	992937	Rear LH Brake Caliper Assy			
1418	990434	Rear LH Brake Pipe			
1419	992946	Rear LH Brake Hose			
1420	993819	Rear Sub Frame			
1421	993820	Rear Sub Frame Mounting			
1422	992813	Rear Anti Roll Bar			
1423	990168	Rear Anti Roll Bar Linkage			
1424	990202	Axle Beam			
1425	990170	Rear Axle Panhard Rod			
1426	990810	Differential Assy			
1427	992706	Propeller Shaft			

[illegible]

No of Items: _____ Assessor: _____

Original copy

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Jun 2018 Edit Reg		19 Jun 2018 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

LCRF PTE LTD, Co. Reg. No.: 201624597K

Main Claimant:

NG XIAN SUI BLISS, ID: S9034855H

Vehicle Reg. No.:

SLP8591G

Claim Type:

TP / 9956568431SG

Vehicle Reg. No. (Insured):

SLH8378Z

Repairer:

Twincar Automotive Pte Ltd (Kaki Bukit) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by **Boyogan, Joane**] Joane.Boyogan@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by **ADRIAN LING**] ... **[Final Rpt due 29/06/2018]**

Date of Loss:

16/06/2018 22:00 - :59

Policy/Cover Note No.:

0999994819

Policy No. (Claimant):

Excess:

[11 Months and 26 Days From LTA Reg Date (Man Yr)]

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AIG_SG (21/06/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS






































[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)



















































Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									











https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=dsp_... 29/6/2018

Claim Documents

***SLP8591G (9956568431SG)**
[SLH8378Z]
TP
NG XIAN SUI BLISS
Jun 16 2018 10:00PM
[LCRF PTE LTD]
Twincar Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/ Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
2	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
3	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
4	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
5	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
6	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
7	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
8	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
9	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
10	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
11	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
12	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
13	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
14	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
15	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
16	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
17	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
18	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
19	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
20	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
21	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
22	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
23	20/06/18 20:54	General View														Load JPG	<input checked="" type="checkbox"/>			
24	20/06/18 20:55	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
25	20/06/18 20:55	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
26	20/06/18 20:55	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
27	20/06/18 20:55	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
28	20/06/18 20:55	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
29	20/06/18 20:55	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
30	20/06/18 20:55	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
31	20/06/18 20:55	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
32	20/06/18 20:55	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
33	20/06/18 20:55	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
34	20/06/18 20:55	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
35	20/06/18 20:55	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
36	20/06/18 20:55	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			
37	20/06/18 20:55	Dismantled Parts														Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
56	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
57	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
58	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
59	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
60	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
61	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
62	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
63	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
64	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
65	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
66	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
67	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
68	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
69	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
70	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
71	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
72	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
73	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
74	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
75	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
76	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
77	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
78	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
79	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
80	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
81	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
82	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
83	20/06/18 20:55	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
84	28/06/18 20:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	28/06/18 20:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	28/06/18 20:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	28/06/18 20:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	28/06/18 20:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
89	28/06/18 20:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
90	28/06/18 20:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
91	28/06/18 20:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
92	28/06/18 20:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
93	28/06/18 20:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
94	28/06/18 20:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
95	28/06/18 20:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
96	28/06/18 20:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
97	28/06/18 20:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
98	28/06/18 20:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
99	28/06/18 20:55	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	21/06/18 13:46	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/LCR18011099/AZ4D3E2

Date: 29/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994819
Claimant Vehicle No : SLP8591G **Insured Vehicle No :** SLH8378Z
 Date of Loss: 16/06/2018 Nature of Claim: TP Claim No: 9956568431SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP8591G**
 Make & Model: KIA CERATO K3, 1.6 (A) Engine No: G4FGGH635748
 Reg. Date: 21/06/2017 (Man. Year: 2017) Chassis No: KNAFZ411MH5720522
 Colour: Blue Odometer: 19687 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
 Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
 Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/06/2018
 Date Inspected: 19/06/2018 Inspected At: Twincar Automotive Pte Ltd (Kaki Bukit)
 BLK 2 KAKI BUKIT, #01-17/18 KAKI
 BUKIT AUTOHUB
 Singapore 417921
 Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Broken	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER BRACKET	Broken	0.00 F	*- F
4	1		*FRT BUMPER SIDE RETAINER RH	Broken	0.00 F	*- F
5	1		*FRT BUMPER SPONGE	Cut	0.00 F	*- F
6	1		*FRT BUMPER SENSOR	Cut	0.00 F	*- F
7	1		*FRT LH BUMPER FOG LAMP	Broken	0.00 F	*- F
8	1		*FRT SUPPORT PANEL	Cracked	0.00 F	*- F
9	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
10	1		*WIPER WASHER TANK	Broken	0.00 F	*- F
11	1		*FRT RH FENDER	Buckled	0.00 F	*- F
12	1		*FRT RH FENDER INNER SHIELD	Cut	0.00 F	*- F
13	1		*FRT RH WHEEL RIM	Cut	0.00 F	*- F
14	1		*FRT RH TYRE (60%)	Cut	0.00 F	*- F
15	1		*FRT RH KNUCKLE ARM	Damaged	0.00 F	*- F
16	1		*FRT RH KNUCKLE ARM BEARING	Damaged	0.00 F	*- F
17	1		*FRT RH LOWER ARM	Damaged	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >