



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 5183T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BUMPER FACE REAR FORESTER IL (N) (CONSISTENT)	BUCKLED / DENTED	540.00	540.00
1	BRKT CORNER R RH (N) (CONSISTENT)	SERVICEABLE	18.00	-
1	BRKT CORNER R LH (N) (CONSISTENT)	SERVICEABLE	18.00	-
1	BRKT SD R RH (N) (CONSISTENT)	TO REPAIR SEE LABOUR	14.40	-
1	BRKT SD R LH (N) (CONSISTENT)	TO REPAIR SEE LABOUR	14.40	-
1	BEAM COMPL R ECU (N) (CONSISTENT)	SERVICEABLE	288.00	-
1	COVER HOOK R (N) (CONSISTENT)	SERVICEABLE	12.60	-
	LESS 20% DISCOUNT		-181.08	-108.00
			724.32	432.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REVERSE SENSOR - 2EYES (SN) (CONSISTENT)	SERVICEABLE	300.00	-
1	SUDRIES (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
			400.00	-
	<b><u>LABOUR</u></b>			
	REPAIR / REPLACE REAR BUMPER AND PANEL. INCLUSIVE OF THE REPAIR OF BRKT SD R RH AND BRKT SD R LH.		1,680.00	280.00
	RESPRAY REAR BUMPER AND PANEL.		1,260.00	420.00
			2,940.00	700.00
	<b>GRAND TOTAL</b>		<b>4,064.32</b>	<b>1,132.00</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>1,132.00</b>

Report Ref No. CC4/ASM18011106/Kea3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.