

ASSIGNMENT

From:

Date:

13/6/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SG 1031 S

at Workshop m/s

SMRT

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Mr. Goh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{1 up}

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No.

SG 1031 S

Yr Regn: Feb / 2016

Type: M.Car / M.Cycle / ☒ Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz

C.C. 6374

Colour

multi-colour

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

902926C1103878

C/No:

WEB62808323130285

Gen. Cond:

☒ Good / Fair / Poor / Burnt

Steering:

☒ Order / Jammed / Leaked / Burnt or

Brake:

☒ Order / Jammed / Leaked / Burnt or

Modi:

☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 275/70 R22.5

R: 275/70 R22.5

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

8/8/2017

D.O.I.

12/6/2018

Survey held at

SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time. File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Insp (\$

☐

: Weekend (\$

Survey Fee:

Transportation

1. S + RS. \$

2. Photos

3. Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$