



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2012 MERCEDES C180 BLUE EFFICIENCY (SKG9172K)

Date of Loss

16 June 2018

Time of Loss

20.20

Loss Description

SKG9172K (INSD) C/W FBG9417L (TP)

Comment

Workshop Details

Total Rebate Amount

46292

Nett Loss Amount

\$26,708.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

13/08/2018



Days of work completion *

55



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
SKG9172K

Registration State

SINGAPORE

Mileage

119970

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2012

ASSESSMENT INFO...

2012

Purchase Date

dd/mm/yyyy



Registration Date *

22/10/2012



Age of Vehicle

5

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

LIM KIM HENG KEN

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... MERCEDES

ASSESSMENT INFO... MERCEDES BENZ

CATEGORY Model

POLICY INFORMAT... C180 BLUE EFFICIENCY

ASSESSMENT INFO... C 180 BLUEEFFICIENCY

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... WDD2040312A774244

CATEGORY Date of Birth

FNOL INFORMATI... 16 June 1974

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 44

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... 27491030018562

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI... 17

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... 

CATEGORY Address

FNOL INFORMATI... 69 CHOA CHU KANG LOOP, #06-06,
689672, Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Business Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Married

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S7418810I

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

20/06/2018



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

225/45R17

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Good

Tyre Condition

Spare wheel

Rear Tyre Size

225/45R17

Front left side

CONTINENTAL6mm

Front right side

CONTINENTAL6mm

Rear left side

CONTINENTAL6mm

Rear right side

CONTINENTAL6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Part Supplied by AXA

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PART)
<input type="checkbox"/>		1	1			FRONT BONNET			Bent	1100				1100	Review
<input type="checkbox"/>		2	1			FRONT BONNET LOGO			Necessary	49				49	Review
<input type="checkbox"/>		3	10			FRONT BONNET INSULATOR CLIP			Necessary	3.8				38	Review
<input type="checkbox"/>		4	1			FRONT BONNET STOPPER (WITH SPRING) LH			Bent	12				12	Review
<input type="checkbox"/>		5	1			FRONT BONNET STOPPER (WITH SPRING) RH			Bent	12				12	Review
<input type="checkbox"/>		6	1			A PILLAR RH (NPA)			Repair	0	0	0	0	0	Deny
<input type="checkbox"/>		7	1			FRONT FENDER RH			Bent	550				550	Review
<input type="checkbox"/>		8	1			FRONT FENDER CHROME MOULDING RH			Necessary	23				23	Review
<input type="checkbox"/>		9	1			FRONT FENDER INNER SHIELD RH (FRONT)			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		10	1			FRONT FENDER INNER SHIELD RH (REAR)			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		11	10			FRONT FENDER INNER SHIELD CLIP			Serviceable	0	0	0	0	0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTRR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART:
<input type="checkbox"/>		12	1			HEADLAMP RH			Cracked	600				600	Review
<input type="checkbox"/>		13	1			HEADLAMP PANEL RH			Bent	142				142	Review
<input type="checkbox"/>		14	1			FRONT GRILLE			Cracked	380				380	Review
<input type="checkbox"/>		15	1			FRONT GRILLE LOGO			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		16	1			FRONT BUMPER			Damaged	730				730	Review
<input type="checkbox"/>		17	10			FRONT BUMPER CLIP			Necessary	3				30	Review
<input type="checkbox"/>		18	1			FRONT BUMPER SIDE BRACKET LH			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		19	1			FRONT FENDER SIDE BRACKET RH			Necessary	20				20	Review
<input type="checkbox"/>		20	1			FRONT BUMPER TOWING COVER			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>		21	1			FRONT NUMBER PLATE BASE			Missing	77				77	Review
<input type="checkbox"/>		22	1			FOG LAMP COVER RH (LED TYPE)			Missing	60				60	Review
<input type="checkbox"/>		23	1			FOG LAMP RH (LED TYPE)			Cracked	145				145	Review
<input type="checkbox"/>		24	1			FRONT BUMPER CHROME MOULDING LH			Necessary	50				50	Review
<input type="checkbox"/>		25	1			FRONT BUMPER CHROME MOULDING RH			Missing	50				50	Review

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTIO (PART)
<input type="checkbox"/>	<input type="text" value="26"/>	<input type="text" value="1"/>			FRONT BUMPER LOWER GRILLE			Deformed	61				61	Review
<input type="checkbox"/>	<input type="text" value="27"/>	<input type="text" value="1"/>			FRONT BUMPER FOAM			Deformed	58				58	Review
<input type="checkbox"/>	<input type="text" value="28"/>	<input type="text" value="1"/>			FRONT BUMPER REINFORCEMENT			Bent	175				175	Review
<input type="checkbox"/>	<input type="text" value="29"/>	<input type="text" value="1"/>			FRONT BUMPER REINFORCEMENT ARM RH			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>	<input type="text" value="30"/>	<input type="text" value="1"/>			SUPPORT PANEL (TOP)			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>	<input type="text" value="31"/>	<input type="text" value="1"/>			SUPPORT PANEL TOP GARNISH			Deformed	26				26	Review
<input type="checkbox"/>	<input type="text" value="32"/>	<input type="text" value="1"/>			RADIATOR AIR GUIDE (TOP)			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>	<input type="text" value="33"/>	<input type="text" value="1"/>			RADIATOR AIR GUIDE (BOTTOM)			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>	<input type="text" value="34"/>	<input type="text" value="1"/>			CONDENSER			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>	<input type="text" value="35"/>	<input type="text" value="1"/>			RADIATOR			Serviceable	0	0	0	0	0	Deny
<input type="checkbox"/>	<input type="text" value="36"/>	<input type="text" value="1"/>			INTERCOOLER			Serviceable	0	0	0	0	0	Deny

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
<input type="checkbox"/>	<input type="text" value="1"/>		LABOUR TO CARRY OUT FRONT REPAIR	600	0	0	Reviewing		1
<input type="checkbox"/>	<input type="text" value="2"/>		TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35	0	0	Reviewing		1

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	RI
<input type="checkbox"/>		3		TO SPRAY PAINTING ON FRONT AFFECTED AREA	600	0	0	Reviewing		
<input type="checkbox"/>		4		TO REMOVE & FIX AIRCON CONDENSER INCLUDING TOP UP AIRCON GAS	0	0	0	Deny		

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE	
<input type="checkbox"/>		1	DAYS OF REPAIR : 5 DAYS	Reviewing			
<input type="checkbox"/>		2	FRONT NUMBER PLATE	Reviewing	35	MISSING	
<input type="checkbox"/>		3	RADIATOR COOLANT	Deny	0	NOT NECESSARY	
<input type="checkbox"/>		4	RIVET (20PCS)	Reviewing	40	NECESSARY	
<input type="checkbox"/>		5	FRONT BUMPER LOWER COVER	Reviewing	99	DEFORMED (SUPPLEMENTARY)	
<input type="checkbox"/>		6	FRONT BUMPER CENTRE BRACKET	Reviewing	53	DEFORMED (SUPPLEMENTARY)	

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		7	HEADLAMP PANEL STOPPER	Reviewing	14	DEFORMED (SUPPLEMENTARY)	

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Claim Amount \$5,464.00

Claim Amount \$5,464.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,235.00	\$1,235.00
Miscellaneous	\$241.00	\$241.00
Excess	-\$400.00	-\$400.00
Spare Parts	\$4,388.00	\$4,388.00

[Submit for Review](#)