

Surveyor

REF: ASM(AXA)

111831 Uhd3 - (W)

ASSIGNMENT

From: Date: 20062018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLN 6324K

at Workshop m/s Kah mider

of 15 Ubi Rd 4

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Rueben

11am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 85

IDAC Accident Report Consistent? : Yes or No

CA / PR Seen Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LTA57363

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLN 6324K Yr Regn: 5117

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda HRV C.C.

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 16152 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMRU1810 GX201973

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil S/Rim / STD A/Rim or

Tyre Size: F: 2.5/60 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 15/6/18

Survey held at

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 21/6/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S L.L.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)