

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III18011163/AEA3Q2

Date: 16/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MC0M0015
Claimant		
Vehicle No : SJS2146G	Insured Vehicle No :	SHC8384D
Date of Loss: 12/06/2018	Nature of Claim: TP	Claim No: MCT18060394

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS2146G		
Make & Model:	KIA CERATO FORTE, 1.6 EX (A)	Engine No:	G4FC9H276070
Reg. Date:	03/08/2009 (Man. Year: 2009)	Chassis No:	KNAFU411MA5101616
Colour:	Grey	Odometer:	167609 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,444.48	3,520.97	5,923.51	62.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,030.00	1,790.00	2,240.00	55.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,474.48	5,310.97	8,163.51	60.58
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	13,474.48	4,200.00	9,274.48	68.83
+ GST 7.00/7.00% (S\$)	943.21	294.00	649.21	68.83
Nett Amount (S\$)	14,417.69	4,494.00	9,923.69	68.83
+ Loss of Use (8.0 x S\$60.00/day) (S\$)		480.00		
(S\$)		4,974.00		
Liabe Amount (50.00%) (S\$)		2,487.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		2,516.00		

INSPECTION

Date of Assignment: 14/06/2018

Date Inspected: 14/06/2018 Inspected At:

MG Solution Pte Ltd (HQ)
23 Kaki Bukit Avenue 4 #02-03B,
VICOM Inspection Centre
Singapore 415933

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Nov 2018)
Parts:	143	KIA CERATO FORTE 1.6 EX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS2146G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Dented	1,094.30 FL	*1,094.30 FL
2	1		*REAR DOOR RH	Distorted	1,120.00 FL	*1,120.00 FL
3	2		*REAR DOOR HINGE RH	Not Necessary	98.40 FL	*- FL
4	1		*REAR DOOR INNER LOCK	Not Necessary	214.20 FL	*- FL
5	1		*REAR DOOR CATCHER LH	Not Necessary	41.10 FL	*- FL
6	1		*REAR DOOR HANDLE LH	Not Necessary	127.20 FL	*- FL
7	1		*REAR DOOR WEATHERSTRIP	Cut	160.00 FL	*160.00 FL
8	1		*REAR DOOR INNER BOARD	Not Necessary	730.00 FL	*- FL
9	1		*REAR DOOR POWER WINDOW MOTOR RH	Not Necessary	547.20 FL	*- FL
10	1		*REAR DOOR REGULATOR RH	Not Necessary	241.80 FL	*- FL
11	1		*ROCKER PANEL RH	Repair	730.00 FL	*- FL
12	1		*REAR BUMPER SIDE RETAINER	Necessary	62.00 FL	*34.00 FL
13	1		*REAR WINDSCREEN MOULDING	Not Necessary	180.00 FL	*- FL
14	1		*REAR FENDER RH	Repair	980.00 FL	*- FL
15	2		*REAR FENDER INNER COWLING RH	Not Necessary	206.00 FL	*- FL
16	1		*REAR FENDER MUDFLAP RH	Not Necessary	80.00 FL	*- FL
17	1		*REAR ALEX	Not Necessary	1,320.00 FL	*- FL
18	1		*REAR SHOCK ABSORBER RH	Not Necessary	280.00 FL	*- FL
19	1		*REAR KNUCKLE ARM WITH BEARING RH	Necessary	320.00 FL	*320.00 FL
20	1		*REAR BUMPER	Torn	695.00 FL	*695.00 FL
21	1		*SET REAR DOOR INNER BOARD CLIPS	Necessary	20.00 FS	*20.00 FS
22	1		*REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
23	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
24	1		*SET REAR FENDER INNER COWLING CLIPS	Not Necessary	20.00 FS	*- FS
25	1		*REAR WHEEL TYRE RH	Not Necessary	350.00 FS	*- FS
26	1		*REAR WHEEL RIM RH	Cut	650.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,367.20	3,863.30
- List Item Discount on L Items 10.00/10.00% (\$)	922.72	342.33
Total Parts (\$)	9,444.48	3,520.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,600.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	800.00
3	TUFF COAT	New	150.00	0.00
4	WIRING CHECK	New	50.00	30.00
5	REMOVE AND REFIX REAR UNDERCARRIAGE	New	450.00	120.00
6	FOUR WHEEL ALIGNMENT	New	100.00	80.00
7	REMOVE AND REFIX REAR WINDSCREEN	New	120.00	0.00
8	TRANFER FRONT DOOR MECHANISM	New	80.00	80.00
9	TRANFER REAR DOOR MECHANISM	New	80.00	80.00
Gross Labour Cost (\$\$)			4,030.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >