

22/03/2002

ASS. REC. BY:

REF: CS/MSG18011177/Dqdz

Special Instruction:

Survivor:
Munnen

Bryan

ASSIGNMENT (Office)

From (Person):

Muhd Ashik

of

MSIG

Date/Time:

20/6/18 @ 9.44am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 3696Y

Insured:

SKZ 9279L

at Workshop m/s

Chunhi Motor

Tel:

64 83 60 16

of

BLK 10 # 01-05/06, Amk Autopoint

Policy No:

80425395MCX

Claim No:

561747

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 18/06/2018

Ins: soon hack motor

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

'up'

Date/Time: 10.27am @ 20/6/18

Person Contacted:

Lynn

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SHA 3696Y - NBA/FCI/4014100/Y

DOA: 24/07/2014

SKZ 9279L - X.


01/7/18 @ 4.11pm revised to Muhd Ashik via Munnen.

Summit

ASSIGNMENT

COE Aug 2025

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 16 days Res.: Yes or No
 Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHA 3696Y Yr Regn: 2017, Aug
 Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) Prime Mover /
 Truck / Trailer or
 Make: Toyota Prius C.C. 1798
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 145203 T/Radio: Insured / Std / NI / NA
 Eng/No: 22R8060478
 C/No: 5TDKB3FU203563192
 Gen. Cond: 6 / Fair / Poor / Burnt
 Steering: 6 / Jammed / Leaked / Burnt or
 Brake: 6 / Jammed / Leaked / Burnt or
 Modi: Nil / STD A/Rim or
 Tyre Size: F: 195/65 R15
 R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 18/06/2018 D.O.I. 20/06/2018

Survey held at Chunni AMIC

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front & Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

NSIG SKZ 9279L

26/07/18 gmm 2/8 21,300/- with 16 days 2 rev
(led \$ 18M4.10, 46%)

[Signature]

15/8/2018

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 16

Resurvey No. of Trip: 3

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation

\$ + RS. \$

Photos

Others

TOTAL

250

10

260

Report Format :

MER-TP

Lump Sum / B.I. (\$

21300

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jun 2018		20 Jun 2018 09:44 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SIANG CHO KEONG TEMPLE, Co. Reg. No.: S89CC0623L		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHA3696Y	Date of Loss:	18/06/2018 14:00 - :59 [10 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	80425395MCX (Comprehensive) Coverage: 15/02/2018 - 14/02/2019
Vehicle Reg. No. (Insured):	SKZ9279L	Policy No. (Claimant):	
		Excess:	
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/06/2018]		
Adj Asg. Remarks:	on WP, OI NOT REPORTED AGREE ON SJE - LKK SURVEY AT AMK AUTOPOINT, SOON HOCK MOTOR CONTACT 6483 6016		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 02 Jul 2018

Preliminary Advice

Insured Vehicle No	: SKZ9279L	Accident Date	: 18/06/2018
TP Vehicle No	: SHA3696Y	Assignment Date	: 20/06/2018
Make	: TOYOTA PRIUS	Est. Duration of Repair	: 14.00
Date of Inspection	: 20/06/2018		
Inspection At	: CHUNNI MOTOR WORK PTE LTD - AMK (HQ) BLK 10 #01-05/06, AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	39,524.10
Revised Amount	:S\$	26,444.70
Check Items (Estimated)	:S\$	0.00
Total	:S\$	26,444.70

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

MC0618078776 / ComfortDelGro Engineering Pte Ltd - Layang
 ENTRY DATE & TIME: 19/06/2018 10:54
 SUBMITTED BY: Huang XiaoYan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/06/2018 10:54
Date Of Accident	18/06/2018 14:30
Exact Location Of Accident	CTE TWDS OUTRAM RD AT OUTRAM EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA3696Y
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
Driver	
Name of Driver	KOH KOK ANN
NRIC No	S0088129E
Date Of Birth	12/05/1951
Occupation	OUTDOOR
Date Of Driving Pass	25/09/1974
Driving Experience	43 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98209216
Fax Number	
Contact Number	
EMail Address	KOKANNKOH1205@YAHOO.COM

Address BLK 233 SIMEI STREET 4 #07-160
Postcode 520233
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 3
Passenger 1
NAME: : -
GENDER: : FEMALE
Passenger 2
NAME: : -
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
POLICE STATION NAME [OTHER] CHANGI N.P.C
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLS REFER TO POLICE REPORT : T/20180618/2172

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKZ9279L
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver AUG YI PING
NRIC/Passport Number S8934965F
Contact Number
Address
Postcode

Insurance Company Name MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage REAR AND FRT
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category NA/UNKNOWN
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage NOT SURE
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLT2197E
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver SEAT QIN FA
NRIC/Passport Number S8610439C
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage FRT
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TAN BENG GEK
Approximate Age
Injuries Sustain NOT SURE
Injured person in which vehicle? SHA3696Y
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

DETAILS OF INJURED PERSON 2

Name AUG YI PING
Approximate Age
Injuries Sustain NOT SURE
Injured person in which vehicle? SKZ9279L
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? YES
Address
Postcode

DETAILS OF INJURED PERSON 3

Name	UNKNOWN
Approximate Age	
Injuries Sustain	NOT SURE
Injured person in which vehicle?	SKZ9279L
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

DETAILS OF INJURED PERSON 4

Name	SEAT QIN FA
Approximate Age	
Injuries Sustain	NOT SURE
Injured person in which vehicle?	SLT2197E
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 19.06.2018 @ 10:00 Hrs

Reporting Centre Personnel's Signature
Name: *Rubbini*
NRIC/FIN No.:

SKETCH PLAN

Along CTE Twds Outram Rd at Outram Exit.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report : T/20180618/2172.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD

CO. REG. NO. 199303821R

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 19.06.2018 @ 10:00 Hrs

Reporting Centre Personnel's Signature

Name: Rubbin

NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20180618/2172

1 of 3

Police Station Of Origin:
Changi N.P.C
9 Simei Street 2 SINGAPORE 529914
Tel No: 1800-5872999

Report No. T/20180618/2172

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/06/2018 19:24		Vide Report No.:		Station Diary No.: 92	
Informant's Particulars					
Name of Informant: KOH KOK ANN			Address: APT BLK 233 SIMEI STREET 4 #07-160 SINGAPORE 520233		
ID Type / ID No.: NRIC NO / S0088129E			Contact No.: Home/Office:		Mobile: 98209216
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 67	Date of Birth: 12/05/1951	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: TAXI DRIVER.			Driving Licence Information: Class: 2B,2A,2,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 18/06/2018 14:30	Type of Location: EXIT
Location: Along Road 1 Traveling Toward Road 2 CENTRAL EXPRESSWAY OUTRAM ROAD AT THE OUTRAM EXIT				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHA3696Y	TAXI	TOYOTA	PRIUS HYBRID 1.8 CVT	Blue	Seriously Damaged	2
SKZ9279L	Car	HYUNDAI	ELANTRA AD 1.6 GLS AT	White	Seriously Damaged	1
SLT2197E	Car	HONDA	VEZEL 1.5X A	Blue	Seriously Damaged	0



**SINGAPORE
POLICE FORCE**



T/20180618/2172

2 of 3

Report No. T/20180618/2172

Police Station Of Origin:

Changi N.P.C

9 Simei Street 2 SINGAPORE 529914

Tel No: 1800-5872999

CONTINUATION OF REPORT

Brief Details.

ON 18/06/2018 AT ABOUT 1430HRS, ALONG CTE TOWARDS OUTRAM EXIT WHILST DRIVING (A) SHA3896Y IN EXTREME LEFT LANE WITH HEAVY TRAFFIC PILING UP. AS I WAS MOVING GRADUALLY, SUDDENLY A CAR (B) SKZ9279L COLLIDED INTO THE REAR OF MY TAXI, THE CAR HAD BEEN ALSO REAR END BY ANOTHER CAR (C) SLT2197E. DUE TO THE HARD IMPACT, MY TAXI JOLTED FORWARD AND TOUCH SLIGHTLY INTO THE REAR OF ANOTHER VEHICLE INFRONT OF ME. HOWEVER, THE SAID VEHICLE HAD DROVE OFF. VEHICLE C) SUSTAINED AT THE FRONT BUMPER AND BONNET SERIOUSLY DENTED, BROKEN HEADLIGHTS, VEHICLE B) SUSTAINED AT THE REAR BUMPER, FRONT BUMPER SERIOUSLY DENTED AND BROKEN FRONT HEADLIGHTS AND REAR SIGNAL LIGHTS. MY TAXI SUSTAINED REAR BUMPER SERIOUSLY DENTED AND BOOT CANNOT BE OPEN. MY BONNET ALSO HAVE DIFFICULTIES IN OPENING UP DUE TO THE IMPACT. POLICE HAD ATTENDED TO THE ACCIDENT REPORT REF TO A/20180618/0082. AMBULANCE THEN CONVEYED MY FEMALE PASSENGER AUNTIE TO SGH WHICH SHE IS ALSO GOING FOR HER APPOINTMENT. MY OTHER PASSENGER WHOM IS A MAID STAYED AT SCENE. PASSENGER AND DRIVER OF VEHICLE B) WAS ALSO SEND TO SGH DUE TO UNKNOWN INJURIES. DRIVER C) SUSTAINED A BLOODY NOSE DUE TO THE IMPACT. I HAVE A DASHCAM FOOTAGE WHICH I HAD HANDED OVER TO TRAFFIC POLICE.

**SINGAPORE
POLICE FORCE**

T/20180618/2172

3 of 3

Report No. T/20180618/2172

Police Station Of Origin:

Changi N.P.C

9 Simei Street 2 SINGAPORE 529914

Tel No: 1800-5872999

CONTINUATION OF REPORT**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

SI MOHAMAD NASRUL BIN ABDUL RASID

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt NOR FAIZAL BIN YAHYA

Contact No.: 65476202



Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

18/06/2018 19:24

Classification Of Case:

SIGNATURE

CHUNNI MOTOR WORK PTE LTD

Survey by LK

REPAIR ESTIMATE

MSIG

VEHICLE NO: SHA 3696Y

DATE : 19.06.2018

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
RADIATOR GRILLE <i>crack</i>			\$ 438.00 ✓
RADIATOR GRILLE EMBLEM <i>See</i>			\$ 86.50 ✓
LAMP ASSY, FOG, RH <i>not mounty crack</i>			\$ 920.00 ✓
LAMP ASSY, FOG, LH <i>not mounty crack</i>			\$ 920.00 ✓
FRONT BUMPER COVER <i>distorted</i>			\$ 490.50 ✓
FRONT BUMPER REINFORCEMENT <i>✓</i>			\$ 691.50 ✓
FRONT BUMPER REINFORCEMENT ABSORBER <i>distorted</i>			\$ 115.70 ✓
FRONT BUMPER SPONGE <i>✓</i>			\$ 78.80 ✓
FRONT BUMPER CENTRE GRILLE <i>HF</i>			\$ 301.90 X
FRONT BUMPER LOWER GRILLE <i>crack</i>			\$ 148.60 ✓
FRONT BUMPER CLIPS <i>See</i>			\$ 22.00 ✓
FRONT BUMPER SIDE RETAINER <i>See</i>		\$ 77.00	\$ 154.00 X
FRONT LOWER CROSSMEMBER <i>not see not ✓</i>			\$ 357.70 ✓
REINFORCEMENT SUB-ASSY, FRONT BUMPER LOWER <i>not ✓</i>			\$ 236.10 ✓
BRACKET, FRONT BUMPER EXTENSION MOUNTING <i>HF</i>			\$ 110.40 X
SUPPORT FR BUMPER, RH <i>HF</i>			\$ 81.70 X
SUPPORT FR BUMPER, LH <i>HF</i>			\$ 81.70 X
FRONT BUMPER CENTRE FRAME <i>not ✓</i>			\$ 236.90 ✓
UNIT ASSY, HEADLAMP, RH (LED) <i>broken</i>			\$ 3,413.40 ✓
UNIT ASSY, HEADLAMP, LH (LED) <i>broken</i>			\$ 3,413.40 ✓
HEAD LAMP PANEL (RH) <i>not ✓</i>			\$ 213.50 ✓
HEAD LAMP PANEL (LH) <i>not ✓</i>			\$ 213.50 ✓
BRACKET, HEADLAMP MOUNTING, RH <i>HF</i>			\$ 25.50 X
BRACKET, HEADLAMP MOUNTING, LH <i>HF</i>			\$ 25.50 X
RADIATOR ASSY <i>not ✓</i>			\$ 1,841.80 ✓
RADIATOR FAN COWLING ASSY <i>not mounty crack</i>			\$ 661.30 ✓
RADIATOR BOTTOM MOUNTING <i>HF</i>			\$ 27.50 X
STAY, RADIATOR SUPPORT, RH <i>HF</i>			\$ 65.70 X
STAY, RADIATOR SUPPORT, LH <i>HF</i>			\$ 65.70 X
CONDENSER ASSY, W/RECEIVER <i>not ✓</i>			\$ 1,304.00 ✓
SUB TOTAL			\$ 16,742.80
LESS 20% <i>25%</i>			\$ 3,348.56
DISCOUNTED TOTAL			\$ 13,394.24
FRONT NO. PLATE <i>✓</i>			\$ 25.00 NETT ✓
FRONT NO PLATE TRIM COVER <i>crack ✓</i>			\$ 30.00 NETT ✓
FRONT NO. PLATE GARNISH <i>crack</i>			\$ 99.00 NETT ✓
			\$ 154.00

15803.20

11852.40

144.00

SHA 3696Y

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
LABOUR CHARGE				
Panel Beating			\$ 350.00	300/-
Spray Painting Charge			\$ 200.00	180/-
Wiring Charge			\$ 50.00	30/-
Towing Charge			\$ 50.00	NH
Remove/Refix Aircon & Refill Gas			\$ 150.00	180/-
TOTAL LABOUR			\$ 800.00	
REAR TRUNK LID COVER <i>Dent</i>			\$ 922.50	✓
REAR TRUNK LID LOCK <i>NH</i>			\$ 447.70	✓
REAR TRUNK LID COVER TRIM BOARD <i>broken</i>			\$ 216.50	✓
REAR TRUNK LID RUBBER <i>deformed</i>			\$ 357.00	✓
REAR TRUNK LID GLASS (BLACK COLOR) <i>broken</i>			\$ 721.30	✓
BOARD ASSY, BACK DOOR TRIM <i>broken SVC</i>			\$ 246.90	X
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>broken</i>			\$ 889.70	✓
REAR TRUNK LID LOGO(PRIUS) <i>NH</i>			\$ 60.80	✓
REAR TRUNK LID LOGO(HYBRID) <i>NH</i>			\$ 52.40	✓
REAR TRUNK LID LOGO(TOYOTA STAR) <i>NH</i>			\$ 52.90	✓
REAR BUMPER <i>broken</i>			\$ 458.60	✓
REAR BUMPER RE-INFORCEMENT <i>NH</i>			\$ 318.80	✓
REAR BUMPER UNDER COVER <i>tear</i>			\$ 552.60	✓
REAR BUMPER SIDE RETAINER <i>SVC</i>			\$ 112.70	X
REAR BUMPER SPONGE <i>NH</i>			\$ 143.40	X
REAR BUMPER UNDER SIDE COVER (RH) <i>SVC</i>			\$ 167.60	X
REAR BUMPER UNDER SIDE COVER (LH) <i>SVC</i>			\$ 232.00	X
REAR BUMPER UNDER SIDE CENTRE COVER <i>tear</i>			\$ 552.60	✓
RETAINER, REAR BUMPER, UPPER SIDE <i>SVC</i>			\$ 30.70	X
RETAINER, REAR BUMPER, SIDE, RH <i>SVC</i>			\$ 94.80	X
RETAINER, REAR BUMPER, SIDE, LH <i>SVC</i>			\$ 94.80	X
SEAL, REAR BUMPER SIDE, RH <i>SVC</i>			\$ 148.40	X
SEAL, REAR BUMPER SIDE, LH <i>deformed SVC</i>			\$ 148.40	NH X
TAIL LAMP ASSY (UPPER) (LH/RH) <i>crack</i>		\$ 557.90	\$ 1,115.80	✓
TAIL LAMP ASSY (LOWER) (LH/RH) <i>crack</i>		\$ 548.40	\$ 1,096.80	✓
REAR END PANEL <i>NH</i>			\$ 602.10	✓
REAR END PANEL GARNISH <i>deformed</i>			\$ 121.60	✓
REAR SPARE TYRE PANEL <i>NH</i>			\$ 667.70	✓
REAR SPARE TYRE CHUSHION (FLR BOARD CENTRE) <i>NH</i>			\$ 101.40	✓
REAR EXHAUST PIPE <i>NH</i>			\$ 1,163.40	✓
REAR EXHAUST PIPE HANGER <i>SVC</i>			\$ 40.70	X
REAR EXHAUST PIPE INSULATOR <i>NH</i>			\$ 314.60	X
REAR EXHAUST PIPE CENTRE INSULATOR <i>NH</i>			\$ 498.60	✓
REAR FENDER, LH <i>Dent</i>			\$ 817.50	✓
REAR FENDER, RH <i>Dent</i>			\$ 817.50	✓
REAR FENDER INNER PANEL, LH <i>Dent</i>			\$ 728.00	✓
REAR FENDER INNER PANEL, RH <i>NH</i>			\$ 728.00	X
REAR FENDER OUTER PANEL, LH <i>NH</i>			\$ 486.00	X
REAR FENDER OUTER PANEL, RH <i>NH</i>			\$ 486.00	X

SHA 3696Y

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
REAR FENDER PANEL, ROOF SIDE OUTER, LH <i>HN</i>			\$ 311.00	✓
REAR FENDER PANEL, ROOF SIDE OUTER, RH <i>HN</i>			\$ 311.00	✓
REAR FENDER REINFORCEMENT SUB, ROCKER PANEL, LH <i>HN</i>			\$ 552.30	✓
REAR FENDER REINFORCEMENT SUB, ROCKER PANEL, RH <i>HN</i>			\$ 552.30	✓
REAR FENDER EXTENSION, ROOF SIDE INNER FRT, LH <i>HN</i>			\$ 265.10	✓
REAR FENDER EXTENSION, ROOF SIDE INNER FRT, RH <i>HN</i>			\$ 265.10	✓
REAR FENDER SHEILD (LH) <i>HN</i>			\$ 134.20	✓
REAR FENDER SHEILD (RH) <i>HN</i>			\$ 134.20	✓
REAR FENDER TRIMBOARD (LH) <i>defected</i>			\$ 725.00	—
REAR FENDER TRIMBOARD (RH) <i>defected</i>			\$ 725.00	—
REAR FENDER SIDE PANEL <i>HN</i>			\$ 165.00	✓
REAR CHASSIS MEMBER <i>HN</i>			\$ 1,180.80	✓
REAR FLOOR BOARD (LH) <i>HN</i>			\$ 301.00	✓
REAR FLOOR BOARD (RH) <i>HN</i>			\$ 301.00	✓
REAR FLOOR UNDER COVER CENTRE <i>HN</i>			\$ 322.00	✓
REAR FLOOR UNDER COVER <i>HN</i>			\$ 334.00	✓
REAR CROSSMEMBER UNDER COVER <i>HN</i>			\$ 353.00	✓
REAR WINDSCREEN GLASS <i>HN</i>			\$ 1,555.80	✓
REAR WINDSCREEN GLASS MOULDING <i>HN</i>			\$ 208.60	✓
SUB TOTAL			\$ 25,505.20	
LESS 20% <i>25%</i>			\$ 5,101.04	
DISCOUNTED TOTAL			\$ 20,404.16	
REAR NO. PLATE WITH TRIM COVER <i>defected</i>			\$ 95-100.00	NETT ✓
REAR TRUNK LID APPS STICKER <i>NK</i>			\$ 40.00	NETT ✓
REAR TRUNK LID COMFORT & TEL NO. STICKER <i>NK</i>			\$ 60.00	NETT ✓
REAR BUMPER REVERSE SENSOR <i>Rem</i>			\$ 135.70	NETT ✓
REAR BUMPER RUBBER MAT <i>defected</i>			\$ 50.00	NETT ✓
REAR WINDSCREEN SEALANT <i>NK</i>			\$ 46.00	NETT ✓
			\$ 431.70	
LABOUR CHARGE				
Panel Beating			\$ 2,000.00	1400/-
Spray Painting Charge			\$ 1,200.00	800/-
Wiring Charge			\$ 100.00	30/-
Tuff Kote			\$ 100.00	60/-
Front Chassis Alignment Charge			\$ 400.00	HN
Remove/Refix Cushion & Upholstery Rear			\$ 150.00	80/-
Remove/Refix Rear Windscreen Glass			\$ 120.00	20/-
Remove/Refix Reverse Sensor			\$ 120.00	40/-
Remove/Refix Exhaust Pipe			\$ 150.00	60/-
TOTAL LABOUR			\$ 4,340.00	
ESTIMATE TOTAL			\$ 39,524.10	

14783.80
~~11087.85~~
 11087.85

431.70

20/06/2018 @ 1130am
 NA Arthur
 P/Pet

27/1/18

2550/-

Photo B&B spray
 with damage parts.

LKK Auto

#16
 12 days.

LKK Auto Centre
 the Repair of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Signature:
 Date:

26655.95

4/5 21,300/-

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18011177/DQD3N2

Date: 15/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80425395MCX
Claimant Vehicle No :	SHA3696Y	Insured Vehicle No :	SKZ9279L
Date of Loss:	18/06/2018	Nature of Claim:	TP
		Claim No:	561747

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA3696Y	Engine No:	2ZRS060478
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU203563192
Reg. Date:	10/08/2017 (Man. Year: 2017)	Odometer:	145203 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,384.10	23,515.95	10,868.15	31.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,140.00	3,140.00	2,000.00	38.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,524.10	26,655.95	12,868.15	32.56
Approved Total (Overridden) (S\$)		21,300.00		
(S\$)	39,524.10	21,300.00	18,224.10	46.11
+ GST 7.00/7.00% (S\$)	2,766.69	1,491.00	1,275.69	46.11
Nett Amount (S\$)	42,290.79	22,791.00	19,499.79	46.11

INSPECTION

Date of Assignment:	20/06/2018	
Date Inspected:	20/06/2018 Inspected At:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint Singapore 568047
Estimated Period of Repair:	16.0 days	

Adjuster: BRYAN TANI

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Aug 2018)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA3696Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Cracked	438.00 FL	*438.00 FL
2	1		*RADIATOR GRILLE EMBLEM	Necessary	86.50 FL	*86.50 FL
3	1		*LAMP ASSY FOG RH	Mounting Cracked	920.00 FL	*920.00 FL
4	1		*LAMP ASSY FOG LH	Mounting Cracked	920.00 FL	*920.00 FL
5	1		*FRONT BUMPER COVER	Distorted	490.50 FL	*490.50 FL
6	1		*FRONT BUMPER REINFORCEMENT	Bent	691.50 FL	*691.50 FL
7	1		*FRONT BUMPER REINFORCEMENT ABSORBER	Distorted	115.70 FL	*115.70 FL
8	1		*FRONT BUMPER SPONGE	Torn	78.80 FL	*78.80 FL
9	1		*FRONT BUMPER LOWER GRILLE	Cracked	148.60 FL	*148.60 FL
10	1		*FRONT BUMPER CENTRE GRILLE	Not fitted	301.90 FL	*- FL
11	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
12	2		*FRONT BUMPER SIDE RETAINER	Serviceable	154.00 FL	*- FL
13	1		*FRONT LOWER CROSSMEMBER	Bent	357.70 FL	*357.70 FL
14	1		*REINFORCEMENT SUB-ASSY,FRONT BUMPER LOWER	Bent	236.10 FL	*236.10 FL
15	1		*BRACKET,FRONT BUMPER EXTENSION MOUNTING	Not Necessary	110.40 FL	*- FL
16	1		*SUPPORT FR BUMPER RH	Not Necessary	81.70 FL	*- FL
17	1		*SUPPORT FR BUMPER LH	Not Necessary	81.70 FL	*- FL
18	1		*FRONT BUMPER CENTRE FRAME	Bent	236.90 FL	*236.90 FL
19	1		*UNIT ASSY,HEADLAMP RH (LED)	Broken	3,413.40 FL	*3,413.40 FL
20	1		*UNIT ASSY,HEADLAMP LH (LED)	Broken	3,413.40 FL	*3,413.40 FL
21	1		*HEAD LAMP PANEL RH	Bent	213.50 FL	*213.50 FL
22	1		*HEAD LAMP PANEL LH	Bent	213.50 FL	*213.50 FL
23	1		*BRACKET HEADLAMP MOUNTING RH	Not Necessary	25.50 FL	*- FL
24	1		*BRACKET HEADLAMP MOUNTING LH	Not Necessary	25.50 FL	*- FL
25	1		*RADIATOR ASSY	Bent	1,841.80 FL	*1,841.80 FL
26	1		*RADIATOR FAN COWLING ASSY	Mounting Cracked	661.30 FL	*661.30 FL
27	1		*RADIATOR BOTTOM MOUNTING	Not Necessary	27.50 FL	*- FL
28	1		*STAY RADIATOR SUPPORT,RH	Not Necessary	65.70 FL	*- FL
29	1		*STAY RADIATOR SUPPORT,LH	Not Necessary	65.70 FL	*- FL
30	1		*CONDENSER ASSY,W/RECEIVER	Bent	1,304.00 FL	*1,304.00 FL
31	1		*REAR TRUNK LID COVER	Dented	922.50 FL	*922.50 FL
32	1		*REAR TRUNK LID LOCK	Bent	447.70 FL	*447.70 FL
33	1		*REAR TRUNK LID COVER TRIM BOARD	Broken	216.50 FL	*216.50 FL
34	1		*REAR TRUNK LID RUBBER	Deformed	357.00 FL	*357.00 FL
35	1		*REAR TRUNK LID GLASS (BLACK COLOR)	Broken	721.30 FL	*721.30 FL
36	1		*BOARD ASSY,BACK DOOR TRIM	Serviceable	246.90 FL	*- FL
37	1		*GARNISH SUB-ASSY,BACK DOOR,OUTSIDE	Broken	889.70 FL	*889.70 FL
38	1		*REAR TRUNK LID LOGO (PRIUS)	Necessary	60.80 FL	*60.80 FL
39	1		*REAR TRUNK LID LOGO (HYBRID)	Necessary	52.40 FL	*52.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR TRUNK LID LOGO (TOYOTA STAR)	Necessary	52.90 FL	*52.90 FL
41	1		*REAR BUMPER	Broken	458.60 FL	*458.60 FL
42	1		*REAR BUMPER RE-INFORCEMENT	Buckled	318.80 FL	*318.80 FL
43	1		*REAR BUMPER UNDER COVER	Torn	552.60 FL	*552.60 FL
44	1		*REAR BUMPER SIDE RETAINER	Serviceable	112.70 FL	*- FL
45	1		*REAR BUMPER SPONGE	Not fitted	143.40 FL	*- FL
46	1		*REAR BUMPER UNDER SIDE COVER RH	Serviceable	167.60 FL	*- FL
47	1		*REAR BUMPER UNDER SIDE COVER LH	Serviceable	232.00 FL	*- FL
48	1		*REAR BUMPER UNDER SIDE CENTRE COVER	Torn	552.60 FL	*552.60 FL
49	1		*RETAINER REAR BUMPER UPPER SIDE	Serviceable	30.70 FL	*- FL
50	1		*RETAINER REAR BUMPER SIDE RH	Serviceable	94.80 FL	*- FL
51	1		*RETAINER REAR BUMPER SIDE LH	Serviceable	94.80 FL	*- FL
52	1		*SEAL, REAR BUMPER SIDE RH	Serviceable	148.40 FL	*- FL
53	1		*SEAL, REAR BUMPER SIDE LH	Serviceable	148.40 FL	*- FL
54	2		*TAIL LAMP ASSY (UPPER)(LH/RH)	Cracked	1,115.80 FL	*1,115.80 FL
55	2		*TAIL LAMP ASSY (LOWER)(LH/RH)	Cracked	1,096.80 FL	*1,096.80 FL
56	1		*REAR END PANEL	Buckled	602.10 FL	*602.10 FL
57	1		*REAR END PANEL GARNISH	Deformed	121.60 FL	*121.60 FL
58	1		*REAR SPARE TYRE PANEL	Buckled	667.70 FL	*667.70 FL
59	1		*REAR SPARE TYRE CUSHION (FLR BOARD CENTRE)	Bent	101.40 FL	*101.40 FL
60	1		*REAR EXHAUST PIPE	Bent	1,163.40 FL	*1,163.40 FL
61	1		*REAR EXHAUST PIPE HANGER	Serviceable	40.70 FL	*- FL
62	1		*REAR EXHAUST PIPE INSULATOR	Not Necessary	314.60 FL	*- FL
63	1		*REAR EXHAUST PIPE CENTRE INSULATOR	Bent	498.60 FL	*498.60 FL
64	1		*REAR FENDER LH	Dented	817.50 FL	*817.50 FL
65	1		*REAR FENDER RH	Dented	817.50 FL	*817.50 FL
66	1		*REAR FENDER INNER PANEL LH	Dented	728.00 FL	*728.00 FL
67	1		*REAR FENDER INNER PANEL RH	Not Necessary	728.00 FL	*- FL
68	1		*REAR FENDER OUTER PANEL LH	Not Necessary	486.00 FL	*- FL
69	1		*REAR FENDER OUTER PANEL RH	Not Necessary	486.00 FL	*- FL
70	1		*REAR FENDER PANEL ROOF SIDE OUTER LH	Not Necessary	311.00 FL	*- FL
71	1		*REAR FENDER PANEL ROOF SIDE OUTER RH	Not Necessary	311.00 FL	*- FL
72	1		*REAR FENDER REINFORCEMENT SUB,ROCKER PANEL LH	Not Necessary	552.30 FL	*- FL
73	1		*REAR FENDER REINFORCEMENT SUB,ROCKER PANEL RH	Not Necessary	552.30 FL	*- FL
74	1		*REAR FENDER EXTENSION ROOF SIDE INNER FRT LH	Not Necessary	265.10 FL	*- FL
75	1		*REAR FENDER EXTENSION ROOF SIDE INNER FRT RH	Not Necessary	265.10 FL	*- FL
76	1		*REAR FENDER SHIELD (LH)	Not Necessary	134.20 FL	*- FL
77	1		*REAR FENDER SHIELD (RH)	Not Necessary	134.20 FL	*- FL
78	1		*REAR FENDER TRIMBOARD RH	Deformed	725.00 FL	*725.00 FL
79	1		*REAR FENDER TRIMBOARD LH	Deformed	725.00 FL	*725.00 FL
80	1		*REAR FENDER SIDE PANEL	Not Necessary	165.00 FL	*- FL
81	1		*REAR CHASSIS MEMBER	Repair	1,180.80 FL	*- FL
82	1		*REAR FLOOR BOARD LH	Not Necessary	301.00 FL	*- FL
83	1		*REAR FLOOR BOARD RH	Not Necessary	301.00 FL	*- FL
84	1		*REAR FLOOR UNDER COVER CENTRE	Not Necessary	322.00 FL	*- FL
85	1		*REAR FLOOR UNDER COVER	Not Necessary	334.00 FL	*- FL
86	1		*REAR CROSSMEMBER UNDER COVER	Not Necessary	353.00 FL	*- FL
87	1		*REAR WINDSCREEN GLASS	Not Necessary	1,555.80 FL	*- FL
88	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	208.60 FL	*- FL
89	1		*FRONT NO PLATE	Bent	25.00 FS	*25.00 FS
90	1		*FRONT NO PLATE TRIM COVER	Bent	30.00 FS	*20.00 FS
91	1		*FRONT NO PLATE GARNISH	Cracked	99.00 FS	*99.00 FS
92	1		*REAR NO PLATE WITH TRIM COVER	Dislodged	100.00 FS	*100.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
93	1		*REAR TRUNK LID APPS STICKER	Necessary	40.00 FS	*40.00 FS
94	1		*REAR TRUNK LID COMFORT & TEL NO STICKER	Necessary	60.00 FS	*60.00 FS
95	1		*REAR BUMPER REVERSE SENSOR	Damaged	135.70 FS	*135.70 FS
96	1		*REAR BUMPER RUBBER MAT	Deformed	50.00 FS	*50.00 FS
97	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	42,833.70	31,162.70
- List Item Discount on L Items 20.00/25.00% (\$)	8,449.60	7,646.75
Total Parts (\$)	34,384.10	23,515.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,350.00	1,700.00
2	SPRAY PAINTING CHARGE	New	1,400.00	980.00
3	WIRING CHARGE	New	150.00	60.00
4	TOWING CHARGE	New	50.00	-
5	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	80.00
6	TUFF KOTE	New	100.00	60.00
7	FRONT CHASSIS ALIGNMENT CHARGE	New	400.00	-
8	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
9	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
10	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
11	REMOVE/REFIX EXHAUST PIPE	New	150.00	60.00
Gross Labour Cost (S\$)			5,140.00	3,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >