

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA4412T

MAKE : HYUNDAI

MODEL : i40

AXIA

DOA: 19.06.2018

Date: 20.06.2018

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	Rear Bumper <i>Defunct</i>			\$ 603.60
1	Rear Bumper Reinforcement <i>X</i>			\$ 504.35
1	Rear Bumper Sponge <i>X</i>			\$ 143.40
10	Rear Bumper clips @ \$2.20 <i>all</i>			\$ 22.00
1	Rear Bumper Under Cover <i>all</i>			\$ 225.00
1	Rear Bumper Stay - RH <i>X</i>			\$ 180.00
1	Rear Bumper Stay - LH <i>X</i>			\$ 180.00
1	Rear Panel <i>X</i>			\$ 592.30
SUB TOTAL				\$ 2,450.65
LESS 20%				490.13
DISCOUNTED TOTAL				\$ 1,960.52
1	Rear Bumper Reverse Sensor <i>shhd</i>			\$ 135.70 Nett
1	Rear Bumper Rubber Mat <i>hee</i>			\$ 50.00 Nett
				\$ 185.70
Labour Charge				
1	Panel Beating			\$ 500.00 <i>200</i>
1	Spray Painting Charge			\$ 500.00 <i>200</i>
1	Wiring Charge			\$ 50.00 <i>X 11</i>
1	R/Refix Reverse Sensor			\$ 120.00 <i>30</i>
1	Tuff Kote			\$ 80.00 <i>X 11</i>
TOTAL LABOUR <i>Before Part p/h</i>				\$ 1170.00
ESTIMATE TOTAL				\$ 3,316.22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL LABOUR

ESTIMATE TOTAL

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.