

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18011211/KGA3Q2

Date: 28/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MC0M0015
Claimant		
Vehicle No : GX4621Y	Insured Vehicle No :	SHA7633C
Date of Loss: 14/06/2018	Nature of Claim: TP	Claim No: MCT18060426

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GX4621Y		
Make & Model:	NISSAN P/UP LOWBED, 2.4 (M)	Engine No:	TD27735846
Reg. Date:	24/05/2004 (Man. Year: 2004)	Chassis No:	JN1AHGD22Z0033189
Colour:	White	Odometer:	442460 km
Engine Capacity:	2664 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185 R14X8	Rear Tyre Size:	185 R14X8
Front Left Side:	Michelin 2 mm	Rear Left Side:	Michelin 3 mm
Front Right Side:	Michelin 2 mm	Rear Right Side:	Michelin 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,109.70	3,806.80	1,302.90	25.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	1,380.00	800.00	36.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,289.70	5,186.80	2,102.90	28.85
Approved Total (Overridden) (S\$)		4,150.00		
(S\$)	7,289.70	4,150.00	3,139.70	43.07
+ GST 7.00/7.00% (S\$)	510.28	290.50	219.78	43.07
Nett Amount (S\$)	7,799.98	4,440.50	3,359.48	43.07
+ Car Rental (8.0 x S\$100.00/day + 7.00% GST) (S\$)		856.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		5,332.95		
Global Sum Settlement (S\$)		5,300.00		

INSPECTION

Date of Assignment:	20/06/2018	
Date Inspected:	20/06/2018 Inspected At:	Chew Goon Motor (AMK)
		Blk 10 Ang Mo Kio Industrial Park 2A,
		#01-15/16 & 17, AMK Autopoint
		Singapore 568047
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Sep 2020)	
Parts:	N/A	NISSAN P/UP LOWBED 2.4 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GX4621Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	955.00 FL	*850.00 FL
2	1		*REAR BUMPER BRACKETS	N/S Repair / O/S Bent	304.00 FL	*152.00 FL
3	1		*REAR BUMPER TOP STEP PLATE	Distorted	275.00 FL	*275.00 FL
4	1		*REAR BUMPER TOP STEP PLATE COVER	Missing	357.00 FL	*357.00 FL
5	1		*REAR BUMPER CENTER STEP BOARD	Serviceable	225.00 FL	*- FL
6	1		*REAR CABIN SIDE PANEL RH	Bent	2,392.00 FL	*1,980.00 FL
7	1		*REAR CABIN SIDE PANEL SHIELD RH	Distorted	203.00 FL	*203.00 FL
8	1		*TAILLAMP ASSY RH	Cut	177.00 FL	*177.00 FL
9	1		*TAILLAMP GASKET	Not Necessary	65.00 FL	*- FL
10	1		*REAR CABIN SIDE PANEL MUDFLAP	Serviceable	152.00 FS	*- FS
11	1		*REAR TYRE RH (30%)	Cut	120.00 FS	*36.00 FS
12	1		*REAR WHEEL RIM	Dented	228.80 FS	*50.00 FS
13	1		*REAR WHEEL BEARING	Jammed	106.20 FS	*106.20 FS
14	1		*SIDE STICKER (CO REG)	Necessary	45.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,605.00	4,206.20
- List Item Discount on L Items 10.00/10.00% (\$\$)	495.30	399.40
Total Parts (\$\$)	5,109.70	3,806.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO SUPPLY BLIND RIVETS, SEALANT TO DISMANTLE / REMOVE REAR CARGO BED PROTECTIVE STEEL PLATE.	New	300.00	250.00
2	TO DISMANTLE / REPLACE REAR WHEEL BEARING.	New	100.00	20.00
3	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST.	New	80.00	60.00
4	LABOUR CHARGE - PANEL BEATING, REPAIRING OF REAR SIDE PANEL INNER PANEL, REAR O/S CHASSIS, CUT, WELD SIDE PANEL AND PARTS REPLACEMENT.	New	1,050.00	700.00
5	TO RESPRAY AFFECTED ARES.	New	650.00	350.00
Gross Labour Cost (\$\$)			2,180.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >