

22/03/2002

ASS. REC. BY:

REF: CS/CTI18011251/T1td321 Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

Menmen

From (Person): Chong Boon Sun

of CTI

Date/Time: 21/06/2018 @ 10:17am

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

JPA 2101

Insured: SGS 5791J

at Workshop m/s

Pang Scooter

Tel: 6271 4618

of Blk 1006 Bukit Meruh Lane 2 # 01-06

Policy No: DMPCSN 3104621600

Claim No: SNM17D04650002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 06/08/2018

CA / REV / REP. / REV 24 HRS

1up

22062018

H.O.D. Endorsement:

Date/Time:

12:19pm @ 21/6/18

Person Contacted:

129

Vehicle ~~IN~~ OUT

Date/Time	Action/Instruction
	(✓) Estimate
	JPA 2101 - X
	SGS 5791J - NA / INC 18000079 / 24
	DOA: 8/12/2017
	Part by Part 4044.30 (Real: 922.70 : 129%)

REF: CTI

ASSIGNMENT

From:

Date: 22/06/2018

Veh No:

JPA 2101 Yr Regn: 9 / 13

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

JPA 2101

Make:

Yamaha Super

C.C. 114.

at Workshop m/s

Pang Scooter

Colour:

Black

A/C: Insured / Std / NI / NA

of 81k 1006, Bkf merch lane 2 # 01-06

Sp. Reading

89460

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

PMYK60540D 0116125

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:


F:

70/90K17

R:

80/90K17

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxxis

IDAC Accident Rpt:

Consistent? : Yes or No

Front

Rear

GIA / PR Seen:

Consistent? : Yes or No

R/Bal.

5

mm

R/Bal.

5

mm

Est. Repairs:

days

Res:

Yes or No

L/Bal.

mm

L/Bal.

mm

Lum Sum:

%

3 Val:

Yes or No

D.O.A.

D.O.I.

22/6/18 @ 1730.

Survey held at

Pang Scooter

CA / REV / REP. / 24 HRS

lup

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 01 OCT 2018

Date/Time: File Pass to?



Prel. Report

Days Of Repair:

5

11/10 Typist



Final Report

Resurvey No. of Trip:

Date/Time: File Return to?

Survey Fee:

220

Transportation

) \$ + RS. \$

) Photos

) Others

TOTAL

220

Report Format :

TP

Lump Sum / L.S. (\$)

4044.30

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Jun 2018		21 Jun 2018 10:17 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	UNKNOWN		
Vehicle Reg. No.:	JPQ2101	Date of Loss:	06/08/2017 00:00 - :59
Claim Type:	TP / SNM17D04650C02	Policy/Cover Note No.:	DMPCSN3104621600
Vehicle Reg. No. (Insured):	SG55791J	Policy No. (Claimant):	
		Excess:	\$0.00
Repairer:	Pang Scooter Service (HQ) BLK 1006 BUKIT MERAH LANE 2 #01-06, 159762 Bukit Merah - Tel: 62714618		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/07/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

JABATAN PENGANGKUTAN JALAN MALAYSIA

PERAKUAN PENDAFTARAN KENDERAAN



NO. PENDAFTARAN:

JPQ2101

No. Siri B 5035502

Nama Pemunya
Berdaftar

CHIA CHEE WEE

840420016677

[MAL]

Alamat

NO. 4 JALAN SERI KAYA 1 SEGAMAT BARU
85000 SEGAMAT JOHOR D.T.

No. Enjin

G399EE116125

No. Casis

PMYKG0540D0116125

Buatan

YAMAHA

Nama Model

YAMAHA 135LC

Keupayaan Enjin

135 S.P

Bahan Bakar

PETROL

Warna

HITAM

Kelas Kegunaan

MOTOSIKAL

Jenis Badan

MOTOSIKAL

Tahun Dibuat

2013

Tarikh Pendaftaran

13/09/2013

Status Pemunya

PERSENDIRIAN

Muatan Tempet

Duduk

2

Kadar Lesen

Kenderaan Motor

6 bulan

12 bulan

RM2.00

RM2.00

B.D.M/B.G.K

B.T.T.

Berat Kerb

B.T.M

B.G.1

B.G.2

B.G.3

B.G.4

B.G.5

B.G.6

B.G.7

B.G.8

B.G.9

B.G.10

B.G.11

B.G.12

Tandatangan Pemunya Berdaftar

Perakuan Pendaftaran ini dikeluarkan

oleh Pengarah JPJ Negeri

JPJ CAWANGAN SEGAMAT

PENASANGAN TEMPATAN

UNTUK KEGUNAAN PEJABAT

- 1.
- 2.
- 3.
- 4.
- 5.
- 6.
- 7.
- 8.
- 9.
- 10.
- 11.
- 12.
- 13.

NOTA PENTING

1. Simpan perakuan ini di tempat yang selamat. Jika perakuan ini hilang, anda dikehendaki melaporkan kepada balai polis dengan segera dan memohon salinan perakuan pendaftaran daripada Pengarah Jabatan Pengangkutan Jalan (JPJ).
2. Semak butir-butir kenderaan di muka ini dan laporkan dengan segera kepada Pengarah JPJ jika terdapat sebarang perubahan.
3. Lesen kenderaan motor yang sah hendaklah sentiasa dipamerkan. Anda boleh membaharui lesen 60 hari sebelum tempohnya tamat.
4. Anda dikehendaki melaporkan secara bertulis dengan segera kepada Pengarah JPJ sekiranya kenderaan anda tidak berlesen.
5. Jika anda menjual kenderaan, serahkan perakuan pendaftaran ini kepada pembeli. Anda dan pembeli dikehendaki mengisi dan mengemukakan borang JPJK3/JPJK3A kepada Pengarah JPJ dalam tempoh tujuh hari dari tarikh penjualan itu.
6. Pemunya berdaftar kenderaan adalah bertanggungjawab di atas segala urusan berkaitan dengan kenderaan sehingga pertukaran milikan telah disempurnakan dan kenderaan telah didaftarkan dengan nama pemilik baru.
7. Jika alamat anda bertukar, kemukakan perakuan pendaftaran ini kepada Pengarah JPJ dalam tempoh tujuh hari dari tarikh pertukaran itu.

BAYARAN-BAYARAN

1	109061 13092013 10:05:48 031000 N 16-18541 ROZAINI 00151 TU 0 00151 JPQ2101 12/09/2013 2101000RM*****5.00 RM*****5.00	11	
2	109061 13092013 10:05:55 035600 N 16-18542 ROZAINI 00152 TU 0 00152 JPQ2101 12/09/2013 2201000RM*****2.00 RM*****2.00	12	
3	0101061 20/08/2014 15:06:01 VELO2010 N FARIDAH 053901 1 0 JPQ2101 12/09/2016 2201000RM*****2.00 RM*****2.00	13	
4	0101061 07/09/2015 16:13:10 VELO2010 N SUSAN 070662 1 0 JPQ2101 12/09/2016 2201000RM*****2.00 RM*****2.00	14	
5		15	
6		16	
7		17	
8		18	
9		19	
10		20	

PERTUKARAN-PERTUKARAN MILIKAN DAN ALAMAT

1		No. K.P./Def. Niaga/Sykt	Tandatangan Pemunya Berdaftar
2		No. K.P./Def. Niaga/Sykt	Tandatangan Pemunya Berdaftar
3		No. K.P./Def. Niaga/Sykt	Tandatangan Pemunya Berdaftar
4		No. K.P./Def. Niaga/Sykt	Tandatangan Pemunya Berdaftar
5		No. K.P./Def. Niaga/Sykt	Tandatangan Pemunya Berdaftar

REKOD-REKOD PEMERIKSAAN

1	5	9
2	6	10
3	7	11
4	8	12



SINGAPORE POLICE FORCE



T/20170808/2188

1 of 3

Police Station Of Origin:
Bukit Merah East N.P.C
A 391 New Bridge Road Police Cantonment
Complex SINGAPORE 088762
Tel No: 1800-2369999

Report No. T/20170808/2188

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/08/2017 23:53	Vide Report No.: A/20170806/0183	Station Diary No.: 236
--	-------------------------------------	---------------------------

Informant's Particulars

Name of Informant: CHIA CHEE WEE	Address: 67 Jalan Jaga Putra 3/5 Taman Jp Perdana 81100		
ID Type / ID No.: FIN NO / G7899123U	Contact No.: Home/Office: Mobile: 93718516		
Nationality: MALAYSIAN	Email:		
Sex: Male	Age: 33	Date of Birth: 20/04/1984	Type of Informant: Rider
Race: Chinese	Language: Chinese		Institution / School Name:
Occupation: Mover	Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 06/08/2017 18:15	Type of Location: X-Junction
Location: Along Road 1 CANTONMENT ROAD				
Junction				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JPQ2101	Motorcycle				Seriously Damaged	1
SGS5791J	Car				Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20170808/2188

2 of 3

Report No. T/20170808/2188

Police Station Of Origin:
Bukit Merah East N.P.C
A 391 New Bridge Road Police Cantonment
Complex SINGAPORE 088762
Tel No: 1800-2369999

CONTINUATION OF REPORT

Rider			
Name	CHIA CHEE WEE	ID No.	G7899123U
Related Vehicle	NIL	Contact No.	93718516
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 6/8/2017 at about 1800hrs, i was riding a motorcycle(JPQ2101) along Outram road planning to turn right into New bridge road to go to PSA. As it was green light, i wanted to turn right and when i was about to turn right, a car(SGS5791J) who was going straight beat the red light and knocked into me and my vehicle and the impact made me flew a distance.



**SINGAPORE
POLICE FORCE**



T/20170808/2188

3 of 3

Report No. T/20170808/2188

Police Station Of Origin:
Bukit Merah East N.P.C
A 391 New Bridge Road Police Cantonment
Complex SINGAPORE 088762
Tel No: 1800-2369999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

A /
DARREN NG CHUAN ZHEN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /

Contact No.:

Authentication Stamp
NP168

Singapore

Signature Of Informant:

Date/Time:
08/08/2017 23:53

Classification Of Case:



SINGAPORE
POLICE FORCE

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000
Fax +65 6547 4900
www.police.gov.sg

Our Ref
Date

TP/IP/41125/2017
26 APRIL 2018

CHIA CHEE WEE
67 Jalan Jaga Putra
3/5 Taman JP Perdeang
81100

Dear Sir,

**ROAD TRAFFIC ACCIDENT INVOLVING JPQ2101 AND SGS5791J ALONG EU TONG
SEN STREET JUNCTION OUTRAM ROAD ON 06 AUGUST 2017 AT ABOUT 6.11PM**

I refer to the above Traffic Accident.

2 We have completed investigation into the case. Our investigation shows that the offence of ***Dangerous Driving under Section 64(1) of the Road Traffic Act Chapter 276***, has been disclosed against ***the driver of SGS5791J***. Court action has been initiated against the ***driver*** for the said offence.

3 Please be informed that our decision does not preclude you from pursuing civil claims.

Yours faithfully,


DYLAN MA, SSG
INVESTIGATION OFFICER
for HEAD INVESTIGATION
TRAFFIC POLICE

PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762

Tel : 6271 4618

Fax : 6273 2632

Taujikh 97495749
22/6/18 @ 1730
Resolving new parts
sur @ /kkantam
5 days

ESTIMATE REPAIR

BIKE NO.: JPQ 2101

DATE ACCIDENT : 06.08.2017

MAKE / MODEL : YAMAHA/JUPITER

[illegible]

Please
confirm

5 days

PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762

Tel : 6271 4618

Fax : 6273 2632

ESTIMATE REPAIR

BIKE NO.: JPQ 2101

DATE ACCIDENT : 06.08.2017

MAKE / MODEL : YAMAHA/JUPITER

Tanji 97495749
22/6/18 @ 1730

Resurvey new parts

1/10/18 5 days
sua @ kkan.com

S/No	DESCRIPTION	AMOUNT
1	R/H REAR FOOT REST	\$ bt 38.00
2	R/H REAR FOOT REST BRACKET	\$ bt 95.00
3	MUFFLER COMP	\$ dd 495.00
4	FRONT COWLING	\$ can 120.00
5	FRONT CENTRE COWLING	\$ cut 95.00
6	F PANEL CENTRE (B)	\$? 110.00
7	R/H LEG SHIELD	\$ can 95.00
8	L/H LEG SHIELD	\$ can 95.00
9	R/H UNDLER LEG SHIELD	\$ can 70.00
10	L/H UNDLER LEH SHIELD	\$? 70.00
11	REAR BOX GIV	\$ mis 230.00
12	BOX BRACKET	\$ can 120.00
13	RADIATOR COMP	\$ dd 295.00
14	RADIATOR FAN	\$ can 110.00
15	RADIATOR BRACKET	\$ bt 45.00
16	COOLANT	\$ can 45.00
17	HANDLER BAR	\$? 85.00
18	HANDLER BRACKET	\$? 65.00
19	UNDLER BRACKET	\$? 185.00
20	STEERING CON	\$? 100.00
21	FORK INNER TUBE x2	\$? 180.00
22	FORK OIL SEAL x2	\$? 50.00
23	FORK OIL	\$? 60.00
24	FRONT WHEEL SHAFT	\$? 45.00
25	FRONT WHEEL RIM	\$? 380.00
26	FRONT BRAKE DISC	\$? 165.00
27	FRONT FENDER	\$ can 95.00
28	HEAD LIGHT	\$? 135.00
29	HEAD LIGHT COVER	\$ cut 65.00
30	BRAKE LEVER	\$ cut 25.00
31	R/H HANDLER END	\$ cut 28.00
32	R/H MIRROR	\$ can 65.00
33	FRONT FOOT REST BRACKET	\$ bt 98.00
34	FRONT FOOT REST RUBBER	\$ by 15.00
35	BRAKE PEDAL	\$ bt 68.00
36	PRESS BODY *photo	\$ 200 450.00
TRANSPORT		\$ 60 80.00
LABOUR		\$ 250 400.00
Total		\$ 4,967.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NOTES

LTA will inform the registered vehicle owner on the status of the GIRO application (i.e. whether successful or rejected). Please allow approximately 1 month for the processing of the GIRO application.
Please continue to renew the vehicle's road tax through other renewal channels until the registered vehicle owner receives a notification letter from LTA that the GIRO application is approved.

The Account Holder(s)' bank will make the necessary deductions from the bank account on LTA's instructions. The deduction will be reflected as "LTA" in the passbook/bank statement.

About 1 month before the GIRO deduction date, LTA will advise the owner of the date when the GIRO application must be made. All the prerequisites that must be met by the stipulated deadline and the GIRO deduction date. Please ensure that the bank or by LTA for each failed deduction. If there is an unsuccessful GIRO deduction, the registered vehicle owner will receive a notice to renew the road tax through other channels. Late renewal fee will be imposed if a vehicle road tax is renewed after its expiry date.

Registered vehicle owners may wish to consider the following before selecting their preferred GIRO deduction date:

PANG SCOOTER SERVICE

Box 1006 Bukit Merah Lane 2 #01-06 Singapore 159701

Tel : 6271 4618 Fax : 6273 2632

ESTIMATE REPAIR

To deduct Road Tax on:

Deadline to fulfil prerequisites before current road tax expiry date

(e.g. Insurance, Vehicle

BIKE NO.: JPO 2101

At least 5 working days

Expiry Date

At least 10 working days

5 Days before DATE ACCIDENT: 08.08.2017

At least 15 working days

10 Days before Expiry Date

MAKE / MODEL: YAMAHA/JUPITER

Approved GIRO arrangements will continue to be in effect until the vehicle is transferred, deregistered, or when the registered vehicle owner writes in to notify LTA to terminate it. To terminate the registered vehicle owner has to write to the LTA reservation below. LTA reserves the right to cancel the GIRO arrangement at any time without assigning any reasons for such cancellation. If updated contact information are provided on this form, LTA will update our records accordingly. For more information on road tax, please visit www.lta.gov.sg

Sl. No.	DESCRIPTION	Amount
1	R/H REAR FOOT REST	25.00
2	R/H REAR FOOT REST BRACKET	25.00
3	MUFFLER COMP	105.00
4	FRONT COWLING	100.00
5	FRONT CENTRE COWLING	25.00
6	F PANEL CENTRE (W)	25.00
7	R/H LEG SHIELD	25.00
8	L/H LEG SHIELD	25.00
9	R/H UNDRLR LEG SHIELD	25.00
10	L/H UNDRLR LEG SHIELD	25.00
11	REAR BOX GIV	25.00
12	BOX BRACKET	25.00
13	RADIATOR COMPRESS REPLY SERVICE	25.00
14	RADIATOR FAN PERMIT NO. 01580	25.00
15	RADIATOR BRACKET	25.00
16	COOLANT	25.00
17	HANDLER BAR	25.00
18	HANDLER BRACKET	25.00
19	UNDER BRACKET	25.00
20	STEERING COM	25.00
21	FORK INNER TUBE x2	25.00
22	FORK OIL SEAL	25.00
23	FORK OIL	25.00
24	FRONT WHEEL SHAFT	25.00
25	FRONT WHEEL RIM	25.00
26	FRONT BRAKE DISC	25.00
27	FRONT FENDER	25.00
28	HEAD LIGHT	25.00
29	HEAD LIGHT COVER	25.00
30	BRAKE LEVER	25.00
31	R/H HANDLER END	25.00
32	R/H MIRROR	25.00
33	FRONT FOOT REST BRACKET	25.00
34	FRONT FOOT REST RUBBER	25.00
35	BRAKE PEDAL	25.00
36	PRESS BODY	25.00

stage will be paid by dresser. For posting in Singapore only

RENEW YOUR ROAD TAX MANUALLY IF YOUR ROAD TAX PROCESSING OF THIS APPLICATION TAKES ABOUT 1 MONTH

Accepted
Please Confirm

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Jun 2018		21 Jun 2018 10:17 Edit Adj Rpt	S\$4,044.30 Edit Estimates	S\$4,044.30 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	UNKNOWN								
Vehicle Reg. No.:	JPQ2101	Date of Loss:	06/08/2017 00:00 - :59 [46 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM17D04650C02	Policy/Cover Note No.:	DMPCSN3104621600						
Vehicle Reg. No. (Insured):	SGS5791J	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Pang Scooter Service (HQ) BLK 1006 BUKIT MERAH LANE 2 #01-06, 159762 Bukit Merah - Tel: 62714618								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 02/07/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***JPQ2101 (SNM17D04650C02)**

[SGS5791J]

TP

UNKNOWN

Aug 6 2017 12:00AM

[-]

Pang Scooter Service

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/10/18 09:23	General View	 Load JPG	☒
2	03/10/18 09:23	General View	 Load JPG	☒
3	03/10/18 09:23	General View	 Load JPG	☒
4	03/10/18 09:23	General View	 Load JPG	☒
5	03/10/18 09:23	General View	 Load JPG	☒
6	03/10/18 09:23	General View	 Load JPG	☒
7	03/10/18 09:23	General View	 Load JPG	☒
8	03/10/18 09:23	General View	 Load JPG	☒
9	03/10/18 09:23	General View	 Load JPG	☒
10	03/10/18 09:23	General View	 Load JPG	☒
11	03/10/18 09:23	General View	 Load JPG	☒
12	03/10/18 09:23	General View	 Load JPG	☒
13	03/10/18 09:23	General View	 Load JPG	☒
14	03/10/18 09:23	General View	 Load JPG	☒
15	03/10/18 09:23	General View	 Load JPG	☒
16	03/10/18 09:23	General View	 Load JPG	☒
17	03/10/18 09:23	General View	 Load JPG	☒
18	03/10/18 09:23	General View	 Load JPG	☒
19	03/10/18 09:23	General View	 Load JPG	☒
20	03/10/18 09:23	General View	 Load JPG	☒
21	03/10/18 09:23	General View	 Load JPG	☒
22	03/10/18 09:23	General View	 Load JPG	☒
23	03/10/18 09:23	General View	 Load JPG	☒
24	03/10/18 09:23	General View	 Load JPG	☒
25	03/10/18 09:23	General View	 Load JPG	☒
26	03/10/18 09:23	General View	 Load JPG	☒
27	03/10/18 09:23	General View	 Load JPG	☒
28	03/10/18 09:23	General View	 Load JPG	☒
29	03/10/18 09:23	General View	 Load JPG	☒
30	03/10/18 09:23	General View	 Load JPG	☒
31	03/10/18 09:23	General View	 Load JPG	☒
32	03/10/18 09:23	General View	 Load JPG	☒
33	03/10/18 09:23	General View	 Load JPG	☒
34	03/10/18 09:23	General View	 Load JPG	☒
35	03/10/18 09:23	General View	 Load JPG	☒
36	03/10/18 09:23	General View	 Load JPG	☒
37	03/10/18 09:23	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	03/10/18 09:23	General View	 Load JPG	☒
39	03/10/18 09:23	General View	 Load JPG	☒
40	03/10/18 09:23	General View	 Load JPG	☒
41	03/10/18 09:23	General View	 Load JPG	☒
42	03/10/18 09:23	General View	 Load JPG	☒
43	03/10/18 09:23	General View	 Load JPG	☒
44	03/10/18 09:23	General View	 Load JPG	☒
45	03/10/18 09:23	General View	 Load JPG	☒
46	03/10/18 09:23	General View	 Load JPG	☒
47	03/10/18 09:23	General View	 Load JPG	☒
48	03/10/18 09:23	General View	 Load JPG	☒
49	03/10/18 09:23	General View	 Load JPG	☒
50	03/10/18 09:23	General View	 Load JPG	☒
51	03/10/18 09:23	General View	 Load JPG	☒
52	03/10/18 09:23	General View	 Load JPG	☒
53	03/10/18 09:23	General View	 Load JPG	☒
54	03/10/18 09:23	General View	 Load JPG	☒
55	03/10/18 09:23	General View	 Load JPG	☒
56	03/10/18 09:23	General View	 Load JPG	☒
57	03/10/18 09:23	General View	 Load JPG	☒
58	03/10/18 09:23	General View	 Load JPG	☒
59	03/10/18 09:23	General View	 Load JPG	☒
60	03/10/18 09:23	General View	 Load JPG	☒
61	03/10/18 09:23	General View	 Load JPG	☒
62	03/10/18 09:23	General View	 Load JPG	☒
63	03/10/18 09:23	General View	 Load JPG	☒
64	03/10/18 09:23	General View	 Load JPG	☒
65	03/10/18 09:23	General View	 Load JPG	☒
66	03/10/18 09:23	General View	 Load JPG	☒
67	03/10/18 09:23	General View	 Load JPG	☒
68	03/10/18 09:23	General View	 Load JPG	☒
69	03/10/18 09:23	General View	 Load JPG	☒
70	03/10/18 09:23	General View	 Load JPG	☒
71	03/10/18 09:23	General View	 Load JPG	☒
72	03/10/18 09:23	General View	 Load JPG	☒
73	03/10/18 09:23	General View	 Load JPG	☒
74	03/10/18 09:23	General View	 Load JPG	☒
75	03/10/18 09:23	General View	 Load JPG	☒
76	03/10/18 09:23	General View	 Load JPG	☒
77	03/10/18 09:23	General View	 Load JPG	☒
78	03/10/18 09:23	General View	 Load JPG	☒
79	03/10/18 09:23	General View	 Load JPG	☒
80	03/10/18 09:23	General View	 Load JPG	☒
81	03/10/18 09:23	General View	 Load JPG	☒
82	03/10/18 09:23	General View	 Load JPG	☒
83	03/10/18 09:23	General View	 Load JPG	☒
84	03/10/18 09:23	General View	 Load JPG	☒
85	03/10/18 09:23	General View	 Load JPG	☒
86	03/10/18 09:23	General View	 Load JPG	☒
87	03/10/18 09:23	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	03/10/18 09:23	General View	 Load JPG	☒
89	03/10/18 09:23	General View	 Load JPG	☒
90	03/10/18 09:23	General View	 Load JPG	☒
91	03/10/18 09:23	General View	 Load JPG	☒
92	03/10/18 09:23	General View	 Load JPG	☒
93	03/10/18 09:23	General View	 Load JPG	☒
94	03/10/18 09:23	General View	 Load JPG	☒
95	03/10/18 09:23	General View	 Load JPG	☒
96	03/10/18 09:23	General View	 Load JPG	☒
97	03/10/18 09:23	General View	 Load JPG	☒
98	03/10/18 09:23	General View	 Load JPG	☒
99	03/10/18 09:23	General View	 Load JPG	☒
100	03/10/18 09:23	General View	 Load JPG	☒
101	03/10/18 09:23	General View	 Load JPG	☒
102	03/10/18 09:23	General View	 Load JPG	☒
103	03/10/18 09:23	General View	 Load JPG	☒
104	03/10/18 09:23	General View	 Load JPG	☒
105	03/10/18 09:23	General View	 Load JPG	☒
106	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
107	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
108	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
109	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
110	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
111	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
112	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
113	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
114	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
115	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
116	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
117	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
118	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
119	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
120	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
121	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
122	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
123	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
124	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
125	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
126	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
127	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
128	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
129	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
130	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
131	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
132	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
133	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
134	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
135	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
136	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
137	03/10/18 09:24	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
139	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
140	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
141	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
142	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
143	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
144	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
145	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
146	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
147	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
148	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
149	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
150	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
151	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
152	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
153	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
154	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
155	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
156	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
157	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
158	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
159	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
160	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
161	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
162	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
163	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
164	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
165	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
166	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
167	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
168	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
169	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
170	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
171	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
172	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
173	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
174	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
175	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
176	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
177	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
178	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
179	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
180	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
181	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
182	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
183	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
184	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
185	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
186	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
187	03/10/18 09:24	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
188	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
189	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
190	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
191	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
192	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
193	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
194	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
195	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
196	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
197	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
198	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
199	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
200	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
201	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
202	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
203	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
204	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
205	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
206	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
207	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
208	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
209	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
210	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
211	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
212	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
213	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
214	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
215	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
216	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
217	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
218	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
219	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
220	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
221	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
222	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
223	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
224	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
225	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
226	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
227	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
228	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
229	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
230	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
231	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
232	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
233	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
234	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
235	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
236	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
237	03/10/18 09:24	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
238	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
239	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
240	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
241	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
242	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
243	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
244	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
245	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
246	03/10/18 09:24	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/06/18 10:18	PRS CONTACT	 Load PDF	
2	21/06/18 10:18	REPAIR ESTIMATE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18011251/T1TD3E2

Date: 03/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3104621600

Claimant Vehicle
No : JPQ2101Insured Vehicle
No : SGS5791J

Date of Loss: 06/08/2017

Nature of Claim: TP

Claim
No: SNM17D04650C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JPQ2101

Make & Model: YAMAHA JUPITER 115 Z1, 114cc

Reg. Date: 13/09/2013 (Man. Year: 2013)

Colour: Black

Engine Capacity: 135 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: G399EE116125

Chassis No: PMYKG0540D0116125

Odometer: 89460 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90 R17

Rear Tyre Size: 80/90 R17

Front Left Side: Maxxis 5 mm

Rear Left Side: Maxxis 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,037.00	3,534.30	502.70	12.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	930.00	510.00	420.00	45.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	4,967.00	4,044.30	922.70	18.58

INSPECTION

Date of Assignment: 21/06/2018

Date Inspected: 22/06/2018 Inspected At:

Pang Scooter Service (HQ)
BLK 1006 BUKIT MERAH LANE 2 #01-06
Singapore 159762

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Oct 2018)	
Parts:	N/A	YAMAHA JUPITER 115 Z1 114cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JPQ2101)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*R/H REAR FOOT REST	Bent	38.00 F	*38.00 FL
2	1		*R/H REAR FOOT REST BRACKET	Bent	95.00 F	*95.00 FL
3	1		*MUFFLER COMP	Dented	495.00 F	*495.00 FL
4	1		*FRONT COWLING	Cracked	120.00 F	*120.00 FL
5	1		*FRONT CENTRE COWLING	Cut	95.00 F	*95.00 FL
6	1		*F PANEL CENTRE (B)	Not Necessary	110.00 F	*- FL
7	1		*R/H LED SHIELD	Cracked	95.00 F	*95.00 FL
8	1		*L/H LED SHIELD	Cracked	95.00 F	*95.00 FL
9	1		*R/H UNDLER LEG SHIELD	Cracked	70.00 F	*70.00 FL
10	1		*L/H UNDLER LEG SHIELD	Deformed	70.00 F	*70.00 FL
11	1		*REAR BOX GIV	Missing	230.00 F	*230.00 FL
12	1		*BOX BRACKET	Cracked	120.00 F	*120.00 FL
13	1		*RADIATOR COMP	Dented	295.00 F	*295.00 FL
14	1		*RADIATOR FAN	Cracked	110.00 F	*110.00 FL
15	1		*RADIATOR BRACKET	Bent	45.00 F	*45.00 FL
16	1		*COOLANT	Necessary	45.00 F	*45.00 FL
17	1		*HANDLER BAR	Bent	85.00 F	*85.00 FL
18	1		*HANDLER BRACKET	Bent	65.00 F	*65.00 FL
19	1		*UNDLER BRACKET	Bent	185.00 F	*185.00 FL
20	1		*STEERING CON	Distorted	100.00 F	*100.00 FL
21	2		*FORK INNER TUBE	Bent	180.00 F	*180.00 FL
22	2		*FORK OIL SEAL	Necessary	50.00 F	*50.00 FL
23	1		*FORK OIL	Necessary	60.00 F	*60.00 FL
24	1		*FRONT WHEEL SHAFT	Bent	45.00 F	*45.00 FL
25	1		*FRONT WHEEL RIM	Bent	380.00 F	*380.00 FL
26	1		*FRONT BRAKE DISC	Bent	165.00 F	*165.00 FL
27	1		*FRONT FENDER	Cracked	95.00 F	*95.00 FL
28	1		*HEAD LIGHT	Cut	135.00 F	*135.00 FL
29	1		*HEAD LIGHT COVER	Cut	65.00 F	*65.00 FL
30	1		*BRAKE LEVER	Cut	25.00 F	*25.00 FL
31	1		*R/H HANDLER END	Cut	28.00 F	*28.00 FL
32	1		*R/H MIRROR	Cracked	65.00 F	*65.00 FL
33	1		*FRONT FOOT REST BRACKET	Bent	98.00 F	*98.00 FL
34	1		*FRONT FOOT REST RUBBER	Torn	15.00 F	*15.00 FL
35	1		*BRAKE PEDAL	Bent	68.00 F	*68.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,037.00	3,927.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	392.70

Total Parts (\$\$)	4,037.00	3,534.30
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PRESS BODY	New	450.00	200.00
2	TRANSPORT	New	80.00	60.00
3	LABOUR	New	400.00	250.00
Gross Labour Cost (S\$)			930.00	510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >