

ASS. REC. BY:

REF:

CS/MST/18011287/Dtb⁷²

Special Instruction:

Surveyor

Merimen

ASSIGNMENT (Office)

From (Person):

Muhd Ashik

of

MSTH

Date/Time: 21062018 335pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 3811G

Insured:

SKB 6729B

at Workshop m/s

Chunni Motor

Tel:

6542 5119

of

Blk 10 AMK Ind Park 2A #03-19

Policy No:

27721681QMY

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

19062018

(Client's Record)

CA / REV / REP. / REV 24 HRS WPI

22062018

H.O.D. Endorsement:

Date/Time:

21062018 337pm

Person Contacted:

Irene

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SHA 3811G - NS/INC13007443/Htu2	DA: 190413
	SKB 6729B - CVI/VALIS011246/Bv	DA: 190618
26/6-	Revert via merimen preli advise.	

Answer

COE Nov 2024

Veh No: SHA 3811G Yr Regn: 2016 / Nov

Type: M/Car / M/Cycle / Bus / Van / Lorry / (1) / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.C. 1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: / T/Radio: Insured / Std / NI / NA

Eng/No: 22RR962379

C/No: JTDK B3Fu503537475

Gen. Cond: 6 / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or Dem

Brake: 1 / Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: — " —

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *Westlake*

Vehicle: IN / OUT

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	19/06/2018	D.O.I.	22/06/2018
Survey held at		Chunni AMK	
Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or			
O/S Front 7 O/S Body 7 O/S Rev			
The U/C / Chassis frame / Body Structure affected due to collision			

Date / Time	Action / Instruction
03/08/18	<p>MSIG 8KB 6729B</p> <p>Pending estimate - Rgn cost exceed 30k</p> <p>Invoice 2/5 32000/- with 23 dgs 2 y (Red: 29297.91 47%)</p> <p><i>[Signature]</i></p> <p>21/8/2018</p>

☐ : Prel. Report
☒ : Final Report

Resurvey No. of Trip: 2

21

Lump Sum / I.B.I: (\$ 32,000)

☐ Weekend (\$)

TOTAL

300
10

310

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jun 2018		21 Jun 2018 15:35 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	PHYLLIS FOO SHER LENG, ID: S1805337C			[Created by Insurer]
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R			
Vehicle Reg. No.:	SHA3811G	Date of Loss:	19/06/2018 21:00 - :59 [19 Months and 1 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP	Policy/Cover Note No.:	27721681QMY (Comprehensive) Coverage: 26/07/2017 - 25/07/2018	
Vehicle Reg. No. (Insured):	SKB6729B	Policy No. (Claimant):		
		Excess:	S\$3,500.00	
Repairer:	Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6542 7162			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/06/2018]			
Driver/Custodian (Insured):	PHYLLIS FOO SHER LENG (51 / Female), NRIC: S1805337C			
Adj Asg. Remarks:	SURVEY AGREE ON SJE - REQUEST TO ASSIGN LKK LIABILITY: 50%/50% CONTACT: MS LYNN/MS IRENE 6542 5119/6542 7162			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail



ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 26 Jun 2018

Preliminary Advice

Insured Vehicle No	: SKB6729B	Accident Date	: 19/06/2018
TP Vehicle No	: SHA3811G	Assignment Date	: 21/06/2018
Make	: TOYOTA PRIUS	Est. Duration of Repair	: 14.00
Date of Inspection	: 22/06/2018		
Inspection At	: CHUNNI MOTOR WORK PTE LTD (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front, o/s bony and o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:SS	61,297.91
Revised Amount	:SS	13,926.88
Check Items (Estimated)	:SS	13,600.75
Total	:SS	27,527.63

Lump Sum Repair	:SS
-----------------	-----

Total Loss Consideration

New for Old Value	:SS
Pre-Accident Value	:SS
COE / PARF Rebate	:SS
Salvage Value	:SS
Margin for Repair	:SS

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

MCD019079652 / ComfortDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 20/06/2018 16:12
 SUBMITTED BY: Janet Lim Slang Gek

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 20/06/2018 16:12
 Date Of Accident 19/06/2018 21:30
 Exact Location Of Accident LORONG CHUAN T JUNCTION OF SERANGOON AVE 3
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHA3811G
 Insured/Policyholder
 Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD
 Co Reg No 199303821R
 Email Address FLEETSAFETY@CDGTAXI.COM.SG
 Mobile Phone No
 Alternative Phone No OFFICE-65508768
 Vehicle Particulars
 Manufacturer TOYOTA
 Model PRIUS HYBRID
 Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category TAXI
 Insurance Company
 Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD
 Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
 Fleet Policy YES
 Policy Number MCOM0015
 Cover Note Number
 Driver
 Name of Driver CHENG CHER KWAN
 NRIC No S00733361
 Date Of Birth 11/10/1952
 Occupation OUTDOOR
 Date Of Driving Pass 27/03/1974
 Driving Experience 44 YEARS AND 2 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-93370363
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address BLK 407 SERANGOON AVENUE 1
#12-89
Postcode 550407
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: : -
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name SERANGOON NEIGHBOURHOOD POLICE CENTRE
Police Station Address ROAD: 50 SERANGOON AVE 2 #01-02 , POSTCODE: 556129 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-4880999 - FAX NO: 64883561
Was notice of Intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT NO: T/20180620/2029 * TYPE OF ACCIDENT :- HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKB6729B
Vehicle Make/Model/Colour TOYOTA
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver UNKNOWN
NRIC/Passport Number
Contact Number 96382266
Address

Postcode

Insurance Company Name

Nature Of Damage

FRONT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

LAMP POST

Vehicle Category

NA/UNKNOWN

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

CHENG CHER KWAN

Approximate Age

Injuries Sustain

NECK

Injured person in which vehicle?

SHA3811G

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

CHOY JIA JIE (PAX)

Approximate Age

Injuries Sustain

NOSE

Injured person in which vehicle?

SHA3811G

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


PORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 20.06.2018 @ 15:30 Hrs


Reporting Centre Personnel's Signature
Name: *Rubbini*
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report : T/20180620/2029.

The impact caused my taxi (A) to loss control and subsequently hit the lamp post.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303824R

Policyholder's Signature
Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 20.06.2018 @ 15:30 Hrs

Reporting Centre Personnel's Signature

Name: Rubbini

NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180620/2029

1 of 4

Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4880999

Report No. T/20180620/2029

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/06/2018 11:54	Vide Report No.:	Station Diary No.: 51
--	------------------	--------------------------

Informant's Particulars

Name of Informant: CHENG CHER KWAN			Address: APT BLK 407 SERANGOON AVENUE 1 #12-89 SINGAPORE 550407		
ID Type / ID No.: NRIC NO / S0073336I			Contact No.: Home/Office: Mobile: 93370363		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 65	Date of Birth: 11/10/1952	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 19/06/2018 21:30	Type of Location: T-Junction
Location: Along Road 1 LORONG CHUAN				
Along Lorong Chuan near the T-junction between Lorong Chuan and Serangoon Avenue 3				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHA3811G	Car	TOYOTA	PRIUS HYBRID 1.8 CVT	Blue	Slightly Damaged	1
SKB6729B	Car	TOYOTA	CAMRY 2.4 AUTO ABS AIRBAG	Silver	Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20180620/2029

Police Station Of Origin:

2 of 4

Serangoon N.P.C

Report No. T/20180620/2029

50 Serangoon Avenue 2 #01-02 SINGAPORE

556129

CONTINUATION OF REPORT

Tel No: 1800-4880999

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	CHENG CHER KWAN	ID No.	S0073336I
Related Vehicle	SHA3811G (Car)	Contact No.	93370363
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	19/06/2018	Date Discharge	20/06/2018
No. of Days granted Medical Leave	04	Degree of Injury	Slight
Passenger			
Name	CHOY JIA JIE	ID No.	NIL
Related Vehicle	SHA3811G (Car)	Contact No.	96667209
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 19/06/2018 at around 2130hrs, I was driving my vehicle SHA3811G (Comfort Taxi) along Lorong Chuan towards Braddell Road. The weather was clear and the road was dry. As I was reaching at the T-junction between Lorong Chuan and Serangoon Avenue 3. I noticed that the traffic light was green, and thus I continued driving forward as I wanted to travel towards braddell road. However, when I reach at the middle of the T-junction, there was a vehicle SKB6729B coming from the opposite direction and turning in to Serangoon Avenue 3, I could not avoid and thus the other vehicle had hit onto the front driver side of my vehicle. The impact was moderate, we stopped our vehicle and came out to make a check. The other driver informed that he noticed that I had signal left and thought I am driving from the slip road to Serangoon Avenue 3. When he was turning in to Serangoon Avenue 3, he noticed my vehicle was already at the middle of the road and thus he could stop in time. As such, his vehicle had hit onto my vehicle.

I would like to state that my signal was on however it was from I was turning from Boundary road to Lorong Chuan and distance was very short as such I need time to change to back to normal. The ambulance and police was here. My passenger and I was conveyed to Tan Tock Seng Hospital. I had suffered neck injury on the left side and was given a 4 days MC. There was CCTV installed inside my vehicle.



**SINGAPORE
POLICE FORCE**



T/20180620/2029

3 of 4

Police Station Of Origin:

Serangoon N.P.C

50 Serangoon Avenue 2 #01-02 SINGAPORE

556129

Tel No: 1800-4880999

Report No. T/20180620/2029

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20180620/2029

Police Station Of Origin:
Serangoon N.P.C
50 Serangoon Avenue 2 #01-02 SINGAPORE
556129
Tel No: 1800-4880999

4 of 4

Report No. T/20180620/2029

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 LAM CHEW KIT

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sgt 3 RASHIDAH BINTE AZMAN

SN 154

Contact No: 95476216

Authentication Stamp

NP158

Signature:

Singapore Police Force

Signature Of Informant:

Date/Time:

20/06/2018 11:54

Classification Of Case:

to survey by LKK

MSIG

REPAIR ESTIMATE

VEHICLE NO: SHA 3811G

DATE : 20.06.2018

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
BONNET <i>1st</i>			S 938.40	✓
BONNET HINGE (RH) <i>1st</i>			S 56.40	✓
BONNET HINGE (LH) <i>1st</i>			S 56.40	✓
RADIATOR GRILLE <i>2 NH</i>			S 438.00	✗ X
RADIATOR GRILLE EMBLEM <i>SVC</i>			S 86.50	X
LAMP ASSY, FOG, RH <i>mounting broken</i>			S 920.00	✓
LAMP ASSY, FOG, LH <i>NH</i>			S 920.00	X
FRONT BUMPER COVER <i>Dented</i>			S 490.50	✓
FRONT BUMPER REINFORCEMENT <i>2 SMC</i>			S 691.50	✓
FRONT BUMPER REINFORCEMENT ABSORBER <i>2 NH</i>			S 115.70	✗ X
FRONT BUMPER SPONGE <i>2 torn</i>			S 78.80	✓
FRONT BUMPER CENTRE GRILLE <i>broken</i>			S 301.90	✓
FRONT BUMPER CLIPS <i>NH</i>			S 22.00	✓
FRONT BUMPER SIDE RETAINER <i>ops broken n/s</i> <i>SVC</i>		S (77.00)	S 154.00	✓
FRONT UNDER COVER <i>2 torn</i>			S 180.80	✓
ENGINE UNDER COVER (RR) <i>2 broken NH</i>			S 453.10	✗ X
COVER, FRONT BUMPER HOLE, RH <i>SVC</i>			S 28.38	X
REINFORCEMENT SUB-ASSY, FRONT BUMPER LOWER <i>2 1st</i>			S 236.10	✓
SUPPORT FR BUMPER, RH <i>NH</i>			S 81.70	X
FRONT BUMPER CENTRE FRAME <i>NH</i>			S 236.90	X
BRACKET, FRONT BUMPER SIDE, RH <i>NH</i>			S 77.00	X
ABSORBER, FRONT BUMPER, LOWER (SPONGE LOWER) <i>2 NH</i>			S 127.70	✗ X
UNIT ASSY, HEADLAMP, RH (LED) <i>broken mounting</i>			S 3,413.40	✓
UNIT ASSY, HEADLAMP, LH (LED) <i>2 broken mounting</i>			S 3,413.40	✓
HEAD LAMP PANEL (RH) <i>2 Dented</i>			S 213.50	✓
TOP PANEL CENTRE <i>2 Dented</i>			S 364.90	✓
TOP PANEL SIDE, RH <i>2 1st</i>			S 69.20	✓
BRACE PANEL <i>2 1st</i>			S 75.20	✓
BRACKET, HEADLAMP MOUNTING, RH <i>2 NH</i>			S 25.50	✗ X
RADIATOR ASSY <i>NH</i>			S 1,841.80	X
RADIATOR FAN COWLING ASSY <i>NH</i>			S 661.30	X
RADIATOR BOTTOM MOUNTING <i>NH</i>			S 27.50	X
RADIATOR FAN BLADE (RH) <i>NH</i>			S 233.10	X
RADIATOR FAN MOTOR (RH) <i>NH</i>			S 543.70	X
DEFLECTOR, RADIATOR SIDE, RH <i>2 NH</i>			S 83.50	✗ X
AIR DUCT <i>NH</i>			S 129.40	X
INLET ASSY, AIR CLEANER <i>NH</i>			S 199.20	X
CONDENSER ASSY, W/RECEIVER <i>NH</i>			S 1,304.00	X
AIRCON DISCHARGE HOSE <i>NH</i>			S 386.90	X
AIRCON LIQUID HOSE & PIPE <i>NH</i>			S 580.45	X
FENDER SUB-ASSY, FRONT RH <i>SMC</i>			S 933.10	✓
FRONT HOUSING ASSY, RH <i>2 Dented</i>		13777.66	S 945.26	✓
FRONT FENDER SHIELD, RH <i>out of stock</i>			S 198.50	✓
FRONT FENDER SHIELD CLIP <i>NH</i>			S 14.90	✓
FRONT FENDER HYBRID EMBLEM, RH <i>1st</i>			S 86.50	✓
PROTECTOR, FRONT FENDER SIDE PANEL, RH <i>2 NH</i>			S 113.90	✗ X

SHA 3811G

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
GUSSET, FRONT FENDER APRON, LOWER RH HN <i>HN</i>			\$ 34.90	X X
MEMBER, FRONT APRON TO COWL SIDE, UPPER RH HN <i>HN</i>			\$ 138.40	X X
MEMBER, FRONT APRON TO COWL SIDE, LOWER FRONT RH HN <i>HN</i>			\$ 82.30	X X
PANEL SUB-ASSY, FRONT DOOR, RH <i>Devoted</i>			\$ 1,238.50	✓
FRONT DOOR HINGE UPPER, RH <i>HN</i>			\$ 82.30	X L
FRONT DOOR HINGE LOWER, RH <i>HN</i>			\$ 91.20	X L
FRONT DOOR CHECK, RH <i>HN</i>			\$ 153.52	X L
FRONT DOOR TRIMBOARD, RH <i>HN</i>			\$ 725.00	X X
FRONT DOOR OUTER MOULDING, RH <i>SVC</i>			\$ 188.60	X
MOTOR ASSY, POWER WINDOW REGULATOR, RH <i>HN</i>			\$ 941.80	X
REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH <i>HN</i>			\$ 228.40	X X
MIRROR ASSY, OUTER REAR VIEW, RH <i>Devoted</i>			\$ 1,374.00	✓
MOULDING, FRONT DOOR WINDOW FRAME, REAR RH <i>SVC</i>			\$ 53.70	X
MOULDING, REAR DOOR WINDOW FRAME, FRONT RH <i>SVC</i>			\$ 69.20	X
ROCKER PANEL, RH <i>HN</i>			\$ 559.20	X
REINFORCE SUB-ASSY, ROCKER, OUTER RH <i>HN</i>			\$ 519.80	X X
FRONT PILLAR UPPER COVER, RH <i>mounting crack</i>			\$ 96.00	✓
FRONT WINDSCREEN GLASS MOULDING <i>HN</i>			\$ 208.60	X L
FRONT WINDSCREEN GLASS PILLAR, RH <i>HN</i>			\$ 339.56	X L
WIPER TOP GARNISH <i>SVC</i>			\$ 668.32	X
WIPER SPARE TANK <i>broken</i>			\$ 183.75	X L
WIPER SPARE TANK MOTOR <i>HN</i>			\$ 242.70	X
WIPER SPARE TANK FLOAT (NECK) <i>SVC</i>			\$ 55.50	X X
FRONT WHEEL RIM (RH) <i>cut</i>			\$ 1,570.55	✓
FRONT WHEEL HUB BEARING (RH) <i>HN</i>			\$ 559.94	X L
FRONT SUSPENSION LOWER ARM (RH) <i>HN</i>			\$ 631.90	X L
FRONT SHOCK ABSORBER (RH) <i>HN</i>			\$ 398.20	X L
ABSORBER TOP MOUNTING, RH <i>HN</i>			\$ 196.20	X
FRONT DRIVE SHAFT (RH) <i>HN</i>			\$ 1,764.00	X L
RACK & PINION ASSY <i>HN</i>			\$ 1,621.30	X L
BAR, STABILIZER <i>HN</i>			\$ 352.40	X L
KNUCKLE, STEERING, RH <i>HN</i>			\$ 580.80	X L
JOINT ASSY, LOWER BALL, FRONT RH <i>HN</i>			\$ 199.98	X
END SUB-ASSY, TIE ROD, RH <i>HN</i>			\$ 159.30	X X
ENGINE UNDER COVER <i>HN</i>			\$ 457.20	X L
ENGINE CROSS MEMBER <i>HN</i>			\$ 2,504.40	X L
ENGINE MOUNTING (LH/RH) <i>HN</i>		\$ 382.70	\$ 765.40	X L
ENGINE MTG (FRONT) <i>HN</i>			\$ 174.63	X L
ENGINE MTG (REAR) <i>HN</i>			\$ 172.90	X L
GEARBOX ASSY <i>HN</i>			\$ 13,850.50	X L
ARM REST ASSY <i>HN</i>			\$ 1,389.90	X X
SENSOR, SPEED, FRONT RH <i>HN</i>			\$ 446.50	X
WIRING FRONT <i>broken</i>			\$ 8,450.50	X L
SUB TOTAL			\$ 67,071.64	
LESS 20% <i>20%</i>			\$ 13,414.33	
DISCOUNTED TOTAL			\$ 53,657.31	
			27874.88	

SHA 3811G

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
FRONT NO. PLATE <i>SVC</i>			\$ 25.00	NETT X
FRONT NO PLATE TRIM COVER <i>SVC</i>			\$ 30.00	NETT X
FRONT NO. PLATE GARNISH <i>NN</i>			\$ 99.00	NETT X
FRONT DOOR COMFORT LOGO. RH <i>HCC</i>			\$ 75.00	NETT ✓
FRONT WINDSCREEN SEALANT <i>A HCC</i>			\$ 46.00	NETT ✓
FRONT TYRE (RH) <i>SVC</i>			\$ 216.00	NETT X
		8121.00	\$ 491.00	
REAR BUMPER <i>CRACK MOUNTING</i>			\$ 458.60	✓
REAR BUMPER CLIPS <i>HCC</i>			\$ 22.00	✓
RETAINER, REAR BUMPER, SIDE, RH <i>SVC</i>			\$ 94.80	X
REAR FENDER, RH <i>Logo Dentist</i>			\$ 817.50	X ✓
REAR FENDER SHEILD (RH) <i>NN</i>			\$ 134.20	X
PANEL SUB-ASSY, REAR DOOR, RH <i>Logo Dentist</i>		2525.10	\$ 1,227.00	X ✓
REAR DOOR RUBBER SEAL OUTER <i>SVC</i>		1893.82	\$ 257.90	X
			\$ 3,012.00	
			\$ 602.40	
			\$ 2,409.60	
			\$ 50.00	NETT ✓
			\$ 80.00	NETT ✓
			\$ 130.00	
			\$ 1,700.00	1200/-
			\$ 1,400.00	800/-
			\$ 80.00	30/-
			\$ 100.00	40/-
			\$ 50.00	NN
			\$ 100.00	NN
			\$ 160.00	60/-
			\$ 200.00	180/-
			\$ 120.00	60/-
			\$ 90.00	NN
			\$ 200.00	150/-
			\$ 200.00	150/-
			\$ 120.00	80/-
			\$ 90.00	NN
			\$ 4,610.00	
			\$ 61,297.91	

LABOUR CHARGE

Panel Beating

Spray Painting Charge

Wiring Charge

Tuff Kote

Towing Charge

Remove/Refix Cushion & Upholstery Rear

Transfer of Door

Remove/Refix Undercarriage (FRT)

Four Wheel Alignment

Remove/Refix Aircon & Refill Gas

Remove/Refix Gearbox

Remove/Refix Dashboard

Remove/Refix Front Windscreen Glass

Remove/Refix Cushion & Upholstery Front

TOTAL LABOUR

ESTIMATE TOTAL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey damaged part(s) during repairs
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

40769.70
4532000/-

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18011287/DTBN2

Date: 23/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A27721681QMY
Claimant Vehicle No :	SHA3811G	Insured Vehicle No :	SKB6729B
Date of Loss:	19/06/2018	Nature of Claim:	TP
		Claim No:	561956

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA3811G	Engine No:	2ZRR962379
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU503537475
Reg. Date:	18/11/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	56,687.91	38,019.71	18,668.20	32.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,610.00	2,750.00	1,860.00	40.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	61,297.91	40,769.71	20,528.20	33.49
Approved Total (Overridden) (S\$)		32,000.00		
(S\$)	61,297.91	32,000.00	29,297.91	47.80
+ GST 7.00/7.00% (S\$)	4,290.85	2,240.00	2,050.85	47.80
Nett Amount (S\$)	65,588.76	34,240.00	31,348.76	47.80

INSPECTION

Date of Assignment:	21/06/2018
Date Inspected:	22/06/2018 Inspected At:

Chunni Motor Work Pte Ltd (HQ)
 Blk 10 Ang Mo Kio Industrial Park 2A,
 #03-19 AMK Autopoint
 Singapore 568047

Estimated Period of Repair: 23.0 days

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Aug 2018)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA3811G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	938.40 FL	*938.40 FL
2	1		*BONNET HINGE RH	Bent	56.40 FL	*56.40 FL
3	1		*BONNET HINGE LH	Bent	56.40 FL	*56.40 FL
4	1		*RADIATOR GRILLE	Not Necessary	438.00 FL	*- FL
5	1		*RADIATOR GRILLE EMBLEM	Serviceable	86.50 FL	*- FL
6	1		*LAMP ASSY,FOG,RH	Mounting Broken	920.00 FL	*920.00 FL
7	1		*LAMP ASSY,FOG,LH	Not Necessary	920.00 FL	*- FL
8	1		*FRONT BUMPER COVER	Dented	490.50 FL	*490.50 FL
9	1		*FRONT BUMPER REINFORCEMENT	Buckled	691.50 FL	*691.50 FL
10	1		*FRONT BUMPER REINFORCEMENT ABSORBER	Not Necessary	115.70 FL	*- FL
11	1		*FRONT BUMPER SPONGE	Torn	78.80 FL	*78.80 FL
12	1		*FRONT BUMPER CENTRE GRILLE	Broken	301.90 FL	*301.90 FL
13	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
14	1		*FRONT BUMPER SIDE RETAINER	O/s Broken/N/s Serviceable	154.00 FL	*77.00 FL
15	1		*FRONT UNDER COVER	Torn	180.80 FL	*180.80 FL
16	1		*ENGINE UNDER COVER RR	Not Necessary	453.10 FL	*- FL
17	1		*COVER,FRONT BUMPER HOLE,RH	Serviceable	28.38 FL	*- FL
18	1		*REINFORCEMENT SUB-ASSY,FRONT BUMPER LOWER	Bent	236.10 FL	*236.10 FL
19	1		*SUPPORT FR BUMPER RH	Not Necessary	81.70 FL	*- FL
20	1		*FRONT BUMPER CENTRE FRAME	Not Necessary	236.90 FL	*- FL
21	1		*BRACKET,FRONT BUMPER SIDE RH	Not Necessary	77.00 FL	*- FL
22	1		*ABSORBER,FRONT BUMPER LOWER (SPONGE LOWER)	Not Necessary	127.70 FL	*- FL
23	1		*UNIT ASSY,HEADLAMP RH (LED)	Mounting Broken	3,413.40 FL	*3,413.40 FL
24	1		*UNIT ASSY,HEADLAMP LH (LED)	Mounting Broken	3,413.40 FL	*3,413.40 FL
25	1		*HEAD LAMP PANEL RH	Dented	213.50 FL	*213.50 FL
26	1		*TOP PANEL CENTRE	Dented	364.90 FL	*364.90 FL
27	1		*TOP PANEL SIDE RH	Bent	69.20 FL	*69.20 FL
28	1		*BRACE PANEL	Bent	75.20 FL	*75.20 FL
29	1		*BRACKET,HEADLAMP MOUNTING,RH	Not Necessary	25.50 FL	*- FL
30	1		*RADIATOR ASSY	Not Necessary	1,841.80 FL	*- FL
31	1		*RADIATOR DAN COWLING ASSY	Not Necessary	661.30 FL	*- FL
32	1		*RADIATOR BOTTOM MOUNTING	Not Necessary	27.50 FL	*- FL
33	1		*RADIATOR FAN BLADE RH	Not Necessary	233.10 FL	*- FL
34	1		*RADIATOR FAN MOTOR RH	Not Necessary	543.70 FL	*- FL
35	1		*DEFLECTOR,RADIATOR SIDE RH	Not Necessary	83.50 FL	*- FL
36	1		*AIR DUCT	Not Necessary	129.40 FL	*- FL
37	1		*INLET ASSY,AIR CLEANER	Not Necessary	199.20 FL	*- FL
38	1		*CONDENSER ASSY,W/RECEIVER	Not Necessary	1,304.00 FL	*- FL
39	1		*AIRCON DISCHARGE HOSE	Not Necessary	386.90 FL	*- FL
40	1		*AIRCON LIQUID HOSE & PIPE	Not Necessary	580.45 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*FENDER SUB-ASSY,FRONT RH	Buckled	933.10 FL	*933.10 FL
42	1		*FRONT HOUSING ASSY,RH	Dented	945.26 FL	*945.26 FL
43	1		*FRONT FENDER SHIELD,RH	Deformed	198.50 FL	*198.50 FL
44	1		*FRONT FENDER SHIELD CLIP	Necessary	14.90 FL	*14.90 FL
45	1		*FRONT FENDER HYBRID EMBLEM,RH	Bent	86.50 FL	*86.50 FL
46	1		*PROTECTOR,FRONT FENDER SIDE PANEL,RH	Not Necessary	113.90 FL	*- FL
47	1		*GUSSET,FRONT FENDER APRON,LOWER RH	Not Necessary	34.90 FL	*- FL
48	1		*MEMBER,FRONT APRON TO COWL SIDE,UPPER RH	Not Necessary	138.40 FL	*- FL
49	1		*MEMBER,FRONT APRON TO COWL SIDE,LOWER FRONT RH	Not Necessary	82.30 FL	*- FL
50	1		*PANEL SUB-ASSY,FRONT DOOR,RH	Dented	1,238.50 FL	*1,238.50 FL
51	1		*FRONT DOOR HINGE UPPER,RH	Bent	82.30 FL	*82.30 FL
52	1		*FRONT DOOR HINGE LOWER,RH	Bent	91.20 FL	*91.20 FL
53	1		*FRONT DOOR CHECK,RH	Bent	153.52 FL	*153.52 FL
54	1		*FRONT DOOR TRIMBOARD,RH	Not Necessary	725.00 FL	*- FL
55	1		*FRONT DOOR OUTER MOULDING,RH	Serviceable	188.60 FL	*- FL
56	1		*MOTOR ASSY,POWER WINDOW REGULATOR,RH	Not Necessary	941.80 FL	*- FL
57	1		*REGULATOR SUB-ASSY,FRONT DOOR WINDOW,RH	Not Necessary	228.40 FL	*- FL
58	1		*MIRROR ASSY,OUTER REAR VIEW,RH	Damaged/Loose	1,374.00 FL	*1,374.00 FL
59	1		*MOULDING,FRONT DOOR WINDOW FRAME,REAR RH	Serviceable	53.70 FL	*- FL
60	1		*MOULDING,REAR DOOR WINDOW FRAME,FRONT RH	Serviceable	69.20 FL	*- FL
61	1		*ROCKER PANEL,RH	Not Necessary	559.20 FL	*- FL
62	1		*REINFORCE SUB-ASSY,ROCKER,OUTER RH	Not Necessary	519.80 FL	*- FL
63	1		*FRONT PILLAR UPPER COVER,RH	Mounting Cracked	96.00 FL	*96.00 FL
64	1		*FRONT WINDSCREEN GLASS MOULDING	Necessary	208.60 FL	*208.60 FL
65	1		*FRONT WINDSCREEN GLASS PILLAR RH	Dented	339.56 FL	*339.56 FL
66	1		*WIPER TOP GARNISH	Serviceable	668.32 FL	*- FL
67	1		*FRONT WHEEL RIM RH	Cut	1,570.55 FL	*1,570.55 FL
68	1		*FRONT WHEEL HUB BEARING RH	Damaged	559.94 FL	*559.94 FL
69	1		*FRONT SUSPENSION LOWER ARM RH	Distorted	631.90 FL	*631.90 FL
70	1		*FRONT SHOCK ABSORBER RH	Distorted	398.20 FL	*398.20 FL
71	1		*ABSORBER TOP MOUNTING RH	Not Necessary	196.20 FL	*- FL
72	1		*FRONT DRIVE SHAFT RH	Distorted	1,764.00 FL	*1,764.00 FL
73	1		*RACK & PINION ASSY	Damaged	1,621.30 FL	*1,621.30 FL
74	1		*BAR,STABILIZER	Distorted	352.40 FL	*352.40 FL
75	1		*KNUCKLE,STEERING RH	Distorted	580.80 FL	*580.80 FL
76	1		*JOINT ASSY,LOWER BALL,FRONT RH	Not Necessary	199.98 FL	*- FL
77	1		*END SUB-ASSY,TIE ROD,RH	Not Necessary	159.30 FL	-
78	1		*ENGINE UNDER COVER	Torn	457.20 FL	*457.20 FL
79	1		*ENGINE CROSS MEMBER	Distorted	2,504.40 FL	*2,504.40 FL
80	1		*ENGINE MOUNTING LH/RH	O/s Damaged/N/s Not Necessary	765.40 FL	*382.70 FL
81	1		*ENGINE MTG (FRONT)	Damaged	174.63 FL	*174.63 FL
82	1		*ENGINE MTG (REAR)	Bent	172.90 FL	*172.90 FL
83	1		*ARM REST ASSY	Serviceable	1,389.90 FL	*- FL
84	1		*SENSOR SPEED,FRONT RH	Not Necessary	446.50 FL	*- FL
85	1		*WIRING FRONT	Broken	8,450.50 FL	*8,450.50 FL
86	1		*REAR BUMPER	Mounting Cracked	458.60 FL	*458.60 FL
87	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
88	1		*RETAINER,REAR BUMPER SIDE RH	Serviceable	94.80 FL	*- FL
89	1		*REAR FENDER RH	Dented	817.50 FL	*817.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
90	1		*REAR FENDER SHIELD RH	Not Necessary	134.20 FL	*- FL
91	1		*PANEL SUB-ASSY, REAR DOOR, RH	Dented	1,227.00 FL	*1,227.00 FL
92	1		*REAR DOOR RUBBER SEAL OUTER	Serviceable	257.90 FL	*- FL
93	1		*WIPER SPARE TANK	Broken	183.75 FL	*183.75 FL
94	1		*WIPER SPARE TANK MOTOR	Not Necessary	242.70 FL	*- FL
95	1		*WIPER SPARE TANK FLOAT (NECK)	Serviceable	55.50 FL	*- FL
96	1		*GEARBOX ASSY	Damaged	11,080.40 FS	*8,000.00 FS
97	1		*FRONT NO PLATE	Serviceable	25.00 FS	*- FS
98	1		*FRONT NO PLATE TRIM COVER	Serviceable	30.00 FS	*- FS
99	1		*FRONT NO PLATE GARNISH	Not Necessary	99.00 FS	*- FS
100	1		*FRONT DOOR COMFORT LOGO RH	Necessary	75.00 FS	*75.00 FS
101	1		*FRONT WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
102	1		*FRONT TYRE RH	Serviceable	216.00 FS	*- FS
103	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS
104	1		*REAR DOOR COMFORT & APPS STICKER RH	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	67,934.54	47,942.61
- List Item Discount on L Items 20.00/25.00% (\$\$)	11,246.63	9,922.90
Total Parts (\$\$)	56,687.91	38,019.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,700.00	1,200.00
2	SPRAY PAINTING CHARGE	New	1,400.00	800.00
3	WIRING CHARGE	New	80.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	50.00	-
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	100.00	-
7	TRANSFER OF DOOR	New	160.00	60.00
8	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	200.00	180.00
9	FOUR WHEEL ALIGNMENT	New	120.00	60.00
10	REMOVE/REFIX AIRCON & REFILL GAS	New	90.00	-
11	REMOVE/REFIX GEARBOX	New	200.00	150.00
12	REMOVE/REFIX DASHBOARD	New	200.00	150.00
13	REMOVE/REFIX FRONT WINDSCREEN GLASS	New	120.00	80.00
14	REMOVE/REFIX CUSHION & UPHOLSTERY FRONT	New	90.00	-
Gross Labour Cost (\$\$)			4,610.00	2,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >