

INSURER

INS - CASE OWNER:

CC6/CTI1801

1294, Uhb3n2

LKK:

IDAC:

Surveyor:

Marius

DOI:

ASSIGNMENT

2/6/18

Date / Time

2/6/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKU 17327

Name of Insured:

WAWBEME LOY BOKHAN

Insured Tel No.:

HP: 9278787

Excess Sec II :SS

D.O.A: 16/6/18

Is driver the owner? (YES / NO)

(YES / NO)

Nature of Accident:

Claim No.:

SWH1801210 2LOV

Policy No.:

DMCPN70667701

Make / Model:

Minda

Place of Accident:

SLP RD TO BRADDELL RD

If NO, Driver Name / Age:

Driver Tel No.:

(V/L/YES/NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SKR 91054



INSRS: WSP: Tel: Liability: RMKS:

Fastech



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:

Date/Time	STAGE	DATE/PIC
2/6/18 vic	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
02/07/18 @ 2:51PM	After call ltr to OI:	02/07/18 - vic
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>
PRELIMINARY ADVICE Date/Time: 02/08/18 Sent By: vic	Confirm by:	
FINALIZATION Date/Time: Confirm with:	Repair Cost: 46 SS 3,000.00 (5 days) Reduction: 75 % Email <input type="checkbox"/> Call <input type="checkbox"/>	
FINAL SETTLEMENT Date/Time: 29/12/18 Confirm with: 27	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
Final Liability: % 100 (Agreed/Assessed) BOLA S/N No.: 27	If NO or B 28, Ass. Lia:	COI REPAIR-ENDED TP
Repair Cost: (w/loss) SS 3,350.00		
Loss of Rental (LOR): SS - ( days)		
Loss of Use (LOU): SS 18000 (S 80 x 6 days)		
Loss of Income (LOI): SS - (S x days)		
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/> [Tick only one]		
GLALTA Search SS 200		
Medical: SS -	1) Claim status: Normal/Reject/Private Settle	
Disbursement: SS - (e.g. Tow/Independent)	2) Report Format:	
Legal Cost SS -	3) Survey fee: 400.00	
Total: SS 3,832.00 Global Sum SS: 5,830.00		
FINAL PAYMENT Date/Time: Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Payee 1: SS 5,830.00 Name 1: FASTECH AUTO PTB LTD		
Payee 2: (Strike if N.A.) SS - Name 2: -		
Payee 3: (Strike if N.A.) SS - Name 3: -		

COPY SENT

08/11/13 wef  
ASS REQ BY: MORUJ

REF:

CRJ

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD TP WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SKR 91057  
at Workshop n/s: H.  
of \_\_\_\_\_  
Insured: SKU 17327  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

Veh No: SKR 91057 Yr Regn: 407  
Type: C Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or CA  
Make: Florida stream C.O. 1799  
Colour: white A/C: Insured / Std / NI / NA  
Sp. Reading: 163259 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: RN 61028486  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Good / Jammed / Leaked / Burnt or  
Brake: Good / Jammed / Leaked / Burnt or  
Modi: Nil / S/Rim / STD A/Rim or  
Tyre Size: F: \_\_\_\_\_  
R: 205/55R16

(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 28  
IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
CA / PR Seen: 2 Consistent?: Yes or No  
Est. Repairs: 5 days Res.: Yes or No  
Lum Sum: 20 % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS 23/4/2022  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIS / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front 6 Rear 6  
R/Bal. \_\_\_\_\_ mm R/Bal. \_\_\_\_\_ mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. 16/6/18 D.O.I. 21/6/18  
Survey held at \_\_\_\_\_  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>20/6/18</u>	<u>have G.A 3 yrs work. LTA 19965 net fozs contact n/s # 5000 with Alu. (prop: \$ 14,773.70 (75%))</u>

Date/Time, File Pass to?  : Preli. Report  : Final Report  
1) \_\_\_\_\_  
Date/Time, File Return to? \_\_\_\_\_  
2) \_\_\_\_\_  
Days Of Repair: \_\_\_\_\_  
Resurvey No. of Trip: \_\_\_\_\_  
Report Format : \_\_\_\_\_  
Lump Sum / I.B.I: (\$) \_\_\_\_\_  
Add Fee:  : Site Insp (\$)  : Interview (\$)  : Tech. Invs (\$)  : Weekend (\$)  : S + RS, SI  
Photos: \_\_\_\_\_  
Others: \_\_\_\_\_  
TOTAL \_\_\_\_\_

ASS REC BY Mercus

REF:

CT1/

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD  WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SKR 91057  
 at Workshop m/s H.  
 of SKU 17327  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SKR 91057 Yr Regn: 407  
 Type:  M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or CA  
 Make: Florida Stream C.C. 1799  
 Colour: white A/C: Insured / Std / Ni / NA  
 Sp. Reading: 163259 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: RN 61028486  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering:  Good / Jammed / Leaked / Burnt or  
 Brake:  Good / Jammed / Leaked / Burnt or  
 Modi: Nil /  SRim / STD A/Rim or  
 Tyre Size: F: \_\_\_\_\_ R: 205/55-20R16  
 BS / DUN / EXNOVA / GY / FS / LIZA /  MIO / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 28  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 CA / PR Seen: 2 Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
23/4/2022  
 Vehicle: IN / OUT

Front 6 mm Rear 6 mm  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 16/6/18 D.O.I. 21/6/18  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>have G.O.A 3 yrs work. LTA 19965 net 8035</u>

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:
Transportation:
Photos:
Others:
TOTAL

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Report Format : \_\_\_\_\_  
 Lump Sum / I.B.I: (\$ \_\_\_\_\_)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18011294/Uhb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 21-06-2018	
		Code : CTI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SKU 1732Z	Veh. Inspected	SKR 9105Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/06/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	16/06/2018	Inspection Date	21/06/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: SNM18D03103C02  
Our ref: CC6/CTI18011294/Uhb3

Date: 02.08.2018

The Motor Claims Department  
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SKR 9105Y**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21.06.2018 at the premises of M/s FASTECH AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$	19,773.70
Revised Estimate Amount	: S\$	6,259.12
"Check" Items Amount	: S\$	-
Market Value	: S\$	28,000.00
LTA Reimbursement Value	: S\$	19,965.00
Nett Value	: S\$	8,035.00

Description of Damage:

The vehicle sustained damages at the  
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

MARCUS CHUA  
Licensed Appraiser

**SELL YOUR CAR BY BIDDING**  
**HIGHEST SELLING PRICE GUARANTEED!**  
**OR GET \$100 CASH!**

honda stream Price Range Depreciation > 10 year Vehicle Type Submit Advanced Search

Home » Used Cars » Hanns Auto » Honda Stream 1.8A (COE till 06/2022)

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

**Car Rental**  
 For Private & Commercial Vehicles  
 Rental From **\$50/Day**

**Trade Online**  
 Start with \$30 Trading Bonus\*  
 Trade Forex and CFDs on  
 Indices Gold Oil Stocks  
[Read More](#)  
\*T&Cs apply. Forex and CFD trading is high risk and can result in the loss of all your invested capital.  
 OFFICIAL SPONSOR

Honda Stream 1.8A (COE till 06/2022)

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

<b>Price</b>	<b>\$28,800</b>	
<b>Depreciation</b>	\$7,200 /yr	?
<b>Reg Date</b>	21-Jun-2007 (3yrs 11mths 30days COE left)	?
<b>Manufactured</b>	2007	?
<b>Mileage</b>	-	?
<b>Transmission</b>	Auto	?
<b>Engine Cap</b>	1,799 cc	?
<b>Road Tax</b>	\$1,076 /yr	?
<b>Power</b>	103.0 kW (138 bhp) View specs of the Honda Stream	?
<b>Curb Weight</b>	1,350 kg	?
<b>Features</b>	Responsive 1.8L I-VTEC Engine, 5 Speed Auto Transmission, ABS, Dual SRS Airbags, Immobiliser, Digital Climatic Control Aircon, Retractable Mirrors.	
<b>Accessories</b>	Leather Seats, Pioneer DVD Player, Knockdown Rear Seats, Reverse Sensors, Remote Alarm, Reverse Camera, Sport Rims.	
<b>Description</b>	New Paintwork, New Pioneer DVD Player, New Reverse Camera, New Car Mat. Great Condition, Lowest Depreciation In The Market, Best Selling 7 Seater Most, Reliable Sporty MPV! Well Maintained By Previous Owner Very Spacious And Big Boot Space, Reliable And Easy Maintenance. Good Fuel Consumption. Regular Maintained. Call Us Now For Viewing.	
<b>COE</b>	\$27,044	?
<b>OMV</b>	\$17,444	?
<b>ARF</b>	\$19,189	?
<b>Dereg Value</b>	\$21,635 as of today (change)	?
<b>No. of Owners</b>	2	?
<b>Type of Veh</b>	MPV	?
<b>Category</b>	COE Car	
<b>Availability</b>	Available	

Add to Shortlist Add to Compare Add a Note

Posted on: 16-Jun-2018 | Last Updated on: 21-Jun-2018

Tags: Honda Stream, 2007 Honda Stream, Honda, Stream, Used Honda

Upfront Payment

more Financial info



Seller Information

<b>Company</b>	Hanns Auto » dealer's pricelist » 39 vehs sold   14 vehs available
<b>Address</b>	1 Commonwealth Lane #03-17 Search cars nearby this location
<b>Location</b>	One Commonwealth
<b>Office No</b>	62712252
<b>Contact Person(s)</b>	Desmond Chan 91717808

Useful Services

Afraid of lemons? Request to have this car evaluated professionally.  
**Vehicle Evaluation**

Find out the market value for your car. Get a free Car Valuation.  
**Free Valuation**

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	3276G
<b>Vehicle Details</b>	
Vehicle No.:	SKR9105Y
Vehicle to be Exported:	No
Intended De-registration Date:	21 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8 A
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	R18A1731965
Chassis No.:	RN61028486
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$17,340.00
Original Registration Date:	24 Apr 2007
First Registration Date:	24 Apr 2007
Transfer Count:	2
Actual ARF Paid:	\$19,074.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	23 Apr 2022
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$26,004.00
COE Rebate Amount:	\$19,965.00
<b>Total Rebate Amount:</b>	<b>\$19,965.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 21 Jun 2018

OK

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

not followed  
 done  
 2/5 @ 5000/-  
 21/6/18  
 Take photo after repair

Qty Particular SKR9105Y

Amount S\$

List Item:

Qty	Particular	SKR9105Y	Amount S\$	
1PCS	REAR WINDSCREEN	11	\$1488.10	X
1PCS	REAR WINDSCREEN MOULDING	rec	\$48.50	—
1PCS	TAILGATE	Bobby D	\$903.20	✓
1PCS	TAILGATE 'H' LOGO	rec	\$35.00	—
1PCS	TAILGATE 'STREAM' EMBLEM	rec	\$32.60	—
1PCS	TAILGATE OUTER GARNISH	one	\$184.50	—
1PCS	TAILGATE INNER LOCK	no/shot d	\$109.50	✓
1PCS	TAILGATE INNER TRIM BOARD	de/one	\$341.50	—
1PCS	TAILGATE INNER TRIM BOARD CLIPS	rec	\$50.00	—
1PCS	TAILGATE INNER TOP SIDE GARNISH	11	\$162.30	X
2PCS	TAILGATE DAMPERS @\$245.10	11	\$490.20	X
1PCS	TAILGATE REAR WIPER ARM	11	\$235.30	X
1PCS	TAILGATE REAR WIPER MOTOR	11	\$488.50	X
1PCS	TAILGATE WEATHERSTRIP	7w1	\$116.90	—
1PCS	REAR BUMPER	no/de	\$665.40	—
2PCS	REAR BUMPER SIDE RETAINERS @\$25.50	best	\$51.00	—
2PCS	REAR BUMPER BRACKETS @\$22.50	best	\$45.00	—
1SET	REAR BUMPER CLIPS	rec	\$39.00	—
1PCS	REAR END PANEL	shot d	\$306.10	—
1PCS	REAR END PANEL LOWER MEMBER	best	\$182.30	✓
1PCS	REAR END PANEL TOP GARNISH	7w1	\$225.60	✓
1PCS	REAR FLOOR PANEL	11	\$912.30	X
2PCS	REAR FLOOR PANEL TOP BOARDS @\$266.50	11	\$533.00	X

(20%)

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Qty      Particular      Amount S\$

List Item:

1PCS	REAR FLOOR PANEL INNER TOP GARNISH	11	\$341.10	X
2PCS	TAILLAMPS @\$338.80	one	\$677.60	✓
2PCS	REAR FENDERS @\$891.10	2	\$1782.20	X
2PCS	REAR FENDER INNER TRIM BOARDS @\$395.20	M/S De/cro	\$790.40	spc
1SET	REAR FENDER INNER TRIM BOARD CLIPS	11	\$60.00	X
2PCS	REAR FENDER QUARTER GLASS @\$671.10	11	\$1342.20	X
1PCS	REAR EXHAUST	11	\$689.30	X
2PCS	REAR EXHAUST MOUNTINGS @\$45.00	11	\$90.00	X
1PCS	REAR SPARE TYRE BRACKET	11	\$285.10	X
<u>List Item Total:</u>			\$13,703.70	

(207)

4398.90  
3519.12

Special Nett Item:

1PCS	REAR WINDSCREEN SEALANT	one	\$80.00	40
1SET	REAR REVERSE CAMERA	shorted	\$500.00	380
1PCS	REAR LICENCE PLATE W/HOLDER	one	\$50.00	40
1SET	REAR FLOOR PANEL INSULATOR	11	\$200.00	X
1PCS	REAR QUARTER GLASS SEALANT N/S	11	\$50.00	X
1SET	REAR REVERSE SENSOR.	NF	\$280.00	X
<u>Special Nett Total:</u>			\$1160.00	

Labour Charge:

TO CHECK WIRING.	\$80.00	30
TO DISMANTLE & REPLACING REVERSE camera	\$80.00	50

# FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No : 20-0006262-D

Qty	Particular	Amount S\$
<u>Labour Charge:</u>		
	TO DISMANTLE & REPLACING REAR WINDSCREEN.	\$150.00 120
11	TO DISMANTLE & REPLACING REAR FENDER QUARTER GLASS.	\$150.00 X
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.	\$150.00 80
11	TO DISMANTLE & REFIX REAR EXHAUST.	\$100.00 X
	TO TRANSFER TAILGATE MECHANISM.	\$100.00 60
11	TO DISMANTLE & REFIX PETROL TANK.	\$100.00 X
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS.	\$2000.00 800
	TO PUTTY & SPRAY PAINTING.	\$1800.00 1000
	TO SPRAY ANTI RUST PROOFING.	\$200.00 60
	Labour Charge Total:	\$4910.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$19,773.70

6259.12  
5007

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

## Shu Pei (LKKAuto)

---

**From:** Lucas Lee <lucas.lee@sg.cntaiping.com>  
**Sent:** Wednesday, 27 June 2018 3:06 PM  
**To:** Shu Pei (LKKAuto)  
**Subject:** RE: Direct Settlement - Accident Involving SKU1732Z (OI : CTI - SNM18D03103C02) and SKR9105Y (TP : LKK REF - CC6/CTI18011294/Uhb3 )on 16.06.2018  
**Attachments:** leeSZ\_SNM18D03103C01-SKU1732Z-LKKDirectSettlementAccidentLtr\_CLCR95.436.pdf; MCHM18079979-SKU1732Z.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Hwang Shiang Yi

### Lucas Lee

Claims Department (Motor)

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6181

Fax (65) 6222 7175/6224 7478

Email: [lucas.lee@sg.cntaiping.com](mailto:lucas.lee@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)



### Disclaimer :

*This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.*

---

**From:** Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]  
**Sent:** Friday, 22 June, 2018 3:55 PM  
**To:** Claims Dept of CTI  
**Cc:** Sharon Han; Angie Foo; Admin A; Vic (LKKAuto)  
**Subject:** Direct Settlement - Accident Involving SKU1732Z (OI : CTI - TBA) and SKR9105Y (TP : LKK REF - CC6/CTI18011294/Uhb3 )on 16.06.2018

**WITHOUT PREJUDICE**

Dear Sharon,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SKR 9105Y at M/s Fastech Auto Pte Ltd.

Enclosed for your perusal is:  
- TP's GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vic and he can be contacted at DID: 6841 2360.

Thank you

Best Regards,

Shu Pei | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



中国太平  
CHINA TAIPING

中国太平保险(新加坡)有限公司  
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
Tel: 6389 6111 Fax: 6222 1033  
Website: www.sg.cntaiping.com  
Co. Reg. No. 200208364E

Our Reference: **SNM18D03103/C01/2**

Date : **27 JUNE 2018**

via Ordinary & Registered Mail

**LAWRENCE LOY BOXUAN  
BLK 817 TAMPINES STREET 81  
#11-586  
SINGAPORE 520817**

Dear Sir / Madam

**ACCIDENT INVOLVING SKU1732Z AND SKR9105Y ON 16 JUNE 2018  
ALONG SLIP ROAD CTE TOWARDS BRADDELL ROAD**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SKR9105Y**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,  
Claims Department

*(This is a computer generated letter and no signature is required.)*

CC : LKK Auto Consultants Pte Ltd  
Attn : VIC  
Ref : CC6/CT118011294/UHB3  
Contact No : 68412360  
via Email : VIC@LKKAUTO.COM

CC : Agent - (AN0421A) - VITESSE SOLUTIONS

F01/LKKDS-2013



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607196-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18011294/Uhb3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 10-01-2019	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKU 1732Z	Veh. Inspected	SKR 9105Y
Policy No.	DMCPSN3066421701	Coverage (\$)	0.00
Claim No.	SNM18D03103/C02/2	Excess (\$)	0.00
Assign From		Assign Date	21/06/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA STREAM (A)	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	RN61028486	Colour	WHITE
Odometer	163259	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 ZR16	MICHELIN	6 mm
L/H Front Tyre	205/55 ZR16	MICHELIN	6 mm
R/H Rear Tyre	205/55 ZR16	MICHELIN	6 mm
L/H Rear Tyre	205/55 ZR16	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/06/2018	Inspection Date	21/06/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 9105Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR WINDSCREEN	NOT NECESSARY	1,488.10	-
1	REAR WINDSCREEN MOULDING	NECESSARY	48.50	48.50
1	TAILGATE	BADLY DENTED	903.20	903.20
1	TAILGATE 'H' LOGO	NECESSARY	35.00	35.00
1	TAILGATE 'STREAM' EMBLEM	NECESSARY	32.60	32.60
1	TAILGATE OUTER GARNISH	CRACKED	184.50	184.50
1	TAILGATE INNER LOCK	DENTED / SHORTED	109.50	109.50
1	TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	341.50	341.50
1	TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	50.00	50.00
1	TAILGATE INNER TOP SIDE GARNISH	NOT NECESSARY	162.30	-
2	TAILGATE DAMPERS @\$245.10	NOT NECESSARY	490.20	-
1	TAILGATE REAR WIPER ARM	NOT NECESSARY	235.30	-
1	TAILGATE REAR WIPER MOTOR	NOT NECESSARY	488.50	-
1	TAILGATE WEATHERSTRIP	TWISTED	116.90	116.90
1	REAR BUMPER	DENTED / DEFORMED	665.40	665.40
2	REAR BUMPER SIDE RETAINERS @\$25.50	BENT	51.00	51.00
2	REAR BUMPER BRACKETS @\$22.50	BENT	45.00	45.00
1	SET REAR BUMPER CLIPS	NECESSARY	39.00	39.00
1	REAR END PANEL	BADLY DENTED	306.10	306.10
1	REAR END PANEL LOWER GARNISH	BENT	182.30	182.30
1	REAR END PANEL TOP GARNISH	TWISTED	225.60	225.60
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	912.30	-
2	REAR FLOOR PANEL TOP BOARDS @\$266.50	NOT NECESSARY	533.00	-
1	REAR FLOOR PANEL INNER TOP GARNISH	NOT NECESSARY	341.10	-
2	TAILLAMPS @\$338.80	CRACKED	677.60	677.60
2	REAR FENDERS @\$891.10	TO REPAIR SEE LABOUR	1,782.20	-
2	REAR FENDER INNER TRIM BOARDS @\$395.20	N/S DEFORMED / CRACKED	790.40	395.20



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR FENDER INNER TRIM BOARD CLIPS	NOT NECESSARY	60.00	-
2	REAR FENDER QUARTER GLASS @\$671.10	NOT NECESSARY	1,342.20	-
1	REAR EXHAUST	NOT NECESSARY	689.30	-
2	REAR EXHAUST MOUNTINGS @\$45.00	NOT NECESSARY	90.00	-
1	REAR SPARE TYRE BRACKET	NOT NECESSARY	285.10	-
	LESS 20% DISCOUNT		-	-881.78
			13,703.70	3,527.12
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	SET REAR REVERSE CAMERA (SN)	SHORTED	500.00	380.00
1	REAR LICENCE PLATE W/HOLDER (SN)	CRACKED	50.00	40.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	200.00	-
1	REAR QUARTER GLASS SEALANT N/S (SN)	NOT NECESSARY	50.00	-
1	SET REAR REVERSE SENSOR (SN)	NOT FITTED	280.00	-
			1,160.00	460.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING .		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE CAMERA.		80.00	50.00
	TO DISMANTLE & REPLACING REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REPLACING REAR FENDER QUARTER GLASS.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY.		150.00	80.00
	TO DISMANTLE & REFIX REAR EXHAUST .	NOT NECESSARY	100.00	-
	TO TRANSFER TAILGATE MECHANISM .		100.00	60.00
	TO DISMANTLE & REFIX PETROL TANK.	NOT NECESSARY	100.00	-
	LABOUR FOR PANEL BEATING , CUT ,WELD,STRAIGHTEN & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL AND REAR FENDERS .		2,000.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,800.00	1,080.00
	TO SPRAY ANTI RUST PROOFING.		200.00	60.00
			4,910.00	2,280.00
<b>GRAND TOTAL</b>			<b>19,773.70</b>	<b>6,267.12</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,000.00
---	--	--	----------

Report Ref No. CC6/CT118011294/Uhb3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.