

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

NZE1617065453.

ESTIMATE

LOW BOON TIN

BLK 180 BUKIT BATOK WEST AVE 8

#07-197

S 650180

TPAXA.
Asher.

Date

:21.06.2018

Vehicle no

:SH 2807 J

Make/Model

:TOYOTA AXIO

Accident date

:07.06.2018

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear boot lid <i>Buckled</i>	1	\$ 753.3 ✓
2	Rear boot lid hinges @ \$106.40 <i>not nec</i>	2	\$ 212.8 x
3	Rear boot lid upper lock <i>Damaged</i>	1	\$ 103.7 ✓
4	Rear boot lid lower lock <i>not nec</i>	1	\$ 24.3 x
5	Rear boot lid weather strip <i>cut</i>	1	\$ 263.7 ✓
6	Rear boot lid handle <i>not nec</i>	1	\$ 230.7 x
7	Rear boot lid centre logo	1	\$ 64.7 ✓
8	Rear boot lid COROLLA emblem <i>not nec</i>	1	\$ 43.1 ✓
9	Rear boot lid AXIO emblem <i>not nec</i>	1	\$ 46.8 ✓
10	Rear boot lid insulation <i>not nec</i>	1	\$ 218.1 x
11	Rear end panel <i>Dented</i>	1	\$ 662.3 ✓
12	Rear end panel inner top garnish <i>Deformed</i>	1	\$ 240.8 ✓
13	Rear bumper <i>Deformed</i>	1	\$ 477.2 ✓
14	Rear bumper side holder @ \$99.80 <i>nec</i>	2	\$ 199.6 <i>70.</i>
15	Rear bumper reflector @ \$59.50 <i>not nec</i>	2	\$ 119 x
16	Rear bumper clips (1set) <i>nec</i>	1	\$ 50 <i>30</i>
17	Rear lamp @ \$413.00 <i>crushed</i>	2	\$ 826 <i>690.</i>
18	Rear lamp housing @ \$157.40 <i>not nec</i>	2	\$ 314.8 x
19	Rear lamp housing bracket @ \$99.50 <i>not nec</i>	2	\$ 199 x
20	Rear fender inner trim @ \$346.60 <i>not nec</i>	2	\$ 693.2 x
21	Rear fender inner shield @ \$62.60 <i>not nec</i>	2	\$ 125.2 x
22	Rear spare tyre top board <i>deformed</i>	1	\$ 567.4 <i>795.</i>
23	Rear spare tyre well <i>Repair</i>	1	\$ 701.6 x
24	Rear spare tyre well insulation @ \$424.20 <i>not nec</i>	3	\$ 1272.6 x
25	Rear LH fender <i>not nec</i>	1	\$ 880.1 x
			\$ 9290
		Less 25% Disc	\$ 2322.5
		Total	\$ 6967.5

Special Nett Items

1	Rear bumper reverse sensor (1set) <i>Damaged</i>	1	\$ 380 <i>200</i>
		Total	\$ 380

200

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

LOW BOON TIN

BLK 180 BUKIT BATOK WEST AVE 8

#07-197

S 650180

Date

:21.06.2018

Vehicle no

:SH 2807 J

Make/Model

:TOYOTA AXIO

Accident date

:07.06.2018

No	Description	Qty	Amount (S\$)
----	-------------	-----	--------------

Labour Cost

1 To supply rear end panel inner sealant			\$ 200 ⁶⁰
2 Remove & reinstall exhaust pipe			\$ 150 x
3 Remove & reinstall reverse sensor			\$ 150 ⁵⁰
4 Remove & reinstall boot lid inner garnish	1960		\$ 200 x
5 Remove, replace & repair consistent to the accident			\$ 1800 ^{qu}
6 Respray painting			\$ 1500 ^{qu}
7 Tuff kote			\$ 150 ⁵⁰
	Total		\$ 4150
	Grand Total		\$ 11497.5

total: \$11545
L/S: 4.1K
06 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: