

INS. CASE OWNER:

CC 6 / TP 180

11375 / K20327

LKK:

IDAC:

ASSIGNMENT

Driver:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A: 3-1-13

Place of Accident:

Is driver the owner? (YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

HHC5195C



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans cab



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

RECEIVED 03 AUG 2018

RECEIVED 03 AUG 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT 3/8/18

27-AUG-2013 TUE 09:10

17803.36 - 20%
= 14,242.69 ✓A901301-047
P. 01

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
 SHC 5195C - III

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident:
 Third Party Insurer:

Ask LKk W

Survey report

12 JUN 2018

Dua

ROEL

NOT Authorised to 14,242.69?
 Proposed L/Sury & Food (bef GST)
 Pls confirm to fax.

SHC 5195C - ROEL

LXS12-0020259

TOYOTA

CROWN TAXI

03.01.2013

III

PART

LIST

1	1	Front Bumper Assembly	\$	Bt/KR 417.40 ✓
2	1	Front bumper centre absorber foam	\$	Mit 125.00 ✓
3	1	Front bumper reinforcement / beam	\$	Bt 269.35 ✓
4	1	Front bumper spot lamp garnish LH	\$	Mit 50.49 ✓
5	1	Front bumper spot lamp garnish RH	\$	Mit 50.49 ✓
6	1	Front bumper centre bracket LH	\$	Mit 15.50 ✓
7	1	Front bumper centre bracket RH	\$	Mit 15.50 ✓
8	1	Front tow hook bracket	\$	R 88.00 X
9	1	Headlamp LH	\$	Bt 411.54 ✓
10	1	Headlamp adjuster switch LH	\$	Sn 138.63 X
11	1	Headlamp RH	\$	Bt 411.54 ✓
12	1	Headlamp adjuster switch RH	\$	Sn 138.63 X
13	1	Side lamp LH	\$	Bt 170.60 ✓
14	1	Indicator light switch LH	\$	Sn 155.00 X
15	1	Side lamp RH	\$	CR 170.60 ✓
16	1	Indicator light switch RH	\$	Sn 155.00 X
17	1	Front support panel assembly	\$	Bt 626.30 ✓
18	1	Radiator grille	\$	Mit 392.16 ✓
19	1	Radiator grille emblem badge	\$	Mit 53.07 ✓
20	1	Radiator overflow pipe	\$	Sn 35.00 X
21	1	Bonnet	\$	Bt 849.31 ✓
22	1	Bonnet under weatherstrip seal	\$	Tn 59.99 ✓
23	1	Bonnet hinge LH	\$	Bt 44.63 ✓
24	1	Bonnet hinge RH	\$	Bt 44.63 ✓
25	1	Bonnet moulding	\$	Dd 161.97 ✓
26	1	Bonnet lock	\$	Bt 75.02 ✓
27	1	Bonnet cable	\$	Tn 44.43 ✓
28	1	Bonnet damper stay	\$	Bt/Pt 199.21 ✓
29	1	Bonnet insulator	\$	\$218.36w CR 436.72 5021A
30	1	Horn unit	\$	Sn Bt 50.00 X
31	1	Horn high pitch / low pitch	\$	Bt 50.00 ✓
32	1	Front fender LH	\$	Bt 732.83 ✓
33	1	Front fender indicator lamp LH	\$	Sn 42.06 X

5659.92

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
 SHC 5195C - III

ROEL

- To resurvey
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Any illegal modification(s) must be resurveyed and approved by the Insurance Company

76	1	Aircon hose - compressor to evaporator	\$	434.94
77	1	Aircon hose - condenser to evaporator	\$	180.00
78	1	Aircon compressor - pump	\$	2,455.48
79	1	Aircon compressor bracket	\$	256.17
80	1	Aircon belt	\$	40.00
81	1	Alternator belt	\$	36.00
82	1	Aircon condensor bottom bushing	\$	15.50
83	1	Air cleaner assembly	\$	548.92
84	1	Air filter	\$	30.00
85	1	Air-cleaner intake duct	\$	84.64
86	1	Air-cleaner intake duct hose (top)	\$	61.83
87	1	Air-cleaner intake hose	\$	166.18
88	1	Air intake resonator top (square)	\$	132.63
89	1	Air intake resonator top bracket	\$	15.00
90	1	Air intake resonator (behind radiator)	\$	265.79
91	1	Air intake resonator (beside fender)	\$	113.38
92	1	Air intake resonator hose (bottom)	\$	51.02
93	1	Air resonator tank top bracket	\$	28.00
94	1	Alternator assembly	\$	2,156.00
95	1	Alternator belt no. 1	\$	36.00
96	1	Alternator belt no. 2	\$	36.00
97	1	Battery	\$	200.00
98	1	Battery tray	\$	91.23
99	1	Battery fastener bracket	\$	27.55
100	1	Battery fastener bolt	\$	12.79
101	1	Fuse box top (cover)	\$	93.01
102	1	Fuse box lower	\$	191.37
103	1	Fuse box centre	\$	367.17
104	1	Fuse box centre cover	\$	22.68
105	1	Engine main harness wire	\$	1,151.75
106	1	Gear box assy	\$	8,038.29
107	1	Gear box cross member	\$	153.59
108	1	Gear box cross member bracket	\$	98.99
109	1	Gear box mounting	\$	112.20
110	1	Engine mounting (2pcs @ \$236.39)	\$	472.78
111	1	Engine lower splashshield cover	\$	294.60
112	1	Engine suspension cross member	\$	905.81
113	1	Engine oil sump	\$	509.30
114	1	Engine oil sump strainer	\$	65.99
115	1	Engine overhaul gasket	\$	440.43
116	1	Engine oil sump sealant	\$	40.00
117	1	Steering wheel	\$	332.00

585.62

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5195C - III

ROEL

160	1	Front wheel bearing with hub RH	\$	Sm 268.00 X
161	1	Front strut bar RH	\$	Sm 100.79 X
162	1	Front strut bar bracket RH	\$	Rt 231.58 ✓
163	1	Steering rack & pinion assy	\$	R 2,639.44 X
164	1	Steering rack end	\$	Sm 205.21 X
165	1	Steering rack & pinion bushing	\$	Sm 25.00 X
166	1	Steering wheel	\$	Sm 850.00 X
167	1	Rear door LH	\$	Rt 931.78 ✓
168	1	Rear door weatherstrip LH	\$	Sm 160.05 X
169	1	Rear door top hinge LH	\$	R 69.02 X
170	1	Rear door bottom hinge LH	\$	R 75.61 X
171	1	Rear door inner lock LH	\$	Tm 404.95 ✓
172	1	Rear door check / arrestor LH	\$	Sm 154.19 X
173	1	Rear door lock striker / latch LH	\$	R 30.00 X
174	1	Rear door outer weatherstrip moulding LH	\$	nd 106.20 ✓
175	1	Rear door outer handle LH	\$	Rt 190.77 ✓
176	1	Rear door outer handle - rubber seal LH	\$	Nu 12.00 ✓
177	1	Rear door inner opening handle LH	\$	Rt 59.86 X
178	1	Rear door inner trim board LH	\$	Set 389.32 X
179	1	Rear door kicking plate / step garnish LH	\$	Sm 93.94 X
180	1	Rear door 1/4 glass LH	\$	Shorted 85.23 ✓
181	1	Rear door 1/4 glass channel weatherstrip LH	\$	Nu 55.18 ✓
182	1	Rear door 1/4 glass pillar LH	\$	R 99.01 X
				2017.69

	\$	57,757.78
25%	\$	14,439.45
TOTAL	\$	43,318.34

Specical Nett

1 Set Radiator Grille Clip	\$	Nu 18.00 ✓
1Set Front bumper fastener clip	\$	Nu 3.00 ✓
1 Front licence plate with holder	\$	Mis 70.00 25SN ✓
1 Front headlamp bracket upper	\$	Mis 3.96 ✓
1Set Front headlamp clip	\$	Mis 16.35 ✓
1Set Radiator grille clip	\$	Nu 3.00 ✓
1Set Bonnet under weatherstrip seal clips	\$	Nu 3.00 ✓
6ps Bonnet insulator clip	\$	Nu 3.50 ✓
8ps Front fender inner cowl clip	\$	Nu 6.00 ✓
1can Radiator coolant	\$	Nu 20.00 ✓

TRANS-CAB AUTO SERVICES PTE LTD

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5195C - III

ROEL

To replace, refix and top up coolant for radiator	\$	170.00 50/
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	Replaced 380.00 X
To dismantle and refit engine cross-member and engine mounting.	\$	nn 380.00 X
To lift-up engine with gear box and refit.	\$	nn 440.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	nn 440.00 X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 250/
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 60/
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	nn 380.00 X
To Remove And Refit Front W/ Screen Glass To Facilitate Bodywork Repair.	\$	170.00 120/
To Check Electrical Lighting Concerned.	\$	Replaced 170.00 X

TOTAL \$ 11,210.00 - 4630

Over All Total \$ 55,529.13

REPAIR DAYS

PART - 12 928.96
 S/M - 285.79
 £ - 4630.

30-DAYS

12 days = 17 844.75
 20% = 3568.95
 = \$ 14275.80

Mei Kwan (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Tuesday, 19 June, 2018 5:12 PM
To: Mei Kwan (LKKAUTO)
Subject: RE: TCS REF:AAD1301-047--Accident involving SHC5195C & YJ9860B on 31/1/2013
Attachments: SHC5195C 03.01.13 - GIA.pdf; AAD1301-047 - ESTIMATE MARKING.pdf

Hi Mei Kwan

Please refer to the above mentioned case, can we request a copy of the survey report?

On our system record Kenneth's was survey the vehicle on 07.01.13 @ 1400hrs.

We enclosed the GIA report and estimate marking for your attention.

Hope to receive the survey report soon.

Thank You very much ☺
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Thursday, 26 April, 2018 1:39 PM
To: jonas.ong <jonas.ong@transcab.com.sg>; Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Cc: 'Jasmine' <jasminetan@transcab.com.sg>; claims@transcab.com.sg
Subject: RE: TCS REF:AAD1301-047--Accident involving SHC5195C & YJ9860B on 31/1/2013

Dear Jonas,

No record found in our system for this case. Please re-confirm.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jonas.ong [mailto:jonas.ong@transcab.com.sg]
Sent: Thursday, 26 April, 2018 1:32 PM
To: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Cc: 'Jasmine' <jasminetan@transcab.com.sg>; claims@transcab.com.sg
Subject: TCS REF:AAD1301-047--Accident involving SHC5195C & YJ9860B on 31/1/2013

Dear Sir/Madam,

Dear Sir/Madam

We are making a claim against the owner of YJ9860B.

Kindly let us know the latest claim settlement status.

Thank you.
Best Regards,
Jonas Ong
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TRANS-CAB AUTO SERVICES PTE LTD			Ref : CC6/TP18011375/Kea3s2	
NO.2 ANG MO KIO STREET 63SINGAPORE 569111			Date : 08-08-2018	
			Code : TP378	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		SHC 5195C	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		07/01/2013	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (M)	c.c	2986	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	LXS120020259	Colour	WHITE / RED	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/65R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/65R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/65R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/01/2013	Inspection Date	07/01/2013	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 9

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5195C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER ASSEMBLY	BENT / CRACKED	417.40	417.40
1	FRONT BUMPER CENTRE ABSORBER FOAM	MISSING	125.00	125.00
1	FRONT BUMPER REINFORCEMENT / BEAM	BENT	269.35	269.35
1	FRONT BUMPER SPOT LAMP GARNISH LH	MISSING	50.49	50.49
1	FRONT BUMPER SPOT LAMP GARNISH RH	MISSING	50.49	50.49
1	FRONT BUMPER CENTRE BRACKET LH	MISSING	15.50	15.50
1	FRONT BUMPER CENTRE BRACKET RH	MISSING	15.50	15.50
1	FRONT TOW HOOK BRACKET	TO REPAIR SEE LABOUR	88.00	-
1	HEADLAMP LH	BROKEN	411.54	411.54
1	HEADLAMP ADJUSTER SWITCH LH	SERVICEABLE	138.63	-
1	HEADLAMP RH	BROKEN	411.54	411.54
1	HEADLAMP ADJUSTER SWITCH RH	SERVICEABLE	138.63	-
1	SIDE LAMP LH	BROKEN	170.60	170.60
1	INDICATOR LIGHT SWITCH LH	SERVICEABLE	155.00	-
1	SIDE LAMP RH	CRACKED	170.60	170.60
1	INDICATOR LIGHT SWITCH RH	SERVICEABLE	155.00	-
1	FRONT SUPPORT PANEL ASSEMBLY	BENT	626.30	626.30
1	RADIATOR GRILLE	MISSING	392.16	392.16
1	RADIATOR GRILLE EMBLEM BADGE	MISSING	53.07	53.07
1	RADIATOR OVERFLOW PIPE	SERVICEABLE	35.00	-
1	BONNET	BENT	849.31	849.31
1	BONNET UNDER WEATHERSTRIP SEAL	TORN	59.99	59.99
1	BONNET HINGE LH	BENT	44.63	44.63
1	BONNET HINGE RH	BENT	44.63	44.63
1	BONNET MOULDING	DENTED	161.97	161.97
1	BONNET LOCK	BENT	75.02	75.02
1	BONNET CABLE	JAMMED	44.43	44.43
1	BONNET DAMPER STAY	BENT / PUNCTURE	199.21	199.21
1	HORN UNIT	SERVICEABLE	50.00	-
1	HORN HIGH PITCH / LOW PITCH	DENTED	50.00	50.00

Report Ref No. CC6/TP18011375/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT FENDER LH	BENT	732.83	732.83
1	FRONT FENDER INDICATOR LAMP LH	SERVICEABLE	42.06	-
1	FRONT FENDER INNER COWLING LH	CRACKED	112.20	112.20
1	FRONT FENDER INNER WHEEL HOUSE PANEL LH	TO REPAIR SEE LABOUR	595.72	-
1	FRONT CHASSIS MEMBER / FRAME LH	TO REPAIR SEE LABOUR	785.83	-
1	SUPPORT PANEL ASSY	REPEATED	626.30	-
1	FRONT TOP PANEL	REPEATED	203.96	-
1	HEADLAMP PANEL LH	REPEATED	107.38	-
1	FRONT FENDER RH	BENT	732.83	732.83
1	FRONT FENDER INDICATOR LAMP RH	SERVICEABLE	42.06	-
1	FRONT FENDER INNER COWLING RH	CRACKED	112.20	112.20
1	FRONT FENDER INNER WHEEL HOUSE PANEL RH	TO REPAIR SEE LABOUR	595.72	-
1	FRONT CHASSIS MEMBER / FRAME RH	TO REPAIR SEE LABOUR	785.83	-
1	HEADLAMP PANEL RH	REPEATED	107.38	-
1	WINDSCREEN WASHER TANK - FILLER NECK	MISSING	80.42	80.42
1	WINDSCREEN WASHER TANK	DENTED	48.06	48.06
1	WINDSCREEN WASHER TANK MOTOR	SERVICEABLE	204.62	-
1	FRONT FUSE BOX - TOP COVER	MISSING	93.01	93.01
1	FRONT FUSE BOX LOWER COVER	CRACKED	191.37	191.37
1	FRONT FUSE BOX CENTRE JUNCTION	CRACKED	367.17	367.17
1	FRONT FUSE BOX CENTRE COVER	CRACKED	22.68	22.68
1	ENGINE MAIN HARNESS WIRE	TO REPAIR SEE LABOUR	1,151.75	-
1	RADIATOR ASSEMBLY	BENT / PUNCTURE	1,890.20	1,890.20
1	RADIATOR FAN BLADE	BROKEN	186.62	186.62
1	RADIATOR COWLING	CRACKED	184.77	184.77
1	RADIATOR TOP MOUNTING BRACKET	TO REPAIR SEE LABOUR	13.58	-
1	RADIATOR LOWER MOUNTING BUSHING	MISSING	14.17	14.17
1	RADIATOR UPPER HOSE	PUNCTURE	31.44	31.44
1	RADIATOR LOWER HOSE	SERVICEABLE	46.67	-

Report Ref No. CC6/TP18011375/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR EXPANSION TANK	DENTED	150.63	150.63
1	RADIATOR OVERFLOW PIPE	SERVICEABLE	35.00	-
1	RADIATOR GRILLE	REPEATED	392.10	-
1	STEERING COLUMN SHAFT	SERVICEABLE	385.00	-
1	FAN CLUTCH	JAMMED	642.98	642.98
1	WATER PUMP	JAMMED	316.55	316.55
1	WATER PUMP PULLEY	SERVICEABLE	124.79	-
1	ENGINE MAIN PULLEY (CRANKSHAFT PULLEY)	SERVICEABLE	323.34	-
1	IDLE PUMP PULLEY	SERVICEABLE	15.00	-
1	AIRCON CONDENSER	BENT / PUNCTURE	1,098.16	1,098.16
1	AIRCON CONDENSER BRACKET	TO REPAIR SEE LABOUR	30.00	-
1	AIRCON CONDENSER TOP MOUNTING	SERVICEABLE	15.80	-
1	AIRCON HIGH-LOW PITCH SWITCH DRIER	SERVICEABLE	69.61	-
1	AIRCON RECEIVER DRIER	DENTED	143.00	143.00
1	AIRCON HOSE - CONDENSER TO COMPRESSOR	SERVICEABLE	324.59	-
1	AIRCON HOSE - COMPRESSOR TO EVAPORATOR	SERVICEABLE	434.94	-
1	AIRCON HOSE - CONDENSER TO EVAPORATOR	SERVICEABLE	180.00	-
1	AIRCON COMPRESSOR - PUMP	TO REPAIR SEE LABOUR	2,455.48	-
1	AIRCON COMPRESSOR BRACKET	TO REPAIR SEE LABOUR	256.17	-
1	AIRCON BELT	SERVICEABLE	40.00	-
1	ALTERNATOR BELT	SERVICEABLE	36.00	-
1	AIRCON CONDENSER BOTTOM BUSHING	SERVICEABLE	15.50	-
1	AIR CLEANER ASSEMBLY	SERVICEABLE	548.92	-
1	AIR FILTER	SERVICEABLE	30.00	-
1	AIR-CLEANER INTAKE DUCT	MISSING	84.64	84.64
1	AIR-CLEANER INTAKE DUCT HOSE (TOP)	DENTED	61.83	61.83
1	AIR-CLEANER INTAKE HOSE	DENTED	166.18	166.18
1	AIR INTAKE RESONATOR TOP (SQUARE)	MISSING	132.63	132.63
1	AIR INTAKE RESONATOR TOP BRACKET	TO REPAIR SEE LABOUR	15.00	-
1	AIR INTAKE RESONATOR (BEHIND RADIATOR)	SERVICEABLE	265.79	-

Report Ref No. CC6/TP18011375/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR INTAKE RESONATOR (BESIDE FENDER)	SERVICEABLE	113.38	-
1	AIR INTAKE RESONATOR HOSE (BOTTOM)	SERVICEABLE	51.02	-
1	AIR RESONATOR TANK TOP BRACKET	TO REPAIR SEE LABOUR	28.00	-
1	ALTERNATOR ASSEMBLY	TO REPAIR SEE LABOUR	2,156.00	-
1	ALTERNATOR BELT NO.1	SERVICEABLE	36.00	-
1	ALTERNATOR BELT NO.2	SERVICEABLE	36.00	-
1	BATTERY TRAY	TO REPAIR SEE LABOUR	91.23	-
1	BATTERY FASTENER BRACKET	BENT	27.55	27.55
1	BATTERY FASTENER BOLT	BENT	12.79	12.79
1	FUSE BOX TOP (COVER)	REPEATED	93.01	-
1	FUSE BOX LOWER	REPEATED	191.37	-
1	FUSE BOX CENTRE	REPEATED	367.17	-
1	FUSE BOX CENTRE COVER	REPEATED	22.68	-
1	ENGINE MAIN HARNESS WIRE	REPEATED	1,151.75	-
1	GEAR BOX ASSY	TO REPAIR SEE LABOUR	8,038.29	-
1	GEAR BOX CROSS MEMBER	SERVICEABLE	153.59	-
1	GEAR BOX CROSS MEMBER BRACKET	SERVICEABLE	98.99	-
1	GEAR BOX MOUNTING	SERVICEABLE	112.20	-
2	ENGINE MOUNTING @ \$236.39	SERVICEABLE	472.78	-
1	ENGINE LOWER SPLASHIELD COVER	SERVICEABLE	294.60	-
1	ENGINE SUSPENSION CROSS MEMBER	SERVICEABLE	905.81	-
1	ENGINE OIL SUMP	SERVICEABLE	509.30	-
1	ENGINE OIL SUMP STRAINER	SERVICEABLE	65.99	-
1	ENGINE OVERHAUL GASKET	NOT NECESSARY	440.43	-
1	ENGINE OIL SUMP SEALANT	NOT NECESSARY	40.00	-
1	STEERING WHEEL	SERVICEABLE	332.00	-
1	POWER STEERING PUMP	TO REPAIR SEE LABOUR	1,127.76	-
1	POWER STEERING BELT	SERVICEABLE	35.00	-
1	POWER STEERING RESERVOIR TANK	SERVICEABLE	302.38	-
1	POWER STEERING INLET / OUTLET PIPE	SERVICEABLE	683.85	-

Report Ref No. CC6/TP18011375/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	POWER STEERING PUMP PULLEY	SERVICEABLE	208.77	-
1	POWER STEERING HOSE - PRESSURE	SERVICEABLE	60.00	-
1	POWER STEERING HOSE - NON PRESSURE	SERVICEABLE	80.00	-
1	CRANKSHAFT PULLEY	SERVICEABLE	323.34	-
1	HEATER HOSE NO. 1	SERVICEABLE	55.50	-
1	HEATER HOSE NO. 2	SERVICEABLE	55.50	-
1	HEATER PIPE NO. 1	SERVICEABLE	98.20	-
1	HEATER PIPE NO. 2	SERVICEABLE	98.20	-
1	TIMING COVER TOP	SERVICEABLE	265.00	-
1	TIMING COVER BOTTOM	SERVICEABLE	78.00	-
1	TIMING BELT	SERVICEABLE	105.00	-
1	TIMING BELT TENSION BEARING	SERVICEABLE	80.00	-
1	THERMOSTAT HOUSING	SERVICEABLE	145.00	-
1	THERMOSTAT UNIT	SERVICEABLE	78.00	-
1	THERMOSTAT TEMPERATURE SENSOR	SERVICEABLE	85.00	-
1	AIR VACUUM VALVE	SERVICEABLE	70.00	-
1	AIR VACUUM VALVE BRACKET	SERVICEABLE	45.00	-
1	FRONT WINDSCREEN GLASS	CRACKED	996.40	996.40
1	FRONT PILLAR INNER GARNISH	SERVICEABLE	101.38	-
1	FRONT WIPER BLADE	SERVICEABLE	68.82	-
1	FRONT WIPER MOTOR	SERVICEABLE	629.14	-
1	FRONT WIPER ARM	SERVICEABLE	78.09	-
1	FRONT WIPER ARM COVER	SERVICEABLE	3.03	-
1	FRONT WIPER GARNISH / WIPER GRILLE	DISTORTED / CRACKED	113.38	113.38
1	FRONT WIPER LINKAGE	SERVICEABLE	321.56	-
1	FRONT KNICKING PLATE	SERVICEABLE	114.11	-
1	REAR KICKING PLATE	SERVICEABLE	91.23	-
1	FRONT SHOCK ABSORBER ASSY LH	BENT	465.00	465.00
1	FRONT SHOCK ABSORBER TOP MOUNTING LH	BENT	132.63	132.63
1	FRONT SHOCK ABSORBER ASSY RH	SERVICEABLE	465.00	-
1	FRONT SHOCK ABSORBER TOP MOUNTING RH	SERVICEABLE	132.63	-
1	FRONT LOWER ARM LH	DISTORTED	517.14	517.14

Report Ref No. CC6/TP18011375/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT SPINDLE ARM LH	SERVICEABLE	124.00	-
1	FRONT WHEEL BEARING WITH HUB LH	SERVICEABLE	268.00	-
1	FRONT STRUT BAR LH	DISTORTED	100.79	100.79
1	FRONT STRUT BAR BRACKET LH	BENT	231.58	231.58
1	FRONT LOWER ARM RH	SERVICEABLE	517.14	-
1	FRONT SPINDLE ARM RH	SERVICEABLE	124.00	-
1	FRONT WHEEL BEARING WITH HUB RH	SERVICEABLE	268.00	-
1	FRONT STRUT BAR RH	SERVICEABLE	100.79	-
1	FRONT STRUT BAR BRACKET RH	BENT	231.58	231.58
1	STEERING RACK & PINION ASSY	TO REPAIR SEE LABOUR	2,639.44	-
1	STEERING RACK END	SERVICEABLE	205.21	-
1	STEERING RACK & PINION BUSHING	SERVICEABLE	25.00	-
1	STEERING WHEEL	SERVICEABLE	850.00	-
1	REAR DOOR LH	BENT	931.78	931.78
1	REAR DOOR WEATHERSTRIP LH	SERVICEABLE	160.05	-
1	REAR DOOR TOP HINGE LH	TO REPAIR SEE LABOUR	69.02	-
1	REAR DOOR BOTTOM HINGE LH	TO REPAIR SEE LABOUR	75.61	-
1	REAR DOOR INNER LOCK LH	JAMMED	404.95	404.95
1	REAR DOOR CHECK / ARRESTOR LH	SERVICEABLE	154.19	-
1	REAR DOOR LOCK STRIKER / LATCH LH	TO REPAIR SEE LABOUR	30.00	-
1	REAR DOOR OUTER WEATHERSTRIP MOULDING LH	DENTED	106.20	106.20
1	REAR DOOR OUTER HANDLE LH	BENT	190.77	190.77
1	REAR DOOR OUTER HANDLE - RUBBER SEAL LH	NECESSARY	12.00	12.00
1	REAR DOOR INNER OPENING HANDLE LH	SERVICEABLE	59.86	-
1	REAR DOOR INNER TRIM BOARD LH	SERVICEABLE	389.32	-
1	REAR DOOR KICKING PLATE / STEP GARNISH LH	SERVICEABLE	93.94	-
1	REAR DOOR 1/4 GLASS LH	SHATTERED	85.23	85.23
1	REAR DOOR 1/4 GLASS CHANNEL WEATHERSTRIP LH	NECESSARY	55.18	55.18
1	REAR DOOR 1/4 GLASS PILLAR LH	TO REPAIR SEE LABOUR	99.01	-

Report Ref No. CC6/TP18011375/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-14,280.26	-4,230.06
			42,840.80	12,690.19
1	BONNET INSULATOR (50%) (SN)	CRACKED	436.72	218.36
1	BATTERY (50%) (SN)	DENTED	200.00	100.00
	LESS 25% DISCOUNT		-159.18	-
			477.54	318.36
	SPECIAL NETT ITEMS			
1	SET RADIATOR GRILLE CLIP (SN)	NECESSARY	18.00	18.00
1	SET FRONT BUMPER FASTENER CLIP (SN)	NECESSARY	3.00	3.00
1	FRONT LICENCE PLATE WITH HOLDER (SN)	MISSING	70.00	25.00
1	FRONT HEADLAMP BRACKET UPPER (SN)	MISSING	3.96	3.96
1	SET FRONT HEADLAMP CLIP (SN)	MISSING	16.35	16.35
1	SET RADIATOR GRILLE CLIP (SN)	NECESSARY	3.00	3.00
1	SET BONNET UNDER WEATHERSTRIP SEAL CLIPS (SN)	NECESSARY	3.00	3.00
6	BONNET INSULATOR CLIP (SN)	NECESSARY	3.50	3.50
8	FRONT FENDER INNER COWLING CLIP (SN)	NECESSARY	6.00	6.00
1	CAN RADIATOR COOLANT (SN)	NECESSARY	20.00	20.00
1	FRONT WINDSCREEN MOULDING (SN)	NECESSARY	113.98	113.98
2	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	FRONT WINDSCREEN INNER SEAL (SN)	NECESSARY	60.00	30.00
2	FRONT TYRE (SN)	SERVICEABLE	360.00	-
2	FRONT TYRE RIM (SN)	SERVICEABLE	240.00	-
			1,000.79	285.79

Report Ref No. CC6/TP18011375/Kea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:8 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF FRONT TOW HOOK BRACKET, FRONT FENDER INNER WHEEL HOUSE PANEL LH, FRONT CHASSIS MEMBER / FRAME LH, FRONT FENDER INNER WHEEL HOUSE PANEL RH, FRONT CHASSIS MEMBER / FRAME RH, ENGINE MAIN HARNESS WIRE, RADIATOR TOP MOUNTING BRACKET, AIRCON CONDENSER BRACKET, AIRCON COMPRESSOR - PUMP, AIRCON COMPRESSOR BRACKET, AIR INTAKE RESONATOR TOP BRACKET, }		3,500.00	2,000.00
	AIR RESONATOR TANK TOP BRACKET, ALTERNATOR ASSEMBLY, BATTERY TRAY, GEAR BOX ASSY, POWER STEERING PUMP, STEERING RACK & PINION ASSY, REAR DOOR TOP HINGE LH, REAR DOOR BOTTOM HINGE LH, REAR DOOR LOCK STRIKER / LATCH LH AND REAR DOOR 1/4 GLASS PILLAR LH. }		-	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,200.00	1,800.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		120.00	40.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.	NOT NECESSARY	170.00	-
	TOWING FEES.		120.00	50.00
	TO DISMANTLE AND REFIT FRONT END SUSPENSION, UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.		380.00	160.00
	TO REMOVE AND RENEW ENGINE AND GEAR BOX MOUNTING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO REMOVE AND REPLACE CORPORATE STICKER.	NOT NECESSARY	330.00	-
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.		380.00	100.00
	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.		170.00	50.00
	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT, VACUUM AND CHARGE-IN-GAS.	REPEATED	380.00	-
	TO DISMANTLE AND REFIT ENGINE CROSS-MEMBER AND ENGINE MOUNTING.	NOT NECESSARY	380.00	-
	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	NOT NECESSARY	440.00	-

Report Ref No. CC6/TP18011375/Kea3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 9 of 9

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRIC POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.		380.00	250.00
	TO TRANSFER OF DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.		170.00	120.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	REPEATED	170.00	-
			11,210.00	4,630.00
GRAND TOTAL			55,529.13	17,924.34
RECOMMENDED COST OF PROPOSED SUM (TO ITS PRE-ACCIDENT CONDITION)				7,000.00

Report Ref No. CC6/TP18011375/Kea3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.