

Surveyor

Taylin

REF: ASM(AXA)

ASSIGNMENT

From: Date: 22062018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBH 2813D

at Workshop m/s: Leong Seng
of Blk 1006 Bukit Merah Lane 2 #01-08

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 97500

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBH 4813D Yr Regn: 2013 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamala FZ16 C.C. 153

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ME121C001D-2020533

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Ni / S/Rim / STD A/Rim or

Tyre Size: F: 160 / 70 R17

R: 140 / 70 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. mm

L/Bal. mm

D.O.A.

D.O.I. 22/6/18 @ 1700

Survey held at Leong Seng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)

☐ : S + RS. SI

☐ : Interview (\$)

☐ : Photos

☐ : Tech. Invs (\$)

☐ : Others

☐ : Weekend (\$)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)