

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR18011405/T1EA3Q2

Date: 27/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994820
Claimant
Vehicle No : FBJ5842C **Insured Vehicle No :** SLR1873D
 Date of Loss: 12/05/2018 Nature of Claim: TP Claim No: 9720688913SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBJ5842C**
 Make & Model: HONDA CB400X, 399cc Engine No: NC47E1004486
 Reg. Date: 16/07/2014 (Man. Year: 2014) Chassis No: NC471004497
 Colour: Maroon Odometer: 0 km
 Engine Capacity: 399 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 120/70 R17 Rear Tyre Size: 160/60 R17
 Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,271.00	1,940.40	330.60	14.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	680.00	170.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,121.00	2,620.40	500.60	16.04
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	3,121.00	2,100.00	1,021.00	32.71
+ GST 7.00/7.00% (S\$)	218.47	147.00	71.47	32.71
Nett Amount (S\$)	3,339.47	2,247.00	1,092.47	32.71
+ Loss of Use (4.0 x S\$30.00/day) (S\$)		120.00		
Nett Liability (S\$)		2,367.00		

INSPECTION

Date of Assignment: 22/06/2018
 Date Inspected: 25/06/2018 Inspected At: New Union Company (HQ)
 BLK 9004 TAMPINES STREET 93
 #01-106
 Singapore 528838
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CRASH BAR ASSY, TOP & BOTTOM	Bent	750.00 F	*750.00 FL
2	1		*RACK FOR BOX	Dented	250.00 F	*250.00 FL
3	1		*HANDLE BAR	Bent	95.00 F	*95.00 FL
4	1		*HAND GUARD ASSY	Cut	185.00 F	*185.00 FL
5	2		*BALANCER	Not Necessary	70.00 F	*- FL
6	1		*WIND SHIELD	Cracked	250.00 F	*250.00 FL
7	1		*FRONT NO PLATE	Necessary	25.00 F	*25.00 FL
8	1		*FOOTREST BRACKET,FRONT	Cut	130.00 F	*130.00 FL
9	1		*GEAR PEDAL	Cut	145.00 F	*145.00 FL
10	1		*FRONT FENDER	Cut	160.00 F	*160.00 FL
11	1		*FRONT WHEEL SHAFT	Not Necessary	45.00 F	*- FL
12	1		*CORN STEER BEARING	Necessary	120.00 F	*120.00 FL
13	2		*FRONT WHEEL BEARING	Necessary	46.00 F	*46.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,271.00	2,156.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	215.60
Total Parts (\$\$)	2,271.00	1,940.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	FORK PRESS	New	120.00	120.00
2	FRONT RIM PRESS	New	80.00	60.00
3	TANK REPAIR	New	120.00	100.00
4	SPRAY PAINT	New	280.00	200.00
5	LABOUR CHARGE	New	250.00	200.00
			Gross Labour Cost (\$\$)	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >