

Form 100

ASS. REC. BY:

REF: CS/MSG18011409 / U-103

Special Instruction

Supervisor:

Murimen

ASSIGNMENT (Office)

From (Person):

Muhd Ashik

MSIG

Date/Time:

22/6/18 @ 4:10pm

Estimated Cost:

Bill to:

OT / TP / RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SJE 7351 X

Inured:

SJK 6339 H

at Workshop m/s:

Tan Lim Motor

Tel:

6858 5151

of:

51 Defu Lane 10

Policy No.:

MSD / vpcB / 17-002586

Claim No.:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 21/06/2018

25/05/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement

Date/Time:

1:00pm @ 22/6/18

Person Contacted:

Caymen

Vehicle: IN OUT

Date/Time

Action/Instruction (✓) Estimate

SJE 7351 X - NA/INC 16011820/r3

DOA: 25/6/2016

SJK 6339 H - CS/Lip 09015637/U/vn

DOA: 12/07/2009

25/6-

Report via merimen

Marans any part price ok check

Est. Repair:

8

days

Res: Yes or No

D.O.A. 21/6/18

DOI 25/6/18

Lump Sum:

20

%

3 Val: Yes or No

Survey held at

CA / REV / REP. / 24 HRS (lup)

30/4/2023

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear &

Date:

Person Contacted:

Vehicle: IN / OUT

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

L7A 18737 4 yrs 10 mths. nett 10263

cost plus 15% + labor less 20%

20/7/18 4/5 @ 5100 confirmed with Darren.
(red. 6851.68 157%)

RECEIVED 23 JUL 2018

[Signature]
23/7/2018

Date/Time, File Pass to?

Prel. Report
 Final Report

Days Of Repair: 8

23/7 Tyast

Resurvey No. of Trip: 1

Survey Fee:

200

Date/Time, File Return to?

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Insp (\$)
 Weekend (\$)

Report Format: TP

Lump Sum / I.B.E: (\$ 5100)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/06/2018 16:23
Date Of Accident	21/06/2018 04:30
Exact Location Of Accident	CAUSEWAY TOWARD SINGAPORE CHECKPOINT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJE7351X
Insured/Policyholder	
Name Of Registered Owner	NOORIA BANU BINTE MOHANED ZIADEEN
NRIC No	S8525773J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93820714
Alternative Phone No	OFFICE-93820714

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ-1.4 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5100101125
Cover Note Number	

Driver

Name of Driver	HAJA MOHIDEEN BIN MAJID
NRIC No	S8528906C
Date Of Birth	11/09/1985
Occupation	INDOOR
Date Of Driving Pass	19/02/2009
Driving Experience	9 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85186316
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name NOORIA BANU BINTE MOHANED ZIADEEN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJE7351X

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name HAJA MOHIDEEN BIN MAJID

Approximate Age

Injuries Sustain

Injured person in which vehicle? SJE7351X

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance?

Address

Postcode



**SINGAPORE
POLICE FORCE**



T/20180621/2087

2 of 4

Police Station Of Origin:
Hong Kah North NPP
370 Bukit Batok Street 31 #01-201
SINGAPORE 650370
Tel No: 1800-5679999

Report No. T/20180621/2087

CONTINUATION OF REPORT

Passenger			
Name	Nooria Banu Binte Mohamed Ziawdeen	ID No.	S8525773J
Related Vehicle	SJE7351X (Car)	Contact No.	93820714
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	21/06/2018	Date Discharge	21/06/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	HAJA MOHIDEEN BIN MAJID	ID No.	S8528906C
Related Vehicle	SJE7351X (Car)	Contact No.	85186316
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	21/06/2018	Date Discharge	21/06/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	Lek Guan Wei	ID No.	S8849222F
Related Vehicle	SJK6339H (Car)	Contact No.	96892648
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 21/06/2018 at about 0430 hrs, I was travelling along Causeway towards Singapore Checkpoint of the extreme left lane. I was slowing down to negotiate a slight bend down a slope when I felt an impact from the rear. I stop my vehicle to make a check and I realised that there was a vehicle V1) SJK6339H had collided onto my vehicle rear. I got down from my vehicle to make a check and discovered that my vehicle rear bumper was dented and scratched. I exchanged particulars with the driver of V1 before leaving the scene. My passenger namely A1) Nooria Banu S8525773J felt nausea and pain on her back and knee area at scene. We later proceed to Ng Teng Fong Hospital for consultation for A1 and myself as I felt pain back area as well.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 5773J

Vehicle Details

Vehicle No.: SJE7351X

Vehicle to be Exported: No

Intended De-registration Date: 25 Jun 2018

Vehicle Make: HONDA

Vehicle Model: JAZZ 1.4A

Primary Colour: Red

Manufacturing Year: 2008

Engine No.: L13A55000265

Chassis No.: JHMGD18508S208258

Maximum Power Output: 60.0 kW (80 bhp)

Open Market Value: \$14,465.00

Original Registration Date: 06 May 2008

First Registration Date: 06 May 2008

Transfer Count: 2

Actual ARF Paid: \$15,912.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Apr 2023

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

PQP Paid: \$19,328.00

COE Rebate Amount: \$18,737.00

Total Rebate Amount: \$18,737.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 25 Jun 2018

OK

Trade Online

Start with \$30 Trading Bonus*



*T&Cs apply. Forex and CFD trading is high risk and can result in the loss of all your invested capital.

Read More

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

New 5 Years Coe Renewal Toyota Wish 1.8A



\$2800 Downpayment Monthly
From \$688 Onwards. Lowest
3.68% P.A @ GV Cars Financing
GV Credit Pte Ltd StarAd.



Browse by Category

Sort by Date Posted 20 results/page

16 vehicles

Honda Jazz

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Jazz		Any	Any	2008	Any	Any	Any	Available
	Honda Jazz	Honda Jazz 1.5A L (New 5-yr COE)	\$35,800	\$7,160 /yr	14-Nov-2008	1,497 cc	-	Hatchback	Available
No Hidden Cost. Immaculate Condition. View To Appreciate. No More Repairs Needed. All Vehicles Are Inspected By Our Professional Workshop And Come With 1 Year Engine And Gearbox Protection Shield. Loa...									
Posted: 24-Jun-2018 Tags: 2008 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda									
	Honda Jazz	Honda Jazz 1.3A (New 5-yr COE)	\$30,800	\$6,160 /yr	06-Aug-2008	1,339 cc	-	Hatchback	Available
Immaculate Condition. Too Good To Scrap. Loan Up To 90%. High Approval Rate. High Trade In. All Vehicles Are Inspected By Our Professional Workshop And Comes With 1 Year Engine And Gearbox Protection ...									
Posted: 24-Jun-2018 Tags: 2008 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda									
	Honda Jazz	Honda Jazz 1.3A	\$9,900	N.A	17-Sep-2008	1,339 cc	109,493 km	Hatchback	Available
(We Assure 100% Genuine Mileage) Well Taken Care Of By Previous Owner. Car Is In Very Good Condition. View To Believe. Call Now To View The Car.									
Posted: 23-Jun-2018 Tags: 2008 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda									
	Honda Jazz	Honda Jazz 1.3A L	\$13,599	N.A	25-Nov-2008	1,339 cc	-	Hatchback	Available
Almost New Honda Jazz 1.3L. 100% Accident Free! New Road Tax! Agent Serviced Record. Ideal For Renewal Of COE. Genuine Mileage. No More Loan. Instant Transfer. Immediate.									
Posted: 22-Jun-2018 Tags: 2008 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda									
Car Buying	Car Selling	Car Ownership							
Car Aftermarket	On The Move:	Lifestyle	<ul style="list-style-type: none"> Buy Tyres Online Latest Special Offers from Tyreset 						
	Honda Jazz	Honda Jazz 1.3A (New 5-yr COE)	\$31,800	\$6,360 /yr	17-Jul-2008	1,339 cc	166,000 km	Hatchback	Available
Flexible Loan! 10 Year COE Optional. 23km/l. Fully Serviced By Kah Motor With Proof, Last Servicing On May 2018. Ideal For Renewal Of COE. Smooth Running Engine And Gearbox, Flexible Bank/In House Loa...									
Posted: 22-Jun-2018 Tags: 2008 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda									
	Honda Jazz	Honda Jazz 1.3A (New 5-yr COE)	\$29,800	\$5,960 /yr	11-Aug-2008	1,339 cc	105,000 km	Hatchback	Available
Low Mileage 105,000Km, Excellent Condition! Buy With A Peace Of Mind From Award Accredited Company! Attractive Loan Package And Competitive Trade In Price! Call Now To Find Out More!									
Autolink Holdings Pte Ltd									
Posted: 21-Jun-2018 Tags: 2008 Honda Jazz, Honda Jazz, Honda, Jazz, Used Honda									
Compare	Honda Jazz	Honda Jazz 1.3A (New 5-yr COE)	\$27,800	\$5,560 /yr	05-Jul-2008	1,339 cc	128,000 km	Hatchback	Available



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)
Lek Guan Wei
NA
Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP028062018
Policy No:		Date of Loss:	21/06/2018
Vehicle Reg. No.:	SJE7351X	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	HAJA MOHIDEEN BIN MAJID		
Make/Model:	HONDA JAZZ, 1.4 (A)	Vehicle Reg. Date:	06/05/2008
Vehicle Colour:	RED		
Engine No:	L13A55000265	Chassis No:	JHMGD18508S208258
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Description of Accident/Loss	REFER TO POLICE REPORT T/20180621/2087		
Present Location:	TAN LIM MOTOR PTE LTD (DEFU)		

*not Affected below
2/5 95100
Shy.
the sh. After up
25/6/18
p/p s:*

COST OF CLAIMS		Amount
Parts		5,711.68
Miscellaneous Items		0.00
Labour		4,240.00
Paintwork Labour		2,000.00
Towing		0.00
	Gross Total (S\$)	11,951.68
	+ GST 7.00% (S\$)	836.62
	Nett Amount (S\$)	12,788.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This claim is handled by: SAM LOW PUI MUN

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Jun 2018)
Parts: 144 HONDA JAZZ 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJE7351X)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*tailgate lid <i>S. 1500</i>	0.00	0.00	*650.00 F
2	1		*tailgate lid inner trimboard <i>reference</i>	0.00	0.00	*60.00 F
3	1		*tailgate lid inner clasing handle / garnish <i>one</i>	0.00	0.00	*10.00 F
4	2		*tailgate lid rubber stopper <i>11</i>	0.00	0.00	*16.00 F X
5	2		*tailgate lid damper <i>11</i>	0.00	0.00	*130.00 F X
6	1		*tailgate lid lock <i>twi/shhd</i>	0.00	0.00	*75.00 F
7	1		*tailgate lid lock stricker <i>11</i>	0.00	0.00	*18.00 F X
8	1		*tailgate lid weatherstrip <i>twi</i>	0.00	0.00	*38.00 F
9	1		*sundries and clips <i>11</i>	0	0.00	*150.00 FS X
10	1		*tailgate lid jazz badge <i>neu</i>	0.00	0.00	*15.00 F
11	1		*tailgate lid outer garnish <i>11</i>	0.00	0.00	*55.00 F X
12	1		*tailgate lid outer garnish with H badge <i>11</i>	0.00	0.00	*10.00 F X
13	1		*back off camera <i>11</i>	0	0.00	*380.00 FS X
14	1		*rear license plate <i>Ref</i>	f	0	*50.00 FS 40
15	1		*rear license plate lamp <i>11</i>	0.00	0.00	*22.00 F X
16	1		*rear wiper motor <i>11</i>	0.00	0.00	*180.00 F X
17	1		*rear windshield glass sealant <i>neu</i>	f	0	*180.00 FS 40
18	1		*rear windshield glass sponge <i>neu</i>	f	0	*100.00 FS 30
19	1		*rear windshield glass weahterstrip <i>neu</i>	0.00	0.00	*20.00 F
20	2		*rear lamp <i>O/S one</i>	140	0.00	*280.00 F
21	6		*rear lamp clip holder <i>11</i>	0.00	0.00	*9.00 F X
22	1		*rear end panel <i>B. 1500</i>	0.00	0.00	*220.00 F
23	1		*rear end panel inner trim <i>twi/de</i>	0.00	0.00	*35.00 F
24	1		*rear luggage floor panel <i>crumpled / succ</i>	0.00	0.00	*480.00 F
25	1		*rear luggage floor panel insulator <i>neu</i>	*	0	*350.00 FS 100
26	1		*rear luggage floor trimboard <i>w. 07/12</i>	0.00	0.00	*135.00 F
27	1		*rear luggage floor panel cross member <i>11</i>	0.00	0.00	*150.00 F X
28	1		*spare tyre - clamp <i>11</i>	0.00	0.00	*10.00 F X
29	2		*rear fender inner trim <i>O/S Del/Toin</i>	148.6	0.00	*297.20 F 120
30	2		*rear fender air vent <i>11</i>	0.00	0.00	*30.00 F X
31	1		*rear bumper <i>Dis</i>	0.00	0.00	*190.00 F
32	2		*rear bumper side retainer <i>Ref</i>	0.00	0.00	*18.00 F
33	2		*rear bumper side holder <i>Ref</i>	0.00	0.00	*8.00 F
34	1		*rear bumper parking sensor <i>shhd</i>	*	0	*450.00 FS 20
35	1		*rear bumper end splashield cover <i>O/S To. 11</i>	0.00	0.00	*18.00 F
36	2		*rear bumper screws <i>neu</i>	0.00	0.00	*10.00 F
37	6		*rear bumper clips <i>neu</i>	0.00	0.00	*12.00 F
38	1		*rear exhaust box <i>twi/twi</i>	0.00	0.00	*280.00 F
39	1		*rear exhaust box heat shield <i>Ref</i>	0.00	0.00	*22.00 F
40	2		*rear exhaust box mount <i>Toin</i>	0.00	0.00	*20.00 F

F=Franchise part. S=SpcNett.

4105.2

Sub Total (\$\$)	2604.6	5,183.20
+ Margin on L,N Items 15.00% (\$\$)		528.48
Total Parts (\$\$)		5,711.68

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	Putty and spray painting of the affected portion.	New 1000	2,000.00
<u>Labour Items</u>			
2	To reinstall of rear bumper parking sensor.	New 50	150.00
3	To reinstall back off camera and settings	New	120.00
4	To rust-proofing of the affected areas.	New 100	250.00
5	To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	New 80	180.00
6	To transfer of tailgate fittings, fixture and perform waterseepage test.	New 11x	180.00
7	To remove and refit rear windscreen glass.	New 120	200.00
8	To check electrical lighting concerned.	New 30	60.00
9	To repair and realign rear exhaust box.	New 80	150.00
10	To drop petrol tank, hoses to facilitate bodywork repair, final checking and testing.	New 60	150.00
	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same. <i>include car-o-liner</i>	New 1500	2,800.00
Gross Labour Cost (S\$)			6,240.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

3000

< END OF ESTIMATES >

3410

51 Defu Lane 10 Singapore 539216
Tel : 6858 5151 (24 hours) Fax : 6858 0877
email@tlmotor.com.sg www.tlmotor.com.sg
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

P-2604.6

2995.29

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	Putty and spray painting of the affected portion.	New 1000	2,000.00
<u>Labour Items</u>			
2	To reinstall of rear bumper parking sensor.	New 50	150.00
3	To reinstall back off camera and settings	New	120.00
4	To rust-proofing of the affected areas.	New 100	250.00
5	To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	New 80	180.00
6	To transfer of tailgate fittings, fixture and perform waterseepage test.	New 11x	180.00
7	To remove and refit rear windscreen glass.	New 120	200.00
8	To check electrical lighting concerned.	New 30	60.00
9	To repair and realign rear exhaust box.	New 80	150.00
10	To drop petrol tank, hoses to facilitate bodywork repair, final checking and testing.	New 60	150.00
○	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same. <i>include car-o-liner</i>	New 1500	2,800.00
Gross Labour Cost (S\$)			6,240.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Defu Lane 10 Singapore 539216
Tel : 6858 5151 (24 hours) Fax : 6858 0877
email@ilmotor.com.sg www.ilmotor.com.sg
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

○

Paint	—	2995.90
Panel sp work	—	410.00
Labour	—	3000.00
		6405.90
200%		1281.18
		5124.72

Labour \$5100 x 8 days

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Jun 2018 Sendback Est	22 Jun 2018 11:01 S\$11,951.68	22 Jun 2018 16:10 Edit Adj Rpt	S\$5,100.00 Edit Estimates	S\$5,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	LEK YAK SOY , ID: S0218432Z								
Main Claimant:	NOORIA BANU BINTE MOHANED ZIADEEN , ID: S8525773J								
Vehicle Reg. No.:	SJE7351X	Date of Loss:	21/06/2018 03:00 - :59 [121 Months and 15 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-000857	Policy/Cover Note No.:	MSD/VPCB/17-002586 (Comprehensive) Coverage: 19/10/2017 - 28/10/2018						
Vehicle Reg. No. (Insured):	SJK6339H	Policy No. (Claimant):	5100101125						
		Excess:	S\$500.00						
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 22/07/2018]								
Driver/Custodian (Insured):	LEK GUAN WEI (/ Male), NRIC: S8849222F								
Adj Asg. Remarks:	Car in. on WP. Please contact us ASAP if you cannot attend this assignment. Liability 100% Contact : 6858 5151								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJE7351X (MSC/V/18-000857)
[SJK6339H]

TP

NOORIA BANU BINTE MOHANED ZIADEEN

Jun 21 2018 3:00AM

[LEK YAK SOY]

Tan Lim Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser <input type="button" value="v"/>
Assessment Reports			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
1	21/06/18 17:11	Accident Statement	 Load HTM	<input type="checkbox"/>
2	22/06/18 11:01	Repairer Estimates	 Load HTM	<input type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/06/18 13:37	Accident Statement From: SC - Reg. No: SJK6339H, Claimant: LEK YAK SOY	 Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/06/18 10:13	Adjuster Immediate Advice	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
1	21/06/18 16:53	Accident Photo [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	21/06/18 16:53	Accident Photo [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	21/06/18 16:53	Accident Photo [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	21/06/18 16:53	Accident Photo [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	21/06/18 16:53	Accident Photo [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	21/06/18 16:53	Accident Photo [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/06/18 17:31	Chassis Number	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	25/06/18 17:31	Odometer Reading	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	25/06/18 17:33	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	25/06/18 17:33	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	25/06/18 17:33	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	25/06/18 17:33	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	25/06/18 17:33	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	25/06/18 17:33	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	25/06/18 17:33	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	25/06/18 17:33	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	25/06/18 17:33	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	25/06/18 17:33	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	25/06/18 17:33	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	25/06/18 17:33	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	25/06/18 17:33	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	25/06/18 17:33	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	25/06/18 17:33	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	25/06/18 17:33	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	25/06/18 17:33	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	25/06/18 17:33	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
21	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
22	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
23	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
24	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
25	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
26	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
27	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
28	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
29	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
30	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
31	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
32	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
33	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
34	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
35	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
36	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
37	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
38	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
39	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
40	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
41	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
42	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
43	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
44	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
45	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
46	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
47	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
48	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
49	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
50	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
51	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
52	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
53	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
54	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
55	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
56	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
57	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
58	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
59	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
60	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
61	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
62	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
63	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
64	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
65	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
66	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
67	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
68	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
69	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
70	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
71	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
72	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
73	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
74	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
75	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
76	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
77	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
78	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
79	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
80	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
81	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
82	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
83	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
84	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
85	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
86	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
87	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
88	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
89	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
90	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
91	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
92	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
93	25/06/18 17:33	General View	 Load JPG	<input checked="" type="checkbox"/>
94	02/07/18 08:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	02/07/18 08:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
1	21/06/18 17:09	Police Report [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
1	21/06/18 17:11	Accident Statement	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
1	21/06/18 16:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	21/06/18 16:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	21/06/18 16:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	21/06/18 16:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	21/06/18 16:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	21/06/18 16:53	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
1	21/06/18 17:08	Sketch Plan	 Load TIF	
2	21/06/18 17:09	Police Report	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18011409/TD3Q2

Date: 26/07/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VPCB/17-002586
Claimant Vehicle No :	SJE7351X	Insured Vehicle No :	SJK6339H
Date of Loss:	21/06/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000857

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJE7351X	Engine No:	L13A55000265
Make & Model:	HONDA JAZZ, 1.4 (A)	Chassis No:	JHMGD18508S208258
Reg. Date:	06/05/2008 (Man. Year: 2008)	Odometer:	91682 km
Colour:	Red		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	5,711.68	3,405.29	2,306.39	40.38	
Miscellaneous Items	0.00	0.00	0.00		
Labour	4,240.00	2,000.00	2,240.00	52.83	
Paintwork Labour	2,000.00	1,000.00	1,000.00	50.00	
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	11,951.68	6,405.29	5,546.39	46.41	
Approved Total (Overridden) (S\$)		5,100.00			
	(S\$)	11,951.68	5,100.00	6,851.68	57.33
+ GST 7.00/7.00% (S\$)	836.62	357.00	479.62	57.33	
Nett Amount (S\$)	12,788.30	5,457.00	7,331.30	57.33	

INSPECTION

Date of Assignment:	22/06/2018	Present Location:	Tan Lim Motor Pte Ltd (Defu)
Date Inspected:	25/06/2018	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10 Singapore 539216
Estimated Period of Repair:	8.0 days		

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Jul 2018)
Parts: 144	HONDA JAZZ 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJE7351X)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*tailgate lid (WCP)	Badly Dented	650.00 F	*650.00 F
2	1		*tailgate lid inner trimboard (WCP)	Deformed / Cracked	60.00 F	*60.00 F
3	1		*tailgate lid inner clasing handle / garnish (WCP)	Cracked	10.00 F	*10.00 F
4	2		*tailgate lid rubber stopper (WCP)	Not Necessary	16.00 F	*- F
5	2		*tailgate lid damper (WCP)	Not Necessary	130.00 F	*- F
6	1		*tailgate lid lock (WCP)	Twisted / Shorted	75.00 F	*75.00 F
7	1		*tailgate lid lock stricker (WCP)	Not Necessary	18.00 F	*- F
8	1		*tailgate lid weatherstrip (WCP)	Twisted	38.00 F	*38.00 F
9	1		*sundries and clips	Not Necessary	150.00 FS	*- FS
10	1		*tailgate lid jazz badge (WCP)	Necessary	15.00 F	*15.00 F
11	1		*tailgate lid outer garnish (WCP)	Not Necessary	55.00 F	*- F
12	1		*tailgate lid outer garnish with H badge (WCP)	Not Necessary	10.00 F	*- F
13	1		*back off camera	Not Necessary	380.00 FS	*- FS
14	1		*rear license plate	Bent	50.00 FS	*40.00 FS
15	1		*rear license plate lamp (WCP)	Not Necessary	22.00 F	*- F
16	1		*rear wiper motor (WCP)	Not Necessary	180.00 F	*- F
17	1		*rear windshield glass sealant	Necessary	180.00 FS	*40.00 FS
18	1		*rear windshield glass sponge	Necessary	100.00 FS	*30.00 FS
19	1		*rear windshield glass weahterstrip (WCP)	Necessary	20.00 F	*20.00 F
20	1		*rear lamp (WCP)	O/S Cracked	280.00 F	*140.00 F
21	6		*rear lamp clip holder (WCP)	Not Necessary	9.00 F	*- F
22	1		*rear end panel (WCP)	Badly Dented	220.00 F	*220.00 F
23	1		*rear end panel inner trim (WCP)	Twisted / Deformed	35.00 F	*35.00 F
24	1		*rear luggage floor panel (WCP)	Crumpled / Buckled	480.00 F	*480.00 F
25	1		*rear luggage floor panel insulator	Necessary	350.00 FS	*100.00 FS
26	1		*rear luggage floor trimboard (WCP)	Warped / Deformed	135.00 F	*135.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
27	1		*rear luggage floor panel cross member (WCP)	Repair	150.00 F	*- F
28	1		*spare tyre - clamp (WCP)	Not Necessary	10.00 F	*- F
29	1		*rear fender inner trim (WCP)	O/S Deformed/ Torn	297.20 F	*148.60 F
30	2		*rear fender air vent (WCP)	Not Necessary	30.00 F	*- F
31	1		*rear bumper (WCP)	Distorted	190.00 F	*190.00 F
32	2		*rear bumper side retainer (WCP)	Bent	18.00 F	*18.00 F
33	2		*rear bumper side holder (WCP)	Bent	8.00 F	*8.00 F
34	1		*rear bumper parking sensor	Shorted	450.00 FS	*200.00 FS
35	1		*rear bumper end splashshield cover (WCP)	Torn	18.00 F	*18.00 F
36	2		*rear bumper screws (WCP)	Necessary	10.00 F	*10.00 F
37	6		*rear bumper clips (WCP)	Necessary	12.00 F	*12.00 F
38	1		*rear exhaust box (WCP)	Dented / Twisted	280.00 F	*280.00 F
39	1		*rear exhaust box heat sheild (WCP)	Bent	22.00 F	*22.00 F
40	2		*rear exhaust box mount (WCP)	Torn	20.00 F	*20.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	5,183.20	3,014.60
+ Margin on L,N Items 15.00/15.00% (\$\$)	528.48	390.69
Total Parts (\$\$)	5,711.68	3,405.29

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Putty and spray painting of the affected portion.	New	2,000.00	1,000.00
Labour Items				
2	To reinstall of rear bumper parking sensor.	New	150.00	50.00
3	To reinstall back off camera and settings	New	120.00	0.00
4	To rust-proofing of the affected areas.	New	250.00	100.00
5	To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	New	180.00	80.00
6	To transfer of tailgate fittings, fixture and perform waterseepage test.	New	180.00	0.00
7	To remove and refit rear windscreen glass.	New	200.00	120.00
8	To check electrical lighting concerned.	New	60.00	30.00
9	To repair and realign rear exhaust box.	New	150.00	60.00
10	To drop petrol tank, hoses to facilitate bodywork repair, final checking and testing.	New	150.00	60.00
11	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New	2,800.00	1,500.00
Gross Labour Cost (S\$)			6,240.00	3,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >