

ASS. REC. BY:

REF: CS/MSG18011415/ARIC/302 Special Instruction:

Survivor:

Meinchen

Adnan  
celvenne fua

ASSIGNMENT (Office)

From (Person):

of

M8/G

Date/Time:

22/6/18 @

Estimated Cost:

Bill to:

OD (T) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM 4807C

Insured:

SV 56 Z

at Workshop m/s

N-51 Automotive

Tel:

6842 0051

of

2 kaki Bukit Ave 2 #01-18

Policy No:

80335810QMX

Claim No:

561995

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/06/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

3:53pm @ 22/6/18

Person Contacted:

Melody

Vehicle (IN) OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLM 4807C - X

SV 56 Z - CC41AXA 11602712 / Kw 2brl

DOA: 21/01/2011

## ASSIGNMENT

Veh No: SLM 4807C Yr Regn: 2017 / MA

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: NISSAN QASHQAI 1-2 c.c 1197

Colour Brown A/C: Insured / Std / NI / NA

Sp. Reading 124,197 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: SYNFEAS 1141792733

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R17

Re:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO/YOKO or

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 20/06/18 D.O.I. 22/06/18

Survey held at TWIN CAR

Vehicle: IN / OUT

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FRUIT

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 11 DEC 2018

☐ : Prelim. Report  
☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:  : Site Insp (\$

) Photos

Others

Report Format :

Lump Sum / I.B.I: (\$ 4800)

□: Interview (\$)

Tech. Invs (\$)

☐ : Weekend (\$) \_\_\_\_\_

TOTAL

200

10

210

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Jun 2018		22 Jun 2018 15:16 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	HIEW MOO YENG PAULINE, ID: S0071771A		
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Vehicle Reg. No.:	SLM4807C	Date of Loss:	20/06/2018 00:00 - :59 [14 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 561995	Policy/Cover Note No.:	80335810QMX Coverage: 27/09/2017 - 26/09/2018
Vehicle Reg. No. (Insured):	SV56Z	Policy No. (Claimant):	
		Excess:	
Repairer:	N-51automotive Pte Ltd (HQ) KAKI BUKIT AUTOHUB, 2 KAKI BUKIT AVE 2 #01-18, 417921 Kaki Bukit - Tel: 6842 0051 /67440510		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/06/2018]		
Adj Asg. Remarks:	on WP. oi non reporting. liability unclear. TP agree with SJE - assign LKK Auto Consultants Pte Ltd contact person: Melody - 6744 0510/ 6842 0051		

#### ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	7200G
<b>Vehicle Details</b>	
Vehicle No.:	SLM4807C
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Oct 2018
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	HRA2339643A
Chassis No.:	SJNFEAJ11U1792733
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$18,725.00
Original Registration Date:	31 Mar 2017
First Registration Date:	31 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$13,725.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Mar 2027
PARF Rebate Amount:	\$10,293.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	30 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,789.00
COE Rebate Amount:	\$42,897.00
<b>Total Rebate Amount:</b>	<b>\$53,190.00</b>

The information contained herein is correct as at 19 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	21/06/2018 12:12
Date Of Accident	20/06/2018 17:40
Exact Location Of Accident	ROCHOR ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLM4807C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005
<b>Vehicle Particulars</b>	
Manufacturer	NISSAN
Model	QASHQAI 1.2
Exact Purpose for which vehicle was being used at time of accident	HIRE & REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
<b>Insurance Company</b>	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29069766MKF
Cover Note Number	N.A
<b>Driver</b>	
Name of Driver	PANG KIM CHOI
NRIC No	S1509031F
Date Of Birth	27/10/1961
Occupation	OUTDOOR
Date Of Driving Pass	18/09/1984
Driving Experience	33 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90020244
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	269A YISHUN STREET 22 #02-533
Postcode	761269
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

All vehicles was already stopped due to pedestrians crossing. When the light turned green and I was about to move. Suddenly a vehicle from the left just drove towards my vehicle out from the yellow box. As a result, the vehicle hit directly onto my vehicle front left portion.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	YES - RETRIEVING
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SV56Z
Vehicle Make/Model/Colour	VOLVO XC90 T5 A/T ABS
Details Of Properties	NIL
Vehicle Category	PRIVATE CAR
Name of Driver	PHEE KIAN SENG
NRIC/Passport Number	S0746015E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Passenger 1

NAME: : PASSENGER 1

GENDER: : FEMALE

# Sketch Plan

SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured my vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS  
REPORTING OFFICER


AIZAM BIN ATAN

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
Personnel

## Sketch Plan





**ACCIDENT STATEMENT (2000 characters)**

All vehicles was already stopped due to pedestrians crossing. When the light turned green and I was about to move. Suddenly a vehicle from the left just drove towards my vehicle out from the yellow box. As a result, the vehicle hit directly onto my vehicle front left portion.

Taxi Voucher No.:

**DECLARATION**

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
AIZAM BIN ATAN

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

21 June 2018 at 10:30 AM

Date/Time:

21 June 2018 at 10:30 AM

# Zero Gravity

#01-25 Kaki Bukit Autohub  
2 Kaki Bukit Avenue 2  
Singapore 417921

Tel: 67412845 / 67477946

Work Order: R001680  
VIN: SLM4807C  
Technician: LSB  
Mileage: 124192  
Date: 25.6.18 17:46



Nissan/Datsun : Qashqai/Dualis : 2013- (J11) : Front Wheel Drive (HT Model - Rear Beam Axle)

## Front : Left

Actual	Before	Specified Range
-0°51'	-0°48'	-1°15' 0°15'
5°26'	5°26'	4°40' 6°10'
0°07'	-0°45'	0°05' 0°09'
11°02'	10°59'	10°00' 11°30'
10°11'	10°11'	8°45' 11°45'

Camber  
Caster  
Toe  
SAI  
Included Angle  
Turning Angle Diff.

## Front : Right

Actual	Before	Specified Range
-0°29'	-0°20'	-1°15' 0°15'
5°13'	5°13'	4°40' 6°10'
0°07'	-0°49'	0°05' 0°09'
11°01'	10°52'	10°00' 11°30'
10°32'	10°32'	8°45' 11°45'

## Front

Cross Camber  
Cross Caster  
Cross SAI  
Total Toe  
Cross Turn Diff.

Actual	Before	Specified Range
-0°22'	-0°28'	-0°36' 0°36'
0°13'	0°13'	-0°36' 0°36'
0°01'	0°07'	
0°14'	-1°34'	0°09' 0°19'

## Rear : Left

Actual	Before	Specified Range
-1°46'	-1°48'	-2°00' -1°00'
-0°04'	-0°04'	0°01' 0°25'

Camber  
Toe

## Rear : Right

Actual	Before	Specified Range
-1°11'	-1°11'	-2°00' -1°00'
0°06'	0°06'	0°01' 0°25'

## Rear

Cross Camber  
Total Toe  
Thrust Angle

Actual	Before	Specified Range
-0°34'	-0°36'	
0°02'	0°02'	0°02' 0°50'
-0°05'	-0°05'	

er: R001669  
 SLM4807C  
 nician: 1111  
 eage: 124191  
 Date 21.6.18 10:56

Nissan/Datsun : Qashqal/Dualis : 2013- (J11) : Front Wheel Drive (HT Model - Rear Beam Axle) : Rest of World with 16", 17" Wheel

Front : Left

Actual	Before	Specified Range
-0°36'		-1°15' 0°15'
		4°40' 6°10'
-0°54'		0°05' 0°09'
		10°00' 11°30'
		8°45' 11°45'

Camber  
 Caster  
 Toe  
 SAI  
 Included Angle  
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°41'		-1°15' 0°15'
		4°40' 6°10'
-0°23'		0°05' 0°09'
		10°00' 11°30'
		8°45' 11°45'

Front

Cross Camber  
 Cross Caster  
 Cross SAI  
 Total Toe  
 Cross Turn Diff.

Actual	Before	Specified Range
0°05'		-0°36' 0°36'
		-0°36' 0°36'
-1°17'		0°09' 0°19'

Rear : Left

Actual	Before	Specified Range
-1°39'		-2°00' -1°00'
-0°03'		0°01' 0°25'

Camber  
 Toe

Rear : Right

Actual	Before	Specified Range
-1°10'		-2°00' -1°00'
0°11'		0°01' 0°25'

Rear

Cross Camber  
 Total Toe  
 Thrust Angle

Actual	Before	Specified Range
-0°29'		
0°08'		0°02' 0°50'
-0°07'		

REMARK:  
 L/H/F MISALIGNMENT

WinAlign 12.1 B896 International 2018.0.1 HS201L

SURVEYOR NAME & COMPANY :	1
NAME :	2
CONTACT :	3
OUR SERVEYOR :	4
CUSTOMER REQUEST :	5
1	6
2	7
3	8
4	

# **N51 AUTOMOTIVE PTE LTD**

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

**GRAB RENTALS PTE LTD**  
 18 SIN MING LANE #01-08 MIDVIEW CITY  
 SINGAPORE 573960

Contact : 66550005 90020244

TPMS LG.

Janice

wheel alignment  
report.

## ESTIMATE

Repair Code : CLM14594  
 Date in : 21/06/2018  
 Vehicle Num. : SLM4807C  
 Model : NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR  
 Chassis/Eng# : SJNFEAJ11U1792733/HRA2339643A

### Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>deformed.</i>	1	1855.00	<del>1,855.00</del> 646
FRONT BUMPER LH FOGLAMP <i>Not new</i>	1	321.60	321.60 x
FRONT BUMPER LH FOGLAMP CHROME GARNISH <i>Not new</i>	1	74.70	74.70 x
FRONT BUMPER SIDE RETAINER L/R <i>LH damaged</i>	2	20.90	<del>41.80</del> 20.9
FRONT BUMPER SPONGE <i>Not new</i>	1	195.70	195.70 x
FRONT GRILLE <i>crushed</i>	1	498.30	498.30 ✓
FRONT LH ABS SENSOR <i>Not new</i>	1	361.20	361.20 x
FRONT LH FENDER <i>Deformed</i>	1	622.70	622.70 ✓
FRONT LH FENDER INNER PANEL <i>Repair</i>	1	355.00	355.00 x
FRONT LH FENDER INNER SHIELD <i>Deformed</i>	1	87.50	87.50 ✓
FRONT LH FENDER SIDE ARCH GARNISH <i>lit</i>	1	483.00	483.00 ✓
FRONT LH HEADLAMP <i>lit</i>	1	559.00	559.00 ✓
FRONT LH KNUCKLE ARM <i>Bent</i>	1	534.30	534.30 ✓
FRONT LH LOWER ARM <i>Bent</i>	1	240.50	240.50 ✓
FRONT LH SHOCK ABSORBER <i>Bent</i>	1	547.50	547.50 ✓
FRONT LH SHOCK ABSORBER TOP MOUNTING <i>Not new</i>	1	99.10	99.10 x
FRONT LH SPORT RIM <i>lit</i>	1	1231.90	<del>1,231.90</del> 680 (2x)
FRONT LH SPORT RIM CAP <i>missing</i>	1	18.50	18.50 ✓



# N51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 90020244

## ESTIMATE

Repair Code : CLM14594

Date in : 21/06/2018

Vehicle Num. : SLM4807C

Model : NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR

Chassis/Eng# : SJNFEAJ11U1792733/HRA2339643A

5238.40  
- 10% 523.84  
4714.56

FRONT LH STABILIZER LINK	2	2938.30	4558.41	32.30	32.30	*
FRONT LH TIE ROD END	1	2642.31	4102.36	112.40	112.40	*
FRONT LH WHEEL BEARING	1	300.20	300.20	300.20	300.20	✓
Subtotal before discount				8,572.20		
Percentage discount 10%				857.22		
Sub-total 1				7,714.98		
FRONT BUMPER CLIPS - SET	1	80.00	80.00	80.00	30	
FRONT GRILLE CLIPS - SET	1	60.00	60.00	60.00	15	
FRONT LH 215/60R17 TYRE	1	480.00	480.00	480.00	*	
FRONT LH DRIVE SHAFT	1	1018.50	1,018.50	1,018.50	*	
FRONT LH FENDER INNER SHIELD CLIPS - SET	1	80.00	80.00	80.00	30	
FRONT LH FENDER SIDE ARCH GARNISH CLIPS - SET	1	40.00	40.00	40.00	20	
Subtotal before discount				1,758.50		
Percentage discount 0%				0.00		
Sub-total 2				1,758.50		
Parts-total				9,473.48		

## LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

100.00 30

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

200.00 ✓

\*\*\* This is a computer-generated document which requires no signature.\*\*\*



# N51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 90020244

## ESTIMATE

Repair Code : CLM14594

Date in : 21/06/2018

Vehicle Num. : SLM4807C

Model : NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR

Chassis/Eng# : SJNFEAJ11U1792733/HRA2339643A

To road test driving, check and resetting wheel alignments system.

~~120.00~~ 80.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

1110

~~700.00~~ 400

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

~~600.00~~ 400

To apply anti-rust chemical on repaired and replaced panel.

~~120.00~~ x.

**Labour Total**

**1,840.00**

**Parts & Labour Total**

**11,313.48**

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 4527.81  
h/s: 3.6K  
5307.56  
4.2K  
5987.56

0.5 Days.

45: 4.8K

ok

5919.56  
-20% 1183.91  
4735.64

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Jun 2018		22 Jun 2018 15:16 <a href="#">Edit Adj Rpt</a>	<b>S\$4,800.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,800.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>


















































Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>HIEW MOO YENG PAULINE</b> , ID: S0071771A									
Main Claimant: <b>GRAB RENTALS PTE LTD</b> , Co. Reg. No.: 201617200G									
Vehicle Reg. No.: <b>SLM4807C</b>		Date of Loss:	20/06/2018 00:00 - :59 [14 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type: <b>TP / 561995</b>		Policy/Cover Note No.:	80335810QMX Coverage: 27/09/2017 - 26/09/2018						
Vehicle Reg. No. (Insured): <b>SV56Z</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>N-51automotive Pte Ltd (HQ)</b> KAKI BUKIT AUTOHUB, 2 KAKI BUKIT AVE 2 #01-18, 417921 Kaki Bukit - Tel: 6842 0051 / 67440510									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Catherine Thia Shi Yi</b> - 6594 2545]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 22/07/2018]									
Adj Asg. Remarks: on WP. oi non reporting. liability unclear. TP agree with SJE - assign LKK Auto Consultants Pte Ltd contact person: Melody - 6744 0510/ 6842 0051									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLM4807C (561995)  
[SV56Z]  
TP  
GRAB RENTALS PTE LTD  
Jun 20 2018 12:00AM  
[HIEW MOO YENG PAULINE]  
N-51automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Assessment Reports									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	11/12/18 13:53	Adjuster Immediate Advice								Load HTM		
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print	
1	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
2	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
3	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
4	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
5	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
6	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
7	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
8	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
9	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
10	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
11	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
12	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
13	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
14	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
15	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
16	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
17	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
18	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
19	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
20	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
21	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
22	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
23	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
24	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
25	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
26	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
27	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
28	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
29	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
30	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
31	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
32	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
33	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	
34	11/10/18 17:56	General View								Load JPG	<input checked="" type="checkbox"/>	



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	11/10/18 17:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/06/18 09:37	TP PRI Request and GIA report	 Load PDF	
2	22/06/18 09:38	TP PRI Request email	 Load PDF	
3	22/06/18 11:13	tp agree with SJE - lkk	 Load PDF	
4	22/06/18 11:14	tp agree with SJE- email -LKK Auto Consultants	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18011415/AR1CD3E2

Date: 17/12/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80335810QMX

Claimant Vehicle No : SLM4807C

Insured Vehicle No : SV56Z

Date of Loss: 20/06/2018

Nature of Claim: TP

Claim No: 561995

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLM4807C

Make &amp; Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)

Engine No: HRA2339643A

Reg. Date: 31/03/2017 (Man. Year: 2016)

Chassis No: SJNFEAJ11U1792733

Colour: Brown

Odometer: 124197 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,473.48	4,877.56	4,595.92	48.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,840.00	1,110.00	730.00	39.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,313.48</b>	<b>5,987.56</b>	<b>5,325.92</b>	<b>47.08</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,800.00</b>		
<b>(S\$)</b>	<b>11,313.48</b>	<b>4,800.00</b>	<b>6,513.48</b>	<b>57.57</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>791.94</b>	<b>336.00</b>	<b>455.94</b>	<b>57.57</b>
<b>Nett Amount (S\$)</b>	<b>12,105.42</b>	<b>5,136.00</b>	<b>6,969.42</b>	<b>57.57</b>

## INSPECTION

Date of Assignment: 22/06/2018

Date Inspected: 22/06/2018 Inspected At:

N-51automotive Pte Ltd (HQ)  
KAKI BUKIT AUTOHUB, 2 KAKI BUKIT  
AVE 2 #01-18  
Singapore 417921

Estimated Period of Repair: 5.0 days

---

**Adjuster:** MOHD RASUL**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Dec 2018)

Parts: M1-SUV NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLM4807C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,855.00 FL	*646.00 FL
2	1		*FRONT BUMPER LH FOGLAMP	Not Necessary	321.60 FL	*- FL
3	1		*FRONT BUMPER LH FOGLAMP CHROME GARNISH	Not Necessary	74.70 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER L/R	N/S Damaged	41.80 FL	*20.90 FL
5	1		*FRONT BUMPER SPONGE	Not Necessary	195.70 FL	*- FL
6	1		*FRONT GRILLE	Cracked	498.30 FL	*498.30 FL
7	1		*FRONT LH ABS SENSOR	Not Necessary	361.20 FL	*- FL
8	1		*FRONT LH FENDER	Dented	622.70 FL	*622.70 FL
9	1		*FRONT LH FENDER INNER PANEL	Repair	355.00 FL	*- FL
10	1		*FRONT LH FENDER INNER SHIELD	Deformed	87.50 FL	*87.50 FL
11	1		*FRONT LH FENDER SIDE ARCH GARNISH	Cut	483.00 FL	*483.00 FL
12	1		*FRONT LH HEADLAMP	Cut	559.00 FL	*559.00 FL
13	1		*FRONT LH KNUCKLE ARM	Bent	534.30 FL	*534.30 FL
14	1		*FRONT LH LOWER ARM	Bent	240.50 FL	*240.50 FL
15	1		*FRONT LH SHOCK ABSORBER	Bent	547.50 FL	*547.50 FL
16	1		*FRONT LH SHOCK ABSORBER TOP MOUNTING	Not Necessary	99.10 FL	*- FL
17	1		*FRONT LH SPORT RIM	Cut	1,108.71 FS	*680.00 FS
18	1		*FRONT LH SPORT RIM CAP	Missing	18.50 FL	*18.50 FL
19	1		*FRONT LH STABILIZER LINK	Not Necessary	32.30 FL	*- FL
20	1		*FRONT LH TIE ROD END	Not Necessary	112.40 FL	*- FL
21	1		*FRONT LH WHEEL BEARING	Necessary	300.20 FL	*300.20 FL
22	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
23	1		*SET FRONT GRILLE CLIPS	Necessary	60.00 FS	*15.00 FS
24	1		*FRONT LH 215/60R17 TYRE	Not Necessary	480.00 FS	*- FS
25	1		*FRONT LH DRIVE SHAFT	Not Necessary	1,018.50 FS	*- FS
26	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	Necessary	80.00 FS	*30.00 FS
27	1		*SET FRONT LH FENDER SIDE ARCH GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 10,207.51 5,333.40

- List Item Discount on L Items 10.00/10.00% (\$\$) 734.03 455.84

Total Parts (\$\$) 9,473.48 4,877.56

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM	New	120.00	80.00
2	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	700.00	400.00
3	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	600.00	400.00
4	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	0.00
5	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTNG HEADLAMP FOCUSING. (TO FR)	New	100.00	30.00
6	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION	New	200.00	200.00
Gross Labour Cost (\$\$)			<b>1,840.00</b>	<b>1,110.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >