

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL; (065) 6256 3561 FAX; (065) 6256 4315

Your Ref: CLS.2017.215700

Date: 04th September 2018

Our Ref: CS3/AXA14023220/Grbs2-1

M/s AXA Insurance Pte Ltd

C/O: ComLaw LLC 64 Cecil Street #06-01 IOB Building Singapore 049711

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SGZ 7057X INSURED VEHICLE: GQ 8751R ACCIDENT DATE: 12/12/2014

We thank you for your instruction on 20/06/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SGZ 7057X from M/s Carlink Consultancy.
- b) Final Repair Bill of SGZ 7057X from M/s EM1 Auto Pte Ltd.
- c) Singapore Accident Statement of Vehicles SGZ 7057X and GQ 8751R.
- d) Colour damaged vehicle photographs of SGZ 7057X.

Pre-Repair Inspection Date: 16/12/2014 at M/s EM-1 Auto Pte Ltd, Blk 8 Sin Ming Industrial Estate Sector C #01-68 Singapore 575643.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

Information Recorded: -

Registration Number

: SGZ 7057X

Make & Model

: Suzuki Swift 1.5 MT

Year of Registration

: 2007

Chassis Number

: JSAEZ21S00406982

Engine Capacity

: 1490 cc

- We recommend that the repairs of the entire damage require about ______ working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.