

ASS. REC. BY:

REF es/FCI18011467 / Krd302

Surveyor
CWS

Kenneth

ASSIGNMENT (Office)

From (Person):

May chun

of

FCI

Date/Time:

23/6/18 @ 12:18pm

Estimated Cost:

Bill to:

OD TP WWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 5804D

Insured:

SHC 3440H

at Workshop m/s:

Trans Carb

Tel:

6287 6666

of

No. 2 AMK sf-63

Policy No:

Claim No:

D18004942 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 21/06/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

8:39am @ 25/6/18

Person Contacted:

Candy

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 5804D - CC3 / EQI14600862 / Ky4342-1 DOA: 12/01/2014
	SHC 3440H - CC3 / FCI18009958 / Gtd3 - DOA: 23/05/2018
	Report from email.

REF: FCI

ASSIGNMENT

Form Date: 25/6/2018

Estimated Cost:

OD: ☒ WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: SHC 5804D

at Workshop n/s

Trans - Carb

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 07 days Res: Yes or No

Lump Sum: 1. B. 1% 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHC 5804D Yr Regn: 07 15

Type: M/Car / M/Cycle / Bus / Van / Lorry ☒ Prime Mover /

Truck / Trailer or

Make: Peugeot ^{Al} Corbiade CC 1995

Colour: m. White / Red A/C: Insured / Std / NI / NA

Sp. Reading: 370929 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VF1A BL15AUC 281666

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inoper / Jammed / Leaked / Burnt orBrake: ☒ Inoper / Jammed / Leaked / Burnt orMod: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: C71 215/60R16

R: F71 141

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 9 mm

L/Bal: 9 mm

D.O.A: 21/6/18

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

26/6 14h pass to Catherine
 @ 9191.94
 (Red: 101, 185.73, 92%.)

RECEIVED 27 JUN 2018

Title/Time: File Pass Not

☐ : Prel. Report

11 typist

☒ : Final Report

Title/Time: File Return Not

Days Of Repair: 7

Resurvey No. of Trip: -

Add Fee: ☐ Site Insp. (\$)☐ Interview (\$)☐ Tech. Insp. (\$)☐ Workshop (\$)

Report Format: TP

Lump Sum / L.B. (\$): 9191.94

Survey Fee:

Transportation:

150

059

27/6/18

100x15: 1500

170+1500

50

22

1742

MOTOR SURVEY ASSIGNMENT

Date	22-06-2018	Our Ref No. D18004942MFSH
Accident Date	21-06-2018	Claim Type. Third Party
Insured Vehicle	SHC3440H	Third Party Vehicle. SHC5804D
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	<i>Handwritten signature and checkmark</i>
Contact No.	62876666/ 62876666	
		Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED: PLEASE LET US HAVE YOUR PRELIMINARY REPO	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241703)



PRI Documents



Close



PRI Header Details

Claim No	D18004942MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & TRANS-C/
Workshop Name	TRANS-CAB AUTO SERVICES PTE LTD (Contact Person : CANDY KONG)	Survey Location & Contact Details	NO. 2 ANG MO KIO STREET 63 Mobile: 62876666 , Phone: 62876666 , Fax: 62571331 EmailId: CANDY.KONG@TRANSCAB.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM US HAVE YOUR PRELIMINARY REPO		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC3440H	TP Vehicle No	SHC5804D
PRI Recieved Date	22-06-2018 05:30:09 PM	Surveyor Appointed Date	23-06-2018 12:17:31 PM	Surveyor Accept Date	25-06-2018 1

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	25-06-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Your Ref: D18004942MFSHOur Ref: CS/FCI18011467/Krd3The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5804D .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 25.06.2018 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>110,377.67</u> .
Revised Estimate Amount	: S\$ <u>9,191.94</u> .
"Check" Items Amount	: S\$ _____ .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages
at rear portion.

Yours faithfully
KENNETH
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/06/2018 13:52
Date Of Accident	21/06/2018 02:25
Exact Location Of Accident	RIVER VALLEY ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5804D
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	TENG FOOK SENG
NRIC No	S0265649C
Date Of Birth	05/09/1946
Occupation	OUTDOOR
Date Of Driving Pass	20/10/1971
Driving Experience	46 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82605905
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 336 HOUGANG AVENUE 7 #12-371
Postcode	530336
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOUGANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 60 HOUGANG AVE 9 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4890999 - FAX NO: 63128989
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACH POLICE REPORT : T/20180621/2032

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC3440H
Vehicle Make/Model/Colour	COMFORT TAXI
Details Of Properties	
Vehicle Category	TAXI
Name of Driver:	C. SIVAKANDAN
NRIC/Passport Number	S1736601G
Contact Number	90571029
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SH7341C
Vehicle Make/Model/Colour	COMFORT TAXI
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	ROSLI
NRIC/Passport Number	
Contact Number	83122658
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TENG FOOK SENG
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHC5804D
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

River valley Road	9	+	9	A= SHC 5804D
	E			B= SHC 34401
	A			C= SH 7341C
	B			

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach police report

DECLARATION

(/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

(GAT/MC SketchPlanForm_V3)

2

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20180621/2032

1 of 4

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20180621/2032

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/06/2018 10:05		Vide Report No.:		Station Diary No.: 22	
Informant's Particulars					
Name of Informant: TENG FOOK SENG		Address: APT BLK 336 HOUGANG AVENUE 7 #12-371 SINGAPORE 530336			
ID Type / ID No.: NRIC NO / S0265649C		Contact No.: Home/Office: Mobile: 82605905			
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Male	Age: 71	Date of Birth: 05/09/1946	Type of Informant: Driver		
Race: Chinese		Language:		Institution / School Name:	
Occupation: Taxi driver		Driving Licence Information: Class: Date of Expiry:			

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 21/06/2018 02:25	Type of Location: Straight Road
Location: Along Road 1 RIVER VALLEY ROAD ALONG RIVER VALLEY ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SH7341C	Car					0
SHC3440H	Car					0
SHC5804D	Car				Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20180621/2032

2 of 4

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20180621/2032

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	C. SIVAKANDAN	ID No.	S1736601G
Related Vehicle	SHC3440H (Car)	Contact No.	90571029
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TENG FOOK SENG	ID No.	S0265649C
Related Vehicle	SHC5804D (Car)	Contact No.	82605905
Hospital/Clinic	POW FAMILY CLINIC & SURGERY	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	21/06/2018	Date Discharge	21/06/2018
No. of Days granted Medical Leave	04	Degree of Injury	Slight

Brief Details.

On 21/06/2018 at about 0225hrs, I was driving my taxi, SHC5804D, and was queuing up along River Valley Road and heading to the taxi stand at Clark Quay. As I was waiting, I felt an impact on the rear of my vehicle.

Due to the impact, my vehicle which was stationary move forward and hit onto the vehicle, SH7341C (Red, HP, 83122658). After the accident, I went down and make a check and spoke to the driver (Vehicle number: SHC3440H) who had hit onto the rear of my vehicle. The said driver informed me that he wanted to apply brake to stop his car however he accidentally apply pressure on the accelerator which resulted in the car moving forward and hit onto my rear. All of us exchanged particular.

After the accident, I felt sick and discomfort however neither police nor ambulance was activated. Due to the accident, the rear bumper of my vehicle was damage, the car sensor was not working and I am unable to close the boot of my vehicle. The front of my vehicle was also damaged.

After resting for a few hours, I then proceeded to the clinic for medical treatment and was given 4 days of MC.

HOUGANG NPC
60 HOUGANG AVE 9
SINGAPORE 538775
Tel: 1800-4890999



**SINGAPORE
POLICE FORCE**



T/20180621/2032

4 of 4

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20180621/2032

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 3 PHUA JIA JUN, MARK

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

21/06/2018 10:05

Officer In Charge Of Case:

TP / GIA /

Staff Sgt TANG SIEW PING

Contact No.: 65476430

Classification Of Case:

Authentication Stamp
NP168



SN 085

Signature:



**SINGAPORE
POLICE FORCE**



T/20180621/2032

3 of 4

Police Station Of Origin:

Hougang N.P.C

60 Hougang Avenue 9 SINGAPORE 538775

Tel No: 1800-4890999

Report No. T/20180621/2032

CONTINUATION OF REPORT

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5804D
Vehicle to be Exported:	Yes
Intended De-registration Date:	21 Jun 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002535
Chassis No.:	VF1ABL15AUC281666
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	16 Jul 2015
First Registration Date:	16 Jul 2015
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Jul 2023
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	15 Jul 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$53,004.00
COE Rebate Amount:	\$33,560.00
Total Rebate Amount:	\$48,558.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 21 Jun 2018

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5804D**AAD1806-199***Not Authored**Resurvey B4paim*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5804D

VF1ABL15AUC281666

RENAULT

LATITUDE

21.6.2018

FCIL**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>AD101</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47 X
4	1 BUMPR BRACKET SIDE RH REAR	\$	<i>SL</i> 135.97 X
5	1 BUMPR RETAINER RH REAR	\$	<i>SL</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>SL</i> 43.61 X
7	1 BUMPR BRACKET SIDE LH REAR	\$	<i>SL</i> 135.97 X
8	1 BUMPR RETAINER LH REAR	\$	<i>SL</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>CM</i> 43.61 ✓
10	1 BUMPER BEAM REAR	\$	<i>B</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>B</i> 225.95 ✓
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95 X
13	1 BOOT REAR	\$	<i>R</i> 2,872.68 X
14	1 BOOT FINISHER	\$	<i>SL</i> 470.06
15	1 BOOT WHEATERSTRIP	\$	<i>SL</i> 323.05
16	1 BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 493.35
17	1 BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 493.35
18	1 BOOT BADGE 'RENAULT'	\$	<i>nn</i> 225.36
19	1 BOOT BADGE	\$	<i>nn</i> 225.36
20	1 BOOT STRUT LH	\$	<i>SL</i> 276.08
21	1 BOOT STRUT RH	\$	<i>SL</i> 276.08
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84
24	1 BOOT INNER TRIM	\$	<i>SL</i> 586.45
25	1 BOOT SWITCH	\$	<i>SL</i> 168.13
26	1 BOOT LOCK	\$	<i>R</i> 202.67
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2 LICENCE PLATE LAMP	\$	<i>SL</i> 50.52
29	2 BOOT RUBBER PLUG	\$	<i>R</i> 221.81

Trans-cab Auto Services Pte Ltd**AAD1806-199**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5804D

30	1 DOOR PANEL REAR LH	\$	R	2,844.66	}	X
31	1 FENDER PANEL INNER TRIM REAR LH	\$	SL	671.45		
32	1 FENDER PANEL REAR LH	\$	R	3,299.13		
33	1 WHEELARCH REAR LH	\$	SL	543.47		
34	1 FENDER PANEL INNER TRIM REAR RH	\$	SL	671.45		
35	1 FENDER PANEL REAR RH	\$	R	3,299.13		
36	1 WHEELARCH REAR RH	\$	SL	543.47		
37	1 TAILLAMP RH	\$	SL	552.55		
38	1 TAILLAMP PANEL RH	\$	R	986.70		
39	1 TAILLAMP LH	\$	SL	552.55		
40	1 TAILLAMP PANEL LH	\$	R	986.70		
41	1 OUTER PANEL REAR (End Panel)	\$	B	1,471.77	✓	
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	CM	404.56	—	
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X	
44	1 SPARE WHEEL PANEL TRIM	\$	SL	612.21	X	
45	1 EXHAUST REAR	\$	R	7,489.05	X	
46	1 EXHAUST CAP REAR	\$	R	230.49	X	
47	1 FUEL FLAP L70Y	\$	SL	343.57	X	
48	1 BUMPER COVER FRT	\$	PJ/M	1,259.42	✓	
49	1 BUMPER SPOILER FRT	\$	SL	181.75	}	X
50	1 BUMPER ABSORBER FRT	\$	SL	394.68		
51	1 BUMPER RETAINER FRT LH	\$	SL	151.41		
52	1 BUMPER SUPPORT FRT	\$	SL	123.88		
53	1 BUMPER RETAINER FRT RH	\$	SL	150.77		
54	1 BUMPER SUPPORT FRT	\$	SL	123.88		
55	1 BUMPER UNDERTRAY FRT	\$	SL	472.83		
56	1 BUMPER GRILLE LOWER FRT	\$	SL	266.80		
57	1 BUMPER FOG LAMP GRILLE LH	\$	SL	207.21		
58	1 BUMPER FOG LAMP GRILLE RH	\$	SL	207.21		
59	1 BUMPER BEAM FRT	\$	R	914.08	}	X
60	1 TOW COVER FRT	\$	SL	28.61		
61	1 RADIATOR GRILLE	\$	CM	1,707.78		
62	1 RADIATOR GRILLE BADGE 'RENAULT'	\$	R	225.36		
63	1 RADIATOR GRILLE FRAME	\$	SL	1,353.75	}	X
64	1 FRAME FULL SUPPORT PANEL	\$	SL	615.90		
65	1 FRAME FULL SUPPORT BRACKET	\$	R	89.79		
66	1 FRONT BRACE PANEL	\$	R	177.22		
67	1 HORN	\$	SL	314.17	}	X
68	1 HORN BRACKET	\$	R	40.45		

Trans-cab Auto Services Pte Ltd

AAD1806-199

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5804D

69	1 HEADLAMP LH	\$	1,184.43
70	1 HEADLAMP RH	\$	1,184.43
71	1 HEADLAMP PANEL FRT LH	\$	152.15
72	1 HEADLAMP PANEL FRT RH	\$	152.15
73	1 BONNET	\$	1,941.63
74	1 BONNET INSULATOR	\$	405.73
75	1 BONNET STRUT LH	\$	88.61
76	1 BONNET STRUT RH	\$	88.61
77	1 BONNET HINGE LH	\$	348.31
78	1 BONNET HINGE RH	\$	348.31
79	1 BONNET LOCK	\$	305.48
80	1 BONNET CABLE	\$	119.19
81	1 BONNET CABLE COVER	\$	161.03
82	1 BONNET SEAL OUTER	\$	92.36
83	1 BONNET SEAL INNER	\$	157.28
84	1 FENDER PANEL FRT LH	\$	783.83
85	1 WHEELARCH FRT LH	\$	278.84
86	1 FENDER BRACKET LOWER LH	\$	15.79
87	1 FENDER INSULATOR LH	\$	130.84
88	1 FENDER INSULATOR RH	\$	130.84
89	1 AIR CLEANER LOWER	\$	271.26
90	1 AIR CLEANER HOSE	\$	76.14
91	1 BASE BATTERY TRAY	\$	363.40
92	1 AIR CLEANER BOX	\$	464.20
93	1 TURBO DUCT	\$	1,027.80
94	1 A/C HEATER VALVE	\$	484.50
95	1 SUBFRAME OUTER FRT	\$	2,652.45
96	1 SUBFRAME BRACKET OUTER LH	\$	92.36
97	1 ENGINE UNDERTRAY	\$	564.98
98	1 A/C CONDENSER	\$	2,020.37
99	1 A/C CONDENSER GARNISH LH UPPER	\$	39.67
100	1 A/C CONDENSER GARNISH RH UPPER	\$	39.67
101	1 A/C CONDENSER GARNISH LH	\$	58.81
102	1 A/C CONDENSER GARNISH RH	\$	59.60
103	1 A/C PIPE CONDENSER TO COMPRESSOR	\$	208.39
104	1 A/C PIPE CONDENSER TO EXPENSION VALVE	\$	658.72
105	1 A/C PIPE COMPRESSOR	\$	334.29
106	1 A/C PIPE	\$	658.72

X

Trans-cab Auto Services Pte Ltd

AAD1806-199

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5804D

107	1 A/C COMPRESSOR	\$	S\$ 2,684.61	}
108	1 AIR COOLER	\$	S\$ 792.60	
109	1 AIR INTERCOOLER HOSE (LONG)	\$	S\$ 1,014.13	
110	1 AIR INTERCOOLER HOSE (Short)	\$	S\$ 375.14	
111	1 TRANSMISSION COOLER	\$	S\$ 1,219.30	
112	1 TRANSMISSION COOLER PAD	\$	S\$ 17.96	
113	1 RADIATOR	\$	S\$ 1,202.20	
114	2 RADIATOR STUD UPPER	\$	S\$ 14.41	
115	2 RADIATOR BUSH UPPER	\$	S\$ 50.12	
116	2 RADIATOR MTG LOWER	\$	S\$ 55.85	
117	1 RADIATOR FAN COWLING	\$	S\$ 820.54	
118	1 RADIATOR FAN MOTOR LH	\$	S\$ 967.36	
119	1 RADIATOR FAN MOTOR RH	\$	S\$ 1,479.46	
120	1 RADIATOR TANK	\$	S\$ 324.62	
121	1 RADIATOR HOSE UPPER	\$	S\$ 240.56	
122	1 RADIATOR HOSE LOWER	\$	S\$ 491.18	
123	1 RADIATOR TANK HOSE	\$	S\$ 61.18	
124	1 AUTO COMPUTER	\$	S\$ 5,032.17	
125	1 INJECTION COMPUTER	\$	S\$ 4,706.30	
126	1 RHD HYDRAULIC POWER(ROCK&PINION)	\$	S\$ 5,154.52	}
127	1 STEERING PUMP ELECTRIC L70Y	\$	S\$ 2,306.90	
128	1 STEERING PINION RACK L70Y	\$	S\$ 4,413.11	

TOTAL	\$	99,633.49
10%	\$	9,963.35
	\$	89,670.15

Special Nett

1 1SET PARKING AID	\$	S\$ 700.00 X
2 1SET REAR BUMPER CLIP	\$	S\$ 66.00 —
3 1SET BUMPER BRACKET CTR CLIP	\$	S\$ 33.00 ✓
4 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	S\$ 10.00 X
5 1SET BUMPER RETAINER RH CLIP RR	\$	S\$ 20.00 X
6 1SET BUMPER BRACKET SIDE CLIP LH RR	\$	S\$ 10.00 X
7 1SET BUMPER RETAINER CLIP LH RR	\$	S\$ 20.00 X
8 1SET BUMPER LOWER REAR RIVET	\$	S\$ 22.00 X
9 1SET BUMPER LOWER REAR CLIP	\$	S\$ 66.00 ✓

Trans-cab Auto Services Pte Ltd

AAD1806-199

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5804D

10	1 EXHAUST MOUNTING REAR	\$	na	17.82	}	X
11	1SET BOOT FINISHER CLIP	\$	na	24.20		
12	1 BOOT STICKER "Trans-cab"	\$	na	30.00		
13	1 BOOT STICKER "6555-3333"	\$	na	30.00		
14	1 BOOT INNER TRIM CLIP	\$	na	45.00		
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00		
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00		
17	1 FENDER INNER TRIM CLIP LH	\$	na	28.00		
18	1 FENDER INNER TRIM CLIP LH	\$	na	28.00		
19	1 TAILLAMP CLIP RH	\$	na	5.00		
20	1 TAILLAMP CLIP LH	\$	na	5.00	}	X
21	2 REAR WINDSCREEN SELANT	\$	na	80.00		
22	1 WINDSCREEN MOULDING	\$	na	100.00		
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00		
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sm na	385.00		
25	1 SPARE TYRE	\$	Sm na	330.00		
26	1SET RADIATOR GRILLE FRAME CLIP	\$	na	52.00		
27	1SET BUMPER CLIP FRT	\$	na	66.00		
28	1 BUMPER BRACKET CLIP FRT LH	\$	na	12.00		
29	1 BUMPER SUPPORT CLIP FRT LH	\$	na	10.50		
30	1 BUMPER BRACKET CLIP FRT RH	\$	na	12.00	}	X
31	1 BUMPER SUPPORT CLIP FRT RH	\$	na	10.50		
32	1 TOW COVER FRT	\$	Sm	14.50		
33	1SET RADAITOR GRILLE SCREW	\$	na	16.00		
34	1SET BUMPER GRILLE LOWER CLIP	\$	na	69.00		
35	1SET FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00		
36	2 FRAME FULL SUPPORT PANEL NUT	\$	na	20.00		
37	2 FRAME FULL SUPPORT PANEL STUD	\$	na	30.00		
38	1 Windscreen moulding	\$	na	100.00		
39	1SET Front licence plate with holder	\$	Bj	80.00		455na

TOTAL \$ 2,787.52

TOTAL PARTS \$ 92,457.67

LABOUR

Putty And Spray Painting Of The Affected Portion. \$ 6,000.00 660

Trans-cab Auto Services Pte Ltd**AAD1806-199**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5804D

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	8001
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	~ 170.00	X
To repair and realign rear exhaust pipe.	\$	~ 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	~ 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	~ 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~ 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00	X
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	~ 380.00	X
Towing Fees.	\$	~ 120.00	X

Trans-cab Auto Services Pte Ltd

AAD1806-199

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5804D

To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00 X
To rust-proofing of the affected areas.	\$	Review 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 301
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	nn 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00 X
To lift-up engine with gear box and refit.	\$	nn 440.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	nn 440.00 X
To remove and refit air bag system and reset.	\$	nn 480.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	nn 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	nn 380.00 X
To replace, refix and top up coolant for radiator	\$	nn 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1806-199

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5804D

To vacuum, replace, refix and recharge Air
Intercooler

\$ *nn* 170.00 X

To Transfer Of Fender Fittings, Attachments And
Perform Water Seepage Test.

\$ *nn* 170.00 X**TOTAL \$ 17,920.00****Over All Total \$ 110,377.67**~~(LUMP-SUM)~~

Repair Days

*20 DAYS**7 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18011467/Krd3e2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 04-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3440H	Veh. Inspected	SHC 5804D
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18004942MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	23/06/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	VF1ABL15AUC281666	Colour	METALLIC WHITE / RED
Odometer	370929	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	9 mm
L/H Front Tyre	215/60 R16	GITI	9 mm
R/H Rear Tyre	215/60 R16	FALKEN	7 mm
L/H Rear Tyre	215/60 R16	FALKEN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	21/06/2018	Inspection Date	25/06/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 8

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5804D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DENTED / DISTORTED	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	CRACKED	43.61	43.61
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	BENT	225.95	225.95
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE 'RENAULT'	NOT NECESSARY	225.36	-
1	BOOT BADGE	NOT NECESSARY	225.36	-
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-

Report Ref No. CS/FCI18011467/Krd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR	2,844.66	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	CRACKED	404.56	404.56
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
1	FUEL FLAP L70Y	SERVICEABLE	343.57	-
1	BUMPER COVER FRT	DENTED / CRACKED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT LH	SERVICEABLE	151.41	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER RETAINER FRT RH	SERVICEABLE	150.77	-

Report Ref No. CS/FCI18011467/Krd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:3 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.21	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	TOW COVER FRT	SERVICEABLE	28.61	-
1	RADIATOR GRILLE	CRACKED	1,707.78	1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	NECESSARY	225.36	225.36
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	-
1	HORN	SERVICEABLE	314.17	-
1	HORN BRACKET	TO REPAIR SEE LABOUR	40.45	-
1	HEADLAMP LH	TO REPAIR SEE LABOUR	1,184.43	-
1	HEADLAMP RH	TO REPAIR SEE LABOUR	1,184.43	-
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	BONNET	TO REPAIR SEE LABOUR	1,941.63	-
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET STRUT LH	SERVICEABLE	88.61	-
1	BONNET STRUT RH	SERVICEABLE	88.61	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	348.31	-

Report Ref No. CS/FCI18011467/Krd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 4 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET LOCK	TO REPAIR SEE LABOUR	305.48	-
1	BONNET CABLE	SERVICEABLE	119.19	-
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	BONNET SEAL INNER	SERVICEABLE	157.28	-
1	FENDER PANEL FRT LH	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	AIR CLEANER LOWER	SERVICEABLE	271.26	-
1	AIR CLEANER HOSE	SERVICEABLE	76.14	-
1	BASE BATTERY TRAY	SERVICEABLE	363.40	-
1	AIR CLEANER BOX	SERVICEABLE	464.20	-
1	TURBO DUCT	SERVICEABLE	1,027.80	-
1	A/C HEATER VALVE	SERVICEABLE	484.50	-
1	SUBFRAME OUTER FRT	SERVICEABLE	2,652.45	-
1	SUBFRAME BRACKET OUTER LH	SERVICEABLE	92.36	-
1	ENGINE UNDERTRAY	SERVICEABLE	564.98	-
1	A/C CONDENSER	SERVICEABLE	2,020.37	-
1	A/C CONDENSER GARNISH LH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH RH UPPER	SERVICEABLE	39.67	-
1	A/C CONDENSER GARNISH LH	SERVICEABLE	58.81	-
1	A/C CONDENSER GARNISH RH	SERVICEABLE	59.60	-
1	A/C PIPE CONDENSER TO COMPRESSOR	SERVICEABLE	208.39	-
1	A/C PIPE CONDENSER TO EXPENSION VALVE	SERVICEABLE	658.72	-
1	A/C PIPE COMPRESSOR	SERVICEABLE	334.29	-
1	A/C PIPE	SERVICEABLE	658.72	-
1	A/C COMPRESSOR	SERVICEABLE	2,684.61	-
1	AIR COOLER	SERVICEABLE	792.60	-
1	AIR INTERCOOLER HOSE (LONG)	SERVICEABLE	1,014.13	-
1	AIR INTERCOOLER HOSE (SHORT)	SERVICEABLE	375.14	-

Report Ref No. CS/FCI18011467/Krd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 5 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TRANSMISSION COOLER	SERVICEABLE	1,219.30	-
1	TRANSMISSION COOLER PAD	SERVICEABLE	17.96	-
1	RADIATOR	SERVICEABLE	1,202.20	-
2	RADIATOR STUD UPPER	SERVICEABLE	14.41	-
2	RADIATOR BUSH UPPER	SERVICEABLE	50.12	-
2	RADIATOR MTG LOWER	SERVICEABLE	55.85	-
1	RADIATOR FAN COWLING	SERVICEABLE	820.54	-
1	RADIATOR FAN MOTOR LH	SERVICEABLE	967.36	-
1	RADIATOR FAN MOTOR RH	SERVICEABLE	1,479.46	-
1	RADIATOR TANK	SERVICEABLE	324.62	-
1	RADIATOR HOSE UPPER	SERVICEABLE	240.56	-
1	RADIATOR HOSE LOWER	SERVICEABLE	491.18	-
1	RADIATOR TANK HOSE	SERVICEABLE	61.18	-
1	AUTO COMPUTER	SERVICEABLE	5,032.17	-
1	INJECTION COMPUTER	SERVICEABLE	4,706.30	-
1	RHD HYDRAULIC POWER (ROCK & PINION)	SERVICEABLE	5,154.52	-
1	STEERING PUMP ELECTRIC L70Y	SERVICEABLE	2,306.90	-
1	STEERING PINION RACK L70Y	SERVICEABLE	4,413.11	-
	LESS 10% DISCOUNT		-9,963.35	-799.33
			89,670.14	7,193.94
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SERVICEABLE	700.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	NOT NECESSARY	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	-

Report Ref No. CS/FCI18011467/Krd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 6 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	-
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547) (SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NECESSARY	52.00	52.00
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER BRACKET CLIP FRT RH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT RH (SN)	NOT NECESSARY	10.50	-
1	TOW COVER FRT (SN)	SERVICEABLE	14.50	-
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	BENT	80.00	45.00
			2,787.52	328.00

Report Ref No. CS/FCI18011467/Krd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET RH REAR, BOOT REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK, BOOT LOCK CATCH, DOOR PANEL REAR LH, FENDER PANEL REAR LH, FENDER PANEL REAR RH,)		4,200.00	800.00
	TAILLAMP PANEL RH, TAILLAMP PANEL LH, SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL), EXHAUST REAR, EXHAUST CAP REAR, BUMPER BEAM FRT, FRAME FULL SUPPORT BRACKET, FRONT BRACE PANEL, HORN BRACKET, HEADLAMP LH, HEADLAMP RH, HEADLAMP PANEL FRT LH, HEADLAMP PANEL FRT RH, BONNET, BONNET HINGE LH, BONNET HINGE RH,)		-	-
	BONNET LOCK AND FENDER PANEL FRT LH.)		-	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	NOT NECESSARY	380.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	REPEATED	170.00	-

Report Ref No. CS/FCI18011467/Krd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 6 of 8

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	30.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	NOT NECESSARY	440.00	-
	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.	NOT NECESSARY	480.00	-
	TO DROP DIESEL TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.	NOT NECESSARY	380.00	-
	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TOWING FEES.	NOT NECESSARY	120.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	660.00
			17,920.00	1,670.00
GRAND TOTAL			110,377.66	9,191.94
RECOMMENDED COST OF REPAIRS				9,191.94

Report Ref No. CS/FCI18011467/Krd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.