

ASS. REC. BY:

REF:

CS3/ALG18011471 / Gzad3ep

Special Instruction:

Survivor  
Muhmm

GK

## ASSIGNMENT (Office)

From (Person) Chin lee ying

of

AIG

Date/Time:

25/6/18 @ 8:27am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJG 2286Z

Insured:

SKK 5689S

at Workshop m/s

Safe Auto

Tel:

9199 3103

of

1 kaki Bukit Ave 6 #01-52 Autobay

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/04/2018

CA / REV / REP. / REV 24 HRS <sup>lup</sup>

26/06/2018 @ morning

H.O.D. Endorsement:

Date/Time: 1:50pm @ 25/6/18

Person Contacted:

Mr Kong

Vehicle: ☒ IN ☐ OUT

Date/Time	Action/Instruction ( X ) Estimate
	SJG 2286Z - X
	SKK 5689S - X
27/6/18	Dismantled

PRS  
xhl.

REF: ALG

ASSIGNMENT

From: Date: 26/6/2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJG 22862

at Workshop n/s

of 1 kaki Bukit Ave 6 # 01-52 n/s

Insured.

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJG 22862 Yr Regn: - /

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Estima c.c. 2362

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading: 140487 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ACR 507062305

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size: F: 25/55 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 26-06-18

Survey held at: w/s 4pm

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/6/18

Submit DAR report.

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to?

2)

Add Fee: ☐ Site Insp. (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

180

20

200

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE  
SKK5689S AND SJG2286Z ON 28/04/2018**

From: Chin, Lee-Ying

To: assignments@lkkauto.com, Admin A

Cc: Fong, Andy-SY

Sent: Monday, 25 June, 2018 8:27:51 AM

Attachments:  [20180621122812.pdf](#)  [20180621160104.pdf](#)  [20180621165428.pdf](#)

---

Hi LKK,

Kindly assist to survey after 12pm today.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths  
Agents for Trade Marks  
(Incorporated with limited liability)

ERIC NG CHING BOON  
RAYNEY WONG KENG LEONG  
AUDREY WONG SU-HSIEN  
PAUL YAP TAI SAN  
ANJALI D/O MUNIANDY  
SEGA PARAM  
TIWARY ANURADHA  
SHARON PARWANI  
ONG BOCK KEE  
DIANE ANG KIM NOI  
RAVENDRA KRISHNASAMY  
ROCHE ENG KENG LOON  
TAY HAO RAN  
JANICE HAN JIA LIN

Unique Entity Number: 200721148H

## ✓ HEAD OFFICE

133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413

Branch: 490 Toa Payoh Lorong 6  
#03-11 HDB Hub  
Singapore 310490

## ✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)  
FAX : (65) 65356802 (General)  
✓: (65) 65355905 (Litigation)  
E-mail : yvonnelim@visionlawllc.com

## BRANCH

TEL : (65) 63580703  
FAX : (65) 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE – PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: SJG 2286 Z (PM)  
Your Ref: SKK 5689 S

21 June 2018

BY FAX 6415 3727 & EMAIL

AIG ASIA PACIFIC INSURANCE PTE. LTD.  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
[Attention : Motor Claim Department]

Dear Sirs,

ACCIDENT INVOLVING MOTOR VEHICLE SJG 2286 Z AND SKK 5689 S ON 28 APRIL 2018 ALONG BUKIT BATOK EAST AVENUE 2 TOWARDS HILLVIEW AVENUE AT ABOUT 1555 HOURS (NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)

We refer to your email of even date whereby parties are not agreeable to each other's list of motor surveyors.

Under the circumstances, no Single Joint Expert has been agreed for this matter.

Please be informed that the said vehicle can be inspected at:

Venue : SAFE AUTO  
1 Kaki Bukit Avenue 6  
#01-52 Autobay@Kaki Bukit  
Singapore 417883  
Contact : Mr. Kong Wei Leang @ 9199 3103 (Please call before going)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

JANICE HAN  
(HEAD OFFICE)

cc: SJG 2286 Z – By fax: 63867787 only

## FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :  
(Name & Signature)

Date & Time of Inspection :

CONFIDENTIALITY  
THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched  
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary  
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

## MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (X) (3) Check (C)  
(4) Not Consistent (NC)

### Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	RE	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	NC	2	✓
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	NW	✓	
1159	993327	Rear End Panel	BT	✓	
1160	993339	Rear End Panel Top Garnish	RE	2	✓
1161	993333	Rear End Panel Inner Trim	Sensor	NW	✓
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	NC	✓	
1182	991328	Tailgate Emblem	NC	3	✓
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber	NC	✓	
1195	994604	Tailgate Glass Moulding	NC	✓	
1196	994607	Tailgate Glass Sealant	NC	✓	
1197	994629	Tailgate Lock	BT	✓	
1198	994651	Tailgate Rubber	Tw	✓	
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: STG 22862

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel	Repair		
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items: \_\_\_\_\_ Assessor: \_\_\_\_\_

original copy

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jun 2018 09:10 <a href="#">Edit Reg</a>		25 Jun 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

Insured:

- , Co. Reg. No.: -

Main Claimant:

-

Vehicle Reg. No.:

**SJG2286Z**

Claim Type:

**TP / 9875309090SG**

Vehicle Reg. No. (Insured):

**SKK5689S**

Repairer:

**Safe Auto (KAKI BUKIT)** 1 KAKI BUKIT AVENUE 6, AUTOBAY , # 01-52, 417883 Kaki Bukit - Tel: 91993103

Handling Insurer:

**AIG Asia Pacific Insurance Pte. Ltd. (Express)** - Tel: 65-6419-3000

Adjuster:

**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **XING GUO QIANG**] ... **[Final Rpt due 09/07/2018]**

Date of Loss:

28/04/2018 00:00 - :59

Policy/Cover Note No.:

(Comprehensive)  
Coverage: 31/07/2017 - 30/07/2018

Policy No. (Claimant):

Excess:

**ASSOCIATED MAIL RECEIVED**

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS**

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SJG2286Z (9875309090SG)**  
**[SKK5689S]**

TP






-

**Apr 28 2018 12:00AM**

[-]

**Safe Auto**

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser		v
Photos/Images															3 per page		v	✓	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print		
1	28/06/18 21:22	General View													1	Load JPG	✓		
2	28/06/18 21:22	General View													1	Load JPG	✓		
3	28/06/18 21:22	General View													1	Load JPG	✓		
4	28/06/18 21:22	General View													1	Load JPG	✓		
5	28/06/18 21:22	General View													1	Load JPG	✓		
6	28/06/18 21:22	General View													1	Load JPG	✓		
7	28/06/18 21:22	General View													1	Load JPG	✓		
8	28/06/18 21:22	General View													1	Load JPG	✓		
9	28/06/18 21:22	General View													1	Load JPG	✓		
10	28/06/18 21:22	General View													1	Load JPG	✓		
11	28/06/18 21:22	General View													1	Load JPG	✓		
12	28/06/18 21:22	General View													1	Load JPG	✓		
13	28/06/18 21:22	General View													1	Load JPG	✓		
14	28/06/18 21:22	General View													1	Load JPG	✓		
15	28/06/18 21:22	General View													1	Load JPG	✓		
16	28/06/18 21:22	General View													1	Load JPG	✓		
17	28/06/18 21:22	General View													1	Load JPG	✓		
18	28/06/18 21:22	General View													1	Load JPG	✓		
19	28/06/18 21:22	General View													1	Load JPG	✓		
20	28/06/18 21:22	General View													1	Load JPG	✓		
21	28/06/18 21:22	General View													1	Load JPG	✓		
22	28/06/18 21:22	General View													1	Load JPG	✓		
23	28/06/18 21:23	Dismantled Parts													1	Load JPG	✓		
24	28/06/18 21:23	Dismantled Parts													1	Load JPG	✓		
25	28/06/18 21:23	Dismantled Parts													1	Load JPG	✓		
26	28/06/18 21:23	Dismantled Parts													1	Load JPG	✓		
27	28/06/18 21:23	Dismantled Parts													1	Load JPG	✓		
28	28/06/18 21:23	Dismantled Parts													1	Load JPG	✓		
29	28/06/18 21:23	Dismantled Parts													1	Load JPG	✓		
30	28/06/18 21:23	Dismantled Parts													1	Load JPG	✓		
31	28/06/18 21:23	Dismantled Parts													1	Load JPG	✓		
32	28/06/18 21:23	Dismantled Parts													1	Load JPG	✓		
33	28/06/18 21:23	Dismantled Parts													1	Load JPG	✓		
34	28/06/18 21:23	Dismantled Parts													1	Load JPG	✓		
35	28/06/18 21:23	Dismantled Parts													1	Load JPG	✓		
36	28/06/18 21:23	Dismantled Parts													1	Load JPG	✓		
37	28/06/18 21:23	Dismantled Parts													1	Load JPG	✓		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	28/06/18 21:23	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	28/06/18 21:23	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	28/06/18 21:23	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	28/06/18 21:23	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	28/06/18 21:23	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18011471/GZ4D3E2

Date: 29/06/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJG2286Z

Insured Vehicle No : SKK5689S

Date of Loss: 28/04/2018

Nature of Claim: TP

Claim No: 9875309090SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SJG2286Z

Make &amp; Model: TOYOTA ESTIMA, 2.4 (A)

Engine No: HIDDEN

Reg. Date: (Man. Year: )

Chassis No: ACR507062305

Colour: Silver

Odometer: 140487 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 25/06/2018

Date Inspected: 26/06/2018 Inspected At:

Safe Auto (KAKI BUKIT)  
1 KAKI BUKIT AVENUE 6, AUTOBAY , #  
01-52  
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
4	1		*REVERSE SENSOR	Not Working	0.00 F	*- F
5	1		*REAR END PANEL	Bent	0.00 F	*- F
6	2		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
7	1		*REAR END PANEL INNER SENSOR	Not Working	0.00 F	*- F
8	1		*TAILGATE	Buckled	0.00 F	*- F
9	3		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
10	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
11	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
12	1		*TAILGATE LOCK	Bent	0.00 F	*- F
13	1		*TAILGATE RUBBER	Twisted	0.00 F	*- F
14	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
F=Franchise part.				<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >