

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: 455 3986
Business Regn No : 269436/00J

Not Authorize
11 Sep 87
Resurvey After Paint
6 days

21, June 2018

EQ Insurance Company Ltd
5 Maxwell Road #17-00
Tower Block MND Complex
S 069110

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle No: GBH684K

Accident involving vehicle No: SJJ545Z/GBH684K/GBE6688B

DOA: 20/06/2018 AT PIE near Steven Road

Description	Qty	Amount	
Lid	1	1,210.40	✓
Lid-doorboard	1	328.20	?
Lid outer handle	1	239.20	✓
Lid lock	1	443.50	✓
End panel	1	441.20	✓
End panel top garnish	1	232.90	✓
Spare tyre boot garnish	1	562.90	?
Rear bumper	1	470.70	✓
Rear bumper retainer @57.50	2	115.00	✓
Rear bumper reflector	1	56.90	✓
Bumper clip		42.00	✓
Taillamp @472.60	2	945.20	✓
Boot weatherstrip	1	304.00	30 days
	parts	5,392.10	
	Parts less 25%	1,348.02	
		4,044.08	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Vehicle No: SJJ545Z

Reverse sensor

CMA 220.00 2005N

To transfer rear windscreen glass.

160.00 1201

To remove damaged parts and attachments.

Repair/reshape dented areas.

Straighten rear chassis

950.00 8001

Replace/align above parts into position

900.00 8001

To spray paint