

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 27 Jun 2018

Preliminary Advice

Insured Vehicle No : GX1883C
 TP Vehicle No : GBC7198C
 Make : TOYOTA HIACE
 Date of Inspection : 26/06/2018
 Inspection At : LIU'S BROTHER AUTO ENGINEERING WORKSHOP (HQ)
 BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT
 SINGAPORE 417883

Accident Date : 08/06/2018
 Assignment Date : 25/06/2018
 Est. Duration of Repair : 5.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,333.40
Revised Amount	:S\$	5,181.40
Check Items (Estimated)	:S\$	
Total	:S\$	5,181.40

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.