

2015/2016

ASS. REC. BY:

REF:

CS/MSG/8011528/Urd3

Special Instruction:

Surveyor

Merimen

ASSIGNMENT (Office)

From (Person):

Katherine Wong

of

MSG

Date/Time:

25/6/2018 @ 4:35pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 7198C

Insured:

GX 1883C

at Workshop m/s

Liu's Brother

Tel:

G7411730

of

Blk I, Kaki Bukit Ave 6 # 01-01 Autobay

Policy No:

A289029347MV

Claim No:

561796

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/06/2018

CA / REV / REP. / REV 24 HRS

1up

26/06/2018

H.O.D. Endorsement:

Date/Time:

4:54pm @ 25/6/18

Person Contacted:

Susan

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction
	(✓) Estimate
	GBC 7198C - NA / IPI 6006523/r3
	GX 1883C - X
27/6/18	Send preli revised via merimen

REF: MS16

ASSIGNMENT

Date: 26/6/2018

Estimated Cost:

OD: ☒ WS / TP RES / DD RES / EVA / INV / MVTo inspect Vehicle No. GBC 7198C
at Workshop no. Liu's Brother
of Blk 1, kaki Bukit Ave 6 # 01-01

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

40

IDAC Accident Rpt:

Consistent?: Yes or No

GI/PR Seen:

Consistent?: Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lump Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS ^{1 up}

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No. GBC 7198C Yr Regn. 8/13

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make: Toyota Grace

cc 2982

Colour: silver

A/C: Insured / Std / NI / NA

Sp. Reading:

212485

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFHT02P300119852

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Jammed / Leaked / Burnt or

Brake: Jammed / Leaked / Burnt or

Modi: S/Rim / STD A/Rim or

Tyre Size:

F:

195/215

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

maxtrek

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

8/6/18

D.O.I.

26/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

C1A29285

sys 2mls.

24/7/18 confd L/S \$ 4000 with Susan. (Red 4333-40, 5210)

RECEIVED 25 JUL 2018

Date/Time, File Pass to?

☐

: Prel. Report

b)

☐

: Final Report

Date/Time, File Return to?

c)

25/7 - typist

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) S + RE. 14

) 10000

) 10000

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech. Insp. (\$

☐

Weekend (\$

Report Format:

merimen

Lump Sum / L.B. (\$

4000/-

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jun 2018		25 Jun 2018 16:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	YONG SENG HUA TRADING & ENGINEERING PTE LTD, Co. Reg. No.: 199409629R		
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N		
Vehicle Reg. No.:	GBC7198C	Date of Loss:	08/06/2018 13:00 - :59 [57 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 561796	Policy/Cover Note No.:	A28902934TMV (Third Party Only) Coverage: 27/02/2018 - 26/02/2019
Vehicle Reg. No. (Insured):	GX1883C	Policy No. (Claimant):	
		Excess:	
Repairer:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/06/2018]		
Driver/Custodian (Insured):	NG KUM SHEA (61 / Male), NRIC: S1315008G, Tel: +6580000000		
Adj Asg. Remarks:	on WP. SURVEY AGREE ON SJE - ASSIGN LKK LIABILITY: 100% CONTACT: SUSAN 6741 1730		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Katherine Wong Chew Shong	Date: 27 Jun 2018

Preliminary Advice

Insured Vehicle No	: GX1883C		
TP Vehicle No	: GBC7198C	Accident Date	: 08/06/2018
Make	: TOYOTA HIACE	Assignment Date	: 25/06/2018
Date of Inspection	: 26/06/2018	Est. Duration of Repair	: 5.00
Inspection At	: LIU'S BROTHER AUTO ENGINEERING WORKSHOP (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,333.40
Revised Amount	:S\$	5,181.40
Check Items (Estimated)	:S\$	
Total	:S\$	5,181.40
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

☐ The vehicle is economical/not economical for repair.

☒ The above survey was conducted on a 'without prejudice' basis.

PARF/COE Rebate Enquiry

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	1196N

Vehicle Details

Vehicle No.:	GBC7198C
Vehicle to be Exported:	No
Intended De-registration Date:	22 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	1KD2312600
Chassis No.:	JTFHT02P300119852
Maximum Power Output:	\$25,820.00
Open Market Value:	20 Aug 2013
Original Registration Date:	20 Aug 2013
First Registration Date:	1
Transfer Count:	\$1,291.00
Actual ARF Paid:	

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	19 Aug 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$56,889.00
COE Rebate Amount:	\$29,346.00
Total Rebate Amount:	\$29,346.00

The information contained herein is correct as at 22 Jun 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1196N
Vehicle Details	
Vehicle No.:	GBC7198C
Vehicle to be Exported:	No
Intended De-registration Date:	26 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	1KD2312600
Chassis No.:	JTFHT02P300119852
Maximum Power Output:	-
Open Market Value:	\$25,820.00
Original Registration Date:	20 Aug 2013
First Registration Date:	20 Aug 2013
Transfer Count:	1
Actual ARF Paid:	\$1,291.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Aug 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$56,889.00
COE Rebate Amount:	\$29,285.00
Total Rebate Amount:	\$29,285.00

The information contained herein is correct as at 26 Jun 2018

OK

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-095512

Date of Request: 22/06/2018

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP
1 Kaki Bukit Ave 6 #01-01
Auto Bay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 22/06/2018
Enquiry By: Susan Low Siew Yian
TP Vehicle No: GX1883C
Accident Date: 08/06/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GX1883C	MSIG Insurance (Singapore) Pte. Ltd.	27/02/2018-26/02/2019	+65 6827 7888

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/06/2018 18:55
Date Of Accident	08/06/2018 13:00
Exact Location Of Accident	PIE TOWARD CLEMENTI AVE 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC7198C
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL LEASING PTE LTD
Co Reg No	199001196N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91818338
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE MANUAL
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-18090757MFCV
Cover Note Number	
Driver	
Name of Driver	YU CHENGQUANG
NRIC No	G6967145X
Date Of Birth	10/01/1988
Occupation	OUTDOOR
Date Of Driving Pass	19/10/2017
Driving Experience	0 YEAR AND 7 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91818338
Fax Number	
Contact Number	
Email Address	NOEMAIL

Sketch Plan

be report correctly the details of the accident. The information provided must be as truthful and accurate as possible. Insurance companies are not an admission of policy. A false reporting may be referred to the Police for investigation. A report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties. The lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

consent under the Personal Data Protection Act (PDPA)

I, My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").

(vi) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(vii) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


**VERIFIED BY AJAX MARS
REPORTING OFFICER
MOHAMMAD SULHANDI BIN
MOHD AFFANDI**

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J Tel: 6744-1730 / 731 Fax: 6744-5746 Email: liusbros@gmail.com

Invoice/Ref No: GBC7198C180608

Estimate

Customer

Name: MSIG Insurance (Singapore) Pte Ltd

Address: Motor Claims Department

4 Shenton Way #21-01

SGX Centre 2

Singapore 068807

Date: 22-06-18

Vehicle No: GBC7198C

Model/Make: Toyota Hiace
Diesel

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate <i>306/155 1927.10</i>	\$ 2,051.60	
2	Tailgate Rubber <i>YWI</i>	\$ 387.90	
3	Tailgate Lock <i>YWI/shield</i>	\$ 359.00	
4	Tailgate "70 KM/H" Sticker <i>neu</i>	\$ 12.00	SN 10
5	Tailgate "8 PAX" Sticker <i>neu</i>	\$ 12.00	SN 10
6	Tailgate "Toyota Logo" Motif <i>neu</i>	\$ 70.50	
7	Number Plate Lamp Outer Garnish <i>grand 18.10</i>	\$ 346.50	
8	Floor Plywood Board <i>one n/c</i>	\$ 200.00	SN X
9	End Panel Outer <i>306/155</i>	\$ 566.10	
10	End Panel Inner <i>neu</i>	\$ 936.20	X
11	End Panel Sealant <i>neu</i>	\$ 50.00	SN X
12	Bumper <i>20 465</i>	\$ 496.50	
13	Bumper Clips 1 set <i>neu</i>	\$ 65.00	SN -
14	Bumper Bracket Lh <i>neu</i>	\$ 178.00	X
15	Tail Lamp Lh <i>neu</i>	\$ 365.10	
16	Number Plate "Metal" <i>neu</i>	\$ 28.00	SN 145.2
17	Tailgate Windscreen Moulding <i>neu</i>	\$ 219.00	X
18	Tailgate Windscreen Sealant <i>neu</i>	\$ 50.00	SN 405.2
	To check all wiring & electrical component for proper function	\$ 60.00	- 20
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	- 60
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,000.00	- 800
	To putty & spray painting & including touch up paint on accident affect	\$ 600.00	- 500
	Remove & reinstall Tailgate Glass to facilitate repairs	\$ 120.00	- 160
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 80.00	-

Total Parts & Labour of estimate for damaged vehicle

\$ 8,333.40

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Used parts survey is on a "Without Prejudice" basis
- Financial modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Allowed
4000/-
1/5 9
5 day
26/6/18
Take photo. After 14

Signature
27/6/18

4484.6
3363.45
5062.48
4049

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jun 2018		25 Jun 2018 16:35 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	YONG SENG HUA TRADING & ENGINEERING PTE LTD , Co. Reg. No.: 199409629R.								
Main Claimant:	GOLDBELL LEASING PTE LTD , Co. Reg. No.: 199001196N								
Vehicle Reg. No.:	GBC7198C	Date of Loss:	08/06/2018 13:00 - :59 [57 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 561796	Policy/Cover Note No.:	A28902934TMV (Third Party Only) Coverage: 27/02/2018 - 26/02/2019						
Vehicle Reg. No. (Insured):	GX1883C	Policy No. (Claimant):							
		Excess:							
Repairer:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 25/07/2018]								
Driver/Custodian (Insured):	NG KUM SHEA (61 / Male), NRIC: S1315008G, Tel: +6580000000								
Adj Asg. Remarks:	on WP. SURVEY AGREE ON SJE - ASSIGN LKK LIABILITY: 100% CONTACT: SUSAN 6741 1730								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBC7198C (561796)

[GX1883C]

TP

GOLDBELL LEASING PTE LTD

Jun 8 2018 1:00PM

[YONG SENG HUA TRADING & ENGINEERING PTE LTD]

Liu's Brother Auto Engineering Workshop

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	25/06/18 11:49	Accident Statement From: SC - Reg. No: GX1883C, Claimant: YONG SENG HUA TRADING & ENGINEERING PTE LTD						Load HTML		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	27/06/18 14:31	Adjuster Immediate Advice						Load HTML		
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	26/06/18 19:44	Chassis Number						Load JPG	☒	
2	26/06/18 19:44	Odometer Reading						Load JPG	☒	
3	26/06/18 19:44	General View						Load JPG	☒	
4	26/06/18 19:44	General View						Load JPG	☒	
5	26/06/18 19:44	General View						Load JPG	☒	
6	26/06/18 19:44	General View						Load JPG	☒	
7	26/06/18 19:44	General View						Load JPG	☒	
8	26/06/18 19:44	General View						Load JPG	☒	
9	26/06/18 19:45	General View						Load JPG	☒	
10	26/06/18 19:45	General View						Load JPG	☒	
11	26/06/18 19:45	General View						Load JPG	☒	
12	26/06/18 19:45	General View						Load JPG	☒	
13	26/06/18 19:45	General View						Load JPG	☒	
14	26/06/18 19:45	General View						Load JPG	☒	
15	26/06/18 19:45	General View						Load JPG	☒	
16	26/06/18 19:45	General View						Load JPG	☒	
17	26/06/18 19:45	General View						Load JPG	☒	
18	26/06/18 19:45	General View						Load JPG	☒	
19	26/06/18 19:45	General View						Load JPG	☒	
20	26/06/18 19:45	General View						Load JPG	☒	
21	26/06/18 19:45	General View						Load JPG	☒	
22	26/06/18 19:45	General View						Load JPG	☒	
23	26/06/18 19:45	General View						Load JPG	☒	
24	26/06/18 19:45	General View						Load JPG	☒	
25	26/06/18 19:45	General View						Load JPG	☒	
26	26/06/18 19:45	General View						Load JPG	☒	
27	26/06/18 19:45	General View						Load JPG	☒	
28	26/06/18 19:45	General View						Load JPG	☒	
29	26/06/18 19:45	General View						Load JPG	☒	
30	26/06/18 19:45	General View						Load JPG	☒	
31	26/06/18 19:45	General View						Load JPG	☒	
32	26/06/18 19:45	General View						Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				☒
33	26/06/18 19:45	General View	 Load JPG	☒
34	26/06/18 19:45	General View	 Load JPG	☒
35	26/06/18 19:45	General View	 Load JPG	☒
36	26/06/18 19:45	General View	 Load JPG	☒
37	26/06/18 19:45	General View	 Load JPG	☒
38	26/06/18 19:45	General View	 Load JPG	☒
39	26/06/18 19:45	General View	 Load JPG	☒
40	26/06/18 19:45	General View	 Load JPG	☒
41	26/06/18 19:45	General View	 Load JPG	☒
42	26/06/18 19:45	General View	 Load JPG	☒
43	26/06/18 19:45	General View	 Load JPG	☒
44	26/06/18 19:45	General View	 Load JPG	☒
45	26/06/18 19:45	General View	 Load JPG	☒
46	26/06/18 19:45	General View	 Load JPG	☒
47	26/06/18 19:45	General View	 Load JPG	☒
48	26/06/18 19:45	General View	 Load JPG	☒
49	26/06/18 19:45	General View	 Load JPG	☒
50	26/06/18 19:45	General View	 Load JPG	☒
51	26/06/18 19:45	General View	 Load JPG	☒
52	26/06/18 19:45	General View	 Load JPG	☒
53	26/06/18 19:45	General View	 Load JPG	☒
54	26/06/18 19:45	General View	 Load JPG	☒
55	27/06/18 16:56	Reinspection Photo	 Load JPG	☒
56	27/06/18 16:57	Reinspection Photo	 Load JPG	☒
57	27/06/18 16:57	Reinspection Photo	 Load JPG	☒
58	27/06/18 16:57	Reinspection Photo	 Load JPG	☒
59	27/06/18 16:57	Reinspection Photo	 Load JPG	☒
60	27/06/18 16:57	Reinspection Photo	 Load JPG	☒
61	27/06/18 16:57	Reinspection Photo	 Load JPG	☒
62	27/06/18 16:57	Reinspection Photo	 Load JPG	☒
63	27/06/18 16:57	Reinspection Photo	 Load JPG	☒
64	25/07/18 09:04	Photo After Spray	 Load JPG	☒
65	25/07/18 09:04	Photo After Spray	 Load JPG	☒
66	25/07/18 09:04	Photo After Spray	 Load JPG	☒
67	25/07/18 09:04	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/06/18 11:49	GBC7198C E-FILE REPORT From: SC - Reg. No: GX1883C, Claimant: YONG SENG HUA TRADING & ENGINEERING PTE LTD.	 Load PDF	
2	25/06/18 11:53	PRI - LIU'S BROTHER AUTO ENGINEERING WORKSHOP	 Load PDF	
3	25/06/18 11:53	SURVEY AGREE ON SJE - ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18011528/UVD3Q2

Date: 01/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A28902934TMV

Claimant Vehicle No : GBC7198C

Insured Vehicle No : GX1883C

Date of Loss: 08/06/2018

Nature of Claim: TP

Claim No: 561796

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBC7198C

Make & Model: TOYOTA HIACE, 3.0 D (M)

Engine No: 1KD2312600

Reg. Date: 20/08/2013 (Man. Year: 2013)

Chassis No: JTFHT02P300119852

Colour: Silver

Odometer: 212485 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: Maxtrek 6 mm

Rear Left Side: Maxtrek 6 mm

Front Right Side: Maxtrek 6 mm

Rear Right Side: Maxtrek 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,393.40	3,502.60	2,890.80	45.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	1,560.00	380.00	19.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,333.40	5,062.60	3,270.80	39.25
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	8,333.40	4,000.00	4,333.40	52.00

INSPECTION

Date of Assignment: 25/06/2018

Date Inspected: 26/06/2018 Inspected At:

Liu's Brother Auto Engineering Workshop (HQ)

BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO

BAY @ KAKI BUKIT

Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 Jul 2018)	
Parts:	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC7198C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	2,051.60 F	*1,927.10 FL
2	1		*REAR TAILGATE RUBBER	Twisted	387.90 F	*387.90 FL
3	1		*REAR TAILGATE LOCK	Twisted / Shorted	359.00 F	*359.00 FL
4	1		*REAR TAILGATE 70KM/H STICKER	Necessary	12.00 FS	*10.00 FS
5	1		*REAR TAILGATE 8 PAX STICKER	Necessary	12.00 FS	*10.00 FS
6	1		*REAR TAILGATE TOYOTA LOGO MOTIF	Necessary	70.50 F	*68.10 FL
7	1		*REAR NUMBER PLATE LAMP OUTER GARNISH	Grazed	346.50 F	*346.50 FL
8	1		*REAR FLOOR PLYWOOD BOARD (CRACKED)	Not Consistent With The Impact	200.00 FS	*- FS
9	1		*REAR END PANEL OUTER	Badly Dented	566.10 F	*566.10 FL
10	1		*REAR END PANEL INNER	Repair	936.20 F	*- FL
11	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
12	1		*REAR BUMPER	Dented	496.50 F	*465.00 FL
13	1		*SET REAR BUMPER CLIPS	Necessary	65.00 FS	*65.00 FS
14	1		*REAR BUMPER BRACKET LH	Not Necessary	178.00 F	*- FL
15	1		*REAR TAIL LAMP LH	Cracked	365.10 F	*365.10 FL
16	1		*REAR NUMBER PLATE METAL	Bent	28.00 FS	*14.00 FS
17	1		*REAR TAILGATE WINDSCREEN MOULDING	Not Necessary	219.00 F	*- FL
18	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,393.40	4,623.80
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,121.20
Total Parts (\$\$)	6,393.40	3,502.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	60.00	20.00
2	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM	New	80.00	60.00
3	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	1,000.00	800.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	600.00	500.00
5	REMOVE & REINSTALL TAILGATE GLASS TO FACILITATE REPAIRS	New	120.00	120.00
6	TO APPLY RUST PROOFING ,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	60.00
Gross Labour Cost (\$\$)			1,940.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >