



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 6408M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BONNET (WCP)	BUCKLED	450.00	450.00
2	FRONT BONNET HINGE LH/RH (WCP)	TO REPAIR SEE LABOUR	40.00	-
1	FRONT BONNET RUBBER SEAL FRONT (WCP)	SERVICEABLE	22.00	-
1	FRONT BONNET RUBBER SEAL INNER (WCP)	SERVICEABLE	13.00	-
1	FRONT BUMPER (WCP)	BUCKLED	320.00	320.00
2	FRONT BUMPER SIDE RETAINER LH/RH (WCP)	DISTORTED	16.20	16.00
20	FRONT BUMPER CLIPS (WCP)	NECESSARY	40.00	40.00
2	FRONT BUMPER SIDE BRACKET LH/RH (WCP)	CRACKED	20.00	20.00
1	FRONT BUMPER SPONGE (WCP)	CRACKED	35.00	35.00
2	FRONT BUMPER LOWER GRILLE CAP LH/RH (WCP)	MISSING	24.00	24.00
4	FRONT BUMPER RIVET (WCP)	NECESSARY	12.00	12.00
1	RADIATOR GRILLE (WCP)	DENTED	55.00	55.00
2	RADIATOR GRILLE MOULDING (WCP)	CRACKED	150.00	150.00
1	RADIATOR GRILLE TOP GARNISH (WCP)	CRACKED	180.00	180.00
1	FRONT GRILLE LOGO (WCP)	NECESSARY	18.00	18.00
1	RADIATOR SUPPORT PANEL (WCP)	CRACKED	190.00	190.00
2	HEADLAMP LH/RH (WCP)	MTG CRACKED	540.00	540.00
2	HEADLAMP TOP PANEL LH/RH (WCP)	BUCKLED	140.20	55.00
8	FRONT SUPPORT PANEL TOP COVER CLIP (WCP)	NOT NECESSARY	32.00	-
1	FRONT BUMPER REINFORCEMENT (ADDITIONAL)(WCP)	BENT	180.00	180.00
	COST PLUS 10%		247.74	228.50
			2,725.14	2,513.50
<u>SPECIAL NETT ITEMS</u>				
1	NUMBER PLATE (SN)	CRACKED	35.00	25.00
1	RADIATOR COOLANT (SN)	NECESSARY	30.00	30.00
			65.00	55.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISCONNCT AND CHECK ELECTRICAL WIRING,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,TEST AND RECTIFY FOR PROPER FUNCTIONING.		30.00	20.00
	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES,RADIATOR AND HOSES.VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		120.00	100.00
	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD FRONT SUPPORT PANEL.TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS.TO REFILL LISTED PARTS BACK SAME.INCLUSIVE OF THE REPAIR OF FRONT BONNET HINGE LH/RH.		700.00	600.00
	TO SPRAY BONNET,FRONT FENDER LH/RH AND FRONT BUMPER.		700.00	600.00
			1,550.00	1,320.00
	GRAND TOTAL		4,340.14	3,888.50
	RECOMMENDED COST OF REPAIRS			3,888.50
	LESS EXCESS			-600.00
	NETT LIABILITY			3,288.50

Report Ref No. CS/AGI18011529/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.