



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 1063J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RH REAR DOOR (CONSISTENT)	TO REPAIR SEE LABOUR	1,211.40	-
1	RHR DOOR GLASS OUTER MOULDING (CONSISTENT)	SERVICEABLE	107.80	-
1	RH REAR HUB CAB(CONSISTENT)	DENTED	195.65	195.65
	LESS 25% DISCOUNT		-378.71	-48.91
			1,136.14	146.74
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(RHR DOOR,RHR FENDER,RH SIDE SKIRT).INCLUSIVE OF THE REPAIR OF RH REAR DOOR .		800.00	200.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (RHR DOOR ,RHR FENDER,RH SIDE SKIRT).		800.00	440.00
	TO CHECK WIRING .	NOT NECESSARY	50.00	-
	TO TUFF COAT.	NOT NECESSARY	50.00	-
	TO REMOVE & REFIT DOOR TRIM ,DOOR GLASS ,WINDOW REGULATOR ,DOOR LOCK TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	-
			1,850.00	640.00
	GRAND TOTAL		2,986.14	786.74
	RECOMMENDED COST OF REPAIRS			786.74

Report Ref No. CC4/ASM18011534/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.