


## SMRT Accident Vehicle Repair Estimates

**Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre**

Reg. No : SMB90A  
 Ref. No : BUS/06/18/5028  
 Reg. Date : 21/06/2018  
 Vehicle Type : BUS -12M  
 Make : MBOC500 (MERCEDES)  
 Model : MERCEDES MBOC500  
 Name of Driver : Ren Chaobo  
 Type of Accident : SIDE SWIPE  
 Date / Time of Accident : 18/06/2018 06:25:00 PM  
 Accident Reported Date / Time : 19/06/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : AIG  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No :  
 Special Instruction to ARC,if any :  
 SMB90A - LEFT FRONT PORTION  
 SKT2564R (TP) - INSURED WITH AIG  
 Prepared Date : 21/06/2018 11:19:00 AM



Sathya Sai

22/6/2018

98072012

- Lump Sum Repair

- Photo after paint.

2 day

**LKK Auto Consultants** hence notify the Repairer of the following:

- To return the vehicle to the original condition
- To display the vehicle to the surveyor
- Parts should be replaced with the same information
- Third party surveyors on a "Without Prejudice" basis
- No illegal modification to be allowed
- Suppliers terms and conditions apply and is subject to final approval from Insurance Company


Acknowledged by Repairer  
 Signature:  
 Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : Mileage : 0  
Work Shop : Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,060.00	0.00
Total Spray Painting Charges	: 480.00	0.00
Total Material Charges	: 828.90	828.90
Other Charges	: 0.00	0.00
<b>TOTAL</b>	<b>: 2,368.90</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 2.00	0.00 <i>2 day</i>
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 22/06/2018 01:52:01 PM	01/01/1900 12:00:00 AM




Prepared / Adjusted Date :

Remarks :

Prepared Date : 22/06/2018 01:52:01 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : Invoice No :  
Quotation Date : Invoice Date :  
Invoice Amount : Prepared Date :



**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
	FRONT	6009358	FRONT BUMPER LH ✓ DMG	1	621.00	10.00	558.90	Replace	Replace	No
	VE	6009511	FRONT FOG LAMP LH ✓ MS	1	300.00	10.00	270.00	Replace	Replace	No
		6009375	RETAINER (MALE & FEMALE) ✓ CUT	1	74.80	10.00	67.32	Replace	Replace	No
<b>TOTAL MATERIALS</b>								<b>896.22</b>	<b>896.22</b>	
<b>TOTAL MATERIALS(Discounted)</b>								<b>828.90</b>	<b>828.90</b>	

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									

**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	1,060.00	<del>0.00</del> 530
<b>Total Labour</b>	<b>1,060.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	480.00	<del>0.00</del> 380
<b>Total Spray Painting &amp; Panel Beating</b>	<b>480.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		