

ASS. REC. BY:

REF: es/FCI18011570/Dqd312

Special Instruction:

Surveyor:

Bryen

ASSIGNMENT (Office)

CWS

From (Person):

Joanne Yong

of

FCI

Date/Time: 25/6/18

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 4646K

Insured:

SHC3907D

at Workshop m/s

Chunni Motor

Tel:

65425119

of

AMK Autopoint #01-05

Policy No:

Claim No:

D18004959 MPSTH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 23/06/2018

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time: 10:01am @ 26/6/18

Person Contacted:

Lynn

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SHA 4646K-CC3/AXA10026028/Kab3g2 DOA: 26/12/2016
	SHC3907D-CC3/AIG12014577/H16lg2y DOA: 25/07/2012
03/7/18 @	1-4pm revised to Joanne Yong by email.

05/11

REF:

Surveyor

ASSIGNMENT

COE Dec 2022

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 10 8 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 8HA 4646K Yr Regn: 2014 Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Prime Mover /

Truck / Trailer or

Make: Hyundai I40 C.C. 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 469009 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDEU463211

C/No: KMHLB41UMFU062615

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: ———

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 23/06/18 D.O.I. 27/06/2018

Survey held at Churni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Body & O/S Rev

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

First Capital SHC 390717

25/07/18 Jinnar 2/5 89001- with 10 days 8 in
(led 16.5359.68, 38%/-)

RECEIVED 26 JUL 2018

Date/Time, File Pass to?

1) 26/7 Jinnar

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final Report

Days Of Repair: 10

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) S + RS. SI

) Photos 8/17

) Others 50/10

TOTAL

Report Format: TP

Lump Sum / I.B.I. (\$) 8900

1615-60

170 + 60

50

50+50

122

602



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004959MFSH
Our Ref: CS/FCI18011570/Dqd3

Date: 03 July 2018

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHA 4646K.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/06/2018 at the premises of M/s CHUNNI MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>14,253.68</u> .
Revised Estimate Amount	: S\$ <u>10,989.52</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the o/s body & o/s rear portion.



Yours faithfully

Bryan Ang Tani
Motor Surveyor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	25-06-2018	Our Ref No. D18004959MFSH
Accident Date	23-06-2018	Claim Type. Third Party
Insured Vehicle	SHC3907D	Third Party Vehicle. SHA4646K
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06,	
Contact Person.	LYNN OR IRENE	
Contact No.	64836016/ 65425119	Fax No. 65426039
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241725)



PRI Documents



Close



PRI Header Details

Claim No	D18004959MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CHUNNI M
Workshop Name	CHUNNI MOTOR WORK PTE LTD (Contact Person : LYNN OR IRENE)	Survey Location & Contact Details	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06, Mobile: 65425119 , Phone: 64836016 , Fax: 65426031 EmailId: CHUNNIMOTOR@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC3907D	TP Vehicle No	SHA4646K
PRI Recieved Date	25-06-2018 06:01:46 PM	Surveyor Appointed Date	25-06-2018 04:47:49 PM	Surveyor Accept Date	26-06-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	26-06-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 3 July 2018 1:49 PM
To: 'Claim Workflow System'; assignments
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004959MFSH/1
Attachments: CSFCI18011570Dqd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SHA 4646K.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 26 June 2018 10:08 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: JOANNEYONG@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004959MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 25 June 2018 4:48 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; JOANNEYONG@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004959MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

To Survey by 1221

DATE : 23.06.2018

TEL : 6542 5119

FAX : 6542 6039 FCI

10635.65
8508.52

SHA 4646X

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,500.00
	Spray Painting Charge			\$ 1,500.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 100.00
	Towing Charge			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Transfer of Door		\$ 120.00	\$ 240.00
	Remove/Refix Undercarriage (RR)			\$ 200.00
	Rear Wheel Alignment			\$ 120.00
	TOTAL LABOUR			\$ 4,150.00
	ESTIMATE TOTAL			\$ 14,253.68
	27/06/2018 @ 1145W			11139.52
	Not Antenna			4/5 8900/-
	2/Same 10 days			
	<i>Tygar</i>			
	LKK Auto			
	<i>9</i>			
	LKK Auto Consultants hence notify the Repairer of the following:			
	• To resurvey before/after spray painting			
	• To display damaged part(s) during resurvey			
	• Parts prices are subject to confirmation			
	• Third party survey is on a "Without Prejudice" basis			
	• No illegal modification(s) is allowed			
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
	Acknowledged by Repairer			
	Signature:			
	Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NAME
ADDRESS

Home Tel.:
VIN:
Registration: SHA 4646 K
Technician:
Mileage: 469009
Time Printed 27.6.18 1:35 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
0°39'		-3°00' 3°00'
3°55'		-0°19' 5°41'
-1°04'		-1°30' 1°30'
15°51'		
16°30'		

Camber
Caster
Toe
SAI

Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°44'		-3°00' 3°00'
3°14'		-0°19' 5°41'
0°16'		-1°30' 1°30'
15°19'		
14°36'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
1°23'		-3°00' 3°00'
0°41'		-3°00' 3°00'
0°32'		-3°00' 3°00'
-0°48'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
0°34'		-3°30' 2°30'
-0°09'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
14°40'		-3°30' 2°30'
22°08'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
-14°06'		-3°00' 3°00'
21°59'		-3°00' 3°00'
-11°08'		-3°00' 3°00'



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18011570/Dqd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 01-08-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3907D	Veh. Inspected	SHA 4646K	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18004959MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	25/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	KMHLB41UMFU062615	Colour	BLUE	
Odometer	469009	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/06/2018	Inspection Date	27/06/2018	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4646K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	TO REPAIR SEE LABOUR	603.60	-
10	REAR BUMPER CLIPS	SERVICEABLE	22.00	-
1	REAR FENDER WITH HOUSING (RH)	DENTED	4,736.80	4,736.80
1	REAR FENDER INNER LINING (RH)	SERVICEABLE	164.40	-
1	REAR WINDSCREEN MOULDING	NECESSARY	60.00	60.00
1	REAR DOOR (RH)	DENTED	1,351.10	1,351.10
1	FRONT DOOR (RH)	DENTED	1,403.05	1,403.05
1	ROCKER PANEL OUTER GARNISH (RH)	CRACKED	483.60	483.60
1	REAR TYRE RIM (RH)	DISTORTED	351.90	351.90
1	REAR WHEEL HUP-CAP (RH)	CUT	150.70	150.70
1	REAR WHEELBEARING ING & HUB	DAMAGED	401.40	401.40
1	REAR TRAILING ARM (RH)	DISTORTED	120.00	120.00
1	REAR ASSIST (RH)	DISTORTED	120.00	120.00
1	REAR SHOCK ABSORBER (RH)	DISTORTED	342.20	342.20
1	REAR SHOCK ABSORBER MOUNTING (RH)	NOT NECESSARY	57.70	-
1	REAR UPPER ARM (RH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (RH)	DISTORTED	204.35	204.35
1	REAR KNUCKLE ARM (RH)	DISTORTED	574.80	574.80
	LESS 20% DISCOUNT		-2,296.67	-2,127.13
			9,186.68	8,508.52
SPECIAL NETT ITEMS				
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	CUT	50.00	50.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
2	REAR FEDNER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	O/S CUT / N/S NECESSARY	200.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR DOOR ADVERTISEMENT LOGO (RH) (SN)	CUT	100.00	100.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (RH) (SN)	NECESSARY	80.00	80.00
1	FRONT DOOR COLOURED COMFORT LOGO (RH)(SN)	NECESSARY	75.00	75.00

Report Ref No. CS/FCI18011570/Dqd3n2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR ADVERTISEMENT LOGO (RH) (SN)	CUT	100.00	100.00
1	REAR TYRE (RH)(SN)	SERVICEABLE	216.00	-
			917.00	701.00
	LABOUR			
	PANEL BEATING INCLUSIVE OF THE REPAIR OF REAR BUMPER.		1,500.00	700.00
	SPRAY PAINTING CHARGE.		1,500.00	700.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE/REFIX REAR WINDSCREEN GLASS.		120.00	80.00
	REMOVE/REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	-
	TRANSFER OF DOOR.		240.00	120.00
	REMOVE/REFIX UNDERCARRIAGE (RR).		200.00	150.00
	REAR WHEEL ALIGNMENT.		120.00	60.00
			4,150.00	1,930.00
GRAND TOTAL			14,253.68	11,139.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,900.00

Report Ref No. CS/FC118011570/Dqd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.