

Surveyor
CWS

Brylen
Serene Ier

ASSIGNMENT (Office)

From (Person)

of

FCI

Date/Time

25/6/18 @ 5.54pm

Estimated Cost

Bill to

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

SHD 4302L

Insured

SHA 2729T

at Workshop m/s

Chunni motor

Tel

6542 5119

of

AMK Autopoint #01-05/06

Policy No.

Claim No.

D18004972MFSH

Sum Insured

Excess

Make of Veh.

(Client's Record)

D.O.A.

21/06/2018

CA / REV / REP. / REV 24 HRS

'DS'

H.O.D. Endorsement

Date/Time

10:01am @ 26/6/18

Person Contacted

Lynn

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SHD 4302L - NS/INC130/0524/HH/k3	DOA: 9/6/2013
	SHA 2729T - CS3/FCI16023821/M/qh3s2	DOA: 7/12/2016
07/7/18 @ 3:31pm	revised to Serene Ier by email.	

Surveys

REF:

ASSIGNMENT

COE June 2020

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

BHD 4302 L

Yr Regn:

2012 June

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) Prime Mover /

Truck / Trailer or

Make:

Hyundai Sonata

C.C

1991

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

32467

T/Radio:

Insured / Std / NI / NA

Eng/No:

D4EAC100881

C/No:

KMHBT41VMCA826529

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60 R16

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

21/06/2018

D.O.I.

27/06/2018

Survey held at

Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

First Capital SMA 27297

26/07/18

Findings 1/5 14000/- with 10 days of my (ded to 6786.76, 33%)

RECEIVED 26 JUL 2018

Date/Time, File Pass to?

17/6/18 AMK

Date/Time, File Return to?

2)

Report Format :

TP

Lump Sum / I.B.I. (\$

14000

Days Of Repair:

10

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

S + RS, SI

Photos

Others

OTR

TOTAL

10 x 15 = 150

170 + 150

50

50 + 50

150

620



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004972MFSH
Our Ref: CS/FCI18011571/Dqd3

Date: 02 July 2018

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 4302L

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/06/2018 at the premises of M/s CHUNNI MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ 20,786.76 .
Revised Estimate Amount	: S\$ 14,142.46 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the n/s front portion.



Yours faithfully

Bryan Ang Tani
Motor Surveyor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	25-06-2018	Our Ref No. D18004972MFSH
Accident Date	21-06-2018	Claim Type. Third Party
Insured Vehicle	SHA2729T	Third Party Vehicle. SHD4302L
Survey Location	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06	
Contact Person.	LYNN OR IRENE	
Contact No.	64836016/ 0	Fax No. 65426039
Survey Type	DIRECT SETTLEMENT: EST. COR - \$20,786.76	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241744)



PRI Documents



Close



PRI Header Details

Claim No	D18004972MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CHUNNI M COMFORT TR/
Workshop Name	CHUNNI MOTOR WORK PTE LTD (Contact Person : LYNN OR IRENE)	Survey Location & Contact Details	AMK AUTOPOINT, SOON HOCK MOTOR, #01-05/06 Mobile: 0 , Phone: 64836016 , Fax: 65426039 EmailId: CHUNNIMOTOR@GMAIL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT: EST. COR - \$20,786.76		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA2729T	TP Vehicle No	SHD4302L
PRI Recieved Date	25-06-2018 06:46:40 PM	Surveyor Appointed Date	25-06-2018 05:53:34 PM	Surveyor Accept Date	26-06-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	26-06-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 2 July 2018 3:31 PM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004972MFSH/1
Attachments: CSFCI18011571Dqd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SHD 4302L.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 26 June 2018 10:06 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004972MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 25 June 2018 5:54 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004972MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Go further by (LKR.)

FCI

Page 1 of 2

SHD 4302L

Qty	Parts Description/ Labour	Type	Unit Price	Amount
				103.50
	Front Tyre (LH) <i>puncung 5070</i>		103.50	S 207.00
				Nett ✓
	Labour Charge			
	Panel Beating			S 1,000.00 600/-
	Spray Painting Charge			S 500.00 400/-
	Wiring Charge			S 50.00 30/-
	Tuff Kote			S 50.00 30/-
	Towing Charge			S 50.00 NN
	Remove/Refix Undercarriage (FRT)			S 200.00 150/-
	FRT Wheel Alignment			S 80.00 60/-
	Remove/Refix Aircon & Refill Gas		1500/-	S 150.00 NN
	Remove/Refix Dashboard			S 450.00 180/-
	Remove/Refix Fuse Box			S 180.00 50/-
	TOTAL LABOUR			S 2,710.00
	ESTIMATE TOTAL			S 20,786.76
				18351.82
				451400/-
	27/06 2018 01150W Not done 4/2018 10 6 chys LKK Auto			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHD 4302 L

Technician:

Mileage: 32467

Time Printed 27.6.18 1:40 PM

Hyundai 05- Sonata (NF)

Front : Left

Actual	BEFORE	Specified Range
8°18'		-0°30' 0°30'
3°56'		3°50' 5°50'
27°28'		-0°05' 0°05'
8°28'		
16°47'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
1°49'		-0°30' 0°30'
3°17'		3°50' 5°50'
-0°01'		-0°05' 0°05'
12°54'		
14°43'		

Front

	Actual	BEFORE	Specified Range
Cross Camber	6°29'		
Cross Caster	0°39'		
Cross SAI	-4°26'		
Total Toe	27°27'		-0°09' 0°09'
Cross Turn Diff.			

Rear : Left

Actual	BEFORE	Specified Range
-1°22'		-1°00' 0°00'
-0°12'		0°00' 0°09'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-1°08'		-1°00' 0°00'
-0°08'		0°00' 0°09'

Rear

	Actual	BEFORE	Specified Range
Cross Camber	-0°14'		
Total Toe	-0°20'		0°00' 0°19'
Thrust Angle	-0°02'		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18011571/Dqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 2729T	Veh. Inspected	SHD 4302L	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18004972MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	25/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI SONATA	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	KMHET41VMCA826529	Colour	BLUE	
Odometer	32467	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	HANKOOK	5 mm	
L/H Front Tyre	215/60 R16	HANKOOK	5 mm	
R/H Rear Tyre	215/60 R16	HANKOOK	5 mm	
L/H Rear Tyre	215/60 R16	HANKOOK	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/06/2018	Inspection Date	27/06/2018	
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4302L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER COVER	BROKEN	538.80	538.80
1	FRONT BUMPER SPONGE	NOT NECESSARY	136.30	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	504.10	-
1	FRONT BUMPER GRILLE (LH)	SERVICEABLE	17.60	-
1	FRONT BUMPER BRACKET TOP (LH)	SERVICEABLE	22.40	-
1	FRONT BUMPER PROTECTOR (LH)	BROKEN	29.20	29.20
1	FRONT BUMPER BRACKET (LH)	SERVICEABLE	20.10	-
1	FRONT BUMPER SIDE BRACKET	SERVICEABLE	14.30	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	1,023.00	1,023.00
1	HEADLAMP (LH)	CUT	797.90	797.90
1	FRONT FENDER (LH)	BUCKLED	593.00	593.00
1	FRONT FENDER SHIELD (LH)	DEFORMED	86.00	86.00
1	FRONT WHEEL RIM (LH)	BENT	284.70	284.70
1	FRONT WHEEL HUB CAP (LH)	CUT	145.00	145.00
1	FRONT WHEEL BEARING	DAMAGED	258.50	258.50
1	FRONT SHOCK ABSORBER (ASSY)(LH)	DISTORTED	203.70	203.70
1	FRONT SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	72.00	-
1	FRONT SHOCK ABSORBER FORK (LH)	DISTORTED	203.30	203.30
1	FRONT SUSPENSION UPPER ARM (LH)	DISTORTED	240.00	240.00
1	FRONT DRIVE SHAFT (LH)	DISTORTED	1,025.00	1,025.00
1	RACK & PINION ASSY	DISTORTED	2,093.00	2,093.00
1	STG TIE END	DISTORTED	66.50	66.50
1	STABILIZER BAR	DISTORTED	213.20	213.20
1	STABILIZER BAR BUSH (LHH)	NOT NECESSARY	12.80	-
1	STABILIZER BAR LINK	DISTORTED	78.30	78.30
1	STABILIZER BRACKET	NOT NECESSARY	23.00	-
1	FRONT SUSPENSION LOWER ARM (LH)	DISTORTED	685.20	685.20
1	KNUCKLE ARM (LH)	DISTORTED	558.60	558.60
1	ENGINE UNDER COVER	NOT NECESSARY	328.70	-
1	ENGINE CROSSMEMBER	DISTORTED	2,143.70	2,143.70
1	ECU BRACKET	BENT	78.30	78.30

Report Ref No. CS/FCI18011571/Dqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ECU UNIT	DENTED	4,028.30	4,028.30
1	CONTROLLER (PWN)	BROKEN	495.80	495.80
1	ABS SENSOR	NOT NECESSARY	250.50	-
1	WIRING-ENGINE	CRACKED	3,187.40	3,187.40
1	WIRING-FRONT	CRACKED	1,879.00	1,879.00
	LESS 20% DISCOUNT		-4,467.44	-4,187.08
			17,869.76	16,748.32
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT TYRE (LH)(50%)(SN)	PUNCTURE	207.00	103.50
			207.00	103.50
	<u>LABOUR</u>			
	PANEL BEATING.		1,000.00	600.00
	SPRAY PAINTING CHARGE.		500.00	400.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		50.00	30.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX UNDERCARRIAGE (FRT).		200.00	150.00
	FRT WHEEL ALIGNMENT.		80.00	60.00
	REMOVE/REFIX AIRCON & REFILL GAS.	NOT NECESSARY	150.00	-
	REMOVE/REFIX DASHBOARD.		450.00	180.00
	REMOVE/REFIX FUSE BOX.		180.00	50.00
			2,710.00	1,500.00
	GRAND TOTAL		20,786.76	18,351.82
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				14,000.00

Report Ref No. CS/FCI18011571/Dqd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.