

Surveyor

REF: CS1/SPF18011597/Klrbs2

Special Instruction:

ASSIGNMENT (Office)

From (Person): Abdul Rahman of SPF Date/Time: 14052018

Estimated Cost: Bill to:

LIS: \$18550.00

Third Parties:

Claimant:

Surveyor: Km Auto

Workshop: Premier Automotive

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SHB 89840 Insured: QX 581L

at Workshop m/s Premier Automotive Tel: 6544 6689

of 23 Changi South Ave 2 # 01-02.

Policy No: Claim No: AEMD/105/009/2017/161 (PD)

Sum Insured: Excess:

Make of Veh: D.O.A. 03122017

(Client's Record)

Do Not Finalize

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 16 days)

Date/Time: Submit Final Fig \$15,400, 12 days (Red \$ 3150 / 17 %; Original days)

Date/Time Action/Instruction

SHB 89840 - X

QX 581L - CS/SPF17023595 / (Gtbe)

Submit Paper Survey

RECEIVED 29 JUN 2018

Lump Sum \$ 15,000.00 confirmed with Kalum. on 29/6/2018 6pm

Signature and date 29/6/2018

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/ Evaluated by:

Fee Charged:

Date:

Basic & Add Transport Photos Others Total

Table with 1 column and 4 rows for fee breakdown and date.

1) Date/Time 29/6/18 File Pass to typist

3) Date/Time File Pass to

5) Date/Time File Pass to

2) Date/Time File Return to

4) Date/Time File Return to

6) Date/Time File Return to

## Catherine Chong (LKK Auto)

---

**From:** Abdul Rahman MOHAMAD SALIM (SPF)  
<Abdul\_Rahman\_Mohamad\_Salim@spf.gov.sg>  
**Sent:** Monday, 14 May, 2018 3:53 PM  
**To:** Catherine Chong (LKK Auto)  
**Cc:** 'Olivia Lau'; Rosalyn TAN (SPF); Frankie THAY (SPF)  
**Subject:** SHB8984C - Request Paper Survey  
**Attachments:** SHB8984C LOD of VisionLaw.pdf

Your Ref: SHB8984C  
Our Ref : AEMD/105/009/2017/161

Dear Cath,

Your preceding mail and our assignment on 8 Feb 2018 have reference.

Attached as requested.

Regards

Abdul Rahman (Mr)  
Accident Claims Officer  
Automotive Engineering & Management Division  
Police Logistics Department  
Singapore Police Force  
DID: (65) 6478 4840 | FAX: (65) 6478 4848



**HOME TEAM**  
TRANSFORMATION 2025  
*One Home, One Team*  
*Building Our Future Together*

**WARNING:** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

---

**From:** Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Saturday, 12 May 2018 3:30 PM  
**To:** Abdul Rahman MOHAMAD SALIM (SPF) <Abdul\_Rahman\_Mohamad\_Salim@spf.gov.sg>  
**Subject:** Request Paper Survey

Dear Mr Abdul Rahman,

Kindly refer to the attachment.

Please assist provide us the LOD for all vehicle for us conduct Paper Survey.

Best Regards,

**Catherine Chong** | Admin  
LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



# SINGAPORE POLICE FORCE

SPF Accidents Claims Section  
Automotive Engg & Mgmt Div  
Police Logistics Department  
No. 1 Mount Pleasant Road  
Block 8 Old Police Academy  
#02-12 Singapore 298333

Your Ref : SHB8984C

Our Ref : AEMD/105/009/2017/161(PD)

Date : 8 February 2018

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd  
Paya Ubi Industrial Park  
51 Ubi Avenue 1 #01/02-25  
Singapore 408933

Via Fax Only: 62564315

Dear Sir,

**ACCIDENT ON 3 DECEMBER 2017 INVOLVING GOVT VEH QX581L AND OTHER VEH SHB8984C**

We refer to the above matter.

- 2 Please arrange for a **Paper Survey** of vehicle no. **SHB8984C** at **M/s Premier Taxis Pte Ltd** of **23 Changi South Ave 2 #03-02, Singapore 486443.**
- 3 For appointment kindly contact Tel: 64488208.
- 4 Estimates were provided by the workshop.
- 5 Thank you.

Yours faithfully,

Abdul Rahman  
Accident Claims Officer  
for ASST DIRECTOR

cc : M/s Vision Law LLC (Ref: AM1-ylv-Ins-P36-105525-18-er  
Via fax: 65356802 only

A FORCE FOR THE NATION

# VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths  
Agents for Trade Marks

(Incorporated with limited liability)

Unique Entity Number: 200721148H

✓ **HEAD OFFICE**

133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413

Branch: 490 Toa Payoh Lorong 6  
#03-11 HDB Hub  
Singapore 310490

2017/161

✓ **HEAD OFFICE**

TEL : (65) 65342811 (Hunting)  
FAX : (65) 65356802 (General)  
✓: (65) 65355905 (Litigation)  
E-mail : yvonnellm@visionlawllc.com

**BRANCH**

TEL : (65) 63580703  
FAX : (65) 63580448 (Conveyancing)

ERIC NG CHING BOON  
RAYNEY WONG KENG LEONG  
AUDREY WONG SU-HSIEN  
PAUL YAP TAI SAN  
ANJALLI D/O MUNIANDY  
SEGA PARAM  
TIWARY ANURADHA  
ONG BOCK KEE  
DIANE ANG KIM NOI  
RAVENDRA KRISHNASAMY  
TAY HAO RAN  
JANICE HAN JIA LIN  
SELWYN TAN YINGXIAN

**WHEN REPLYING PLEASE QUOTE OUR REFERENCE – PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER**

Our Ref: AM1-yiv-Ins-P36-105525-18-er  
Your Ref: QX 581 L

1 February 2018

**URGENT**

BY AIR MAIL



**SPF ACCIDENT CLAIMS SECTION**

Automotive Engineering & Management Division  
Police Logistics Department  
1 Mount Pleasant Road  
Block 8 Old Police Academy  
Singapore 298333

Dear Sirs,

**CLAIMANT : PREMIER TAXIS PTE LTD**  
**ACCIDENT INVOLVING SHB 8984 C & QX 581 L ON 03-DEC-2017 AT JUNCTION OF DICKSON ROAD AND PERAK ROAD AT ABOUT 2230 HOURS**

We are instructed by the above named to claim damages against you/your insured in connection with a road traffic accident on **03-Dec-2017 AT JUNCTION OF DICKSON ROAD AND PERAK ROAD AT ABOUT 2230 HOURS** involving our client's vehicle registration number **SHB 8984 C** and vehicle registration number **QX 581 L** driven by you/your insured at the material time.

We are instructed that the accident was caused by you/your insured's negligent driving and /or management of your/your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

1.	Costs of Repair	\$19,848.50
2.	Loss of Use (16 days x \$112.16 per day)	\$ 1,794.56
3.	Pre-repair Loss of Use (21 days x \$112.16 per day)	\$ 2,355.36
4.	Survey report fees	\$ 250.00
5.	Cost Contribution (at this stage) (With GST)	\$ 1,284.00
6.	Disbursements (at this stage) (With GST)	\$ 128.40
	<b>TOTAL:</b>	<b>\$25,660.82</b>

.../2 to be continued next page

**CONFIDENTIALITY**  
THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

Continuation Sheet  
Page 2

Our Ref: AM1-ylv-Ins-P36-105525-18-er  
Your Ref: QX 581 L

1 February 2018

**SPF ACCIDENT CLAIMS SECTION**

Automotive Engineering & Management Division  
Police Logistics Department  
1 Mount Pleasant Road  
Block 8 Old Police Academy  
Singapore 298333

We enclose a copy of each of the following documents for your consideration:-

- (a) Police/GIA/SAS report lodged by driver of SHB 8984 C;
- (b) Certificate of Insurance;
- (c) Registration Card;
- (d) Certification letter;
- (e) Final Repair Bill;
- (f) Surveyor's report & invoice; and
- (g) **239 original photographs** depicting the damages to motor vehicle SHB 8984 C.
  - (P.S:- Original photographs will be sent to insurance co. only)
  - (P.S:- Kindly return us all original photographs within 7 days hereof)

***We have notified your insurers of the accident and a pre-repair inspection of our client's vehicle was carried out by your insurers.***

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully

ANJALLI M  
(HEAD OFFICE)  
Encl.

**CONFIDENTIALITY**

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.



# AUTOMOBILE INSPECTION REPORT

NO. 7/12/TP011/I  
ACC DATE 03-Dec-17

To: PREMIER AUTOMOTIVE SERVICES PTE LTD  
23 CHANGI SOUTH AVE 2 #01-02 S'PORE 486443

General Condition: Poor/Fair/Good/Excellent

Reg. No.	SHB 8984 C	Make/Model	KIA OPTIMA 1.7 TAXI AUTO	Year	2014
Engine No.	D4FDDH308957	Chassis No.	KNAGM414ME5455540	Colour	Metallic Silver
Condition of Tyres			Speedometer Reading - Km		Battery flat
Front N/S	MAXXIS 205/65R16	worn	10 %	Front O/S	MAXXIS 205/65R16 worn 10 %
Rear N/S	MAXXIS 205/65R16	worn	10 %	Rear O/S	MAXXIS 205/65R16 worn 10 %

vs Requested By YOURSELF On 12-Dec-17 The Above Vehicle

Was Inspected At ( 12-Dec-17 ) PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVE 2 #01-02 S'PORE 486443

And The Undermentioned Damage Was Noted:-

Front windscreen glass bent, distorted and cracked, windscreen o/s pillar and lower panel bent, cab scuttle panel buckled, wiper centre garnish bent and snapped, side garnishes twisted, snapped and dislodged, bonnet assy. buckled, twisted, folded and displaced, hinges twisted, lock twisted and jammed, damper bent and loosened, support panel buckled, twisted and folded, top garnish twisted, cracked and deformed, o/s headlamp smashed, n/s headlamp dislodged, fasteners snapped, grille assy. smashed and ripped off, bumper twisted, torn, flattened and dislodged, o/s protector and fog lamp cover grazed, twisted and snapped, tow hook cover dislodged, fasteners snapped, lower centre grille snapped off, inner sponge snapped off, reinforcement twisted and displaced, o/s front wheel assy. grazed, bent, pushed backwards and out of alignment, wheel cover grazed, sliced and bent, tyre wall grazed, o/s fender twisted, buckled and flattened, inner shield buckled, torn and dislodged, windscreen washer container buckled and displaced, meter cracked, o/s inner panel buckled and folded, body member twisted, radiator expansion tank dented, bent and displaced, n/s fender twisted and buckled, n/s inner panel and body member bent, bulkhead assy. pushed to the n/s, air intake duct broken and dislodged, air cleaner assy. displaced, air con condenser and radiator assy. twisted and dislodged, electrical fan assy. bent and dislodged, intercooler unit displaced and sandwiched, engine and auto transmission assy. displaced and sagged, mountings torn.

Photographs:-	239 Copies	were taken at time of inspection and are attached .
The Repairers estimate was for a total amount of	\$	28,028.00
After adjustment the estimate was revised and agreed at	\$	23,267.00

**SPECIAL REMARKS**

The Repairers were **NOT AUTHORISED** to proceed with the repairs.  
**Survey was carried out without prejudice.**  
The above were due to impact to the frontal o/s portion of the taxi.  
Alternatively, we recommend that repairs be carried out on a Lump Sum basis instead, @\$18,550/- Nett.

  
**MICHAEL EE** Dip A.Eng., AMIRTE., AMSAE., AMSOE., AMMI., MSAAA

Date 27-Dec-17



**APPENDIX 'A'**

**TO REPORT NO: 7/12/TP011/I**  
**REGN. NO: SHB 8984 C**

47 Jalan Pemimpin  
#02-07 Halcyon 2  
Singapore 577200

T 6448 8208  
F 6442 9690  
E kmautoassessors@gmail.com  
Regn. No. 200907340Z

Nature of Work and Materials	Repairers Estimate \$	Remarks	Amount Revised \$
1 pce front windscreen glass	801.00	bent, distorted, cracked	801.00
1 pce front windscreen moulding	101.00	necessary	101.00
1 pce front wiper centre garnish	368.00	bent & snapped	368.00
2 pcs front wiper side garnishes <i>n/s X not Damage o/s v</i>	86.00	twisted, snapped, dislodged	86.00/43
1 pce front wiper linkage assy. <i>X repair</i>	168.00	bent, bracket snapped	168.00 X
1 pce bonnet	979.00	buckled, twisted, folded, displaced	979.00
1 pce bonnet insulator	219.00	not necessary	-
1 pce bonnet lock assy.	36.00	twisted & jammed	36.00
1 pce bonnet damper <i>X not Damage</i>	70.00	bent & loosened	70.00 X
2 pcs bonnet hinges	46.00	twisted	46.00
1 pce front support panel assy.	645.00	buckled, twisted, folded	645.00
1 pce front support panel top garnish	357.00	twisted, cracked, deformed	357.00
1 pce front grille assy.	385.00	smashed, ripped off	385.00
2 pcs headlamps assy.	2,076.00	o/s smashed, n/s fastener snapped	2,076.00
1 pce front bumper fascia	531.00	twisted, torn, flattened, dislodged	531.00
1 pce front bumper lower centre grille	174.00	snapped off	174.00
1 pce front bumper tow-hook cover	14.00	dislodged, fasteners torn	14.00
2 pcs front bumper protectors <i>n/s X o/s v</i>	106.00	o/s only - grazed, twisted, snapped	53.00
2 pcs front bumper fog lamp covers <i>n/s X o/s v</i>	132.00	o/s only - grazed, twisted, snapped	66.00
1 pce front bumper inner sponge <i>nn</i>	110.00	snapped off, dislodged	110.00
1 pce front bumper reinforcement	328.00	twisted & displaced	328.00
1 pce front bumper lower beam	21.00	twisted	21.00
2 pcs front bumper side retainers	32.00	snapped	32.00
1 pce front bumper emblem	48.00	necessary	48.00
1 pce engine lower o/s splash cover	144.00	bent, torn, dislodged	144.00
1 pce engine lower n/s splash cover <i>X not Damage</i>	144.00	bent, torn, dislodged	144.00 X
1 pce engine lower centre splash cover	173.00	bent, torn, dislodged	173.00
2 pcs front fenders <i>L/S X repair RH v</i>	768.00	twisted, buckled, flattened	768.00 / 324
2 pcs front fender inner shields <i>LH X repair RH v</i>	240.00	o/s only - buckled, torn	120.00
2 pcs front wheel house panels <i>LH X repair RH v</i>	934.00	o/s only - buckled, folded	467.00
1 pce windscreen washer container	47.00	buckled & torn	47.00
2 pcs windscreen washer motors	96.00	cracked & snapped	96.00
1 pce o/s front wheel rim <i>X not Damage</i>	246.00	grazed & bent	246.00 X
1 pce o/s front wheel cover	116.00	grazed, sliced, bent	116.00
1 pce o/s front wheel hub assy. <i>X not Damage</i>	230.00	warped	230.00 X
1 pce o/s front knuckle arm	547.00	bent	547.00
1 pce o/s front knuckle arm bearing <i>X re-use</i>	134.00	necessary	134.00 X
1 pce o/s front ball-joint	59.00	bent & loosened	59.00
1 pce o/s front lower arm	439.00	twisted	439.00
1 pce o/s front shock absorber	330.00	bent & stiffened	330.00
1 pce front stabilizer bar	243.00	not necessary	-
2 pcs front stabilizer bar links <i>o/s v</i>	172.00	o/s only - bent	86.00
1 pce o/s steering tie rod	61.00	bent	61.00
1 pce air intake duct assy.	204.00	broken & dislodged	204.00
1 pce air cleaner assy.	174.00	housing cracked, fasteners snapped	174.00
1 pce engine o/s mounting	323.00	bent & torn	323.00
<i>c/f</i>	13,657.00		12,403.00
<b>Total Amount Revised</b>		\$	
<b>Lump Sum Repairs Amount</b>		\$	
<b>It is estimated that the repairs will take</b>		<b>days to complete.</b>	



**APPENDIX 'A'**

**TO REPORT NO: 7/12/TP011/I**  
**REGN. NO: SHB 8984 C**

Nature of Work and Materials	Repairers Estimate \$	Remarks	Amount Revised \$
	b/f 13,609.00		12,355.00
	1367		
1 pce engine rear mounting	244.00	bent & torn	244.00
1 pce transmission mounting <i>X not done</i>	235.00	bent & torn	235.00 X
1 pce intercooler unit	800.00	dented & bent	800.00
1 pce intercooler hose - B	313.00	dented & torn	313.00
1 pce alternator assy. <i>X not done</i>	904.00	distorted, housing snapped	904.00 X
1 pce radiator assy.	699.00	dented, bent, cracked	699.00
1 pce radiator expansion tank	34.00	dented, bent, displaced	34.00
2 pcs radiator top mountings	36.00	twisted & torn	36.00
1 pce radiator top hose	78.00	torn	78.00
1 pce radiator bottom hose	64.00	torn	64.00
1 pce electrical fan assy.	596.00	bent, snapped, s/circuited	596.00
1 pce air con condenser	805.00	dented & twisted	805.00
1 pce air con discharge hose	129.00	twisted & folded	129.00
1 pce air con suction hose	177.00	twisted & folded	177.00
1 pce air con liquid pipe	215.00	twisted & folded	215.00
1 pce air con compressor assy.	1,991.00	clutch assy. grazed, bent	1,991.00
1 pce air con belt	16.00	grazed & sliced	16.00
1 pce air con belt tensioner	231.00	warped	231.00
			19,922.00
	21224	less 10%	1,992.20
	21,176.00		17,929.80
<b>S.NETT</b>			
1 pce front windscreen primer	60.00	necessary	60.00
1 pce front windscreen sealant	50.00	necessary	50.00 40
1 pce front windscreen ERP bracket	26.00	necessary	26.00 10
1 set bonnet insulator clips	42.00	necessary	42.00 X
1 set front support panel top garnish clips	21.00	necessary	21.00
1 set grille clips	14.00	necessary	14.00
1 set front bumper clips	35.00	necessary	35.00
1 pce front no. plate with casing	50.00	dented & bent	50.00 35
2sets front fender inner shield clips <i>ok</i>	56.00	necessary	56.00 28
Towing charges.	50.00		50.00
Remove front windscreen glass assy., to enable necessary repairs, check, replace damaged glass and fittings, refit glass assy.	150.00		120.00 100
Remove dashboard panel assy. and steering column assy. to enable necessary repairs, check and refit same.	350.00		280.00 150
	22128		
c/f	22,080.00		18,733.80
<b>Total Amount Revised</b>		\$	
<b>Lump Sum Repairs Amount</b>		\$	
It is estimated that the repairs will take		days to complete.	



**APPENDIX 'A'**

**TO REPORT NO:** 7/12/TP011/I  
**REGN. NO:** SHB 8984 C

Nature of Work and Materials	Repairers Estimate \$	Remarks	Amount Revised \$
b/f	22,080.00 <i>22178</i>		18,733.80
Remove necessary air con. parts and fittings to enable necessary repairs, check, replace damaged parts, refit same, vacuum and recharge gas.	150.00		<del>120.00</del> <sup>100</sup>
Remove radiator assy. and all fittings to enable necessary repairs, check, replace damaged parts, refit and test engine cooling system.	120.00		<del>80.00</del> <sup>50</sup>
Lift out engine assy. to enable necessary repairs, check, refit same and start-up engine.	450.00		<del>350.00</del> <sup>200</sup>
Dismantle and remove o/s front suspensions assy. to enable necessary, repairs, check, replace damaged parts, reassemble, refit same, bleed brakes.	250.00		<del>200.00</del> <sup>100</sup>
Check and realign wheels (computerised).	100.00		60.00
Remove damaged parts, jack and cut out damaged body panels, jack out, straighten up damaged body panels and repair body parts and fittings, whichever possible and necessary, replace and weld necessary damaged parts, refit and align whichever parts necessary (incl. alignment of body structure).	2,000.00		<del>1,600.00</del> <sup>1200</sup>
Realign body structure on Chassis Alignment System.	400.00		<del>250.00</del> <sup>150</sup>
Paint replacement parts and repaint damaged sections with welded portions in and outside.	1,800.00		<del>1,400.00</del> <sup>1080</sup>
Rustproof replacement parts and touch-up damaged sections.	350.00		<del>250.00</del> <sup>50</sup>
Conduct diagnostic programming and calibration.	280.00		<del>180.00</del> <sup>50</sup>
<b>TOTAL</b>	<i>28028</i> 27,980.00	<i>1/5 14900 / 12/17/12</i>	23,223.80
Total Amount Revised	\$	23,223.80	
Lump Sum Repairs Amount	\$	18,550.00	
It is estimated that the repairs will take	SIXTEEN	days to complete.	



Your Ref: AEMD/105/009/2017/161 (PD)

Date: 02<sup>nd</sup> June 2018

Our Ref: CS1/SPF18011597/K1rbs2

**M/s Automotive Engineering & MGT Division**

Accident Claim Section

(Singapore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

(The Motor Claims Department)

Attn: Abdul Rahman

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:  
SHB 8984C INSURED VEHICLE: QX 581L ACCIDENT DATE: 03/12/2017**

We thank you for your instruction on 14/05/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SHB 8984C from M/s KM Auto Assessors Pte. Ltd.
- b) Colour damaged vehicle photographs of SHB 8984C.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SHB 8984C
Make & Model	: Kia Optima 1.7 Taxi Auto
Year of Registration	: 2014
Chassis Number	: KNAGM414ME5455540

2. We recommend that the repairs of the entire damage require about 12 (Twelve) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8984C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT WINDSCREEN GLASS	BENT / DISTORTED / CRACKED	801.00	801.00
1	FRONT WINDSCREEN MOULDING	NECESSARY	101.00	101.00
1	FRONT WIPER CENTRE GARNISH	BENT / SNAPPED	368.00	368.00
2	FRONT WIPER SIDE GARNISHES	N/S NO DAMAGE / O/S TWISTED	86.00	43.00
1	FRONT WIPER LINKAGE ASSY	TO REPAIR SEE LABOUR	168.00	-
1	BONNET	BUCKLED	979.00	979.00
1	BONNET INSULATOR	NOT NECESSARY	219.00	-
1	BONNET LOCK ASSY	TWISTED / JAMMED	36.00	36.00
1	BONNET DAMPER	NO DAMAGE	70.00	-
2	BONNET HINGES	TWISTED	46.00	46.00
1	FRONT SUPPORT PANEL ASSY	BUCKLED	645.00	645.00
1	FRONT SUPPORT PANEL TOP GARNISH	TWISTED	357.00	357.00
1	FROTN GRILLE ASSY	SMASHED	385.00	385.00
2	HEADLAMPS ASSY	O/S SMASHED / N/S FASTENER SNAPPED	2,076.00	2,076.00
1	FRONT BUMPER FASCIA	TWISTED	531.00	531.00
1	FRONT BUMPER LOWER CENTRE GRILLE	SNAPPED OFF	174.00	174.00
1	FRONT BUMPER TOW-HOOK COVER	DISLODGE / FASTENER TORN	14.00	14.00
2	FRONT BUMPER PROTECTORS	N/S NOT NECESSARY / O/S GRAZED/TWISTED/ SNAPPED	106.00	53.00
2	FRONT BUMPER FOG LAMP COVERS	N/S NOT NECESSARY / O/S GRAZED/TWISTED/ SNAPPED	132.00	66.00
1	FRONT BUMPER INNER SPONGE	DISLODGE	110.00	110.00
1	FRONT BUMPER REINFORCEMENT	TWISTED	328.00	328.00
1	FRONT BUMPER LOWER BEAM	TWISTED	21.00	21.00

Report Ref No. CS1/SPF18011597/K1rbs2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT BUMPER SIDE RETAINERS	SNAPPED	32.00	32.00
1	FRONT BUMPER EMBLEM	NECESSARY	48.00	48.00
1	ENGINE LOWER O/S SPLASH COVER	BENT / TORN	144.00	144.00
1	ENGINE LOWER N/S SPLASH COVER	NO DAMAGE	144.00	-
1	ENGINE LOWER CENTRE SPLASH COVER	BENT / TORN	173.00	173.00
2	FRONT FENDERS	N/S TO REPAIR SEE LABOUR / O/S TWISTED	768.00	384.00
2	FRONT FENDER INNER SHIELDS	N/S NOT NECESSARY / O/S BUCKLED	240.00	120.00
2	FRONT WHEEL HOUSE PANELS	N/S TO REPAIR SEE LABOUR / O/S BUCKLED	934.00	467.00
1	WINDSCREEN WASHER CONTAINER	BUCKLED / TORN	47.00	47.00
2	WINDSCREEN WASHER MOTORS	CRACKED / SNAPPED	96.00	96.00
1	O/S FRONT WHEEL RIM	NO DAMAGE	246.00	-
1	O/S FRONT WHEEL COVER	GRAZED	116.00	116.00
1	O/S FRONT WHEEL HUB ASSY	NO DAMAGE	230.00	-
1	O/S FRONT KNUCKLE ARM	BENT	547.00	547.00
1	O/S FRONT KNUCKLE ARM BEARING	RE-USE	134.00	-
1	O/S FRONT BALL-JOINT	BENT	59.00	59.00
1	O/S FRONT LOWER ARM	TWISTED	439.00	439.00
1	O/S FRONT SHOCK ABSORBER	BENT	330.00	330.00
1	FRONT STABILIZER BAR	NOT NECESSARY	243.00	-
2	FRONT STABILIZER BAR LINKS	O/S BENT	172.00	86.00
1	O/S STEERING TIE ROD	BENT	61.00	61.00
1	AIR INTAKE DUCT ASSY	BROKEN	204.00	204.00
1	AIR CLEANER ASSY	HOUSING CRACKED	174.00	174.00
1	ENGINE O/S MOUNTING	BENT / TORN	323.00	323.00
1	ENGINE REAR MOUNTING	BENT / TORN	244.00	244.00
1	TRANSMISSION MOUNTING	NO DAMAGE	235.00	-
1	INTERCOOLER UNIT	DENTED / BENT	800.00	800.00
1	INTERCOOLER HOSE - B	DENTED / TORN	313.00	313.00

Report Ref No. CS1/SPF18011597/K1rbs2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ALTERNATOR ASSY	NO DAMAGE	904.00	-
1	RADIATOR ASSY	DENTED	699.00	699.00
1	RADIATOR EXPANSION TANK	DENTED	34.00	34.00
2	RADIATOR TOP MOUNTINGS	TWISTED / TORN	36.00	36.00
1	RADIATOR TOP HOSE	TORN	78.00	78.00
1	RADIATOR BOTTOM HOSE	TORN	64.00	64.00
1	ELECTRICAL FAN ASSY	BENT	596.00	596.00
1	AIR CON CONDENSER	DENTED / TWISTED	805.00	805.00
1	AIR CON DISCHARGE HOSE	TWISTED	129.00	129.00
1	AIR CON SUCTION HOSE	TWISTED	177.00	177.00
1	AIR CON LIQUID PIPE	TWISTED	215.00	215.00
1	AIR CON COMPRESSOR ASSY	GRAZED / BENT	1,991.00	1,991.00
1	AIR CON BELT	GRAZED	16.00	16.00
1	AIR CON BELT TERSIONER	WARPED	231.00	231.00
	LESS 10% DISCOUNT		-	-1,741.20
			21,224.00	15,670.80
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT WINDSCREEN PRIMER (SN)	NECESSARY	60.00	60.00
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	FRONT WINDSCREEN ERP BRACKET (SN)	NECESSARY	26.00	10.00
1	SET BONNET INSULATOR CLIPS (SN)	NOT NECESSARY	42.00	-
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN)	NECESSARY	21.00	21.00
1	SET GRILLE CLIPS (SN)	NECESSARY	14.00	14.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	35.00	35.00
1	FRONT NO. PLATE WITH CASING (SN)	DENTED / BENT	50.00	35.00
2	SETS FRONT FENDER INNER SHIELD CLIPS (SN)	N/S NOT NECESSARY / O/S NECESSARY	56.00	28.00
			354.00	243.00
	<b><u>LABOUR</u></b>			
	TOWING CHARGES.		50.00	50.00
	REMOVE FRONT WINDSCREEN GLASS ASSY, TO ENABLE NECESSARY REPAIRS, CHECK, REPLACE DAMAGED GLASS AND FITTINGS, REFIT GLASS ASSY.		150.00	100.00

Report Ref No. CS1/SPF18011597/K1rbs2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE DASHBOARD PANEL ASSY AND STEERING COLUMN ASSY TO ENABLE NECESSARY REPAIRS,CHECK AND REFIT SAME.		350.00	150.00
	REMOVE NECESSARY AIR CON,PARTS AND FITTINGS TO ENABLE NECESSARY REPAIRS,CHECK,REPLACE DAMAGED PARTS,REFIT SAME,VACUUM AND RECHARGE GAS.		150.00	100.00
	REMOVE RADIATOR ASSY AND ALL FITTINGS TO ENABLE NECESSARY REPAIRS,CHECK,REPLACE DAMAGED PARTS,REFIT AND TEST ENGINE COOLING SYSTEM.		120.00	50.00
	LIFT OUT ENGINE ASSY TO ENABLE NECESSARY REPAIRS,CHECK,REFIT SAME AND START-UP ENGINE.		450.00	200.00
	DISMANTLE AND REMOVE O/S FRONT SUSPENSIONS ASSY.TO ENABLE NECESSARY,REPAIRS,CHECK,REPLACE DAMAGED PARTS,REASSEMBLE,REFIT SAME,BLEED BRAKES.		250.00	100.00
	CHECK AND REALIGN WHEELS (COMPUTERISED).		100.00	60.00
	REMOVE DAMAGED PARTS,JACK AD CUT OUT DAMAGED BODY PANELS,JACK OUT,STRAUGHTEN UP DAMAGED BODY PANELS AND REPAIR BODY PARTS AND FITTINGS,WHICHEVER POSSIBLE AND NECESSARY,REPLACE AND WELD NECESSARY DAMAGED PARTS,REFIT AND ALIGN WHICHEVER PARTS NECESSARY (INCL ALIGNMENT OF BODY STRUCTURE). INCLUSIVE OF THE REPAIR OF FRONT WIPER LINKAGE ASSY, N/S FRONT FENDERS AND N/S FRONT WHEEL HOUSE PANELS.		2,000.00	1,200.00
	REALIGN BODY STRUCTURE ON CHASSIS ALIGNMENT SYSTEM.		400.00	150.00
	PAINT REPLACEMENT PARTS AND REPAINT DAMAGED SECTIONS WITH WELDED PORTIONS IN AND OUTSIDE.		1,800.00	1,080.00
	RUSTPROOD REPLACEMENT PARTS AND TOUCH-UP DAMAGED SECTIONS.		350.00	50.00
	CONDUCT DIAGNOSTIC PROGRAMMING AND CALIBRATION.		280.00	50.00
			6,450.00	3,340.00
<b>GRAND TOTAL</b>			<b>28,028.00</b>	<b>19,253.80</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>15,400.00</b>

Report Ref No. CS1/SPF18011597/K1rbs2



Report Ref No. CS1/SPF18011597/K1rbs2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.