

REF: CS/SPF18011602 / TITbed Special instruction:  
 From (Person): Abdul Rahman of SPF Date/Time: 26062018  
 Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_  
 OD / IB / WS / TP RES / OD RES / EVA / INV / MV / CS  
 To inspect Vehicle No: SLX 6960X Insured: QX 5320  
 at Workshop n/s: Motor Image Tel: \_\_\_\_\_  
 of: 75 Long Kell Rd  
 Policy No: \_\_\_\_\_ Claim No: AEMD/105/009/2018/080  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 Make of Veh: \_\_\_\_\_ D.O.A. 18062018  
 (Client's Record) 04/07/2018 @ 10am owner waiting  
 CA / REV / REP. / REV 24 HRS 'wp' H.O.D. Endorsement \_\_\_\_\_  
 Date/Time: 26062018 1:15pm Person Contacted: Jeff Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SLX 6960X - X	
	QX 5320 - X	
	Submit Prel report	3 working days
	liability not clear, & still under investigation	1 week end
		Total: 4 days.

\$2500 - \$3500 (range)

28/7 - reopen submit final report 21/8/19

File pass to typist

P/P \$2513.60

(Red: 1853.36; 42%)

21/11/19 1st DOE 21/8/19, reopen ref only ↓

08/11/13 wef  
ASS REQ BY

Tanjin

REF: SPF

### ASSIGNMENT

From Date 01/07/2018

Estimated Cost

ON TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLX G960X  
at Workshop m/s: Motor Image  
of: 25 Leng Kee Rd

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


10 am @ owner waiting

Make of Veh.

Jeff

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (w/p)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLX G960X Yr Regn: 2018, April.

Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Subaru Forestar c.c

Colour: Black A/C: Insured / Std / NI / NA

Sp Reading: 7255 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: SP1535KCS56106703

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  Inorder / Jammed / Leaked / Burnt or

Brake:  Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275 / 60 R17

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 4/7/18 @ 1045

Survey held at: Motor Image Leng Kee

Des. of Damages: Frt /  Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 27 AUG 2010

Date/Time, File Pass to?

1) 27/8 Typist

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / I.B.I: (\$ - )

Preli. Report  
 Final Report

Days Of Repair: 3

Resurvey No. of Trip: -

Add Fee:  Site Insp (\$ )

Interview (\$ )

Tech. Invs (\$ )

Weekend (\$ )

Survey Fee:

Transportation: S + RS \$

Photos

Others

TOTAL

280

280

## Denise Tay (LKKAuto)

---

**From:** Darren <claims@teamworkgarage.com>  
**Sent:** Tuesday, 27 August 2019 12:12 PM  
**To:** Denise Tay (LKKAuto); Taufikh (LKKAuto)  
**Subject:** RE: FW9361G YAMAHA RXZ

Hi Denise,

This case we submitted independence report already. Please proceed

Darren  
Teamwork Garage Pte Ltd  
53 Ubi Avenue 1  
#01-24 Paya Ubi Industrial Park  
Singapore 408934  
Tel: 68442475  
Fax: 68442474

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Tuesday, 27 August 2019 10:44 AM  
**To:** Taufikh (LKKAuto); 'Darren'  
**Subject:** RE: FW9361G YAMAHA RXZ

Dear Darren,

Can confirm the repair cost?

COR l/s \$1600 , 4 days.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sur@lkkauto.com](mailto:sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Taufikh (LKKAuto) <Taufikh@lkkauto.com>  
**Sent:** Thursday, 22 August 2019 10:00 AM  
**To:** 'Darren' <claims@teamworkgarage.com>  
**Cc:** Denise Tay (LKKAuto) <denisetay@lkkauto.com>  
**Subject:** RE: FW9361G YAMAHA RXZ

Hi Darren,

COR l/s \$1600 , 4 days.

Regards  
Taufikh  
Lkk Auto

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : LENG KEE  
CONTACT NO :  
REFERENCE : INS/IC/LHI/034/2018  
DATE : 19-JUN-2018

S()  
TEL :  
FAX :

OWNER'S NAME : WONG TAT KAI  
ADDRESS : 257 ARCADIA ROAD  
#06-03  
S(289851)  
TELEPHONE NO : 97433789

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 180034819  
VEHICLE NO : SLX6960X  
MODEL CODE : SJ5EK7C  
MODEL/YEAR : FORESTER 2.0I-L AWD CVT  
ENGINE NO : FB20YD12488  
CHASSIS NO : JF1SJ5KC5JG106703  
MILEAGE : 1 KM  
DATE IN : 19/06/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : JEFF TEH TENG CHUEN  
ACCIDENT DATE : 19/06/2018

Print Date : 19/06/2018  
Print Time : 12:05:10

Tanpin 97495749-  
WP  
4/7/18 01045  
Resurvey before paint  
Sup@lkkauto.com  
03 days

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLX6960X

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	TO SUPPLY AND REPLACE REAR BUMPER ASSY AND REAR EXHAUST COVER	1680.00	560
2	ZZ/002	TO RESPRAY REAR BUMPER ASSY	880.00	440
3	ZZ/003	TO REMOVE AND CHECK REVERSE SENSOR CONDITION	60.00	40
4	ZZ/004	SUNDRIES	50.00	20
TOTAL LABOUR CHARGES			2670.00	

3372.04

6377.04

MOTORIMABE ENTERPRISES PTE. LTD.  
 25 LENG KEE ROAD  
 SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLX6960X

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	BUMPER FACE REAR FORESTER IL	57704SG012	540.00	del ✓		
2	BRKT SD R RH	(1) 57707SG080	14.40	? + )		
3	BRKT SD R LH	57707SG090	14.40	? + )		
4	BEAM COMPL R EU	57711SG0219P	288.00	? + )		
5	COVER BMPR R (EXHAUST)	57731SG060	14.40	cut ✓		
SUB TOTAL			871.20	0.00	0.00	0.00
LESS DISCOUNT ( NETT-20 %)			174.24	0.00	0.00	0.00
GRAND TOTAL			696.96	0.00	0.00	0.00
OVERALL TOTAL			696.96			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

6. Cover hook R

57731SG060NN

12-60 cut ✓

ROTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLX6960X

TOTAL LABOUR CHARGES	2670.00
TOTAL SPARE PARTS CHARGES	696.96
GRAND TOTAL	3366.96 *

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

FINALIZED : ACCIDENT/BODY REPAIRS  
WORKSHOP : LENG KEE  
CONTACT NO :  
REFERENCE : INS/IC/LHI/034/2018  
DATE : 19-JUN-2018

SPF ACCIDENT CLAIMS SECTION  
POLICE LOGISTIC DEPT  
NO.1 MOUNT PLEASANT RD BLK B OLD POLICE ACADEMY  
S(298333)  
TEL : 64784841/64784836  
FAX : 64670160  
MR.SAMAD SURAT

OWNER'S NAME : WONG TAT KAI  
ADDRESS : 257 ARCADIA ROAD  
#06-03  
S(289851)  
TELEPHONE NO : 97433789

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 180034819  
VEHICLE NO : SLX6960X  
MODEL CODE : SJ5EK7C  
MODEL/YEAR : FORESTER 2.0I-L AWD CVT  
ENGINE NO : FB20YD12488  
CHASSIS NO : JF1SJ5KC5JG106703  
MILEAGE : 1 KM  
DATE IN : 19/06/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : JEFF TEH TENG CHUEN  
ACCIDENT DATE : 19/06/2018

Print Date : 05/08/2019  
Print Time : 14:44:40

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLX6960X

---

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	TO SUPPLY AND REPLACE REAR BUMPER ASSY AND REAR EXHAUST COVER	1680.00	560.00
2	ZZ/002	TO RESPRAY REAR BUMPER ASSY	880.00	440.00
3	ZZ/003	TO REMOVE AND CHECK REVERSE SENSOR CONDITION	60.00	40.00
4	ZZ/004	SUNDRIES	50.00	20.00
5	ZZ/005	TO REPAIR REAR END PANEL (SUPP)	560.00	560.00 (A) rec ✓
6	ZZ/006	TO RESPRAY END PANEL (SUPP)	440.00	440.00 (M) rec ✓
TOTAL LABOUR CHARGES			3670.00	2060.00

MOTORIMAGE ENTERPRISES PTE. LTD.  
 25 LENG KEE ROAD  
 SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLX6960X

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	BUMPER FACE REAR FORESTER IL	57704SG012	540.00			OK
2	BRKT SD R RH	(1) 57707SG080	14.40			X
3	BRKT SD R LH	57707SG090	14.40			X
4	BEAM COMPL R EU	57711SG0219P	288.00			X
5	COVER HOOK R	57731SG010NN	12.60			OK
6	COVER BMPR R (EXHAUST)	57731SG060	14.40			OK
SUB TOTAL			567.00	0.00	0.00	0.00
LESS DISCOUNT ( NETT-20 %)			113.40	0.00	0.00	0.00
GRAND TOTAL			453.60	0.00	0.00	0.00
OVERALL TOTAL			453.60			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLX6960X

---

NETT ITEM	567.00
LESS 20 %	-113.40
NETT AMOUNT	453.60

LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00

SPECIAL NETT AMOUNT	0.00
---------------------	------

S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00

TOTAL LABOUR CHARGES	2060.00
TOTAL SPARE PARTS CHARGES	453.60

---

TOTAL CHARGES	2513.60
ADD 7 % GST	175.95

---

GRAND TOTAL	2689.55
-------------	---------

---



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18011602/T1tbe2	
ACCIDENT CLAIM SECTION(SINGAPORE POLICE FORCE)1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333		Date : 28-08-2018	
ATTN : ABDUL RAHMAN		Code : SPF	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	QX 532D	Veh. Inspected	SLX 6960X
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/080	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	26/06/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	SUBARU FORESTER	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JF1SJ5KC5JG106703	Colour	BLACK
Odometer	7255	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	225/60 R17	YOKOHAMA	6 mm
L/H Front Tyre	225/60 R17	YOKOHAMA	6 mm
R/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm
L/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	18/06/2018	Inspection Date	04/07/2018
Survey held at	25 LENG KEE ROAD		
Repairer	MOTOR IMAGE ENTERPRISES PTE LTD		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 6960X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BUMPER FACE REAR FORESTER IL (N)	DEFORMED	540.00	540.00
1	BRKT SD R RH (N)	NOT NECESSARY	14.40	-
1	BRKT SD R LH (N)	NOT NECESSARY	14.40	-
1	BEAM COMPL R EU (N)	NOT NECESSARY	288.00	-
1	COVER BMPR R (EXHAUST) (N)	CUT	14.40	14.40
1	COVER HOOK R (N)	CUT	12.60	12.60
	LESS 20% DISCOUNT		-176.76	-113.40
			707.04	453.60
<b>SPECIAL NETT ITEMS</b>				
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			50.00	20.00
<b>LABOUR</b>				
	TO SUPPLY AND REPLACE REAR BUMPER ASSY AND REAR EXHAUST COVER.		1,680.00	560.00
	TO RESPRAY REAR BUMPER ASSY.		880.00	440.00
	TO REMOVE AND CHECK REVERSE SENSOR CONDITION.		60.00	40.00
	TO REPAIR REAR END PANEL. (ADDITIONAL)		560.00	560.00
	TO RESPRAY END PANEL. (ADDITIONAL)		440.00	440.00
			3,620.00	2,040.00
<b>GRAND TOTAL</b>			<b>4,377.04</b>	<b>2,513.60</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,513.60</b>

Report Ref No. CS/SPF18011602/T1tbe2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,500

RECOMMENDED REPAIR DAYS : 3  
WEEKEND : 1  
TOTAL DAYS : 4

MOHAMAD TAUFIKH  
M.MATAI, AMSAE-A  
Automotive Assessor

ADRIAN LING WAI PING  
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI  
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.