

1952/10

INS. CASE OWNER

Jas

CC 4 ASM 1623, T1263

LKK:

IDAC:

Surveyor:

Taufik

DOI:

ASSIGNMENT

27/6/18

Date / Time:

26/6/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SDY 8382R

Name of Insured:

SON BOH POCK

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

23/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

PRAM CHIN BOO

Driver Tel No.:

(V/L YES / NO)

Claim No.:

S8M0U6761 53714

Policy No.:

P1984595

Make / Model:

TOYOTA

Place of Accident:

TE

OI GIA REPORT YES / NO : TP GIA REPORT YES / NO

Insured Liability:

%

Final ? Yes / No

SLM 27465

SEN 7524B

SDY 8382R

SLR 5487C



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

01

SLR 9587C
VERMOGEN
TP

Date/Time:

27/6/18
Ahner

SLR 5487C - X

SDY 8382R - X

Stamato/aim.

27.6.18 @ 8.23am

CALLED OO (CONFIRMED) ACCIDENT. DID INVOLVED IN 5 VEH (C O/D)
RIP THE 2ND VEH. INFORM TP CLAIM AGREE TO SETTLE
AND AWARE ABOUT NCD ISSUE.
Email WSP LIABILITY CLAIM.

RECEIVED 16 OCT 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: Email 5.7.18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

45 SS3,900

(5 days) Reduction:

73 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time: 01.10.18

Confirm with: ETEL

Email ☒ Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.: 28

If NO or B 28, Ass. Lia: 0%

Repair Cost:

w/651

SS 4,173.00

5 VEH (C O/D AND)

Loss of Rental (LOR):

SS -

(days)

Loss of Use (LOU):

SS 250.00

(S50 x 5 days)

Loss of Income (LOI):

SS -

(S x days)

LOR only ☐LOU only ☒LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

4350

Total:

SS 4,425.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 01.10.18

Confirm with: ETEL

Email ☒ Call ☐

Payee 1:

SS 4,425.00

Name 1: VERMOGEN ACE PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

REF: ASM(XA)

ASSIGNMENT

From:

Date:

26062018

Estimated Cost:

OD TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLR 9587C

at Workshop m/s

Vermogen

of

6 Benoi Sector

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

476K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLR 9587C

Yr Regn:

2017 Aug.

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Axio

C.C.

1446

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

3655

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NIKE 1657137402

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size:

F:

175/65R15

R:

77

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

27/6/18 01050

Survey held at

Vermogen

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

45:43.900 (RED: 10,353.10 73%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp. (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18011623/T1eb3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 26-06-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDY 8382R	Veh. Inspected	SLR 5987C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	26/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	23/06/2018	Inspection Date		
Survey held at	VERMOGEN ACE PTE LTD 1 BUKIT BATOK CRESCENT #04-54/55 WCEGA PLAZA SINGAPORE 658064			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



SLR9587C

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 23/6/2018

Vehicle Reg. No. : SLR9587C
Vehicle Reg. Date: 31-Aug-2017
Make / Model : T. AXIO HYBRID 1.5G A
Engine No. : 1NZR435714
Chassis No. : NKE1657137902

COST OF CLAIMS

Parts Cost / List Items :	\$ 12,190.80
Plus/Less 25%	\$ 3,047.70
Total Cost / List :	\$ 9,143.10
Special Nett Items :	\$ 510.00
Total Parts Amount :	\$ 9,653.10
Total Labour Amount :	\$ 4,600.00
Gross Total :	\$ 14,253.10
GST % : 7%	\$ 997.72
Nett Amount :	\$ 15,250.82

Surveyor Name and Company :

Tan Jiah 97445749
Date of survey : 27/6/18 @ 1050

Part by Part / Lump Sum : 5 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : sur@lkkauto.com

Fax No :

HP No :

This claim is handled by : PAULO BALDOZ

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLR9587C
 Vehicle Reg. Date: 31/8/2017
 Make / Model : T. AXIO HYBRID 1.5G A
 Engine No. : 1NZR435714
 Chassis No. : NKE1657137902

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear boot	bt ✓	\$1,093.00		
2	1	Rear boot insulator paste	x } XNN	\$298.60		
3	1 set	Rear boot insulator clip - set	x } XNN	\$50.00		
4	2	Rear boot hinge	Rx	\$197.50		
5	1	Rear boot lock	Rx	\$185.20		
6	1	Rear boot lock catch	x NNN	\$49.10		
7	1	Rear boot lock sensor	2 DT	\$274.80		
8	1	Rear boot cable	x } XNN	\$49.10		
9	1	Rear boot chrome garnish	x } XNN	\$312.40		
10	1 set	Rear boot chrome garnish clip - set	x }	\$30.00		
11	1	Rear boot weatherstrip	wt ✓	\$211.60		
12	1	Rear boot emblem - Logo	wt ✓	\$59.90		
13	1	Rear boot emblem - Hybrid	wt ✓	\$75.00		
14	1	Rear boot emblem - Corolla	wt ✓	\$66.80		
15	1	Rear boot emblem - Axio	wt ✓	\$68.50		
16	2	Rear number plate lamp LH/RH	x NNN	\$157.00		
17	1	Rear bumper	dt ✓	\$780.20	700	
18	2	Rear bumper reflector LH/RH	x NNN	\$184.80		
19	2	Rear bumper side retainer LH/RH	wt ✓	\$177.60	118	
20	1 set	Rear bumper clip - set	wt ✓	\$64.00		
21	2	Taillamp LH/RH	LH-104 ✓, RH-104	\$1,189.20	900	
22	2	Taillamp panel LH/RH	Rx	\$511.40		
23	1 set	Taillamp clip - set	wt ✓	\$30.00		
24	2	Taillamp lower bracket LH/RH	200	\$165.20		
25	1	Rear end panel	Rx	\$662.10		
26	1	Rear end panel top garnish	Rx	\$240.90		
27	1 set	Rear end panel top garnish clip	x wt ✓	\$40.00		
28	2	Rear impact bracket LH/RH	Rx	\$174.00		
29	1	Spare tyre panel	x }	\$737.70		
30	1	Spare tyre board	x }	\$441.30		
31	1	Spare tyre tools sponge	x }	\$265.90		
32	1	Spare tyre tools clips	x }	\$9.50		
33	2	Rear fender LH/RH	x } XNN	\$1,669.20		
34	2	Rear fender side board LH/RH	x }	\$687.20		
35	2	Rear fender inner shield LH/RH	x }	\$187.00		
36	1	Exhaust silencer	x }	\$693.10		
37	1	Rear windscreen glass moulding	x }	\$108.00		
38	1	Rear number plate with frame	x }		\$ 50.00	
39	1	Taillamp seal	x }		\$ 80.00	
40	1	Rear end panel sealant	x }		\$ 80.00	

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLR9587C
 Vehicle Reg. Date: 31/8/2017
 Make / Model : T. AXIO HYBRID 1.5G A
 Engine No. : 1NZR435714
 Chassis No. : NKE1657137902

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Reverse sensor	<i>new</i>	<i>200</i>	\$ 300.00	
42	0	0				
43	0	0				
44	0	0				
45	0	0				
46	0	0				
47	0	0				
48	0	0				
49	0	0				
50	0	0				
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	Z				

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]



SLR9587C

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 23/6/2018

Vehicle Reg. No. : SLR9587C
Vehicle Reg. Date: 31-Aug-2017
Make / Model : T. AXIO HYBRID 1.5G A
Engine No. : 1NZR435714
Chassis No. : NKE1657137902

COST OF CLAIMS

Parts Cost / List Items :	\$	12,190.80
Plus/Less <u>25%</u>	\$	3,047.70
Total Cost / List :	\$	9,143.10
Special Nett Items :	\$	510.00
Total Parts Amount :	\$	9,653.10
Total Labour Amount :	\$	4,600.00
Gross Total :	\$	14,253.10
GST % : <u>7%</u>	\$	997.72
Nett Amount :	\$	15,250.82

Surveyor Name and Company :

Tanjun 97445749
Date of survey : 27/6/18 @ 1050
Part by Part / Lump Sum : 5 days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : sur@lkhauto.com
Fax No : _____
HP No : _____

This claim is handled by : PAULO BALDOZ

15-4100

P= 4500.70
-25%
3375.53
S= 200
L= 1600
5175.53
-20%
4140.42

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLR9587C**

Vehicle Reg. Date: **31/8/2017**

Make / Model : **T. AXIO HYBRID 1.5G A**

Engine No. : **1NZR435714**

Chassis No. : **NKE1657137902**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear boot	bt ✓	\$1,093.00		
2	1	Rear boot insulator paste	X	\$298.60		
3	1 set	Rear boot Insulator clip - set	X	\$50.00		
4	2	Rear boot hinge	Rx	\$197.50		
5	1	Rear boot lock	Rx	\$185.20		
6	1	Rear boot lock catch	Y	\$49.10		
7	1	Rear boot lock sensor	?	\$274.80	* ✓	
8	1	Rear boot cable	X	\$49.10		
9	1	Rear boot chrome garnish	Y	\$312.40		
10	1 set	Rear boot chrome garnish clip - set	X	\$30.00		
11	1	Rear boot weatherstrip	wt ✓	\$211.60		
12	1	Rear boot emblem - Logo	wt ✓	\$59.90		
13	1	Rear boot emblem - Hybrid	wt ✓	\$75.00		
14	1	Rear boot emblem - Corrolla	wt ✓	\$66.80		
15	1	Rear boot emblem - Axio	wt ✓	\$68.50		
16	2	Rear number plate lamp LH/RH	X	\$157.00		
17	1	Rear bumper	RL ✓	\$780.20		
18	2	Rear bumper reflector LH/RH	X	\$184.80		
19	2	Rear bumper side retainer LH/RH	wt ✓	\$171.60		
20	1 set	Rear bumper clip - set	wt ✓	\$64.00		
21	2	Taillamp LH/RH	LH-104 / RH-1	\$1,189.20	* ✓	
22	2	Taillamp panel LH/RH	Rx	\$511.40		
23	1 set	Taillamp clip - set	wt ✓	\$30.00		
24	2	Taillamp lower bracket LH/RH	?	\$165.20	* ✓	
25	1	Rear end panel	Rx	\$662.10		
26	1	Rear end panel top garnish	Rx wt ✓	\$240.90		
27	1 set	Rear end panel top garnish clip	Rx wt ✓	\$40.00		
28	2	Rear impact bracket LH/RH	X	\$174.00		
29	1	Spare tyre panel	X	\$737.70		
30	1	Spare tyre board	X	\$441.30		
31	1	Spare tyre tools sponge	X	\$265.90		
32	1	Spare tyre tools clips	X	\$9.50		
33	2	Rear fender LH/RH	X	\$1,669.20		
34	2	Rear fender side board LH/RH	X	\$687.20		
35	2	Rear fender inner shield LH/RH	X	\$187.00		
36	1	Exhaust silencer	Y	\$693.10		
37	1	Rear windscreen glass moulding	X	\$108.00		
38	1	Rear number plate with frame	X		\$ 50.00	
39	1	Taillamp seal	X		\$ 80.00	
40	1	Rear end panel sealant	X		\$ 80.00	

P = 4500.70

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLR9587C**

Vehicle Reg. Date: **31/8/2017**

Make / Model : **T. AXIO HYBRID 1.5G A**

Engine No. : **1NZR435714**

Chassis No. : **NKE1657137902**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Reverse sensor	<i>new</i>	<i>200</i>	<i>\$ 300.00</i>	
42	0	0				
43	0	0				
44	0	0				
45	0	0				
46	0	0				
47	0	0				
48	0	0				
49	0	0				
50	0	0				
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	Z				

SN = 200

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]
$$L = 1600$$



Service Request Details

Claim

S8M00LZ6

Reference

None 

Loss Date

June 23, 2018

Request Date

June 26, 2018

Due Date

July 3, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

26062018 @ 955am
Pila veh in.
TauAlkh.

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLR9587C

Make

TPVD TOYOTA

Model

AXIO HYBRID

Service Address

...

Primary Contact/Insured

SOH POH HOCK

BLK 411A FERNVALE ROAD, #22-76, 791411, Singapore
91893288

Claim Handler

TAN Jas

6568804844

jas.tan@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TO:

Dear Sirs,

CLAIMANT:

ACCIDENT INVOLVING SLR9857C, SDY8382R, SKN7534B, SLM2341S and SLL7841M
on


23/6/2018 At 1205HRS

I/WE LCRF PTE LTD, am/are the registered Owner of Vehicle No. SLR9857C

Please note that I have assigned all compensation monies due -to me/us in the above said accident to **Vermogen ACE Pte Ltd**.

I/We, hereby authorize you to release all compensation monies pertaining to the above said accident to **Vermogen ACE Pte Ltd** and forward your settlement cheque to **Vermogen ACE Pte Ltd** whom I/we had authorized to collect the said compensation monies.

Thankyou.



Signature of Claimant
(company Stamp, if applicable)

Name : _____
NRIC No. : _____
Date : _____

JAS

« MANDATE REQUEST FOR S8M00LZ6

Type

🔔 Question

Message

Liability: 5 Vehicle chain collusion and Insured was the 2nd vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$4,173.00 (w/GST) Loss of Use: \$800.00 (8days x \$100) GIA search fee: \$2.00 Total: \$4,975.00 Immediate Advice with Mandate and marked estimate uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (14/09/2018)

[Reply](#)



Re:MANDATE REQUEST FOR S8M00LZ6

Type

🔗 Question

Message

hi, please offer 5 days @\$50 / day.

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SDY 8382R (Insd veh)	Model:	TOYOTA
	SLR 9587C (TP veh)		COROLLA AXIO HYBRID
Date of Accident:	23/06/2018		1.5G A

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	15,250.82
Final Repair Cost	:	\$	4,173.00
Loss of Use	:	\$	250.00
Rental (if any)	:	\$	
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	4,425.00

Is Third Party Workshop GIA Registered?		☐ YES	☒ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: ____		
BOLA Liability: ____ (%)		Assessed Liability (*): ____ 0 ____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks				

Payment Instruction: Payee's Breakdown		
1)	VERMOGEN ACE PTE LTD	4,425.00

NUR SHAQILAH BTE ABDOL
WAHAB

01/11/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18011623/T1eb3s2	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 01-11-2018	
ATTN: JAS TAN		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SDY 8382R	Veh. Inspected	SLR 9587C
Policy No.	P1984595	Coverage (\$)	0.00
Claim No.	S8M00LZ6	Excess (\$)	0.00
Assign From	JAS TAN	Assign Date	26/06/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA AXIO	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	NKE1657137902	Colour	BLACK
Odometer	36853	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/65R15	TOYO	6 mm
L/H Front Tyre	175/65R15	TOYO	6 mm
R/H Rear Tyre	175/65R15	TOYO	6 mm
L/H Rear Tyre	175/65R15	TOYO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/06/2018	Inspection Date	27/06/2018
Survey held at	VERMOGEN ACE PTE LTD 1 BUKIT BATOK CRESCENT #04-54/55 WCEGA PLAZA SINGAPORE 658064		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 9587C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT (CONSISTENT)	BENT	1,093.00	1,093.00
1	REAR BOOT INSULATOR PASTE (CONSISTENT)	NOT NECESSARY	298.60	-
1	SET REAR BOOT INSULATOR CLIP (CONSISTENT)	NOT NECESSARY	50.00	-
2	REAR BOOT HINGE (CONSISTENT)	TO REPAIR SEE LABOUR	197.50	-
1	REAR BOOT LOCK (CONSISTENT)	TO REPAIR SEE LABOUR	185.20	-
1	REAR BOOT LOCK CATCH (CONSISTENT)	NOT NECESSARY	49.10	-
1	REAR BOOT LOCK SENSOR (CONSISTENT)	DENTED	274.80	274.80
1	REAR BOOT CABLE (CONSISTENT)	NOT NECESSARY	49.10	-
1	REAR BOOT CHROME GARNISH (CONSISTENT)	NOT NECESSARY	312.40	-
1	SET REAR BOOT CHROME GARNISH CLIP (CONSISTENT)	NOT NECESSARY	30.00	-
1	REAR BOOT WEATHERSTRIP (CONSISTENT)	CUT	211.60	211.60
1	REAR BOOT EMBLEM - LOGO (CONSISTENT)	NECESSARY	59.90	59.90
1	REAR BOOT EMBLEM - HYBRID (CONSISTENT)	NECESSARY	75.00	75.00
1	REAR BOOT EMBLEM - COROLLA (CONSISTENT)	NECESSARY	66.80	66.80
1	REAR BOOT EMBLEM - AXIO (CONSISTENT)	NECESSARY	68.50	68.50
2	REAR NUMBER PLATE LAMP LH/RH (CONSISTENT)	NOT NECESSARY	157.00	-
1	REAR BUMPER (CONSISTENT)	DEFORMED	780.20	700.00
2	REAR BUMPER REFLECTOR LH/RH (CONSISTENT)	NOT NECESSARY	184.80	-
2	REAR BUMPER SIDE RETAINER LH/RH (CONSISTENT)	NECESSARY	171.60	118.00
1	SET REAR BUMPER CLIP (CONSISTENT)	NECESSARY	64.00	64.00
2	TAILLAMP LH/RH (CONSISTENT)	CRACKED	1,189.20	900.00
2	TAILLAMP PANEL LH/RH (CONSISTENT)	TO REPAIR SEE LABOUR	511.40	-
1	SET TAILLAMP CLIP (CONSISTENT)	NECESSARY	30.00	30.00
2	TAILLAMP LOWER BRACKET LH/RH (CONSISTENT)	CRACKED	165.20	165.20
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	662.10	-
1	REAR END PANEL TOP GARNISH (CONSISTENT)	DEFORMED	240.90	240.90
1	SET REAR END PANEL TOP GARNISH CLIP (CONSISTENT)	NECESSARY	40.00	40.00

Report Ref No. CC4/ASM18011623/T1eb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR IMPACT BRACKET LH/RH (CONSISTENT)	NOT NECESSARY	174.00	-
1	SPARE TYRE PANEL (CONSISTENT)	NOT NECESSARY	737.70	-
1	SPARE TYRE BOARD (CONSISTENT)	NOT NECESSARY	441.30	-
1	SPARE TYRE TOOLS SPONGE (CONSISTENT)	NOT NECESSARY	265.90	-
1	SPARE TYRE TOOLS CLIPS (CONSISTENT)	NOT NECESSARY	9.50	-
2	REAR FENDER LH/RH (CONSISTENT)	NOT NECESSARY	1,669.20	-
2	REAR FENDER SIDE BOARD LH/RH (CONSISTENT)	NOT NECESSARY	687.20	-
2	REAR FENDER INNER SHIELD LH/RH (CONSISTENT)	NOT NECESSARY	187.00	-
1	EXHAUST SILENCER (CONSISTENT)	NOT NECESSARY	693.10	-
1	REAR WINDSCREEN GLASS MOULDING (CONSISTENT)	NOT NECESSARY	108.00	-
	LESS 25% DISCOUNT		-3,047.70	-1,026.92
			9,143.10	3,080.78
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE WITH FRAME (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	TAILLAMP SEAL (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REVERSE SENSOR (SN) (CONSISTENT)	NOT WORKING	300.00	200.00
			510.00	200.00
	<u>LABOUR</u>			
	TO STRAIGHTEN AND PANEL BEATING ACCIDENT AREA. REAR PORTION, BOOTLID, REAR BUMPER, REAR END PANEL, SPARE TYRE PANEL, TAIL LAMP PANEL LH/RH, REAR FENDER LH/RH. INCLUSIVE OF THE REPAIR OF REAR BOOT HINGE, REAR BOOT LOCK, TAILLAMP PANEL LH/RH AND REAR END PANEL.		1,800.00	700.00
	TO REMOVE AND REFIT INTERIOR TRIMS, SEATS AND UPHOLSTERY.		250.00	50.00
	TO REMOVE AND TRANSFER BOOTLID COMPONENTS.		150.00	60.00
	TO REMOVE AND REPLACE REVERSE SENSOR.		150.00	30.00
	TO REMOVE AND REFIT EXHAUST PIPE AND RE-ALIGN.	NOT NECESSARY	200.00	-
	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND RECONNECT.		100.00	30.00
	TO RUST PROOF AFFECTED AREAS.		150.00	30.00

Report Ref No. CC4/ASM18011623/T1eb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY, RESPRAY PAINTING AND POLISH AFFECTED AREAS. BOOTLID, REAR BUMPER, REAR END PANEL, SPARE TYRE PANEL, TAIL LAMP PANEL LH/RH, REAR FENDER LH/RH.		1,800.00	700.00
			4,600.00	1,600.00
GRAND TOTAL			14,253.10	4,880.78
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,900.00

Report Ref No. CC4/ASM18011623/T1eb3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.