



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2004303
INV Date 04/06/2020
Reference CC6/EQI18011627/Aea3q2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. SJL 3144S
Insured Veh. SJP 712B
Claim No. DM18HO01416/JT
Policy No. DMPPHQ18-001203
Accident Date 02/06/2018
Inspection Date 25/06/2018

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC6/EQI18011627/Aea3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 04-06-2020		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJP 712B	Veh. Inspected	SJL 3144S
	Policy No.	DMPPHQ18-001203	Coverage (\$)	0.00
	Claim No.	DM18HO01416/JT	Excess (\$)	0.00
	Assign From		Assign Date	25/06/2018
2. Vehicle Particulars & Condition				
	Make & Model	HONDA CITY	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	MRHGM26709P020126	Colour	GREY
	Odometer	189710	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/65 R15	GOODRIDE	6 mm
	L/H Front Tyre	185/65 R15	GOODRIDE	6 mm
	R/H Rear Tyre	185/65 R15	GOODRIDE	6 mm
	L/H Rear Tyre	185/65 R15	GOODRIDE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/06/2018	Inspection Date	25/06/2018
	Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 3144S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	611.20	463.70
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	62.40	32.00
1	TAILLAMP	NOT NECESSARY	422.30	-
1	TAILLAMP LOWER BRACKET	NOT NECESSARY	62.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	912.20	-
1	REAR FENDER COWLING	NOT NECESSARY	369.20	-
1	REAR FENDER AIR VENT RH	NOT NECESSARY	90.20	-
	LESS 20% DISCOUNT		-505.90	-99.14
			2,023.60	396.56
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	25.00	25.00
1	SET TAIL LAMP CLIP (SN)	NOT NECESSARY	25.00	-
1	SET REAR FENDER COWLING CLIP (SN)	NOT NECESSARY	25.00	-
1	REVERSE SENSOR (SN)	NOT NECESSARY	220.00	-
			295.00	25.00
	<u>LABOUR</u>			
	PANEL BEATING ,REMOVING AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER RH .		1,400.00	200.00
	SPRAY PAINTING TO AFFECTED AREA.		1,200.00	400.00
	TUFF COAT.	NOT NECESSARY	250.00	-
	WIRING CHECK .		180.00	30.00
	TO REMOVE AND REFIX REVERSE SENSOR .		150.00	50.00
	DISTANCE SETTING FOR REVERSE SENSOR .	NOT NECESSARY	80.00	-
			-	-
			-	-
			-	-
			3,260.00	680.00
	GRAND TOTAL		5,578.60	1,101.56

Report Ref No. CC6/EQI18011627/Aea3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			850.00
---	--	--	--------

Report Ref No. CC6/EQ118011627/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJL 3144S

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

