

ASS. REC. BY:

REF: 18/CT18011641/Kcbn2

Special Instruction:

Surveyor: Kenneth ASSIGNMENT (Office)

From (Person): Sharon Han of CTL Date/Time: 26062018 3:15pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: G8D 8157J Insured: GBH 1479E

at Workshop m/s Cheng Hoe Motor Tel: 6755 6142

of Blk 1019 Yishun Ind Park A #01-374

Policy No: DM VCSN1804041800 Claim No: SNM18D0302400

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 16062018
(Client's Record)

CA / REV / REP. / REV 24 HRS wpi Blk 10 Amk Ind Park A #01-04
H.O.D. Endorsement: _____

Date/Time: 26062018 4:30pm Person Contacted: June Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>G8D 8157J - X</u>
	<u>GBH 1479E - X</u>

ASS. REC. BY:

REF: C721

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop mv's Chery Iloc

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 08 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBD 8157J Yr Regn: 05, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS Cabstar cc 2953

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading 114935 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNISC2F2480856821

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: Quation 195 R15 X8

R: Kaplan 165 R13 X8

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 9 9 mm

L/Bal. 5 mm

L/Bal. 9 9 mm

D.O.A. 16/6/18

D.O.I. 26/6/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

& R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/6 File pass to Catherine

10/6 U/L by 858501 confirm E Rep. (Red. 30911, 38%) (cost price)

RECEIVED 11 JAN 2019

Date/Time, File Pass to? : Prell. Report : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 8
Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:	
Transportation:	
S - RS - SI	
Fuel/Oil	
Others	
TOTAL	220

Report Format: TP
Lump Sum / I.B.I: (\$ 58501)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Jun 2018 Sandback Est	26 Jun 2018 11:18 S\$9,441.00	26 Jun 2018 15:15 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	GA CONSTRUCTION PTE LTD, Co. Reg. No.: 198903443C								
Main Claimant:	GA CONSTRUCTION PTE LTD, Co. Reg. No.: 198903443C								
Vehicle Reg. No.:	GBD8157J	Date of Loss:	16/06/2018 14:00 - :59 [36 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03024C02	Policy/Cover Note No.:	DMVCSN1804041800						
Vehicle Reg. No. (Insured):	GBH1479E	Policy No. (Claimant):	DMCVSN3037021801						
		Excess:	S\$0.00						
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]								
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/07/2018]								
Driver/Custodian (Insured):	PANG SOON FOOK (61 / Male), NRIC: S1278401E, Tel: +6598239955								
Adj Asg. Remarks:	EST \$10,101.87, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
<input type="checkbox"/> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3443C
Vehicle Details	
Vehicle No.:	GBD8157J
Vehicle to be Exported:	No
Intended De-registration Date:	19 Jun 2018
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Primary Colour:	Blue
Manufacturing Year:	2014
Engine No.:	ZD30344295K
Chassis No.:	JN15C2F24Z0856821
Maximum Power Output:	-
Open Market Value:	\$25,287.00
Original Registration Date:	26 May 2015
First Registration Date:	26 May 2015
Transfer Count:	0
Actual ARF Paid:	\$1,265.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 May 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$59,999.00
COE Rebate Amount:	\$41,596.00
Total Rebate Amount:	\$41,596.00

The information contained herein is correct as at 19 Jun 2018

OK



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
GA CONSTRUCTION PTE LTD

Singapore

Claimant Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

PARTICULARS OF CLAIM			
Claim Type:	Third Party	Ref. No:	TP/CHINA
Policy No:		Date of Loss:	16/06/2018
Vehicle Reg. No.:	GBD8157J	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	PANG SOON FOOK	Driver (Insured):	PANG SOON FOOK
Make/Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Vehicle Reg. Date:	26/05/2015
Vehicle Colour:	Blue		
Engine No:	ZD30344295K	Chassis No:	JN1SC2F24Z0856821
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO NOTICE OF REPORTING (FILED AT HONG KAH NORTH NPP). I STOP BEHIND OF GBB5993S, HOWEVER MOTOR LORRY GBH1479E DID NOT STOP IN TIME AND HIT ONTO MY LORRY REAR PORTION. THE IMPACT PUSH FORWARD MY LORRY TO HIT ONTO THE REAR OF GBB5993S. NO ONE WAS INJURED.		
Remarks:	VEHICLE SEND IN TO ANG MO KIO WORKSHOP ON 25/06/2018 @ 0900.		
Present Location:	CHENG HOE MOTOR PTE LTD (AMK)		

*Not Authorized
1/1 Imp @ 7
Today, Repair After Rain*

COST OF CLAIMS	Amount
Parts	4,826.00
Miscellaneous Items	1,185.00
Labour	3,430.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	9,441.00
+ GST 7.00% (\$)	660.87
Nett Amount (\$)	10,101.87

This claim is handled by: DORLYN LI YAZHU

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 26 Jun 2018)
Parts: N/A NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Cheng Hoe Motor Pte Ltd/GBD8157J/26/06/2018 11:18
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*1 pc front bumper	<i>Dell</i>	0.00	0.00	*550.00 F ✓
2	1		*1 pc front grille	<i>Dell</i>	0.00	0.00	*280.00 F ✓
3	1		*1 pc front grille logo	<i>Mc</i>	0.00	0.00	*55.00 F ✓
4	1		*6 pcs front grille clips @ \$3.50/pc	<i>Mc</i>	0.00	0.00	*21.00 F ✓
5	1		*1 pc front panel	<i>Bj</i>	0.00	0.00	*700.00 F ✓
6	1		*1 pc front panel emblem CABSTAR	<i>Mc</i>	0.00	0.00	*40.00 F ✓
7	1		*2 pcs headlamps @ \$300/pc	<i>CM</i>	0.00	0.00	*600.00 F ✓
8	1		*1 set front windscreen glass moulding	<i>Mc</i>	0.00	0.00	*300.00 F ✓
9	1		*1 pc aircon blower assy	<i>Mc</i>	0.00	0.00	*450.00 F X
10	1		*1 pc aircon evaporator assy	<i>Mc</i>	0.00	0.00	*950.00 F X
11	1		*1 pc rear tailgate	<i>Bj</i>	0.00	0.00	*700.00 F ✓
12	1		*1 pc rear tailgate sticker CABSTAR	<i>Mc</i>	0.00	0.00	*45.00 F ✓
13	1		*1 pc rear LH taillamp assy	<i>CM</i>	0.00	0.00	*85.00 F ✓
14	1		*1 pc rear LH taillamp panel	<i>Mc</i>	0.00	0.00	*50.00 F X

F=Franchise part.

Total Parts (S\$)

4,826.00

Cheng Hoe Motor Pte Ltd/GBD8157J/26/06/2018 11:18. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount	
Miscellaneous Items				
1	1	1 pc ERP bracket	25.00	X ✓
2	1	1 pc front number plate	25.00	X ✓
3	1	1 pc rear number plate	25.00	✓
4	1	1 pc rear safety bar	450.00	✓
5	1	1 pc tailgate aluminium plating	380.00	350 ✓
6	1	1 set reverse sensor	200.00	✓
7	1	1 unit front windscreen glass sealant	40.00	✓
8	1	2 pcs tailgate stickers @ \$20/pc	40.00	✓
Sub Total (S\$)			1,185.00	

Estimates on Labour

No	Particulars	Lab.Type	Amount	
Labour Items				
1	Remove & refix front windscreen glass	New	100.00	✓
2	Remove & refix aircon condenser,check,vacuum & refill gas	New	100.00	✓
3	Remove & refix dashboard assy to facilitate repair	New	250.00	✓
4	Remove & refix front bumper,grille,headlamps;to cut,weld & renew front panel;knocking & repair front wiper panel & realign the same	New	750.00	650 ✓
5	Putty & respray front panel,grille,front wiper panel,cornal panel & all affected areas	New	700.00	550 ✓
6	Remove & refix tailgate,LH taillamp,LH taillamp panel;knocking & repair rear lower panel & realign the same	New	800.00	650 ✓
7	Putty & respray tailgate,rear lower panel,taillamp panels & all affected areas	New	700.00	500 ✓
8	Rustproofing	New	30.00	✓
Gross Labour Cost (S\$)			3,430.00	

Cheng Hoe Motor Pte Ltd/GBD8157J/26/06/2018 11:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18011641/KCBN2

Date: 14/01/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMVCSN1804041800
Claimant Vehicle No :	GBD8157J	Insured Vehicle No :	GBH1479E
Date of Loss:	16/06/2018	Nature of Claim:	TP
		Claim No:	SNM18D03024C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD8157J	Engine No:	ZD30344295K
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Chassis No:	JN1SC2F24Z0856821
Reg. Date:	26/05/2015 (Man. Year: 2014)	Odometer:	114935 km
Colour:	Blue		
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195R15X8	Rear Tyre Size:	165R13X8 (D)
Front Left Side:	OVATION 5 mm	Rear Left Side:	KAPSEN 9/9 mm
Front Right Side:	OVATION 5 mm	Rear Right Side:	KAPSEN 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,826.00	3,376.00	1,450.00	30.05
Miscellaneous Items	1,185.00	1,105.00	80.00	6.75
Labour	3,430.00	2,830.00	600.00	17.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,441.00	7,311.00	2,130.00	22.56
Approved Total (Overridden) (S\$)		5,850.00		
	(S\$) 9,441.00	5,850.00	3,591.00	38.04
+ GST 7.00/7.00% (S\$)	660.87	409.50	251.37	38.04
Nett Amount (S\$)	10,101.87	6,259.50	3,842.37	38.04

INSPECTION

Date of Assignment:	26/06/2018	
Date Inspected:	26/06/2018 Inspected At:	Blk 10 AMK Ind Park 2A #01-04 Repairer:Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	8.0 days	

Adjuster: KENNETH KONG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 14 Jan 2019)	
Parts:	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD8157J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 pc front bumper	Dented/Cut	550.00 F	*550.00 F
2	1		*1 pc front grille	Dented	280.00 F	*280.00 F
3	1		*1 pc front grille logo	Necessary	55.00 F	*55.00 F
4	1		*6 pcs front grille clips @ \$3.50/pc	Necessary	21.00 F	*21.00 F
5	1		*1 pc front panel	Bent	700.00 F	*700.00 F
6	1		*1 pc front panel emblem CABSTAR	Necessary	40.00 F	*40.00 F
7	1		*2 pcs headlamps @ \$300/pc	Cracked	600.00 F	*600.00 F
8	1		*1 set front windscreen glass moulding	Necessary	300.00 F	*300.00 F
9	1		*1 pc aircon blower assy	Serviceable	450.00 F	*- F
10	1		*1 pc aircon evaporator assy	Serviceable	950.00 F	*- F
11	1		*1 pc rear tailgate	Bent	700.00 F	*700.00 F
12	1		*1 pc rear tailgate sticker CABSTAR	Necessary	45.00 F	*45.00 F
13	1		*1 pc rear LH taillamp assy	Cracked	85.00 F	*85.00 F
14	1		*1 pc rear LH taillamp panel	Repair	50.00 F	*- F
Total Parts (S\$)					4,826.00	3,376.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 pc ERP bracket (Not Necessary)	25.00	0.00
2	1	1 pc front number plate (Serviceable)	25.00	0.00
3	1	1 pc rear number plate (Dented)	25.00	25.00
4	1	1 pc rear safety bar (Bent)	450.00	450.00
5	1	1 pc tailgate aluminium plating (Necessary)	380.00	350.00
6	1	1 set reverse sensor (Cracked)	200.00	200.00
7	1	1 unit front windscreen glass sealant (Necessary)	40.00	40.00
8	1	2 pcs tailgate stickers @ \$20/pc (Necessary)	40.00	40.00
Sub Total (S\$)			1,185.00	1,105.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Remove & refix front windscreen glass	New	100.00	100.00
2	Remove & refix aircon condenser,check,vacuum & refill gas	New	100.00	100.00
3	Remove & refix dashboard assy to facilitate repair	New	250.00	250.00
4	Remove & refix front bumper,grille,headlamps;to cut,weld & renew front panel;knocking & repair front wiper panel & realign the same	New	750.00	650.00
5	Putty & respray front panel,grille,front wiper panel,cornal panel & all affected areas	New	700.00	550.00
6	Remove & refix tailgate,LH taillamp,LH taillamp panel;knocking & repair rear lower panel & realign the same	New	800.00	650.00
7	Putty & respray tailgate,rear lower panel,taillamp panels & all affected areas	New	700.00	500.00
8	Rustproofing	New	30.00	30.00
Gross Labour Cost (S\$)			3,430.00	2,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >