

22/07/2017

ASS. REC. BY:

REF:

CS3/A26170043K4 / K156-1

Special Instruction:

Surveyor:

kalvin

ASSIGNMENT (Office)

mermon

From (Person):

Salha

of

ACU

Date/Time:

26062018

Estimated Cost:

Bill to:

OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKK 6745 G

Insured:

SKR 269713

at Workshop m/s

Kent seng

Tel:

67588367

of

Blk 1017 #01-240 4thun incl Part A

Policy No:

2406 401110

Claim No:

85514418945G -003

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 11/3/2017

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time: 2/5/2017 2:42 pm

Person Contacted:

Kent seng

Vehicle IN / OUT

Date/Time

Action/Instruction (X -) Estimate

SKK 6745G - X

SKR 269713 - X

survey: 2/5/2017 ; dicman he: 3/3/2017 ; after repair: 6/5/2017

(\$ 6,485.00 Red - 52%)

02/07/18

Submit Paper Survey

HS \$ 5,800.00 / 4 days

RECEIVED 02 JUL 2018

(02/11/13)

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: 2/3/12

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKK 67456

at Workshop m/s Kent Seng

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKK 67456 Yr Regn: WAAG, 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW X3 XDRIVE c.c. 2993

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 77879 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAWY520500854166

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245 / 45 R19

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Conti

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. _____

D.O.I. 2/3/12 1556

Survey held at Kent Seng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

AZH 'PR'
No Est.

Date/Time, File Pass to?

1) 9/3/2017 - TYPH

Date/Time, File Return to?

2) _____

☐ : Preli. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

S + RS, SI

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I: (\$ _____)

Catherine Chong (LKK Auto)

From: Syed-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>
Sent: Tuesday, 26 June, 2018 10:17 AM
To: SUR; Mei Kwan (LKKAuto); Catherine Chong (LKK Auto)
Subject: AIG ref: 8551441894SG-003 II URGENT
Attachments: 8551441894SG.pdf

Importance: High

Dear Team,

Previously repairer had agreed to LKK being the SJE, however did not forward estimate during inspection.

Enclosed is the TP surveyor report for your adjustment and input on the COR please.

thank you,

PLEASE NOTE THAT CONTENTS OF THIS EMAIL SHOULD NOT BE CONSTRUED AS ANY ADMISSION OF LIABILITY ON THE PART OF OUR INSURED AND/OR INSURERS. WE HEREBY MAINTAIN FULL RESERVATION OF RIGHTS AND ALL DEFENCES AVAILABLE TO US

Saliha Syed Yusoff
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1917 | Fax +(65) 68357416

saliha.syed-yusoff@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient,

you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

MCHM17025050 / Chong Hui Motor Pte Ltd - Yishun
ENTRY DATE & TIME: 01/03/2017 14:50

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report promptly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/03/2017 14:50
Date Of Accident	01/03/2017 11:10
Exact Location Of Accident	ALONG CTE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKK6745G
Insured/Policyholder	
Name Of Registered Owner	NG HAN HOE
NRIC No	S1628988D
Email Address	kenny818181@gmail.com
Mobile Phone No	(LOCAL) +65-97498181
Alternative Phone No	Others-97498181

Vehicle Particulars

Manufacturer	BMW
Model	X3 XDRIVE30D ABS 4WD SR HID NAV
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car

Insurance Company

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5082812963
Cover Note Number	20/08/16 - 19/08/17

Driver

Name of Driver	TAN GEIK HUA
NRIC No	S1737090A
Date Of Birth	10/06/1966
Occupation	Indoor
Date Of Driving Pass	24/10/1991
Driving Experience	25 Years And 4 Months
Gender	Female
Mobile Number	(Local) +65-97836603
Fax Number	
Contact Number	
Email Address	3737chris@gmail.com

Address 420 MILTONIA CLOSE
 Postcode 768396
 Was driver an employee of the Insured's Company No
 If No, Relationship of the Driver with the Insured Spouse
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident Collision- Change/cross lane
 Weather Conditions DRIZZLING
 Road Surface DAMP

Other Information

Was any foreign vehicle involved in this accident? No
 Was any body injured in the Accident? No
 Was any other material or property damaged? Yes
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. Yes
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? No
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? No
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH ATTACHED. * THIRD PARTY CLAIM BY KENT SENG REPAIRER *

Attachment(s)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? Yes
 Remarks/ Reasons: FOOTAGE GIVEN TO REPAIR WORKSHOP
 Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKR2697B
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver PANG SEE HWEE
 NRIC/Passport Number
 Contact Number 98665800
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

Sketch Plan #2

Note: Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own policy. Please check your policy for more information.

() Claim Own Policy () Claim TP (X) Claim OD/TP at other workshop () Reporting Only
(By Kant Song repairer)

Describe Circumstances of the Accident

Sketch Plan

Along
CTE



A- SKK 6745G

B- SKK 2697B

Pang See Hwee

HP- 9666 3800

I was moving straight when out of sudden car B cut into my lane abruptly without warning thus causing its rear left collided with the front right of my car. No one was injured.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If Driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Person (YS)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

VEHICLE NO.: SKK 6745 GINSURER : HTUCDOA : 6/3/17 @ 11:13am

1. Please report correctly the details of the accident to speed up the claim process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers, of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' law firm/law-firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firm/law-firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law-firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (YS)

P.T.O.

FRONT PORTION

3 Rep'r Days

VEHICLE NO:

SKK 62456

LKK SUR:

Tel: 6256 3561

Fax: 6256 4315

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	Rehnd		1
1005	992341	Frt Bumper Clips	re		6
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	clerk		1 RH
1008	991433	Frt Bumper Reinforcement	clerk		1
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad	clerk		1
1013	991363	Frt Bumper Grille RH		3	
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor	clerk		1
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp	clerk		1
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding	clerk		2
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	clerk		1
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	CR		1
1030	991821	Frt RH Headlamp Assy	CR		1
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		Sealing cover LHM			1
		(1/4) Headlamp wiper cover 8			1
		no 3319			

Claim Documents

*SKK6745G (8551441894SG)
 [SKR2697B]
 TP
 NG HAN HOE
 Mar 1 2017 12:00AM
 [Pang See Hwee]
 Kent Seng Car Services

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	Use Viewer
Assessment Reports						1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)				Thumbnail	Print
1	07/03/17 10:34	Accident Statement From: SC - Reg. No: SKR2697B, Claimant: PANG SEE HWEI				 Load HTM	
Photos/Images						3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	06/03/17 16:53	General View				 Load JPG	☒
2	06/03/17 16:53	General View				 Load JPG	☒
3	06/03/17 16:53	General View				 Load JPG	☒
4	06/03/17 16:53	General View				 Load JPG	☒
5	06/03/17 16:53	General View				 Load JPG	☒
6	06/03/17 16:53	General View				 Load JPG	☒
7	06/03/17 16:53	General View				 Load JPG	☒
8	06/03/17 16:53	General View				 Load JPG	☒
9	06/03/17 16:53	General View				 Load JPG	☒
10	06/03/17 16:53	General View				 Load JPG	☒
11	06/03/17 16:53	General View				 Load JPG	☒
12	06/03/17 16:53	General View				 Load JPG	☒
13	06/03/17 16:53	General View				 Load JPG	☒
14	06/03/17 16:53	General View				 Load JPG	☒
15	06/03/17 16:53	General View				 Load JPG	☒
16	06/03/17 16:53	General View				 Load JPG	☒
17	06/03/17 16:53	General View				 Load JPG	☒
18	06/03/17 16:53	General View				 Load JPG	☒
19	06/03/17 16:53	General View				 Load JPG	☒
20	06/03/17 16:53	General View				 Load JPG	☒
21	06/03/17 16:53	General View				 Load JPG	☒
22	06/03/17 16:53	General View				 Load JPG	☒
23	06/03/17 16:53	General View				 Load JPG	☒
24	06/03/17 16:53	General View				 Load JPG	☒
25	06/03/17 16:53	General View				 Load JPG	☒
26	06/03/17 16:53	General View				 Load JPG	☒
27	06/03/17 16:53	General View				 Load JPG	☒
28	06/03/17 16:53	General View				 Load JPG	☒
29	06/03/17 16:53	General View				 Load JPG	☒
30	06/03/17 16:53	General View				 Load JPG	☒
31	06/03/17 16:53	General View				 Load JPG	☒
32	06/03/17 16:53	General View				 Load JPG	☒

33	06/03/17 16:53	General View	1	Load JPG	☒
34	06/03/17 16:53	General View	1	Load JPG	☒
35	06/03/17 16:53	General View	1	Load JPG	☒
36	06/03/17 16:53	General View	1	Load JPG	☒
37	06/03/17 16:53	General View	1	Load JPG	☒
38	06/03/17 16:53	General View	1	Load JPG	☒
39	06/03/17 16:53	General View	1	Load JPG	☒
40	06/03/17 16:53	General View	1	Load JPG	☒
41	06/03/17 16:53	General View	1	Load JPG	☒
42	06/03/17 16:54	Reinspection Photo	1	Load JPG	☒
43	06/03/17 16:54	Reinspection Photo	1	Load JPG	☒
44	06/03/17 16:54	Reinspection Photo	1	Load JPG	☒
45	06/03/17 16:54	Reinspection Photo	1	Load JPG	☒
46	06/03/17 16:54	Reinspection Photo	1	Load JPG	☒
47	06/03/17 16:54	Reinspection Photo	1	Load JPG	☒
48	06/03/17 16:54	Reinspection Photo	1	Load JPG	☒
49	06/03/17 16:54	Reinspection Photo	1	Load JPG	☒
50	06/03/17 16:54	Reinspection Photo	1	Load JPG	☒
51	06/03/17 16:54	Reinspection Photo	1	Load JPG	☒
52	06/03/17 16:54	Reinspection Photo	1	Load JPG	☒
53	06/03/17 16:54	Reinspection Photo	1	Load JPG	☒
54	06/03/17 16:54	Reinspection Photo	1	Load JPG	☒
55	06/03/17 16:55	Reinspection Photo	1	Load JPG	☒
56	06/03/17 16:55	Reinspection Photo	1	Load JPG	☒
57	06/03/17 16:55	Reinspection Photo	1	Load JPG	☒
58	06/03/17 16:55	Reinspection Photo	1	Load JPG	☒
59	06/03/17 16:55	Reinspection Photo	1	Load JPG	☒
60	06/03/17 16:55	Reinspection Photo	1	Load JPG	☒
61	06/03/17 16:55	Reinspection Photo	1	Load JPG	☒
62	06/03/17 16:55	Reinspection Photo	1	Load JPG	☒
63	06/03/17 16:55	Reinspection Photo	1	Load JPG	☒
64	06/03/17 16:55	Reinspection Photo	1	Load JPG	☒
65	06/03/17 16:55	Reinspection Photo	1	Load JPG	☒
66	06/03/17 16:55	Reinspection Photo	1	Load JPG	☒
67	06/03/17 16:55	Reinspection Photo	1	Load JPG	☒
68	06/03/17 16:55	Reinspection Photo	1	Load JPG	☒
69	06/03/17 16:55	Reinspection Photo	1	Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/03/17 15:54	TP GIA REPORT	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Reset Save Print

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG17004314/K1H3S2
Date: 30/03/2017REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100401110
Claimant Vehicle No:	SKK6745G	Insured Vehicle No:	SKR2697B
Date of Loss:	01/03/2017	Nature of Claim:	TP
		Claim No:	8551441894SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKK6745G	Engine No:	30258496N57D30A
Make & Model:	BMW X3 XDRIVE, 3.0 (A)	Chassis No:	WBAWY520500B54166
Reg. Date:	20/08/2013 (Man. Year: 2013)	Odometer:	77879 km
Colour:	Silver		
Engine Capacity:	2993 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/45R19	Rear Tyre Size:	245/45R19
Front Left Side:	Continental 7 mm	Rear Left Side:	Continental 7 mm
Front Right Side:	Continental 7 mm	Rear Right Side:	Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	02/03/2017	
Date Inspected:	02/03/2017	Inspected At:
		Kent Seng Car Services (HQ)
		BLK 1017 YISHUN INDUSTRIAL PARK A
		#01-240
		Singapore 768759
Estimated Period of Repair:	3.0 days	

Adjuster: KALVIN ANG WEI KUN

Manager: Ashley Chong Chin Yan

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	0.00F	*-F
2	6		*FRT BUMPER CLIPS	Necessary	0.00F	*-F
3	1		*FRT BUMPER SIDE RETAINER RH	*Check	0.00F	*-F
4	1		*FRT BUMPER REINFORCEMENT	*Check	0.00F	*-F
5	1		*FRT BUMPER PAD	*Check	0.00F	*-F
6	1		*FRT BUMPER GRILLE RH	*Check	0.00F	*-F
7	1		*FRT BUMPER SENSOR	*Check	0.00F	*-F
8	1		*FRT RH BUMPER FOG LAMP	*Check	0.00F	*-F
9	1		*FRT GRILLE CHROME MOULDING	*Check	0.00F	*-F
10	1		*FRT SUPPORT PANEL	*Check	0.00F	*-F
11	1		*FRT LH HEADLAMP ASSY	Cracked	0.00F	*-F
12	1		*FRT RH HEADLAMP ASSY	Cracked	0.00F	*-F
13	1		*(RH) HEADLAMP WASHER COVER & NOZZLE	Missing	0.00F	*-F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >



PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers
Block 779 Yishun Avenue 2 #01-1545 Singapore 760779
Tel : 62934822 Fax : 62963283

VEHICLE INSPECTION REPORT

Report No.	TP/0019/17	Date of Report	: 20 March 17
To :	Ng Han Hoe	Date of Request	: 2 March 17
		Report requested by	: Ng Han Hoe
420, Miltonia Close		Date of Accident	: 1 March 17
Singapore 768396		Date of Inspection	: 2 March 17
		Claim No.	: Third Party Claim

PARTICULARS OF DAMAGED VEHICLE

Registration Plate No	: SKK 6745 G	Odometer Reading	: 77,879 km
Make	: Bmw	Carrying Capacity	: 4
Model	: X3 (A)	Radio / Cassette / CD	: Yes
Year of Manufacture	: 2013	Air-Conditioner	: Yes
Colour	: Metallic Silver	Wing Mirror	: Yes
Engine Capacity	: 2,993 cc	Clock	: Yes
Engine No	: --	Seat Belts	: Yes
Chassis / Frame No	: WBAWY520500B54166	Others	: Nil

TYRE CONDITION

Front Left	: 7mm	Front Right	: 7mm
Make	: Continental	Make	: Continental
Rear Left	: 7mm	Rear Right	: 7mm
Make	: Continental	Make	: Continental
Spare	:	Road Wheels Type	: Alloy

(The above represents the approximate remaining life of tyre treads)

Jack & Tools	: Intact	Spare Tyre	: No
--------------	----------	------------	------

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Body Work	: Good
Paint Work	: Good
Handbrake	: Serviceable
Footbrake	: Serviceable
Steering	: Serviceable
Apparent engine modification	: Nil

This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.

ASSESSMENT

	<u>Repairer's Estimate (S \$)</u>	<u>Our Recommendation (S \$)</u>
Spare Parts :	10,155.00	8,250.40
Labour Charges :	1,430.00	1,030.00
Paint Work :	700.00	350.00
Towing Charges :	0.00	0.00
Others :	0.00	0.00
Totals :	12,285.00	9,630.40

Reduction (S \$) : 4,585.00

Recommended Reserve (S \$) : 7,700.00 (Lump Sum)

Estimated Normal Period of Repairs : 6 working days

CONTRIBUTIONS BY INSURED

Excess (S \$) : N/A

Others : --

GENERAL REMARKS

WITHOUT PREJUDICE

Continuation Sheet

The Assignment

The survey was conducted at Kent Seng Car Services, Block 1017, Yishun Industrial Park A, #01-240, Singapore 768759.

Follow-up inspection has been conducted.

Point of Impact

At the front portion.

Damages

The front bumper, front bumper sponge, front chrome grilles, headlamps assembly, etc.

Other parts were also found damaged. (see schedule for details)

Adjustment / Recommendation

We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle and we list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is \$9,630.40

Conclusion

The repairer has agreed to undertake repairs at a lump sum of \$7,700.00

We now revert to you for your decision on repairs.

Very truly yours

PRIORITY SERVICES



JIMMY S. T. LEE AMSOE, AMIRTE, AMSAE-AUS, MSAAA
Motor Appraiser


LAWRENCE NG
Motor Appraiser

Encl. Photographs of the damaged vehicle taken by us during inspection.

Vehicle No : SKK 6745 G Bmw X3 (A)

TP/0019/17

Workshop : Kent Seng Car Services

Replacement of Parts	Condition	Repairer's Estimate (S S)	Dist. %	Our Recommendation (S S)	Dist. %
To Supply :					
1pc. Front bumper	Dented	1,058.00		1,058.00	5
1pc. Front bumper RH side sensor	Malfunction	346.00		346.00	5
1pc. Front bumper RH centre sensor	Malfunction	346.00		346.00	5
1pc. Front bumper RH side bracket	Cracked	130.00		130.00	5
1pc. Front bumper LH side bracket <i>X not Damage</i>	Cracked	130.00		130.00	<i>X</i> 5
1pc. Front bumper inner sponge	Cracked	101.00		101.00	5
1pc. Front bumper reinforcement	Refit	560.00		--	5
1pc. Front bumper reinforcement RH bracket	Broken	32.00		32.00	5
1pc. Front bumper reinforcement LH bracket <i>X 100% 1/1</i>	Bent	32.00		32.00	<i>X</i> 5
1pc. Front bumper RH fog lamp	Cracked	231.00		231.00	5
1pc. Front bumper RH side grille	Cracked	109.00		109.00	5
1pc. Front bumper LH fog lamp	Refit	231.00		--	5
1pc. Front bumper LH side grille	Refit	109.00		--	5
1pc. Front bumper centre garnish grille	Refit	263.00		--	5
1pc. Front bumper centre garnish <i>X not Damage</i>	Cracked	550.00		550.00	<i>X</i> 5
1pc. Front bumper centre garnish lower moulding	Cracked	193.00		193.00	5
1pc. Front RH chrome grille	Cracked	185.00		185.00	5
1pc. Front LH chrome grille	Cracked	185.00		185.00	5
1pc. RH headlamp	Loop Cracked	1,857.00		1,857.00	5
1pc. RH headlamp washer nozzle cover	Broken / Dislodged / Missing	47.00		47.00	5
1pc. RH headlamp washer nozzle	Cracked	233.00		233.00	5
1pc. RH headlamp HID control unit <i>X not Damage</i>	Malfunction	505.00		505.00	<i>X</i> 5
1pc. LH headlamp	Loop Cracked	1,857.00		1,857.00	5
1pc. LH headlamp washer nozzle cover	Refit	47.00		--	5
1pc. LH headlamp washer nozzle	Refit	233.00		--	5
1pc. LH headlamp HID control unit <i>X not Damage</i>	Malfunction	505.00		505.00	<i>X</i> 5
Sub-Total :-					
Total Discount :-		10,075.00		8,632.00	
		--		431.60	
		10,075.00		8,200.40	
Special Nett Items :-					
Iset. Front bumper fasteners					
		Necessary	80.00	50.00	
Total For Parts :-					
		10,155.00		8,250.40	
Labour Charges :					

Vehicle No : SKK 6745 G Bmw X3 (A)

TP/0019/17

Workshop : Kent Seng Car Services

Replacement of Parts	Condition	Repairer's Estimate (S S)	Dist. %	Our Recommendation (S S)	Dist. %
To remove & replace the above listed parts, knock, straighten & reshape, cut & weld body panel parts where necessary, re-position & re-align, replacement of parts to the original position including adjustment. @ 1 inch		1,300.00		1,000.00 400	
Apply rust coating on the replaced & repaired panels.		60.00		--	
Check wiring & lighting system.		70.00		30.00	
Spray Painting :					
To putty & spray repaired & replaced body panels.		700.00		350.00 300	
Grand Total :-		12,285.00		9,630.40	

Surveyed By : Lawrence Ng

U/S 5800 / 4 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS3/AIG17004314/K1sbs2-1		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120 ATTN: SALIHA		Date : 09-07-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKR 2697B	Veh. Inspected	SKK 6745G	
Policy No.	2100401110	Coverage (\$)	0.00	
Claim No.	8551441894SG	Excess (\$)	0.00	
Assign From	SALIHA	Assign Date	26/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. X3 XDRIVE	c.c	2993	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WBAWY520500B54166	Colour	SILVER	
Odometer	77879	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45R19	CONTINENTAL	7 mm	
L/H Front Tyre	245/45R19	CONTINENTAL	7 mm	
R/H Rear Tyre	245/45R19	CONTINENTAL	7 mm	
L/H Rear Tyre	245/45R19	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/03/2018	Inspection Date	02/03/2017	
Survey held at	KENT SENG VEHICLE REPAIRER BLK 1017 YISHUN INDUSTRIAL PARK A #01-240 SINGAPORE 768759			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 6745G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DENTED	1,058.00	1,058.00
1	FRONT BUMPER RH SIDE SENSOR	MALFUNCTION	346.00	346.00
1	FRONT BUMPER RH CENTRE SENSOR	MALFUNCTION	346.00	346.00
1	FRONT BUMPER RH SIDE BRACKET	CRACKED	130.00	130.00
1	FRONT BUMPER LH SIDE BRACKET	NOT DAMAGE	130.00	-
1	FRONT BUMPER INNER SPONGE	CRACKED	101.00	101.00
1	FRONT BUMPER REINFORCEMENT	REFIT	560.00	-
1	FRONT BUMPER REINFORCEMENT RH BRACKET	BROKEN	32.00	32.00
1	FRONT BUMPER REINFORCEMENT LH BRACKET	TO REPAIR SEE LABOUR	32.00	-
1	FRONT BUMPER RH FOG LAMP	CRACKED	231.00	231.00
1	FRONT BUMPER RH SIDE GRILLE	CRACKED	109.00	109.00
1	FRONT BUMPER LH FOG LAMP	REFIT	231.00	-
1	FRONT BUMPER LH SIDE GRILLE	REFIT	109.00	-
1	FRONT BUMPER CENTRE GARNISH GRILLE	REFIT	263.00	-
1	FRONT BUMPER CENTRE GARNISH	NOT DAMAGE	550.00	-
1	FRONT BUMPER CENTRE GARNISH LOWER MOULDING	CRACKED	193.00	193.00
1	FRONT RH CHROME GRILLE	CRACKED	185.00	185.00
1	FRONT LH CHROME GRILLE	CRACKED	185.00	185.00
1	RH HEADLAMP	LOOP CRACKED	1,857.00	1,857.00
1	RH HEADLAMP WASHER NOZZLE COVER	BROKEN / DISLODGED / MISSING	47.00	47.00
1	RH HEADLAMP WASHER NOZZLE	CRACKED	233.00	233.00
1	RH HEADLAMP HID CONTROL UNIT	NOT DAMAGE	505.00	-
1	LH HEADLAMP	LOOP CRACKED	1,857.00	1,857.00
1	LH HEADLAMP WASHER NOZZLE COVER	REFIT	47.00	-
1	LH HEADLAMP WASHER NOZZLE	REFIT	233.00	-
1	LH HEADLAMP HID CONTROL UNIT	NOT DAMAGE	505.00	-
	LESS 5% DISCOUNT		-	-345.50
			10,075.00	6,564.50

Report Ref No. CS3/AIG17004314/K1sbs2-1

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No..2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER FASTENERS (SN)	NECESSARY	80.00	50.00
			80.00	50.00
	<u>LABOUR</u>			
	TO REMOVE & REPLACE THE ABOVE LISTED PARTS, KNOCK, STRAIGHTEN & RESHAPE, CUT & WELD BODY PANEL PARTS WHERE NECESSARY, RE-POSITION & RE-ALIGN, REPLACEMENT OF PARTS TO THE ORIGINAL INCLUDING ADJUSTMENT. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT LH BRACKET.		1,300.00	400.00
	APPLY RUST COATING ON THE REPLACED & REPAIRED PANELS.	NOT NECESSARY	60.00	-
	CHECK WIRING & LIGHTING SYSTEM.		70.00	30.00
	TO PUTTY & SPRAY REPAIRED & REPLACED BODY PANELS.		700.00	300.00
			2,130.00	730.00
	GRAND TOTAL		12,285.00	7,344.50
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,800.00

Report Ref No. CS3/AIG17004314/K1sbs2-1

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.