

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4367E
 Ref. No : TAX/06/18/2114
 Reg. Date : 20/12/2013
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : TEO BOON HAN STALWART WILSON
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 25/06/2018 10:40:00 AM
 Accident Reported Date / Time : 25/06/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096701
 Special Instruction to ARC, if any :
 SLK3074S
 Prepared Date : 25/06/2018 03:37:14 PM



Sathya Sai

26/6/2018

98072012

SathyaSai@lkkamto.com

- Lump Sum Repair
- Question mark item photo
- Photo after paint.

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U90-5718641

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	0.00
Total Spray Painting Charges	: 936.00	0.00
Total Material Charges	: 2,369.82	2,369.82
Other Charges	: 945.00	0.00
TOTAL	: 5,095.82	0.00
Lum Sum Total	: 5,100.00	0.00
No. of Repair Days	: 5.00	0.00 2 days
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 26/06/2018 01:47:32 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 26/06/2018 01:46:51 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	845.00	0.00 400
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00	0.00 ?
TO REPSRAY REAR BUMPER	378.00	0.00 200
Total Spray Painting & Panel Beating	936.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 50
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 40
TO REMOVE / REFIT SEAT	120.00	0.00 x
TO REMOVE & REFIT FUEL TANK	120.00	0.00 x
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0.00 x
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 x
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 x
Total Other Costs	945.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
61602-47091		6505476	FENDER RR/LH <i>R</i>	1	766.80	25.00	575.10	Replace	Replace	No
65638-47021		6505477	FENDER LINER <i>?</i> RR/LH	1	141.30	25.00	105.97	Replace	Replace	No
	COMMON		SMRT LOGO <i>✓ NEC</i>	1	7.80	0.00	7.80	Replace	Replace	No
	COMMON		STICKER DECAL 6555 <i>✓ NEC</i> 8888	1	21.60	0.00	21.60	Replace	Replace	No
62720-47031			QUARTER GLASS <i>X</i> RR/LH	1	168.10	25.00	126.07	Replace	Replace	No
	COMMON	4006314	SEALANT SIKAFLEX <i>X</i>	1	37.00	0.00	37.00	Replace	Replace	No
62940-16060			DUCT ASSY, <i>?</i> QUARTER	1	70.40	25.00	52.80	Replace	Replace	No
52592-47021			BUMPER SEAL, RR <i>?</i> LH	1	88.90	25.00	66.67	Replace	Replace	No
58307-47060		6505522	END PANEL <i>?</i>	1	602.10	25.00	451.57	Replace	Replace	No
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No
52159-47905		6505548	BUMPER REAR <i>✓ CUT</i>	1	458.60	25.00	343.95	Replace	Replace	No
52161-16010			BUMPER CLIPS <i>✓ NEC</i>	10	1.61	25.00	12.07	Replace	Replace	No
76088-47020		6505617	BUMPER LIP COVER <i>✓ Reform</i> RR/LH	1	72.20	25.00	54.15	Replace	Replace	No
			PIXEL STICKER <i>✓ NEC</i>	2	60.00	0.00	120.00	Replace	Replace	No
52576-47020		6505550	BUMPER SIDE <i>?</i> RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No
58308-47011			UNDER COVER SUB- <i>?</i> ASSY, RR FLOOR	1	514.50	25.00	385.87	Replace	Replace	No
81561-47170		6505461	TAIL LAMP LH <i>X</i>	1	548.40	10.00	493.56	Replace	Replace	No
TOTAL MATERIALS								2,962.31	2,962.28	
TOTAL MATERIALS(Discounted)							2,369.82	2,369.82		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									