

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	10	FRONT SUPPORT PANEL TOP GARNISH CLIPS	Reviewing	30	NECESSARY	
	11	COOLANT	Reviewing	60	NECESSARY	
	12	AIRCON GAS	Reviewing	80	NECESSARY	

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R/R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
 	1		TOWING CHARGE.	60	0	0	Reviewing		
 	2		TRANSFER REAR BOOTLD MECHANISM AND ACCESSORIES.	100	0	0	Reviewing		
 	3		REMOVE & REFIT REAR WINDSCREEN GLASS.	0	0	0	Reviewing		
 	4		WIRING CHECK AND RECTIFY WHERE ENECESSARY.	100	0	0	Reviewing		
 	5		LABOUR TO REMOVE REAR ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.	1000	0	0	Reviewing		
 	6		PUTTY & SPRAY PAINT REAR & ALL AFFECTED AREAS. (INNER & OUTER)	1400	0	0	Reviewing		
 	7		LABOUR TO REMOVE FRIT ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL SEAT, CUT / WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.	600	0	0	Reviewing		
 	8		AIRCON SYSTEM REPAIRS INCLUDING REPLACING ABOVE PARTS, PERFORM AIRCON LEAK TEST AND REFILL AIRCON GAS.	150	0	0	Reviewing		

EDIT	S/R NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPUJ BTRFN	DISC QUANTY%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	13	2			REAR BUMPER EXTENSION FILLER (L/HRH)			Cracked	120		25		180	Reviewing	
	14	1			REAR BUMPER CENTER DUST COVER			Serviceable	0		25		0	Reviewing	
	15	2			REAR BUMPER DUST COVER (L/HRH)			Serviceable	0		25		0	Reviewing	
	16	1			REAR END PANEL			Dented	630		25		472.5	Reviewing	
	17	1			REAR END PANEL TOP GARNISH			Deformed	121.6		25		91.2	Reviewing	
	18	2			REAR FENDER INNER TRIM BOARD (L/HRH)			Serviceable	0		25		0	Reviewing	
	19	1			FRONT BONNET			Dented	780		25		585	Reviewing	
	20	1			FRONT BONNET LOCK			Damaged	80.6		25		60.45	Reviewing	
	21	2			FRONT BONNET HINGE (L/HRH)			Dented	45.5		25		68.25	Reviewing	
	22	1			FRONT BONNET INSULATOR			Bent	280		25		210	Reviewing	
	23	1			FRONT BUMPER			Damaged	490.5		25		367.88	Reviewing	
	24	1			FRONT BUMPER TOYOTA LOGO			Necessary	87.1		25		65.33	Reviewing	
	25	1			FRONT BUMPER RADIATOR GRILLE			Broken	231.2		25		173.4	Reviewing	
	26	1			FRONT BUMPER LOWER GRILLE			Serviceable	0		25		0	Reviewing	
	27	1			FRONT BUMPER REINFORCEMENT			Serviceable	0		25		0	Reviewing	
	28	1			FRONT BUMPER REINFORCEMENT FOAM			Cracked	78.8		25		59.1	Reviewing	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Sum Insured	0		License Type		
Market Value	0		License Issue Date		mm/dd/yyyy
			License Expiration Date		mm/dd/yyyy
			Address	BLK 218D, BOON LAY AVENUE, #09-309, 644218, Singapore	
			Address type	Personal Correspondence	
			Gender	Male	
			Marital status	Unknown	
			Identification #	S8633578F	

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
DHAKAL Raghav	6/26/18 1:34 PM	11291.24	11291.24	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
LTA PARF COE Rebate Details.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 8, 2018
Immediate Advice with Mandate.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 8, 2018
Lkk Survey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 8, 2018
Lkk Rasurvey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 8, 2018
Immediate Advice.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	July 3, 2018
TP ESTIMATE- MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	June 28, 2018
SPY2433T INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	June 26, 2018
SLP1306K GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	June 26, 2018
SLQ7567D TP GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	June 26, 2018
TP PRI RECEIVED FROM WORKSHOP.msg	Letters and Correspondence	Workshop	DHAKAL Raghav	June 26, 2018