



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
Chassis No: JHMRC1890GC208387
License No: SKM1677S
Mileage: 39880
Engine No: K24W72013501

Document No: SVO18037542
Printed By: ARYCHUA
Order Date: 28. June 2018
Order Time: 12:15:02 PM
Service Advisor: ARY CHUA WAI NGEE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	incld GST
	TP DIRECT SETTLEMENT (J/NO: 70746)						
	OWNER: ZAINAL BIN SAPARI						
	OWNER INSURER: FWD INSURANCE PTE LTD						
	ACC DATE: 25/06/2018@09.10AM						
	SURVEYED BY: ADRIAN LING(LKKAUTO)28/06/2018@12.12PM						
	REF NO: SNM18D03141						
	TP INSURER: CHINA TAIPING INSURANCE (S) PTE LTD						
	TP VEH: GBH1851M						
04656-T6A-310ZZ	PAN SET,3RD SEAT	1	331.30	25	248.47	17.39	265.86
66100-T6A-300ZZ	PANEL COMPRR.	1	451.70	25	338.77	23.71	362.48
68100-T6A-Q10ZZ	TAILGATE COMP	1	1,049.80	25	787.35	55.11	842.46
74440-T6A-003	WEATHERSTRIPTAILGATE	1	115.10	25	86.32	6.04	92.36
74890-T6A-J01	GARNISH ASSYRR.LICENSE	1	225.90	25	169.42	11.86	181.28
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	1	172.10	25	129.07	9.03	138.10
73211-T6A-Q02	GLASS SET,RR.WINDSHIELD	1	991.20	25	743.40	52.04	795.44
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	17.60	25	26.40	1.85	28.25
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	16.60	25	12.45	0.87	13.32
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	16.60	25	12.45	0.87	13.32
73221-SR4-000	SPACERRR.W/SHIELD	4	3.90	25	11.70	0.82	12.52
73226-SZW-000	DAMPERSTD 5X5	2	8.30	25	12.45	0.87	13.32
76711-T6A-003	CAPPIVOT	1	4.70	25	3.52	0.25	3.77
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
33500-T6A-003	TAILLIGHT ASSYR.	1	821.70	25	616.27	43.14	659.41
34150-T6A-003	LIGHT ASSYR.LID	1	378.60	25	283.95	19.88	303.83
34155-T6A-003	LIGHT ASSYL.LID	1	378.60	25	283.95	19.88	303.83
76720-T4N-H01	ARM,RR.WIPER	1	41.70	25	31.27	2.19	33.46
76730-S3N-003	BLADEWINDSHIELD WIPER	1	42.00	25	31.50	2.21	33.71
75701-T6A-000	EMBLEMH	1	25.80	25	19.35	1.35	20.70
84615-T6A-N72ZD	LINING COMP,R.RR.SIDE	1	705.40	25	529.05	37.03	566.08
84640-T6A-003ZA	LINING ASSYRR.PANEL	1	101.60	25	76.20	5.33	81.53
04715-T6A-900ZZ	FACERR.BUMPER	1	557.20	25	417.90	29.25	447.15
71502-T6A-003ZF	FACER.RR.BUMPER GARNISH	1	75.30	25	56.47	3.95	60.42
71507-T6A-003ZF	FACEL.RR.BUMPER GARNISH	1	75.30	25	56.47	3.95	60.42
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	18.70	25	14.02	0.98	15.00
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	18.70	25	14.02	0.98	15.00
72841-SH3-315	OILSHEET	1	39.90	25	29.92	2.09	32.01
91505-TM8-003	CLIPBUMPER	18	2.00	25	27.00	1.89	28.89
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
NMDVR-IROADV9-2C	DVR,IROAD 2 CHANNEL	1	435.00		435.00	30.45	465.45
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
38387-SLE-003	ANTENNA ASSY,L.RR.	1	59.40	25	44.55	3.12	47.67
74940-TR0-003	BUZZER ASSYSMART	1	58.90	25	44.17	3.09	47.26
90650-SYY-003	GROMMETTAIL LIGHT	1	1.90	25	1.42	0.10	1.52
	SUM PARTS:				6,019.25	421.32	6,440.57
BOSUN	0672	1	30.00		30.00	2.10	32.10
	SUNDRIES						
BOBC	EXT-YBH	1	100.00		100.00	7.00	107.00
	BODY UNDERSIDE COATING (N)						

W.D=12

(A) in main estimate

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

SERVICE PRE-INVOICE

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
Chassis No: JHMRC1890GC208387
License No: SKM1677S
Mileage: 39880
Engine No: K24W72013501

Document No: SVO18037542
Printed By: ARYCHUA
Order Date: 28. June 2018
Order Time: 12:15:02 PM
Service Advisor: ARY CHUA WAI NGEE

BOJSE	0672	1	100.00	100.00	7.00	107.00
	BODY JOINT SEALANT.					
BML02I	EXT-YJ	1	120.00	120.00	8.40	128.40
	INSPECT RR LIGHTING MECHANISMS.					
	PERFORM WATER					
	TEST.(N)					
BA02R	EXT-YJ	1	140.00	140.00	9.80	149.80
	REMOVE & RENEW REVERSE					
	SENSORS-4 PCS (N)					
BOMISC1	EXT-YJ	1	280.00	280.00	19.60	299.60
	REMOVE & INSTALL REVERSE CAMERA					
	& CALIBRATION					
BG02R	EXT-YJ	1	300.00	300.00	21.00	321.00
	REPLACE REAR WINDSCREEN.(N)					
BOMISC1	0626	1	300.00	300.00	21.00	321.00
	REMOVE,INSTALL & CALIBRATE FR &					
	RR CAR VIEW CAMERA					
BOMISC1	0626	1	350.00	350.00	24.50	374.50
	RESET VEHICLE SMART KEY					
	ACCESS/ENTRY SYSTEM DOORS					
BKOT00R	EXT-YJ	1	350.00	350.00	24.50	374.50
	REMOVE & RENEW RR FLOOR					
	INSULATOR.(N)					
BMI03D	EXT-YJ	1	350.00	350.00	24.50	374.50
	REMOVE & INSTALL RR COMPARTMENT					
	LININGS WITH GLASS					
	GARNISHES.(N)					
BKTG02R	EXT-YJ	1	450.00	450.00	31.50	481.50
	REMOVE & TRANSFER ITEMS TO NEW					
	TAILGATE. ADJUST &					
	ALIGN TAILGATE.(N)					
BP01R	EXT-YBH	1	2,700.00	2,700.00	189.00	2,889.00
	SPRAY PAINTI ON					
	REPAIRED/REPLACED AREAS.(10PX					
	\$450)					
BKRP22B	EXT-YJ	1	3,360.00	3,360.00	235.20	3,595.20
	CUT OFF & RENEW RR FLOOR PANEL					
	RR R PANEL.					
	STRAIGHTEN ALIGN & RENEW DAMAGE					
	PARTS.					
BO-V-KOOL-RWS	SUPPLY & INSTALL SOLAR FILM ON					
	REAR WINDSCREEN.	1	300.00	300.00	21.00	321.00
SUM LABOUR:			8,930.00		625.10	9,555.10
SUM EXT SERVICE:			300.00		21.00	321.00
TOTAL SGD			15,249.25		1,067.42	16,316.67

Total Payable (SGD)

16,316.67

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Jun 2018		27 Jun 2018 14:32 Edit Adj Rpt	\$15,249.25 Edit Estimates	\$15,249.25 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	M/S MIN PHYO CONSTRUCTION PTE LTD , Co. Reg. No.: 200810354R								
Main Claimant:	ZAINAL BIN SAPARI , ID: S1690964E								
Vehicle Reg. No.:	SKM1677S	Date of Loss:	25/06/2018 09:00 - :59 [17 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03141C02	Policy/Cover Note No.:	DMCVSN3014341800 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBH1851M	Policy No. (Claimant):	PNPV2018-00000896						
		Excess:	\$0.00						
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 06/07/2018]								
Driver/Custodian (Insured):	MIN KHIN MAUNG THAN (35 / Male), NRIC: G2127955U, Tel: +6590605292								
Adj Asg. Remarks:	EST \$26,400.83, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKM1677S (SNM18D03141C02)
[GBH1851M]
TP
ZAINAL BIN SAPARI
Jun 25 2018 9:00AM
[M/S MIN PHYO CONSTURCTION PTE LTD]
Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		☒
No	Finalized On	Torque 5 Pte Ltd (Kaki Bukit)								Thumbnail	Print
1	25/06/18 11:50	Accident Statement								Load HTM	
									3 per page		☒
No	Finalized On	Torque 5 Pte Ltd (Kaki Bukit)								Thumbnail	Print
1	25/06/18 11:49	INSURANCE CERT [Linked Accident Report Documents]								Load JPG	☒
2	25/06/18 11:49	Driving License [Linked Accident Report Documents]								Load JPG	☒
3	25/06/18 11:49	Identification Card [Linked Accident Report Documents]								Load JPG	☒
4	25/06/18 11:49	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
5	25/06/18 11:49	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
6	25/06/18 11:49	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
7	25/06/18 11:49	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
8	25/06/18 11:49	Driving License [Linked Accident Report Documents]								Load JPG	☒
9	25/06/18 11:49	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
10	25/06/18 11:49	Accident Photo [Linked Accident Report Documents]								Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print
1	06/08/18 18:59	General View								Load JPG	☒
2	06/08/18 18:59	General View								Load JPG	☒
3	06/08/18 18:59	General View								Load JPG	☒
4	06/08/18 18:59	General View								Load JPG	☒
5	06/08/18 18:59	General View								Load JPG	☒
6	06/08/18 18:59	General View								Load JPG	☒
7	06/08/18 18:59	General View								Load JPG	☒
8	06/08/18 18:59	General View								Load JPG	☒
9	06/08/18 18:59	General View								Load JPG	☒
10	06/08/18 18:59	General View								Load JPG	☒
11	06/08/18 18:59	General View								Load JPG	☒
12	06/08/18 18:59	General View								Load JPG	☒
13	06/08/18 18:59	General View								Load JPG	☒
14	06/08/18 18:59	General View								Load JPG	☒
15	06/08/18 18:59	General View								Load JPG	☒
16	06/08/18 18:59	General View								Load JPG	☒
17	06/08/18 18:59	General View								Load JPG	☒
18	06/08/18 18:59	General View								Load JPG	☒
19	06/08/18 18:59	General View								Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Torque 5 Pte Ltd (Kaki Bukit)	Thumbnail	Print
20	06/08/18 18:59	General View	 Load JPG	☒
21	06/08/18 18:59	General View	 Load JPG	☒
22	06/08/18 18:59	General View	 Load JPG	☒
23	06/08/18 18:59	General View	 Load JPG	☒
24	06/08/18 18:59	General View	 Load JPG	☒
25	06/08/18 18:59	General View	 Load JPG	☒
26	06/08/18 18:59	General View	 Load JPG	☒
27	06/08/18 18:59	General View	 Load JPG	☒
28	06/08/18 18:59	General View	 Load JPG	☒
29	06/08/18 18:59	General View	 Load JPG	☒
30	06/08/18 18:59	General View	 Load JPG	☒
31	06/08/18 18:59	General View	 Load JPG	☒
32	06/08/18 18:59	General View	 Load JPG	☒
33	06/08/18 18:59	General View	 Load JPG	☒
34	06/08/18 18:59	General View	 Load JPG	☒
35	06/08/18 18:59	General View	 Load JPG	☒
36	06/08/18 18:59	General View	 Load JPG	☒
37	06/08/18 18:59	General View	 Load JPG	☒
38	06/08/18 18:59	General View	 Load JPG	☒
39	06/08/18 18:59	General View	 Load JPG	☒
40	06/08/18 18:59	General View	 Load JPG	☒
41	06/08/18 18:59	General View	 Load JPG	☒
42	06/08/18 18:59	General View	 Load JPG	☒
43	06/08/18 18:59	General View	 Load JPG	☒
44	06/08/18 18:59	General View	 Load JPG	☒
45	06/08/18 18:59	General View	 Load JPG	☒
46	06/08/18 18:59	General View	 Load JPG	☒
47	06/08/18 18:59	General View	 Load JPG	☒
48	06/08/18 18:59	General View	 Load JPG	☒
49	06/08/18 18:59	General View	 Load JPG	☒
50	06/08/18 18:59	General View	 Load JPG	☒
51	06/08/18 19:00	General View	 Load JPG	☒
52	06/08/18 19:00	General View	 Load JPG	☒
53	06/08/18 19:00	General View	 Load JPG	☒
54	06/08/18 19:00	General View	 Load JPG	☒
55	06/08/18 19:00	General View	 Load JPG	☒
56	06/08/18 19:00	General View	 Load JPG	☒
57	06/08/18 19:00	General View	 Load JPG	☒
58	06/08/18 19:00	General View	 Load JPG	☒
59	06/08/18 19:00	General View	 Load JPG	☒
60	06/08/18 19:00	General View	 Load JPG	☒
61	06/08/18 19:00	General View	 Load JPG	☒
62	06/08/18 19:00	General View	 Load JPG	☒
63	06/08/18 19:00	General View	 Load JPG	☒
64	06/08/18 19:00	General View	 Load JPG	☒
65	06/08/18 19:00	General View	 Load JPG	☒
66	06/08/18 19:00	General View	 Load JPG	☒
67	06/08/18 19:00	General View	 Load JPG	☒
68	06/08/18 19:00	General View	 Load JPG	☒
69	06/08/18 19:00	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Torque 5 Pte Ltd (Kaki Bukit)	Thumbnail	Print
70	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
71	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
72	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
73	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
74	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
75	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
76	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
77	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
78	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
79	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
80	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
81	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
82	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
83	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
84	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
85	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
86	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
87	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
88	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
89	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
90	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
91	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
92	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
93	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
94	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
95	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
96	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
97	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
98	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
99	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
100	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
101	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
102	06/08/18 19:00	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/06/18 14:32	OI GIA	 Load PDF	
2	27/06/18 14:32	REPAIR EST WITH TP GIA	 Load PDF	
No	Finalized On	Torque 5 Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	25/06/18 11:49	Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
2	25/06/18 11:49	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/09/18 14:45	Supplementary	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Torque 5 Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	25/06/18 11:50	Accident Statement	 Load HTM	

Assessment Reports			1 per page	☒
No	Finalized On	Torque 5 Pte Ltd (Kaki Bukit)	Thumbnail	Print
Photos/Images			3 per page	☒
No	Finalized On	Torque 5 Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	25/06/18 11:49	INSURANCE CERT	 Load JPG	☒
2	25/06/18 11:49	Driving License	 Load JPG	☒
3	25/06/18 11:49	Identification Card	 Load JPG	☒
4	25/06/18 11:49	Accident Photo	 Load JPG	☒
5	25/06/18 11:49	Accident Photo	 Load JPG	☒
6	25/06/18 11:49	Accident Photo	 Load JPG	☒
7	25/06/18 11:49	Accident Photo	 Load JPG	☒
8	25/06/18 11:49	Driving License	 Load JPG	☒
9	25/06/18 11:49	Accident Photo	 Load JPG	☒
10	25/06/18 11:49	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Torque 5 Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	25/06/18 11:49	Sketch Plan	 Load JPG	☒
2	25/06/18 11:49	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18011738/ARD3E2

Date: 03/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN3014341800

Claimant Vehicle
No : SKM1677SInsured Vehicle
No : GBH1851M

Date of Loss: 25/06/2018

Nature of Claim: TP

Claim
No: SNM18D03141C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKM1677S**

Make & Model: HONDA ODYSSEY, 2.4 (A)

Engine No: K24W72013501

Reg. Date: 18/01/2017 (Man. Year: 2016)

Chassis No: JHMRC1890GC208387

Colour: Black

Odometer: 39880 km

Engine Capacity: 2356 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,583.84	6,049.25	2,534.59	29.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,180.00	9,200.00	6,980.00	43.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	24,763.84	15,249.25	9,514.59	38.42
+ GST 7.00/7.00% (\$\$)	1,733.47	1,067.45	666.02	38.42
Nett Amount (\$\$)	26,497.31	16,316.70	10,180.61	38.42

INSPECTION

Date of Assignment: 27/06/2018

Date Inspected: 28/06/2018 Inspected At:

Kah Motor Co Sdn Bhd (Ubi)
15 Ubi Road 4
Singapore 408610

Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Sep 2018)
Parts:	M1-MPV	HONDA ODYSSEY 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKM1677S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PAN SET, 3RD SEAT	Necessary	248.47 FS	*248.47 FS
2	1		*TAILGATE COMP	Distorted	787.35 FS	*787.35 FS
3	1		*WEATHERSTRIPTAILGATE	Cut	86.32 FS	*86.32 FS
4	1		*LOCKTAILGATE	Not Necessary	136.27 FS	*- FS
5	1		*STAY ASSYR.TAILGATE OPEN	Not Necessary	121.05 FS	*- FS
6	1		*STAY ASSYL.TAILGATE OPEN	Not Necessary	121.05 FS	*- FS
7	1		*GARNISH ASSYRR.LICENSE	Cracked	169.42 FS	*169.42 FS
8	1		*MOLDING ASSYRR.LICENSE GARN	Cracked	129.07 FS	*129.07 FS
9	1		*GLASS SET,RR.WINDSHIELD	Necessary	743.40 FS	*743.40 FS
10	2		*MOLDINGRR.WINDSHIELD SIDE	Necessary	26.40 FS	*26.40 FS
11	1		*MOLDINGR.RR.WINDSHIELD CORNER	Necessary	12.45 FS	*12.45 FS
12	1		*MOLDING.RR.WINDSHIELD CORNER	Necessary	12.45 FS	*12.45 FS
13	1		*SPACERRR.W/SHIELD (4PCS)	Necessary	11.70 FS	*11.70 FS
14	1		*DAMPER STD 5X5 (2PCS)	Necessary	12.45 FS	*12.45 FS
15	1		*CAPPIVOT	Necessary	3.52 FS	*3.52 FS
16	1		*WINDSCREEN SEALANT	Necessary-1PC ONLY	120.00 FS	*60.00 FS
17	1		*TAILLIGHT ASSYR	Cut	616.27 FS	*616.27 FS
18	1		*TAILLIGHT ASSYL	Not Necessary	616.27 FS	*- FS
19	2		*LIGHT ASSYLICENSE	Not Necessary	46.80 FS	*- FS
20	1		*LIGHT ASSYR.LID	Cracked	283.95 FS	*283.95 FS
21	1		*LIGHT ASSYL.LID	Cracked	283.95 FS	*283.95 FS
22	1		*CAMERA ASSYMVCS RR	Not Necessary	382.35 FS	*- FS
23	1		*ANTENNA ASSY,L.RR	Not Necessary	44.55 FS	*- FS
24	1		*BUZZER ASSYSMART	Not Necessary	44.17 FS	*- FS
25	1		*WIPER MOTOR ASSY	Not Necessary	176.77 FS	*- FS
26	1		*ARM,RR.WIPER	Cut	31.27 FS	*31.27 FS
27	1		*BLADEWINDSHIELD WIPER	Cut	31.50 FS	*31.50 FS
28	1		*EMBLEMH	Necessary	19.35 FS	*19.35 FS
29	1		*LINING COMP,R.RR.SIDE	Deformed	529.05 FS	*529.05 FS
30	1		*LINING ASSYRR.PANEL	Deformed	76.20 FS	*76.20 FS
31	1		*LINING COMPL.RR.SIDE	Not Necessary	529.05 FS	*- FS
32	1		*LINING ASSYTAILGATE LOWER	Not Necessary	151.65 FS	*- FS
33	1		*POCKETTAILGATE LINING PULL	Not Necessary	7.87 FS	*- FS
34	1		*FACERR.BUMPER	Deformed	417.90 FS	*417.90 FS
35	1		*FACER.RR.BUMPER GARNISH	Deformed	56.47 FS	*56.47 FS
36	1		*FACEL.RR.BUMPER GARNISH	Deformed	56.47 FS	*56.47 FS
37	1		*SPACERRR.BUMPER SIDE	Necessary	14.02 FS	*14.02 FS
38	1		*SPACERL.RR.BUMPER SIDE	Necessary	14.02 FS	*14.02 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*REFLECTOR ASSYR.RR	Not Necessary	33.37 FS	*- FS
40	1		*REFLECTOR ASSYL.RR	Not Necessary	33.37 FS	*- FS
41	1		*OILSHEET	Necessary	29.92 FS	*29.92 FS
42	18		*CLIPBUMPER	Necessary	27.00 FS	*27.00 FS
43	4		*ACT RR.SENSOR	Damaged	320.00 FS	*320.00 FS
44	1		*DVR.IROAD 2 CHANNEL	Missing	435.00 FS	*435.00 FS
45	1		*NUMBER PLATE WITH CASING	Bent	45.00 FS	*45.00 FS
46	1		*SUNDRIES	Necessary	60.00 FS	*30.00 FS
47	1		*ANTENNA ASSY,L.RR	Necessary	44.55 FS	*44.55 FS
48	1		*BUZZER ASSYSMART	Necessary	44.17 FS	*44.17 FS
49	1		*GROMMETTAIL LIGHT	Necessary	1.42 FS	*1.42 FS
50	1		*PANEL COMP, REAR	Distorted	338.77 FS	*338.77 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	8,583.84	6,049.25
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING SERVICE	New	60.00	0.00
2	SUPPLY & INSTALL SOLAR FILM ON REAR WINDSCREEN	New	300.00	300.00
3	BODY UNDERSIDE COATING	New	100.00	100.00
4	BODY JOINT SEALANT	New	100.00	100.00
5	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	New	180.00	120.00
6	REMOVE & RENEW REVERSE SENSORS	New	240.00	140.00
7	REPLACE RR WINDSCREEN	New	350.00	300.00
8	REMOVE, INSTALL & CALIBRATE FRONT CAR VIEW CAMERA	New	350.00	300.00
9	REMOVE & INSTALL REVERSE CAMERA & CALIBRATION	New	350.00	280.00
10	STRAIGHTEN ALIGN & PULL BACK EXHAUST SYSTEM	New	350.00	0.00
11	RESET VEHICLE SMART KEY ACCESS / ENTRY SYSTEM DOORS	New	400.00	350.00
12	REMOVE & INSTALL REAR A/C WITH FITTINGS A/C GAS	New	400.00	0.00
13	REMOVE & INSTALL FUEL TANK FUEL PIPES	New	450.00	0.00
14	REMOVE & RENEW RR FLOOR INSULATOR	New	450.00	350.00
15	REMOVE & RENEW RR FLOOR INSULATOR	New	450.00	0.00
16	REMOVE & INSTALL RR COMPARTMENT LININGS WITH GLASS	New	550.00	350.00
17	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &	New	550.00	450.00
18	STRAIGHTEN ALIGN & PULL BACK EXHAUST SYSTEM	New	550.00	0.00
19	SPRAY PAINTING ON REPAIRED / REPLACED AREAS (10PX\$450)	New	4,500.00	2,700.00
20	CUT OFF & RENEW RR FLOOR PANEL RR R PANEL	New	5,500.00	3,360.00
Gross Labour Cost (\$\$)			16,180.00	9,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >