

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

AIG Asia Pacific Insurance Pte. Ltd
 AIG Building
 78 Shenton Way #08-16
 Singapore (079120)
 ATTN: MOTOR CLAIM DEPARTMENT
 Tel : 6419 3000 Fax : 6835 7416

*Not Authorized
 U/Smp 87
 Running After Paint*

ACCIDENT REPAIR ON : SKB3302T
MODEL : FORD MONDEO
POLICY NO : GA126811
CHASSIS NO : WF0DXXGBBDBD84677
MANUFACTURING YEAR : 2011
DATE / TIME OF ACCIDENT: 25/06/2018 Time: 2030Hrs ALONG WEST COAST HIGHWAY TWDS CITY
THIRD PARTY VEHICLE NO : SKU6128K

Date: 20/06/2018
 Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price S\$	Condition	Amount S\$
S/N					
1	Bootlid <i>R ?</i>	1			
2	Bootlid Emblem <i>?</i>	1			
3	Bootlid Lettering "Mondeo" <i>MC -</i>	1			
4	Bootlid Lettering "Ecoboost" <i>MC -</i>	1			
5	Bootlid Finisher <i>CM -</i>	1			
6	Bootlid Weatherstrip <i>SM X</i>	1			
7	Boot Lid Lamp LH <i>SM X</i>	1			
8	Boot Lid Lamp RH <i>SM X</i>	1			
9	Bootlid Gasket LH <i>SM X</i>	1			
10	Bootlid Gasket RH <i>SM X</i>	1			
11	Rear Bumper <i>BR -</i>	1			
12	Rear Bumper Side Retainer LH <i>SM X</i>	1			
13	Rear Bumper Side Retainer RH <i>DR -</i>	1			
14	Rear Bumper Centre Bracket <i>?</i>	1			
15	Rear Bumper Bracket (17B930) <i>?</i>	1			
16	Rear Bumper Lower Spoiler <i>?</i>	1			
17	Rear Bumper Sensor <i>?</i>	1			
18	Rear Bumper Sensor Ring <i>?</i>	1			
19	Rear Bumper Reflector LH <i>SM X</i>	1			
20	Rear Bumper Reflector RH <i>SM X</i>	1			
21	Rear Bumper Tow Cover <i>DR -</i>	1			
22	Rear Bumper Reinforcement <i>?</i>	1			
23	Rear Bumper Sponge <i>?</i>	1			
24	Rear Bumper Lock Assy <i>R X</i>	1			
25	Rear End Panel <i>R X</i>	1			
26	Rear End Panel Top Garnish <i>SM X</i>	1			
27	Tail Lamp LH <i>SM X</i>	1			
28	Tail Lamp RH <i>SM X</i>	1			
29	Tail Lamp Bracket LH <i>R X</i>	1			
30	Tail Lamp Bracket RH <i>R X</i>	1			
31	Rear Fender LH <i>R X</i>	1			
32	Rear Fender RH <i>R X</i>	1			
33	Rear Fender Shield LH <i>SM X</i>	1			
34	Rear Fender Shield RH <i>SM X</i>	1			

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 its subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

Sub-Total: -
 Less Discount 20% -
Total Parts: -

Special Nett Items

1	Anti-rust coating	4	80.00	na	320.00	X
2	Rear Bumper Clips	10		na	-	✓
3	Rear End Panel Top Garnish Clips	10		na	-	X
4	Rear Fender Shield Clips	20		na	-	X
					Total Parts:	320.00

Labour Charges For Front and Side Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.				1,500.00	400l
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities				1,500.00	600l
3	Provide skill labour to disconnect and check electrical wiring				30.00	20l
4	Remove and refit rear end panel lining and garnish to facilitate repair			na	100.00	X
5	Remove and replace bumper sensors				100.00	60l
6	Realign Exhaust Pipe			na	50.00	X
7	Remove and replace exhaust pipe/system to facilitate repair recommended specification			na	120.00	X
Total Labour:					3,400.00	
					Total Parts & Labour:	3,720.00
					GST 7%	260.40
					Grand Total:	3,980.40

Estimate Repair Duration 10 days
 4 days

ACCIDENT VEHICLE OF : SKB3302T

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by:

Name : Kenneth
 Company : CKK
 Date : 29/6/18
 Time : 10am
 Contact No: 96910663
 Email : _____