

**REPAIR ESTIMATE\***

VEHICLE NO : SH 6781Y

DATE 27/6/2018 15:12

AXIA  
JM

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>X repair</i>			\$ 562.30
	Front Bumper Bracket Top (RH) <i>?</i>			\$ 22.40
	Front Bumper Retainer Mounting <i>?</i>			\$ 9.20
	<b>SUB TOTAL</b>			<b>\$ 593.90</b>
	<b>LESS 20%</b>			<b>\$ 118.78</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 475.12</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>350.00</del> <sup>100</sup>
	Spray Painting Charge			\$ <del>250.00</del> <sup>200</sup>
	<b>TOTAL LABOUR</b>			<b>\$ 600.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 1,075.12</b>

*Kalvin (CA)*  
*28/6/18 10:10hrs*  
*2 Pys*  
*PIP*  
*After Rep phl*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.